

INGHAM COUNTY

Monumentation and Remonumentation Project

P.O. Box 319 - Mason, MI 48854
(517) 676-7210

Ingham County Peer Review Committee Meeting minutes March 25, 1997.
Meeting held in the Conference Room at the Hilliard Building in Mason, MI

Present: Ron Lester, PS; Maurice Mahieu, PS; Ron Helsel, PS; Dave Clifford, PS, representing Enger Engineering; David Lohr, PS; Larry Bryan, PS; and Doug Stover, Director, Ingham County Equalization Office.

Ron Lester called meeting to order at 9:30 A.M.

Clifford, Lohr, Bryan, and Mahieu seated to review one private corner submitted by Helsel.


Lester moved **F-10, Ingham Township** be accepted into Ingham County Remonumentation plan. Clifford seconded. Corner **accepted** after discussion and technical review.

This portion of meeting recessed and reconvened with Bryan, Clifford, Lohr, and Helsel seated to review one private corner submitted by Mahieu.

Lester moved **C-12, White Oak Township** be accepted into Ingham County Remonumentation plan. Clifford seconded. Corner **accepted** after discussion and technical review.

Meeting adjourned at 9:40 A.M.

Next peer review meeting scheduled as needed and requested by monumentation surveyors.



Ronnie M. Lester, PS
Ingham County Representative



DUC
 JUL
 T 700
 25 Aug 97
 50
 C. 3/4" Bar & Yellow Plastic Cap Stamped
 PA345 PS 25837 NRZ
 Found Nail & Tag #18998 in W. Side 30" Maple 30° 35.75
 Found Nail & Tag #18998 in N. Side 35" # OAK 100° 20.39
 Set Nail & Tag #28409 in S.E. Side 10" Maple 215° 45.42
 Found NUT #18998 in S. Side 23" Maple 280° 25.45
 Found Nail & Tag #18998 in N. Side 56" OAK 285° 40.75

50
 C-11
 B. Searched at apparent location of
 Corner and Found 1/2" Bar & Mutilated
 Cap 2' East of Centerline Procter
 Road opposite Anchor Post to West,
 Notching All Forty Withnesses.
 Drakes 10" OAK Still stands (Now 56")
 and withness distance is not best
 match to 1/2" Iron. Pulled 36.0'
 from Face of 56" OAK and Examined
 6'x6' hole 2' Deep into natural
 ground. Hole encompassed location
 of iron. Found No further indi-
 cation of corner. As road appears
 to be cut about 2-3' believe stone
 was destroyed in this cut.
 Accepted 1/2" Iron as perpetuation
 of corner because of inability
 to recover any other evidence
 of a historical nature. Replaced
 1/2" Bar with 3/4" Bar & PA345
 Cap.