INGHAM COUNTY

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 1 PG 639

FILED

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	Sec. 25 T. 1 N. R. 1 E.	M-9, M-11
2. PROPERTY CONTROLLING IN SECTION	T. N. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

Jul 18 4 04 PM '72
REGISTER OF DEEDS
Ronald M. Lewis
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Ronnie M. Lester do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on June 9, 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

M-9 Original monument and accessories obliterated

M-11 Original monument and accessories obliterated

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

M-9 Set 1/2" bar of centerline of Holland Rd. & Parman Rd. Original measurement West in close accord with measured distance West. Prorated measurements North and South.

M-11 Set 1/2" bar 18.48' North of found NW Corner of Section 31, T1N, R2E on township line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-9 1/2" bar centerline Holland & Parman Roads
Nail & Tag East side power pole, NW, 75.78'
Nail & Tag Northside 12" Maple, SW, 69.59'
Nail & Tag West side fence post, SE, 46.74'
M-11 1/2" bar centerline Fitchburg Rd. & Parman Roads
Centerline iron fence post, NW, 67.60'
Centerline iron fence post, WNW, 71.57'
Nail & Tag South side fence post, SE, 50.75'

SIGNED BY Ronnie M. Lester DATE June 14, 1972

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

320 Form No. ML M735
DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 3 PG 115

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY 30	T. 1 N. R. 2 E.	A-9, B-10, A-10, A-11
2. PROPERTY CONTROLLING IN SECTION	T. N. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R. E. W.	
4. LOT NO.	, RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Oscar Boss, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above identified with circles on index code diagram — over — were, in a field survey on MAY 5 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

FILED

APR 25 9 21 AM '74

REGISTER OF DEEDS

Enid M. Lewis

INGHAM COUNTY, MICH.

A. Description of original monument and accessories and or subsequent restoration:

A-9 UNKNOWN

B-10 "

A-10 "

A-11 "

B. Description of corner evidence found and or method applied in restoring or re-establishing corner:

A-9 Set IRON - FENCE LINE

B-10 SET IRON - FENCE INTERSECTION

A-10 SET IRON - FENCE ROW

A-11 FD. IRON

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-9 East 31.15 Nail fd. W/S fence post
S.30°E. 34.23 Nail top stump
North 35.54 5/8" iron

B-10 West 19.0 Nail S/S fence
S.50°W. 56.95 Nail E/S Dlb. Trunked Maple
South 20.36 Nail W/S Muti-trunked tree 8"

A-10 Top of South edge cement covert
23.3 N.50°W.
iron

A-11 N.30°W. 72.9 Nail E/S tele pole
East 47.2 Nail fd. S/S fence post
N.20°E. 29.5 top of cement covert

SIGNED BY Oscar Boss DATE 4-10-74

SURVEYOR'S MICHIGAN REGISTRATION NO. 13574 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY Oscar Boss DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

701

Form No. MLM735
DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 3 PG 321

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 1 N. R. 1 E.	K-8, K-9
2. PROPERTY CONTROLLING IN SECTION	T. N. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

FILED

JAN 29 1 40 PM '75

REGISTER OF DEEDS
Enid M. Lewis
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, George M. Young do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on Jan. 7, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

K-8, Original corner and accessories not found.

K-9, Original corner and accessories not found.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

K-8, Set R.R. Spike on line midway between K-9 and K-7.

K-9, Found 3/4" Iron Pipe

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-8, R.R. Spike - Nail in 30" Oak N 30° E 76.67'
Nail in 24" Hickory N 85° E 29.06'
Nail in 18" Oak S 45° E 38.4'

K-9, 3/4" Iron Pipe- Nail in 15" Hickory S 45° E 71.57'
Nail in 20" Oak S 25° W 132.06'
Nail in 10" Oak N 45° W 80.05'

STATE OF MICHIGAN
GEORGE M. YOUNG
LAND SURVEYOR
No. 17640
REGISTERED LAND SURVEYOR

SIGNED BY George M. Young DATE January 20, 1975

SURVEYOR'S MICHIGAN REGISTRATION NO. 17640 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____ (SEAL)
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

804 Form No. MLM736
DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 3 PG 323

FILED

JAN 29 1 49 PM '75

REGISTER OF DEEDS

Enid M. Lewis

INGHAM COUNTY, MICH

REGISTER OF DEEDS STAMP AND FILING NUMBER

FOR CORNERS OF —:	LOCATED IN —:				CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 1	N. * S. R. 1	E. ** W.		I-7, J-7, K-7
2. PROPERTY CONTROLLING IN SECTION	, T.	N. S. R.	E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION	, T.	N. S. R.	E. W.		

4. LOT NO. , RECORDED PLAT

5. PRIVATE CLAIMS

I, George M. Young do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram — over) were in a field survey on Jan. 7, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 , found, recovered, restored, established or re established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

I-7, Original monument not found

J-7, Original monument not found

K-7, Original monument not found

B. Description of corner evidence found and or method applied in restoring or re-establishing corner:

I-7, Found 1/2" iron pipe in pavement.

J-7, Set 1" iron pipe in creek bed midway between I-7 and K-7.

K-7, Found RR spike set beside stone.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corners:

I-7, 1/2" iron pipe - Nail in 15" Maple N 85° E 35.09'
Nail in 24" Oak West 22.10'
Nail in 24" Oak S 45° W 40.18'

J-7, Set 1" iron pipe - Nail in 10" Oak NW 28.10'
Nail in 10" Poplar NW 26.90'
Nail in 18" Poplar SE 12.60'

K-7, R.R. Spike & Stone - Nail in Power Pole N 45° W 38.00'
Nail in 8" Cedar N 10° E 49.68'
Nail in 8" Cedar N 20° E 44.70'

STATE OF MICHIGAN
GEORGE M. YOUNG
LAND SURVEYOR
NO. 17640
REGISTERED LAND SURVEYOR

SIGNED BY George M Young DATE January 20, 1975

SURVEYOR'S MICHIGAN REGISTRATION NO. 17640 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Form No. MLM735
DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.
FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 3 PG 365

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 1 N. R. 2 E.	A-6 and A-8
2. PROPERTY CONTROLLING IN SECTION	T. N. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R. E. W.	

4. LOT NO. , RECORDED PLAT

5. PRIVATE CLAIMS

FILED

APR 1 9 59 AM '75

REGISTER OF DEEDS

Ernie M. Lewis

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, George M. Young do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index / code diagram—over) were in a field survey on Feb. 27, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and / or subsequent restoration:

A-6 Original monument and accessories lost and obliterated.

A-8 Original monument and accessories lost and obliterated.

B. Description of corner evidence found and / or method applied in restoring or re-establishing corner:

A-6 Restored corner by proportionate measurement.

A-8 Found 1/2" iron rod in road intersection.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-6 Set 1/2" rod in Mon. Box - Nail in P.P. N 85° W 50.72'
Nail in 30" Maple S 25° W 80.98'
Nail in 36" Maple N 89° E 27.06'

A-8 1/2" Iron with Cap. - Nail in 12" Walnut NW 46.83'
Nail in 15" Ash S.S.W. 49.97'
Nail in Power Pole SE 91.55'

STATE OF MICH. GEORGE M. YOUNG LAND SURVEYOR No. 17640 REGISTERED LAND SURVEYOR

SIGNED BY George M Young DATE March 17, 1975

SURVEYOR'S MICHIGAN REGISTRATION NO. 17640 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY ..... DATE .....
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY ..... DATE .....
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. .....

826 Form No. MLM735 DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 3 PG 603

FILED

JUL 21 3 57 PM '76

REGISTER OF DEEDS

Ernest M. O'Brien

INGHAM COUNTY, MICH

REGISTER OF DEEDS STAMP AND FILING NUMBER

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T 1 N. R. 1 E.	K-10
2. PROPERTY CONTROLLING IN SECTION 26	T ... N. S. R. ... E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION ...	T. ... N. S. R. ... E. W.	
4. LOT NO. ... , RECORDED PLAT ...		
5. PRIVATE CLAIMS ...		

I, OSCAR BOSS, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on JUNE 18, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ..., 19..., found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

K-10 UNKNOWN

B. Description of corner evidence found and or method applied in restoring or re-establishing corner.

K-10 IRON SET AT SPLIT BETWEEN NE CORNER AND SE CORNER

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-10 E.1/4 COR., SEC. 26, T.1N.-R.1E.
S. 40° E. 44.92 NAIL W/S 36" TREE (OAK)
N. 35° E. 46.46 NAIL W/S 18" OAK
N. 72° W. 29.15 NAIL S/S 15" ASH.

SIGNED BY Oscar Boss DATE 7-1-76

SURVEYOR'S MICHIGAN REGISTRATION NO. 13574 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY ... DATE ...
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY ... DATE ...
MICHIGAN REGISTERED LAND SURVEYOR

STATE OF MICHIGAN OSCAR BOSS LAND SURVEYOR SEAL NO. 13574 REGISTERED

SURVEYOR'S MICHIGAN REGISTRATION NO. ...

981

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 26, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

INGHAM COUNTY-STOCKBRIDGE TWP.

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 5 PG 293

FILED

SEP 11 4 40 PM '79

REGISTER OF DEEDS

Paula Johnson

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 1 N. R. 2 E.	A-7
2. PROPERTY CONTROLLING IN SECTION	,T. S., R. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. S., R. W.	

4. LOT NO. , RECORDED PLAT

5. PRIVATE CLAIMS

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on June 22, 19 79, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on , 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

A-7
Post set in original government survey by Joseph Wampler dated between Nov. 14 and 22, 1825.
Corner identified as a stone by Wm. Berryman, County Surveyor, date unknown and in the records of the Ingham Co. Road Commission, revised grid map, 1969.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-7
Excavated a hole 8' x 9' to an average depth of 4.0' on the centerline of Parman Road and mostly north of tree/fence line to the east. Found large pointed stone lying on its side pointing north surrounded by pottery and smaller rocks 1.0' below road surface, ± 7.8' north of tree/fence line to the east and ± 1.0' east of the centerline of Parman Road. Accepted pointed stone for corner as called for in the records of the Ingham County Road Commission and records attributed to Wm. Berryman, County Surveyor. Measured north + 2652' to apparent location of A-6 and ± 2692' south to A-8. Excavation conducted by Ingham County Survey and Remonumentation Project crew.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-7
NW Corner, Section 19, T1N-R2E
Set 4" x 36" concrete monument with ½" x 38" rerod and cap #18998 with concrete collar and cover in location of pointed stone described above:
Nail & tag, #18998, southwest side power pole, SW, 53.09'
Nail & tag, #18998, east side 15" Maple, SE, 144.59'
Nail & tag, #18998, north side 6" Wild Cherry, ENE, 35.67'
Nail & tag, #18998, west side power pole, NW, 238.95'

SIGNED BY Ronnie M. Lester DATE Sept 6, 1979

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998 (SEAL)

STATE OF MICHIGAN — RONNIE M. LESTER LAND SURVEYOR No. 18998 — REGISTERED LAND SURVEYOR

SIGNED BY DATE

APPROVED AND SIGNED BY CHIEF SURVEY PARTY DATE 9-6-79

MICHIGAN REGISTERED LAND SURVEYOR

Director, Ingham County Survey and Remonumentation Project

(SEAL)

STATE OF MICHIGAN — LESTER LAND SURVEYOR No. — REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 17624

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

1675

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

LIBER 6 PG 179

INGHAM COUNTY - BUNKERHILL TWP.

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 1 N. S., R. 1 E. W.	L-9
2. PROPERTY CONTROLLING IN SECTION	,T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

FILED

JUN 1 12 47 PM '81

REGISTER OF DEEDS

Pamela Johnson

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 18, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on_____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

L-9 A. Description of original monument and accessories and/or subsequent restoration:

Original government survey by J. Wampler, February 8, 1826.
Corner referred to in a survey by T.J. Brown, County Surveyor, February 10, 1859 (v.2, p.351).

L-9 B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Excavated 10' x 10' on occupation line South and centerline road East and West. Found no evidence of physical monumentation. Excavated 6' x 5' at computed location of corner. Found 7" iron machinery piece at natural ground in excavation. Accepted this iron as perpetuated location of corner. Measured East 2631.20'. Measured West 2634.69'. Corner falls 6' North of centerline of road approximately 7' East of fenceline South. Excavation conducted by Ingham County Survey and Remonumentation Project crew.

L-9 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

South 1/4 Corner, Section 24, T1N, R1E
Set concrete monument and collar at location described above:
Nail & tag, #18998, North side 8" Hickory, S80°W, 92.30'
Nail & tag, #18998, North side 6" Maple, S45°W, 67.58'
Nail & tag, #18998, Northeast side 6" Poplar, S45°E, 64.22'
Nail & tag, #18998, telephone pole, North, 90.80'

SIGNED BY Ronnie M. Lester DATE 5/21/81

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

STATE OF MICHIGAN (SEAL) RONNIE M. LESTER LAND SURVEYOR No. 18998 REGISTERED LAND SURVEYOR

~~FOR STATE AND UNITED STATES AGENCIES~~

SIGNED BY_____ DATE_____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY Gary D. Lester DATE 5-26-81

MICHIGAN REGISTERED LAND SURVEYOR

Director, Ingham County Survey and Remonumentation Project

SURVEYOR'S MICHIGAN REGISTRATION NO. 17624

GARY D. LESTER LAND SURVEYOR No. REGISTERED LAND SURVEYOR

(SEAL)

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

1927

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 7 PAGE 116

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY 13	T. 1 N. R. 1 E.	K-7
2. PROPERTY CONTROLLING IN SECTION ____	T. ____ N. S. R. ____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION ____	T. ____ N. S. R. ____ E. W.	
4. LOT NO. ____ , RECORDED PLAT ____		
5. PRIVATE CLAIMS ____		

FILED

MAY 10 1 11 PM '89

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Timothy B. Van Gieson, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 17, 19 86, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on December 17, 19 86, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

K-7: Railroad spike set beside stone
Recorded Liber 3 Page 322
Nail in 8" Cedar N10°E 49.68'
Nail in 8" Cedar N20!E 44.70'
Nail in Power Pole N45°W 38.00'

B. Description of corner evidence found and or method applied in restoring or re-establishing corner.

K-7: Found railroad spike. Set 3/4"x18" pipe in place of spike.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-7: 3/4"x18" pipe
60-d in 8" Elm S36°E 25.98'
S.E. Corner garage S33°W 241.25'
60-d in power pole S68°W 258.75'
60-d in power pole N33°W 37.75'

SIGNED BY Timothy B Van Gieson DATE December 20, 1986

SURVEYOR'S MICHIGAN REGISTRATION NO. 24621

STATE OF MICHIGAN TIMOTHY B. VAN GIESON LAND SURVEYOR No. 24621 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

2262

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 7 PAGE 117

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY 13	T. 1 N. S., R. 1 E. W.	L-5, L-7
2. PROPERTY CONTROLLING IN SECTION ———	T. ——— N. S., R. ——— E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION ———	T. ——— N. S., R. ——— E. W.	
4. LOT NO. ———, RECORDED PLAT ———		
5. PRIVATE CLAIMS ———		

FILED

MAY 10 1 11 PM '89

REGISTER OF DEEDS

[illegible] MICH

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Timothy B. Van Gieson, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 17, 19 86, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on December 17, 19 86, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of Law:

A. Description of original monument and accessories and or subsequent restoration:

L-5: 1/2"x18" re-rod
Recorded Liber 6 Page 196
Nail & tag fence post South 64.34'
Nail & tag 10" Elm S15°W 65.60'
Nail & tag fence post S50°W 53.06'
Nail & tag 36" Oak S60°W 104.20'

L-7: Post
Government Notes
Aspen 16" S87.5°W 6.70 chains

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

L-5: Found 1/2"x18" rod laying on side. Set 3/4"x48" pipe at pro-rated split between Northwest and Northeast Corners of Section 13. (iron set 12" below ground surface 41' more or less North of Catholic Church Road)

L-7: Set 3/4"x48" pipe at pro-rated split between Southwest and Southeast Corners of Section 13. (iron falls on South edge of existing ditch)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-5: 3/4"x48" pipe
60-d in 36" Maple S86°E 233.48'
60-d in 10" Cherry S10°W 65.49'
60-d in 18" Norway Pine S61°W 146.63'
60-d in power pole N18°W 149.30'

L-7: 3/4"x48" pipe
60-d in 12" Maple N04°E 54.96'
60-d in clump 18" Maples N90°E 116.15'
60-d in clump 2" Maples S65°W 5.80'
60-d in 8" Elm N12°W 36.25'

SIGNED BY Timothy B. Van Gieson DATE December 19 86

SURVEYOR'S MICHIGAN REGISTRATION NO. 24621

STATE OF MICHIGAN — TIMOTHY B. VAN GIESON — LAND SURVEYOR No. 24621 — REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY ——— DATE ———
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY ——— DATE ———
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. ———

2263

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 7 PAGE 119

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY 13	T. 1 N. ☒ S., R. 1 E. ☒ W.	14, M-7
2. PROPERTY CONTROLLING IN SECTION	T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

FILED

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Timothy B. Van Gieson, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 17, 19 86, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on December 17, 19 86, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

14: No record of corner being set

M-7: Post
Corner set during original government survey. Did not obtain notes with original accessories

B. Description of corner evidence found and or method applied in restoring or re-establishing corner.

14: Set 3/4"x36" pipe at pro-rated split between East 1/4 Post and Southeast Corner.

M-7: Set 3/4"x36" pipe 7.92 (12 links) South of Southwest Corner of Section 18, T1N, R2E, Stockbridge Township, Ingham County, Michigan. Said Southwest Corner was found in remonumentation survey. Corner recorded in Liber 5 Page 293.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

14: Set 3/4"x36" pipe
60-d in 36" Oak N19°E 100.26'
60-d in 36" Oak S15°E 66.77'
60-d in Twin 18" Oak N68°W 29.71'
60-d in 18" Sassafrass N12°W 93.92'

M-7: Set 3/4"x36" pipe
60-d in Twin 18" Ash N28°E 83.84'
60-d in 10" Cherry N63°E 39.28'
60-d in Twin 10" Cherry N89°E 52.71'
60-d in power pole S49°W 47.19'

SIGNED BY [signature] DATE December 20, 1986

SURVEYOR'S MICHIGAN REGISTRATION NO. 24621

STATE OF MICHIGAN ☆ TIMOTHY B. VANGIESON LAND SURVEYOR No. 21621 ☆ REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

2265

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET