SOURCE: Corner Recordation Certificate

TRANSCRIBED from ~~DUPLICATE~~ ORIGINAL on file at Register of Deeds

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF— | LOCATED IN— | CORNER CODE NUMBER

1. PUBLIC LAND SURVEY 25 T 1 N R 2 W | M-11

2. PROPERTY CONTROLLING IN SECTION ____ T ____ S R ____

3. MISCELLANEOUS PROPERTY IN SECTION ____ T ____ S R ____

4. LOT NO. ____ RECORDED PLAT ____

5. PRIVATE CLAIMS ____

LIBER 2 PG 207 FILED

Nov 28 10 53 AM '72

REGISTER OF DEEDS

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Fred N. White, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 3, 4 and 5 above (identified with circled up index code diagram – over) were, in a field survey on September 15, 19 72 established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules thereto as required in the current manual of survey instructions of the United State Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore: that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ____, 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

Original Corner & Witnesses Obliterated.

B. Description of corner evidence found and or method applied in restoring or re-establishing corner:

Found 1/4" iron rod

Verified by adjoining corners & property lines.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1/4" iron rod

Anchor Post	North	26.54'
Anchor Post	South	27.12'
Telephone Pole	S03°00'W	29.54'

SIGNED BY Fred N. White DATE 10-25-72

SURVEYOR'S MICHIGAN REGISTRATION NO. 12034 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY ____ (Chief of Survey Party) DATE ____

APPROVED AND SIGNED BY ____ (Michigan Registered Land Surveyor) DATE ____ (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. ____

127 Form No. BLM73B DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

Onondaga township T 1 N, R 2 W M-11 corner code 1 attachment no. p. 1 of 1

SOURCE: CORNER RECORDATION CERTIFI

TRANSCRIBED from ~~ORIGINAL~~ DUPLICATE on file at REMON. OFFIC

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 3 PG 367

FOR CORNERS OF— | LOCATED IN— | CORNER CODE NUMBER

1. PUBLIC LAND SURVEY — T. 1 S. R. 1 E. | C-12, C-11, D-11 C-13, C-12, C-13, D-13, C-13

2. PROPERTY CONTROLLING IN SECTION — T. — N. S. — E. —

3. MISCELLANEOUS PROPERTY IN SECTION — T. — N. S. — E. —

4. LOT NO. — RECORDED PLAT —

5. PRIVATE CLAIMS —

FILED

Apr 22 12 08 PM '75

REGISTER OF DEEDS

MACOMB COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Ronald W Kaiser do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on March 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of Law:

A. Description of original monuments and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C-11 found iron bar
C-12 Set ¾" rebar - Swight property line after measurement
C-13 Set ¾" rebar at recorded distance of 1.00
D-13 Set chiseled cross on concrete sidewalk after measurement
E-13 found monument box
E-12 found lead plug
E-11 found pipe
D-11 found 1" pipe broken off & brought to surface with ¾" rebar

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-12
18" iron bar set flush
5' North of witness post
16 Mile Road 66.00
18 Mile Road 67.00
Hunt & Common Road

C-13
80 iron bar set flush
5' East of witness post
and 5.00 West of the East line of the West 33.00 feet of the North 33.00 feet of the Southwest ¼ of Section 1
80 iron bar set flush 61.00

D-13
16 Mile Road 40.00
18 Mile Road 67.00
18 Mile Road 80.00
80 iron pin set flush
in the East line of the West 33.00 feet of the Southwest ¼ of Section 1

E-13
80 iron pin set flush
the East line of the West 33.00 feet
80 iron pin set flush
Section 1

E-12
on the East line of the West 33.00 feet of the Southwest ¼ of Section 1
Hunt & Common Road
16 Mile Road 66.00
18 Mile Road 67.00

E-11
5' East of the East line of the West 33.00 feet of the Southwest ¼ of Section 1
18 Mile Road
Set 18" iron bar
Flush

D-11
on the East line of the West 33.00 feet of the Southwest ¼ of Section 1
18 Mile Road 67.00
80 iron pin set flush
Point of beginning

SIGNED BY Ronald W Kaiser DATE Mar 20, 1975

SURVEYOR'S MICHIGAN REGISTRATION NO. 23707

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ (CHIEF OF SURVEY PARTY) DATE _____

APPROVED AND SIGNED BY _____ (CHIEF, BUREAU OF LAND SURVEYS) DATE _____

STATE OF MICHIGAN RONALD W. KAISER LAND SURVEYOR NO. 23707 REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
FORM APPROVED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

SOURCE: Corner Recordation Certificate L. 3, P. 367

TRANSCRIBED from ORIGINAL ~~DUPLICATE~~ on file at Ingham Co. Register of Deeds

Leslie T1N - R1W
Corner Codes: C-11, C-12, C-13, D-11, D-13, E-11, E-12, E-13
Surveyor: Ronald W. Keller #20707

B. C-11 Found monument box
C-12 Set 5/16" rebar, single proportionate measurement
C-13 Set 5/16" rebar at recorded government jog
D-13 Set 5/16" rebar, single proportionate measurement
E-13 Found monument box
E-12 Found boat spike
E-11 Found iron bar
D-11 Found 1" pipe below blacktop, brought to surface with 5/16" rebar

C. C-12
18" Oak S45E 26.45'
1' North of old fence west
16" Hick. S23W 44.29'
18" Hick. N16W 57.33'
Nail gravel roadbed

C-13
20" Oak S5E 41.20'
Rd. sign S15E 28.00'
SW cor. of tele. box N70E 43.65'
Near N. edge road gravel
24" Oak S37W 51.00'

D-13
16" Hick. S70E 45.30'
18" Oak S20W 37.20'
12" Hick. N45W 20.57'
36" Oak North 15.25'
in line with fence to north
near N. edge road gravel

E-13
Rd. sign N60E 32.22'
Fen. cor. post South 37.81'
Rd. sign S45W 71.45'
NE cor. sec. 5 West 44.65'

E-12
On line with E & W fence
Cedar fence cor. post West 31.72'
P. pole N60W 66.83'
P. pole S80E 88.65'

E-11
South guard rail post S60W 82.16'
NE cor. culvert abutment S50W 82.08
W. R/W fence West 51.50'
Cor. is 6 W. of W. edge south bound pavement

D-11
On line with N & S fence
2' South of blacktop
18" Oak N80W 71.22'
18" Oak South 29.20'
Fen. cor. post North 29.80'

LESLIE township T 1 N, R 1 W C-11 corner code 1A attachment no. p. 1 of 1

Dec 30 31

SOURCE: CORNER RECORDATION CERTIFICATE

TRANSCRIBED from ORIGINAL ~~DUPLICATE~~ on file at REGISTER OF DEEDS

INGHAM COUNTY

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 3 PG 623

FILED

OCT 7 1 23 PM '76

REGISTER OF DEEDS

Enid M. Lewis

INGHAM COUNTY, MICH

REGISTER OF DEEDS STAMP AND FILING NUMBER

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 1 N. R. 1 W.	A-9 A-11
2. PROPERTY CONTROLLING IN SECTION	T. N. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

I, Maynard R. Dyer, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on August 25, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ..... 19 ..... found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

A-9 Northwest corner Section 30, T1N, R1W
Original monument and accessories obliterated.

A-11 Southwest corner Section 30, T1N, R1W.
Original monument and accessories obliterated.

B. Description of corner evidence found and or method applied in restoring or re-establishing corner.

A-9 Set 1/2" bar and cap G.L.O. falling of 3.30' South of recorded corner at Northeast corner of Section 25, T1N, R2W, Onondaga Township.

A-11 Used corner that is recorded as S.E. corner of Section 25, T1N, R2W, Onondaga Township as Southwest corner of Section 30. Line run East and West indicates Onondaga corner should be South 15.84' or G.L.O. falling from corner as recorded. This corner also may have become common corner by use over the years.

C. Description of monument or corner as recovered or established in perpetuate existing the position of the corner.

A-9 Northwest corner Section 30, T1N, R1W
Nail and tag in South side of 24" maple, W.N.W., 89.59' 68.59'
Found nail and tag in North side 30" maple E.S.E., 87.92'
Nail and tag in South side of 12" ash, E.N.E., 109.09'

A-11 Southwest corner Section 30, T1N, R1W
Anchor post, North, 26.59'
Anchor post, Soth, 27.12'
Nail and tag in S.E. side of twin 8" wild cherry, N.E., 27.40'

SIGNED BY Maynard R. Dyer DATE August, 27, 1976

SURVEYOR'S MICHIGAN REGISTRATION NO. 21565 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

STATE OF MICHIGAN MAYNARD R. DYER No. 21565 REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION ... 1971
REVISED MAY 16, 1973

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

Sec 19
30

330

INGHAM COUNTY

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 3 PG 624

FILED

OCT 7 1 23 PM '76

REGISTER OF DEEDS

David M. Lewis

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 1 N., R. 1 W.	B-10 B-11
2. PROPERTY CONTROLLING IN SECTION	,T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

I, Maynard R. Dyer, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on August 25, 19 76 established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on , 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B-10 Center of Section 30, T1N, R1W
No record of corner being set in original goverment survey. Evidence points to corner being established by County Surveyor A.P. Drake in June 1878. The records show he surveyed most of the South 1/2 of Section 30 at this time and set various 1/4 corners. Even though record doesnt show witnesses, I believe he established this corner.

B-11 Original monument and accessories lost.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

B-10 Set 1/2" bar and cap at base of old fence post. Found this old post 4' North of fence west and 1' East of North-South fence. Measurements West and South support this location.

B-11 Set 1/2" bar and cap G.L.O. prorated distance between S.E. and S.W. corner of Section 30 on line. Falls on centerline of road on old fence North. 2655.40' East 2636.82' West.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-10 Center of Section 30, T1N, R1w.
Nail and tag in East side of fence corner post, S.S.W., 4.92'
Nail and tag in North side of 12"(1 of 7) cottonwood, West, 59.18'

B-11 South 1/4 corner of Section 30, T1N, R1W.
S.W. corner of steel transmission tower, NN.E., 37.14'
S.E. corner of steel transmission tower, N.E., 42.15'
Nail and tag in South side 36" oak, W.N.W., 68.00'

SIGNED BY Maynard R. Dyer DATE August 27, 1976

SURVEYOR'S MICHIGAN REGISTRATION NO. 21565

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

STATE OF MICHIGAN — MAYNARD R. DYER — LAND SURVEYOR (SEAL) 21565 — REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

All 30 31

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

999 MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

[redacted] COUNTY - LESLIE TWP. [redacted]

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 1 N. ~~S.~~, R. 1 ~~E.~~ W.	B-9
2. PROPERTY CONTROLLING IN SECTION ____	,T. ____ N. S., R. ____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION ____	,T. ____ N. S., R. ____ E. W.	
4. LOT NO. ____ , RECORDED PLAT ____		
5. PRIVATE CLAIMS ____		

L 4 P. 359

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on June 29, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B-9
Post set in original government survey by Harvey Parke, February, 1826.
Corner referred to in miscellaneous Ingham County Surveyor Records, surveyor and date unknown.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

B-9
Excavated hole 6' x 5.8' to an average depth of 3' in the centerline of Bellevue Road on an extended fence line to the north and south. Found an iron 10" below surface on centerline of road and field separation north and south. Found a pointed wood stake 2.3' below the surface, above a 12" pointed cedar post, 2.5' below the surface, which was supported by a 1' x 8" stone, 2.37' below the surface, ± 1' north of the centerline of Bellevue Road on a fence line to the north and south. Accepted 12" cedar post as corner.
Excavation conducted by Ingham County Survey and Remonumentation Project crew.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-9
S¼ Corner, Section 19, T1N-R1W
Set 4" x 36" concrete monument with ½" x 38" rerod and cap #18998, with concrete collar and cover in location of 12" wood stake described above:
Nail & tag, #18998, south side 24" Maple, WNW, 145.39'
Nail & tag, #18998, north side 24" Maple, WSW, 137.57'
Nail & tag, #18998, northwest side 6" Elm, SW, 72.61'
Centerline of top bolt on north side of northwest leg of Power Tower ± 6' above ground, South, 165.6'

SIGNED BY Ronnie M. Lester DATE 9/13/78

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

STATE OF MICHIGAN (SEAL) RONNIE M. LESTER LAND SURVEYOR No. 18998 REGISTERED LAND SURVEYOR

~~SIGNED~~ DATE ____

APPROVED AND SIGNED BY ____ CHIEF OF SURVEY PARTY 9.13.78 DATE ____
MICHIGAN REGISTERED LAND SURVEYOR
Director, Ingham County Survey and Remonumentation Project

STATE OF MICHIGAN GARY D. LESTER LAND SURVEYOR No. 17624 REGISTERED

SURVEYOR'S MICHIGAN REGISTRATION NO. 17624

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

dec 19 30

SOURCE: CORNER RECORDATION CERTIFICATE L.5, P.17

TRANSCRIBED from ~~ORIGINAL~~ DUPLICATE on file at Remonumentation Office

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 5 PAGE 17

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 1N N. S., R. 1W E. W.	C-10
2. PROPERTY CONTROLLING IN SECTION	T. ____ N. S., R. ____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. ____ N. S., R. ____ E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

FILED
OCT 10 3 59 PM '70
REGISTER OF DEEDS
INGHAM COUNTY, MICH.
REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Richard W. Steadman, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on August 7, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Original Monument: wood post set by Harvey Parke, U.S. Deputy Surveyor in 1826; bearing trees: 24" W. Oak S20°W 09 lks. and 20" W. Oak N13°E 41-1/2 lks. In County Surveyor's Records, Volume 3, Page 74, T. J. Brown, County Surveyor notes this corner was marked by a post and witnessed by a 5" Maple S43-1/2°W 68 lks. and a 12" W. Oak S84°E 33-1/4 lks.; date: May 6, 1873.

I find no other references to this corner in the public record.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Dug hole in Blackmore Road opposite fences East and West, and found a stone with broken china about 15" below the surface.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Raised location of stone to surface with 1/2" iron pipe.

Witnesses:			
	24" Oak	S.E.	33.75 ft.
	Telephone pole	East	46.44 ft.
	22" Oak	N.E.	35.11 ft.

SIGNED BY Richard W. Steadman DATE October 10, 1970

SURVEYOR'S MICHIGAN REGISTRATION NO. 11370 (SEAL)

STATE OF MICHIGAN
RICHARD W. STEADMAN
LICENSED SURVEYOR
NO 11370
REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 20, 1971
REVISED MAY 14, 1970

1405 MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

Dec 30

SOURCE: CORNER RECORDATION CERTIFICATE L.5, P.21

TRANSCRIBED from ~~ORIGINAL~~ DUPLICATE on file at Remonumentation Office

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

L. 5 P. 21

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T 1N N. R. 1W W.	C-11
2. PROPERTY CONTROLLING IN SECTION	T N. R. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T N. R W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

FILED

Oct 18 4 00 PM '70

REGISTER OF DEEDS

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Richard W. Steadman do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on August 8, 19 74, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned on lines 3 4 and 5 above were, in a field survey on, 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or by a Decree of a Court of Law:

A. Description of original monument and accessories and or subsequent restoration

Original Monument: wood post set by Harvey Parke, U.S. Deputy Surveyor in 1826; bearing trees: 28" W. Oak N56°E 13-1/2 lks. and 12" W. Oak N88°E 179 lks. According to Volume 1, Page 12, County Surveyor's Records (1845), this corner was used to establish the 1/8 post next North; according to Volume 1, Page 2 (1943), it was used to set the 1/8 post next East. I find no further pertinent information in the public record.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner.

Dug large hole in the intersection of Blackmore and Olds Roads, but found nothing but a boat spike. Re-established corner the same distance South of the 1/8 line fence next North, that said fence is South of the quarter corner next North; also the same distance West of the 1/8 line fence next East, that said fence is West of the quarter corner next East.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

Set 1/2" iron pipe and monument box to mark the corner.

Witnesses:	N.E. corner conc. headwall	E.S.E.	40.63 ft.
	N.W. corner conc. headwall	E.N.E.	34.52 ft.
	24" Oak	N.E.	48.72 ft.
	18" Oak	N.W.	65.48 ft.
	38" Oak	S.W.	106.99 ft.

SIGNED BY Richard W. Steadman DATE October 10, 1970

SURVEYOR'S MICHIGAN REGISTRATION NO. 11370

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

STATE OF MICHIGAN
RICHARD W. STEADMAN
LAND SURVEYOR
NO. 11370
REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

1403

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1973

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

Sec 30, 31

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 5 PG 155

FILED

JAN 16 3 16 PM '79

REGISTER OF DEEDS

[signature]

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	Sec. 20 T. 1 N., R. 1 W.	C-9
2. PROPERTY CONTROLLING IN SECTION	____, T. ____ N. S., R. ____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	____, T. ____ N. S., R. ____ E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

I, Austin C. Williams, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on Nov. 22, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

C-9 Original monument and accessories obliterated

B. Descriptio of corner evidence found and/or method applied in restoring or re-establishing corner:

C-9 Found 5/8" iron rod in Monument Box at intersection of centerlines of Bellevue Road and Blackmore Road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-9 Nail & tag in fence post N40°E 4730'
Nail & tag in p.p. S46°E 70.40'
Nail & tag in 12" Spruce S30°W 42.90'

SIGNED BY Austin C. Williams DATE Jan. 8, 1979

SURVEYOR'S MICHIGAN REGISTRATION NO. 21275 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

STATE OF MICHIGAN AUSTIN C. WILLIAMS LAND SURVEYOR No. 21275 REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

1542

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 26, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

Sec 19
30

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

East ¼ Post & South ¼ Post — Section 24 — Onondaga Township

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 1 N. X, R. 2 X W.	M-8, L-9
2. PROPERTY CONTROLLING IN SECTION	,T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

LIBER 5 PG 365
FILED

Dec 11 8 14 AM '79
REGISTER OF DEEDS
Paula Johnson
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Glenn A. Fauser, RLS, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on August, 19 78, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
M-8 found 3/4" pinched pipe 5' East of centerline of Ridley Rd.:East ¼ Post
L-9 found 1/2" re-rod 4.4' North of centerline of Bellevue Rd.:South ¼ Post

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-8 East ¼ Post			
S 45° E	12" Walnut	45.24' to nail & ribbon	Corner is 5'
N 30° E	16" Walnut	53.21' to nail & ribbon	East of center
N 25° W	24" Maple	82.45' to nail & ribbon	line Ridley
N 45° W	24" Maple	87.25' to nail & ribbon	Road.
L-9 South ¼ Post			
North	Fence Corner Post	36.08' existing tag RLS 12034	
S 25° W	12" Cedar	48.90' to nail & washer	
S 50° W	14" Cedar	44.90'	
S 50° E	Northeast Corner of porch House #3771	57.80'	

SIGNED BY Glenn A. Fauser DATE 10-15-79

SURVEYOR'S MICHIGAN REGISTRATION NO. 18657

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

STATE OF MICHIGAN — GLENN A. FAUSER — LAND SURVEYOR — (SEAL) 18657 — REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

1738

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

Dec 19
30

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 6 PAGE 271

Leslie Township

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 1 N. S., R. 1 E. W.	A-10
2. PROPERTY CONTROLLING IN SECTION	,T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

FILED

Mar 29 10 34 AM '85

REGISTER OF DEEDS

Lucia J. Johnson

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Larry A. Bryan, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on January 5, 1985, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

A-10 Original monument and accessories obliterated.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-10 Found retangular shaped iron with notch in top.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-10 West 1/4 corner Sec. 30
Set nail & tag East side 8" Ash, N5°E, 19.15'
Set nail & tag West side 5" Ash, S5°W, 27.16'
Top rock East 1/4 corner Section 25 T1N, R2W, South, 6.8'

SIGNED BY Larry A. Bryan DATE 3-19-85

SURVEYOR'S MICHIGAN REGISTRATION NO. 25832

(SEAL)

STATE OF MICHIGAN
LARRY A. BRYAN
LAND SURVEYOR
No. 25832
REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

5053 2019

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

Sec 30