950	00	3821	Liber8

Page 518

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in INGHAM COUNTY Located In: Corner Code # EILED Delhi Township 11/28/1995 09:01:27 REGISTER OF DEEDS PAULA JOHNSON 1. Public Land Survey R2W T 3N Т R T R INCHAM COUNTY, HI R 2. Property Controlling R T in Section S R Miscellaneous S R Register of Deeds Stamp & File Number Property in Section 4. Lot No. _, Recorded Plat 5. Private Claims _

Steadman , in a field survey on October 24 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformation of the transfer of the Management of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1). 1-01-1827: Wood post set by Musgrove Evans, U. S. Deputy Surveyor; bearing trees: 4" B. Ash S34°W 9 links and 12" B. Ash N30°E 6 links.
- 2). 12-12-1854: Record of Surveys, Vol. 2, Page 227, County Surveyor Anson Jackson surveyed Section 33 and notes the following witnesses but gives no monument description: 6" B. Ash S34°W 9 links and 10" B. Ash S30°E 15-1/4 links.

(Continued on back)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found stone projecting about 2" above ground with angle iron on N.W. side. Broke off top of angle iron in attempt to remove it; bottom still in place. Set standard Ingham County Remonumentation 3/4" iron rod and cap on the north side of the stone to help mark its location.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Left 6" wide by 24" long granite stone in place as found to mark the corner with 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" on north side of stone and remainder of angle iron at N.W. edge below surface, and took the following witnesses (bearings are magnetic):

Set nail and tag 11370 in NE side 48" Bitternut (Rowe's B.T.) N80°W 25.43 feet Set nail and tag 11370 in E. side 10" Bitternut N50°W 53.02 feet. Found nail and tag 11370 in W. side Telephone Pole Fence Post N03°E 14.27 feet Found nail and tag 18994 in W. side Telephone Pole Fence Post N32°E 5.45 feet Set nail and tag 11370 in SW side Telephone Pole Fence Post S68°E 6.64 feet Center 1.2 foot square Concrete Fence Post (horseshoe in top) N82°W 14.75 feet

Signed by Kiele	Waterman	Dato November 6, 1995
Surveyor's Michigan License No	11370	FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 20,

P.A. 345 INGHAM COUNTY PEER APPROVED 11/07/95 ML

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1963

F-11, T3N, R2W

Part A - Continued

- 3). 10-07-1896: Record of Survey, Vol.4, Page 10, County Surveyor W. A. Rowe surveyed Section 28 and notes "Long granite stone set from which 6" S. Oak N84-1/2°W 81 lks., 4" Hickory N19-3/4°W 98-1/2 lks., 8" Bitternut N85°W 40 lks." (26.4 feet).
- 4). 5-05-1973: Land Corner Recordation Certificate (Rec. 1-05-79, L5-P115), R. W. Steadman L.P.S. 11370 states "at position determined by projection of fences and measurement from Rowe's B.T., found long narrow stone with smaller stones around it; set angle iron along N.W. edge of stone to help mark the corner; witnesses: 42" Bitternut (Rowe's B.T.) N85°W 26.59 ft., Telephone Pole NO3°W 14.27 ft., 6" Bitternut N50°W 53.23 ft."
- 5), 5-10-1973: Certified Survey (Rec. 5-11-73, L1-P716), R. W. Steadman notes "found long narrow stone, 42" Bitternut N85°W 26.59 ft., T. Pole NO3°W 14.27 ft., 6" Bitternut N50°W 53.23 ft."
- 6). 5-13-1974: Certified Survey Map (Rec. 5-15-74, L1-P1236), R. W. Steadman notes "found stone, set angle iron at N.W. side of stone" and gives the same witnesses as 5). above.
- 7). 4-02-1975: Land Corner Recordation Certificate (Rec. 8-29-78, L4-P318), Ron Helsel L.P.S. 18994 calls for "long narrow stone, 42"

 Butternut N50°W 53.23', Power Pole
- 8). 4-02-1975: Certified Survey Map (Rec. 6-02-75, L2-P361), Ron Helsel calls for the same monumentation and witnesses as 7). above.
- 9). 2-10-1987: Certified Survey Map (Rec. 7-15-87, L5-P264), M. F. Fouty L.P.S. 18989 found a long narrow stone witnessed by 42"
 Bitternut N85°W 26.59', 6" Bitternut N50°W 53.23', NE Cor. 12" square iron anchor post West 14.17'.
- 10). 9-30-1988: Certified Survey Map (Rec. 7-31-90, L6-P302), L. A. Bryan L.P.S. 25832 states "found pointed rock with angle iron along north side, fence North and East; found nail and tag in west side power pole North 14.27', set nail and tag in north side 60" Butternut N85°W 26.59', set nail and tag in west side 10" Butternut N50°W 53.23'."
- 11). 3/12/1992: Certified Survey Map (Rec. 3-25-93, L6-P1117), R. W. Steadman notes "stone with angle iron at NW side" and gives the same witnesses as 5). above.
- 12). 6-25-1992: Certified Survey Map (Rec. 2-08-93, L6-P1103), D. R. Lohr L.P.S. 30090 notes "S. 1/4 Cor. Sec. 28, T3N, R2W, L5-P115".

Rest No 3092 CRNR 9.00 MSSR 2.00 Total 11.00

Print.

•					
		950	0003823 Liber&	3 Page5	i22
		RECORDATION CE	RTIFICATE		
For corners in INGHAM COUNTY		ment of Act 74, Mich.	P.A. 1970		1.
(County)	Located In:	Corner Code #			
Delhi Township 1. Public Land Survey	T 011 - 011			FILED 11/28/1995 09:01:30	
1. Public Land Survey	T <u>3N</u> R <u>2W</u> T R	<u>F11</u>	et.	REGISTER OF DEEDS PAULA JOHNSON	
	T R T R			INGHAN COUNTY, NI	
2. Property Controlling	S T R				
in Section 3. Miscellaneous	S T R S T R	<u></u>			
Property in Section	S T R		Register of	Deeds Stamp & File Nu	ımber
4. Lot No, I	Recorded Plat				
5. Private Claims				J J J J J	J K L M
			3		
R. W. Steadman	, in a field survey onOctobe	r 28 , ₁₉ 9	4		-11
do hereby certify that under re-	quirements of P.A. 74, Michigan P.A. conformance with regulations and rule	of 1970, the comer points m	pentioned	3-17-16-15	1413
manual of survey instruction	is of the United States Departmen	nt of the Interior Bureau	of land 7		
5 above were in conformance	of a Court of Law and/or that the corn with the rules of the Michigan Boar	rd of Professional Surveyor	sorbya II	20 21 22	23-24-
as expressed below:	ablished, re-established, monumented	d, re-monumented, recovered	ed, found	29 28 27	2625
NOTE: Not more than 4 co	omers, all in the same fown and re	ange, may be recorded	11		
A. Description of original	monument and accessories and	Mor cubecquent restaut	13		
1). 1-01-1827:	Wood post set by U	. S. Deputy Su	ırvevor Musar	ove Evans: be	aring
	trees: 4" Beech S6	O°E 3 links an	nd 22" Beech	N60°W 26 link	S .
2). 6-15-1875:	Record of Surveys,	Vol. 3, Page	108, County	Surveyor T. J	•
	Brown calls for a links.	post from whic	:h 3" B. Cher	ry \$22-1/2°E	113
(Continued on b	nank I				
(Sanothaca on L	Jacky				
B. Description of corner e	evidence found and/or method a	pplied in restoring or re	establishing comer:		
round 3/4" iror	n pipe and cap 1137 f Onondaga Road and	O in good cond	lition in mor	ument box in	the
			o the west.	OF MI	Million
		•		ATE.	CAN
				STEADMA	
				LAND SURVEYO	R 2
				NO. 11370	
				W. S. AND	sikily and
	•			Million	Millian
C. Description of monume	ent for comer and accessories e	stablished to pernetuate	locating the position	n of the comer:	
Left the 3/4" i	iron pipe and cap 1	1370 in monume	nt box as fo	und to mark th	ie
corner and took	c the following with	nesses (bearin	gs are magne	tic):	
Found nail and SW corner of Ho	tag 11370 in N. signuse Foundation N65	de Telephone P	o1e S34°E 38	.75 feet	
Found Accolade,	. Inc. nail and tag	in N. side 14	" Annla cose	E 33.70 feet	**
Dec nair and to	ag 11370 in E. side arage Foundation S60	LUMBE BUTE NA.	2°W 01 00 r-	et	
		,	-		
N.0		v v			
Signed by Tuku	I W. Sterdma.	Ų noto	November 18	1005	

P.A. 345 INGHAM COUNTY
PEER APPROVED 11/21/95 KC

Surveyor's Michigan License No.

Part A - Continued

Managhan Managhan Angai

- 3). 12-07-1881: Record of Surveys, Vol. 3, Page 184, County Surveyor A. P. Drake calls for a stone from which 3" B. Cherry S22-1/2°E 113-1/4 links.
- 4). 10-07-1896: Record of Survey, Vol. 4, Page 10, County Surveyor W. A. Rowe calls for stone and crockery from which 14" B. Cherry \$22-1/2°E 113 links and 2" Maple S82°E 42 links.
- 5). 7-06-1971: Land Corner Recordation Certificate (Rec. 7-26-71, L1-P135) G. D. Lester L.P.S. 17624 "found 1/2" bar 10.5' West of east edge of asphalt on Onondaga Road. Corner supported by old fence to East and field measurement South in close accord with original government measure. Nail and tag in Power Pole SE 39.07', nail and tag in corner post East 26.70', nail and tag in Power Pole NW 83.92'."
- 6). 7-06-1971: Certified Survey Map (Rec. 8-03-71, L1-P32) G. D. Lester calls for the monument and witnesses given in 5). above.
- 7). 2-23-1973: Certified Survey Map (Rec. 5-11-73, L1-P729) R. M. Lester L.P.S. 18998 calls for the monument and witnesses given in 5). above.
- 8). 5-04-1974 (1973): Land Corner Recordation Certificate (Rec. 1-05-79, L5-P110) R. W. Steadman L.P.S. 11370 "dug hole, searching for stone, but found only a circle of small stones with broken china and glass around them. The circle of state of about the size of a large pointed stone which lies on the ground on the east side of the road. The 1/2" iron rod recorded in L1-P135 is about 1 foot North and 1 foot East. Raised location of center of circle of stones to surface with 3/4" iron pipe and set monument box; witnesses: Telephone Pole S.E. 38.75 ft. (found-1995), Wood Anchor Post (down-1995) East 27.74 ft., Power Pole (new pole-1995) N.W. 83.66 ft.
- 9). 5-10-1973: Certified Survey Map (Rec. 5-11-73, L1-P716) R. W. Steadman calls for "stones, broken dishes, glass raised with 3/4" pipe and cap in mon. box" and gives the same witnesses as 8). above.
- 10). 10-22-1973: Certified Survey Map (Rec. 11-09-73, L1-P1020) Ron Helsel L.P.S. 18994 notes "NE Corner Sec. 32, T3N, R2W (L1-P135)".
- 11). 4-02-1975: Certified Survey Map (Rcc. 6-02-75, L2-P361) Ron Helsel calls for 3/4" iron and cap in mon. box; power pole S.E. 38.75 ft., power pole N.W. 83.66 ft., anchor post East 27.74 ft.
- 12). 8-07-1975: Certified Survey Map (Rec. 9-08-75, L2-P480, re-recorded 1-15-76, L2-P595) F. N. White L.P.S. 12034 calls for "SW Cor. Sec. 28, T3N, R2W (L2-P361)".

THE PROPERTY AND ADDRESS OF THE PARTY AND ADDR

13). 7/07/1977: Certified Survey Map (Rec. 9-26-77, L3-P50) R. M. Lester "found 1/2" pipe and cap in mon. box, rec. L1-P135", and calls for the witnesses given in 5). above.

(Continued on Page 3)

Rept No 3092 CRMR 11.00 MSSR 2.00 Total 13.00

Parison rocks

1

E-11, T3N, R2W - Page 3

Part A - Continued

- 14). 4-27-1978: Certified Survey Map (Rec. 5-30-78, L3-P333) R. M. Lester calls for the same monument and witnesses as 13). above.
- 15). 5-01-1978: Certified Survey Map (Rec. 5-30-78, L3-P351) R. M. Lester calls for the same monument and witnesses as 13). above.
- 16). 9-08-1978: Certified Survey Map (Rec. 11-29-78, L3-P621) G. M. Young L.P.S. 17640 calls for the same monument and witnesses given in 13). above.
- 17). 10-11-1978: Certified Survey Map (Rec. 11-17-78, L3-P606) A. C. Williams L.P.S. 21275 calls for the witnesses in 5). above but gives no monument description.
- 18). 4-11-1980: Land Corner Recordation Certificate (Rec. 7-30-80, L6-P67) A. S. Pierson L.P.S. 13039 calls for 1/2" pipe in monument box; Power Pole N46°W 83.66', Telephone Pole S37°E 38.76', Telephone Pole S81°W 114.50', 6" Apple S83°E 33.80'.
- 19). 4-14-1980: Certified Survey Map (Rec. 7-30-1980, L4-P75) A. S. Pierson calls for the monument and witnesses given in 18). above.
- 20). 10-01-1980: Certified Survey Map (Rec. 2-02-81, L4-P185) A. S. Pierson calls for "SE Corner Section 29, T3N, R2W. Delhi Twp., Ingham Co., Mich." but gives no manufact of allogates.
- 21). August 1982: Certified Survey Map (Rec. 10-05-82, L4-P592) G. M. Young calls for "S.E. Corner Sec. 29, T3N, R2W, Delhi Twp., Ingham County, MI recorded in Liber 6, Page 67", and gives the witnesses listed in 18). above.
- 22). 4-14-1983: Certified Survey Map (Rec. 5-03-83, L4-P714) G. M. Young "found 1/2" pipe in monument box" and calls for the witnesses given in 18). above.
- 23). 11-22-1986: Certified Survey Map (Rec. 10-06-87, L5-P323) D. K. Richardson L.P.S. 31603 calls for "NE Cor. Sec. 32, T3N, R2W (L6-P67)".
- 24). 2-10-1987: Certified Survey Map (Rec. 7-15-1987, L5-P264) M. F. Fouty L.P.S. 18989 "found mon. box; nail and tag in power pole SE 39.07', nail and tag in corner post East 26.70', nail and tag in power pole NW 83.92'."
- 25). 9-30-1988: Certified Survey Map (Rec. 7-31-90, L6-P302) L. A. Bryan L.P.S. 25832 states "Found bar and cap at the intersection of Harper and Onondaga Roads. Set nail and tag in west side 14" Apple East 33.5', found nail and tag in Northeast side utility pole S35°E 38.8', set nail and tag in Southwest side power pole S20°E 156.12', set nail and tag in north side 20" Maple S75°W 85.20'."
- 26). 8-22-1991: Certified Survey Map (Roc. 12-09-91, L6-P876) Ron Helsel of Accolade, Inc., Mason, Michigan "found 1/2" iron and cap in mon. box 1' West of C/L Onondaga Road & on C/L Harper Road to West; found N & T NE side P. Pole N50°W 83.85', found N & T NE side Guy Pole S30°E 38.95', set N & T N. side 16" Apple East 33.73', set N & T E. side 12" Maple S20°W 71.95'."

OF AVCARD W.
STEADMAN
LAND
SURVEYOR
NO.
11370
AND SURVEYOR
NO.

Richard W. Straduran November 18, 1995

P.A. 345 INGHAM COUNTY
PEER APPROVED 11/21/95 MC

Filling Requirement of Act 7 For corners in INGHAM COUNTY Located In: Corner	Register of Deeds Stamp & File Number
INGHAM COUNTY Located In: Corner Corn	Register of Deeds Starnp & File Number
1. Public Land Survey T 3N R 2W G-11 T R T R T R T R T R 1. P. Section S T R 2. Property Controlling S T R In Section S T R 2. Property in Section S T R Property in Section S T R 4. Lot No. Recorded Plat 5. Private Claims 1. R. W. Steadman in a field survey on July 1 do hereby certal, that under requirements of P 77, Michigan P A of 1970, the contribution of S and Secure P A of 1970, the contribution of S and Secure P A of 1970, the contribution of S and Secure P A of 1970, the contribution of S and Secure P A of 1970, the contribution of S and Secure P A of 1970, the four manual of Secure P A of 1970, the four manual o	Register of Deeds Stamp & File Number
T R T R T R T R T R T R T R T R T R T R	Register of Deeds Stamp & File Number
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Section S T R 4. Lot No. Recorded Plat 5. Private Claims 1, R. W. Steadman, in a field survey on July 1 do hereby cerely that inches requirements of PA 77, Michigan PA of 1970, the contributed or survey instructions on the Usines Scales Desarrouss of the filter Management of the filter of	Register of Deeds Stamp & File Number
2. Property Controlling S T R In Section S T R 3. Miscellaneous S T R Property in Section S T R 4. Lot No. Recorded Plat 5. Private Claims 1. R. W. Steadman in a field survey on July 1 do hereby certily that single requirements of PA74, Michigan PA of 1970, the contribution of survey in the survey of the files. Miscelland acceptance of the Usines Scales Descriptors of the files. Miscelland Contribution of the Usines Scales Descriptors of the files.	19 96 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
in Section S T R 3. Miscellaneous S T R Property in Section S T R 4. Lot No, Recorded Plat 5. Private Claims	19 96 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
Property in Section S R	19 96 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
5. Private Claims I, R. W. Steadman, in a field survey on	
5. Private Claims I, R. W. Steadman, in a field survey on	
do hereby carely that those requirements of PA 7/4 Michigan PA of 1970, the com- in that) mich above was in containing with top recurrence from the viscolor at a marginal or clayery respicators on the relations because the surface of the factor in the part of the part of the factor of the part of the factor	
do hereby carely that those requirements of PA 7/4 Michigan PA of 1970, the com- in that) mich above was in containing with top recurrence from the viscolor at a marginal or clayery respicators on the relations because the surface of the factor in the part of the part of the factor of the part of the factor	
do hereby carely that those requirements of PA 7/4 Michigan PA of 1970, the com- in that) mich above was in containing with top recurrence from the viscolor at a marginal or clayery respicators on the relations because the surface of the factor in the part of the part of the factor of the part of the factor	, 19
	mer points mentioned
Manda markeraby, teachar, a fe-sure of Carland Arabin Committee manner.	Scared in the current
27(1922年1928)1922年1922年1922年1922年1922年1922年1922年1922	SUVEYOR OF DY A
Date (# 17 Four to Lew, established, re-established, monumented) re-monument	ted, recovered, found
NOTE: Not more than 4 corners, all in the same town and range, may be	recorded 11
description.	. withesses, but no monument
(Continued on back)	
B. Description of comer evidence found and/or method applied in real Found 3/4" from pipe and cap (markings natised with second Box which was shifted location of upper box and replaced 3/4" (Remonumentation 3/4" from rod and cap.	ot legible) in original monument bo
On the basis of the information listed in Part A the above monumentation represents the best evidence to of this corner.	
	SURVEYOR
C. Description of monument for corner and accessories established to	o perpetuate locating the position of the conver
Set 3/4" smooth iron rod and cap stamped over pointed stone and took the followin	P. A. 345, PS 11370" in monument
Found nail and tag 18994 in S. side Tele Found nail and tag 25832 (L. A. Bryan) i Found nail and tag 25832 in NE side Powe Set nail and tag 11370 in E. side Power Set nail and tag 11370 in N. side 14" Oa	n N. Side 20" Oak S87"E 92.35 feet r Pole S15"E 90.88 feet Pole S26"W 90.40 feet
SEC MELL SHO CER TIRLO IN M. 2102 TO A	ਰ ਵਿਚਦ ਦੇ ਦਰਵਾਵੇਂ ਦੇ ਦਵਾਵੇਂ
Ser hell end red trato in w. 21de 14. Of	

G-11, T3N, R2W


Part A, Continued

- 3). 10-07-1896: Record of Surveys, Vol. 4, Page 10, County Surveyor W. A. Rowe notes "Pointed blue stone from which is a 6" Sugar N26-3/4°E 64 links, a 14" S. Oak N24-1/2°W 106 links, and a 5" Sycamore N70°W 36-1/4 links".
- 4). 1-01-1969: County Road Commission Corner Grid Sheet calls for iron and stone witnessed by 20" Hickory NE 59.39 ft., 18" Oak NW 34.09 ft., 40" Oak SE 89.50 ft., fence post East 27.98 ft.
- 5). 9-06-1973: Land Corner Recordation Certificate (Rec. 1-05-79, L5-P113), R. W. Steadman L.P.S. 11370 "dug hole in Eifert (erroneously stated as Onondaga) Road opposite fencelines East and West at found 1/2" iron rod; continued digging and about 18" below to surface, found a large pointed bluish colored stone. Raised location of stone to surface with 3/4" iron pipe and monumen box; witnesses: 20" Hickory NE 59.39 ft., 18" Oak NW 34.09 f 40" Oak SE 89.60 ft.
- 6). 9-06-1973: Certified Survey Map (Rec. 3-07-74, L1-P1141), R. W. Steadma notes "found 1/2" rod over stone, replaced rod with 3/4" iro pipe and cap, set mon. box" and gives witnesses from Item 5 above.
- 7). 5-13-1974: Certified Survey Map (Rec. 5-15-74, L1-P1236), R. W. Steadma notes "set 3/4" pipe and cap in monument box over stone (197 and gives the witnesses from Item 5 above.

o chrone region - uniquely reli-

The second and an electrocological decological and

- 8). 9-29-1976: Land Corner Recordation Certificate (Rec. 2-16-78, L4-P135), R. M. Lester L.P.S. 18998 note: "found 1/2" pipe & cap 11730 and Steadman tag in Ni side 24" Oak NW 34.08 ft., nail and Steadman tag in W. side 18" Hickory NE 59.39 ft.
- 9). 9-29-1976: Certified Survey Map (Rec. 11-16-76, L2-P934), R. M. Lester calls for a 1/2" pipe in mon. box and gives the witnesses from Item 8 above.
- 10). 9-24-1979: Certified Survey Map (Rec. 10-02-79, L3-P1038), Ron Helsel L.P.S. 18994 notes "SW Cor. Sec. 27, T3N, R2W (L5-P113)" by gives no monument nor witness descriptions.
- 11). 3-19-1992: Certified Survey Map (Rec. 3-25-93, L6-P1117), R. W. Steads calls for 3/4" iron pipe in monument box and gives the witnesses from Item 5 above.
- 12). 4-10-1992: Certified Survey Map (Rec. 4-12-93, L6-P1134), Ron Helsel notes "found P & C in mon. box; found P & C 33.00 feet West set N & T 18" Walnut S70°W 25.97 feet, set N & T 14" Elm St 67.05 feet, set N & T Power Pole N60°E 71.25 feet.
- 13). 6-25-1992: Certified Survey Map (Rec. 2-06-93, L6-P1103), D. R. Lohr L.P.S. 30090 notes "SE Cor. Sec. 28, T3N, R2W, L5-P113" bu gives no monument nor witness descriptions.
- 14). 1-03-1994: Certified Survey Map (Rec. 4-21-94, L7-P155), G. A. Fauser L.P.S. 18657 notes "found iron in mon. box, L5-P113" but gives no witnesses.



In Public Land Survey	Filing Requirement of Act 74, Mich. P.A. 1970	
Defin Township 1 Public Land Survey 1 T JW R 2W, G.12 1 R 1 R 1 R 1 R 1 R 1 R 1 R 1	tor comers in	To the second
Public Land Survey		960043542
Froposty Controlling S T R	1 Public Land Survey T 3W R 2W G-12	REGISTER OF DEEDS
Property Controlling S T R R Resident S T R R Register of Deeds Stamp & File Number Misself Property in Sec S T R R Register of Deeds Stamp & File Number A Lot No Recorded Plat R Register of Deeds Stamp & File Number A Lot No Recorded Plat R Register of Deeds Stamp & File Number A Lot No Recorded Plat R Register of Deeds Stamp & File Number A Lot No Recorded Plat R Register of Deeds Stamp & File Number A Lot No Recorded Plat R Register of Deeds Stamp & File Number R R Register of Deeds Stamp & File Number R R Register of Deeds Stamp & File Number R R R R R R R R R R R R R R R R R R R	relief to the control of the Research to the control of the contro	Paula Johnson
A Lot No Recorded Plat 1 Fortents Original 2 Fortents Original 3 Fortents Original 4 Fortents Original 5 Fortents Original 5 Fortents Original 6 Fortents Original 7 Fortents Original 8 Fort	eline ja karantari kana jarah T <u>ana Rama</u> ntari k <u>ana jada di</u> ngan katabulan ka	
3 Miscolamodus S T R R Register of Deeds Stamp & File Number Property in Sec S T R R Register of Deeds Stamp & File Number Property in Sec S T R R Register of Deeds Stamp & File Number A Lot No Recorded Plat T A A Michigan & A of 15/0 the corner point membered in less 1 and 2 above were in conformation in regulations and miscolamosis in secure of a management of typ a decree of a Court of Law and for the state of Law 15 unity or by a Decree of a Court of Law, established, re-established management of typ a decree of a Court of Law and for the state of Law 15 unity or by a Decree of a Court of Law, established, re-established, management of typ a decree of a Court of Law and for the first owner than 2 course points membered in the Number of the State of the Stangard Court of Law, established, re-established, management of typ a decree of a Court of Law, established, re-established, re-established on this conflictation. A Description of original monument and accessories and/or subsequent restoration. 1) 12-28-1825 U S Public Land Survey Field Notes, Deputy Surveyor Musgrove Evans "marked the 1/4 Sec Coc on an Elm 22" dia. 2) 12-08-1840 Record of Surveys, Vol. 1, Page 67, County Surveyor Anson Jackson notes "Corner Tree, 22" Elm: 3) 12-16-1873. Record of Surveys, Vol. 3, Page 59, Deputy County Surveyor T. J. Brown notes "Elm 22" dia corner tree now almost gone: 4) 01-01-1969. Ingham County Read Commission Corner Grid Sheet calls for "stone on P. (?), anch. post West 30.7 feet, anch, post East 30.6 feet." (Continued on back) B Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 3/4" smooth fron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic). Found nat and tag 11370 in S. side 10*8 Sci Eler ST4*2 36.2 feet. Found national and tag 11370 in S. side 10*8 Sci Eler ST4*2 36.2 feet. Found national and tag 11370 in S. side 20*8 Sci Eler ST4*2 36.2 feet. Found national and tag 11370		
1 Foreign W. Streethins in a faild survey on August 22, 1996, do hereby state that under requirements of the A. Michigan M. A. of 1978. The corner points mentioned in hiers 1 and 2 above were in conformance of the United Chairts. Department of the Interior. Bureau of Land Management of by a decice of a Court of Law and for flittle to corner points mentioned in lines 3. A and 5 above were in conformance of the United Chairts. Department of the Interior. Bureau of Land Management of by a decice of a Court of Law and for flittle to corner points mentioned in lines 3. A and 5 above were in conformance with the rules of the Chairts and State of Land Surveys or by a Decice of a Court of Law, established, re-established, interior than 2 Lorents; all in the sense form of the Chairts and State of Land Surveys or by a Decice of a Court of Law, established, re-established, multiple of the Chairts and State of Land State of Land State of Court of Law, established, re-established, multiple of the Chairts of Law and for this certificatio. 10. 12-28-1826. U. S. Public Land Surveys Field Notes, Deputy Surveyor Musgrove Evans marked the 1/4 Sec. Cor. on an Elm 22" dia. 21. 12-08-1840. Record of Surveys, Vol. 1, Page 67. Country Surveyor Anson Jackson notes "Corner Tree, 22" Elm. 22. 12-08-1840. Record of Surveys, Vol. 3, Page 59, Deputy Country Surveyor T. J. Brown notes "Elm 22" dia. corner tree now almost gone 4) 01-01-1969. Ingham Country Road Commission Corner Grid Sheet calls for "stone on P. (?), anch, post West 30.7 feet, anch, post East 30.6 feet." (Continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. Found axial and tag 11370 in S. side Power Pole SR?*W 43.58 feet Set 131 and tag 11370 in S. side Power Pole SR?*W 43.58 feet Found 12" iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic). Found axial and tag 11370 in S. side Power Pole SR?*W 43.58 feet Found 12" iron rod and cap	3 Miscellaneous S T R R	
1. Forbard VI. Steedman, and field survey on August 22, 1996, do bereby state that under requirements of P.A. Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Understand of the Interior. There are of Land Management or by a decire of a Court of Law and for third the corner points mentioned in lines. 3.4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveys or by a Docese of a Court of Law. established, restablished, restablished on the restablished on the restablished on the restablished on the restablished for the restablished resta	Property in Sec S T R R	Register of Deeds Stamp & File Number
1. Forbard VI. Steedman, and field survey on August 22, 1996, do bereby state that under requirements of P.A. Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Understand of the Interior. There are of Land Management or by a decire of a Court of Law and for third the corner points mentioned in lines. 3.4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveys or by a Docese of a Court of Law. established, restablished, restablished on the restablished on the restablished on the restablished on the restablished for the restablished resta		
1. Focused W. Steedman, in a field survey on August 22, 1996, do hereby state that under requirements of IA. A Michigan IP. & 1970 the corner points mentioned in lines 1 and 2 above were in conformance with regulations are fruent to the function of interest in the final corner in regulations are fruent to the function of interest in the function in lines 3.4 and 5 above were in conformance with the corner primary interintent of later because of Land Management of by a decree of a Court of Law and for function of the function of the function of Law and for function of the conformance with the rules of the Court of Law and for function of the Court of Law and for functio	4 Lot No Recorded Plat	The first term of the state of
1. For Just 17. Septiment in a field survey on August 22, 1996, do hereby state that under requirements of IP.A. 74. Methygan IP.A. of 1970 the corner points mentioned in lines 1 and 2 above were in conformance with regulations and nines therefore as required in the current manual of survey instructions of the United States Denatured of the Interior. Britain of Justines Denatured of the Interior. Britain of Justines Denatured of the Interior (Denature) and Management of by a denies of a Court of Law and Interior Law and Interior County Interior of Justines Denatured of Law State Interior Law and Interior County Interior of Law State Interior Law State	5 Virvate Claims i i i i i i	
di P.A. 24 Machagia P.A. of 1970 the cories points mentioned in lane 1 and 2 above were in conformance with regulations and rules therefore as required in the current main of survey instructions of the United States Legislations and rules therefore as required in the corner points mentioned in lanes 3.4 and 5 above were in conformance with the rules of the Machagian Board of Land Surveyors or by a Decree of a Court of Law and by the rules of the Machagian Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, maintained the corner occurred found as expressor below. NOTE: Not mere than 2 comety, still in the sense fown and drings, may be recorded on this certificate. A Description of original monument and accessories and/or subsequent restoration: 1) 12-28-1826. U.S. Public Land Survey Field Notes, Deputy Surveyor Musgrove Evans marked the 1/4 Sec. Cor. on an Elm 22" dia. 2) 12-08-1840. Record of Surveys, Vol. 1, Page 67, County Surveyor Anson Jackson notes "Corner Tree, 22" Elm." 3) 12-15-1871. Record of Surveys, Vol. 3, Page 59, Deputy County Surveyor T. J. Brown notes "Elm 22" dia. corner tree now almost gone 4) 01-01-1969 Ingham County Road Commission Corner Grid Sheet calls for "stone on P. (?), anch. post West 30.7 feet, anch, post East 30.6 feet." (Continued on back) B Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found axle shaft over stone in monument box in Elfert Road opposite fence line East and tree line West. Replaced axle with standard Ingham County Remonumentation rod and cap. C Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic). Found nail and tag 11370 in S. side Power Pole N46"E 80.87 feet Set 131370 in S. side Power Pole S87"V 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"V 43.58 feet Fo		
di P.A. 24 Machagia P.A. of 1970 the corner points mentioned in lines. 1 and 2 above were in conformance with regulations and males therefore as required in the current maint of survey instructions of the United States benatiment of the Interior. Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned is lines. 3.4 and 5 above were in conformance with the rules of the Machagian Board of Land Surveyors or by a Decree of a Court of Law, established, re-established. MOTE: Not mere than 2 cometa, still in the sense fower and drings, may be recorded on this certificate. A Description of original monument and accessories and/or subsequent restoration: 1) 12-28-1826. U.S. Public Land Survey Field Notes, Deputy Surveyor Musgrove Evans inarked the 1/4 Sec. Cor. on an Elm 22" dia. 2) 12-08-1840. Record of Surveys. Vol. 1, Page 67. County Surveyor Anson Jackson notes "Corner Tree, 22" Elm." 3) 12-15-1871. Record of Surveys. Vol. 3, Page 59. Deputy County Surveyor T. J. Brown notes "Elm 22" dia. corner tree now almost gone. 4) 01-01-1969 Ingham County Road Commission Corner Grid Sheet calls for "stone on P. (?), anch. post West 30.7 feet, anch, post East 30.6 feet." (Continued on back) B Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found axie shall over stone in monument box in Eifert Road opposite fence line East and free line West. Replaced axie with standard Ingham County Remonumentation rod and cap. C Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic). Found nati and tag 11370 in S. side Power Pole N46"E 80.87 feet Set rail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nation and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nation and tag 11370 in S. side Power Pole S87"W 43.58 feet Found na	I. Richard W. Steadman, in a field survey on August 22, 1996, do hereby state that under requirements	
Continued on back) Buesau of Land Management of by a decree of a Court of Law and for that the corner purpose mentioned in lines 3.4 and 5 shows were in conformance with the rules of the Machagan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, machagan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, machagan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, machagan Board of Law and Survey Field Notes, Deputy Surveyor Musgrove Evans 'trianked the 1/4 Sec. Cor. on an Elm 22" dia. 1) 12-28-1826 U. S. Public Land Survey Field Notes, Deputy Surveyor Musgrove Evans 'trianked the 1/4 Sec. Cor. on an Elm 22" dia. 2) 12-08-1840 Record of Surveys. Vol. 1, Page 67. County Surveyor Anson Jackson notes "Corner Tree, 22" Elm." 3) 12-16-1871 Record of Surveys, Vol. 3, Page 59, Deputy County Surveyor T. J. Brown notes "Elm 22" dia corner tree now almost gone: 4) 01-01-1969: Ingham County Road Commission Corner Grid Sheet calls for "stone on P. (?), anch. post West 30.7 feet, anch. post East 30.6 feet." (Continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. Found axle shaft over stone in monument box in Eifart Road opposite fence line East and tree line West. Replaced axle with standard Ingham County Remonumentation rod and cap. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic): Found nail and tag 11370 in S. side Power Pole N46"E 80.87 feet Set nail and dag 11370 in S. side Power Pole 874"E 38.82 feet LAND LAND SIZEMBAN LAND SURVEYOR NO. 11370 11370 11370 114-28-1826 U.S. Service of the Control of the corner in the Corner of House Found and cap 30090 N85"W 32.96 feet	of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance	
NOTE: Not more than. 2 comers, all in the same town and range, may be recorded on this contribute. 11 12-28-1826 U.S. Public Land Survey Field Notes, Deputy Surveyor Musgrove Evans "marked the 1/4 Sec. Cor. on an Elm 22" dia." 2) 12-08-1840 Record of Surveys; Vol. 1, Page 67. County Surveyor Anson Jackson notes "Corner Tree, 22" Elm. 3) 12-16-1871. Record of Surveys; Vol. 3, Page 59, Deputy County Surveyor T. J. Brown notes "Elm 22" dia. corner tree now almost gone." 4) 01-01-1969. Ingham County Road Commission Corner Grid Sheet calls for "stone on P. (?), anch. post West 30.7 feet, anch. post East 30.6 feet." (Continued on back) Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found axle shaft over stone in monument box in Elfert Road opposite fence line East and tree line West. Replaced axie with standard Ingham County Remonumentation rod and cap. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic): Found nail and tag 11370 in S. side Power Pole N46"E 80.87 feet Set nail and dag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet	States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or	The second are seen as the distance than
NOTE: Not more than 2 comers, all in the sense town and range, may be recorded on this certificate. 11 A Description of original monument and accessories and/or subsequent restoration: 1) 12-28-1826 U. S. Public Land Survey Field Notes, Deputy Surveyor Musgrove Evans "marked the 1/4 Sec. Cor. on an Elm 22" dia. 2) 12-08-1840 Record of Surveys, Vol. 1, Page 67, County Surveyor Anson Jackson notes "Corner Tree, 22" Elm." 3) 12-16-1871 Record of Surveys, Vol. 3, Page 59, Deputy County Surveyor T. J. Brown notes "Elm 22" dia. corner tree now almost gone. 4) 01-01-1969 Ingham County Road Commission Corner Grid Sheet calls for "stone on P. (?), anch. post West 30.7 feet, anch. post East 30.6 feet." (Continued on back) B Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found axle shalf over stone in monument box in Elfert Road opposite fence line East and tree line West. Replaced axle with standard Ingham County Remonumentation rod and cap. C Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic). Found nail and tag 11370 in S. side Power Pole N46"E 80.87 feet Set nail and tag 11370 in S. side 14" Box Elder S74"E 38.62 feet NE Corner of House Foundation 576"W 94.55 feet Found nail and tag 11370 in S. side Power Pole N86"E 80.87 feet Set nail and tag 11370 in S. side Power Pole N86"E 80.87 feet Set nail and tag 11370 in S. side Power Pole N86"E 80.87 feet Set nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet	that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the fulles of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established.	
on this certificate. A Description of original monument and accessories and/or subsequent restoration: 1) 12-28-1826 U. S. Public Land Survey Field Notes, Deputy Surveyor Musgrove Evans 'marked the 1/4 Sec. Cor. on an Elm 22" dia." 2) 12-08-1840 Record of Surveys. Vol. 1, Page 67, County Surveyor Anson Jackson notes "Corner Tree, 22" Elm." 3) 12-16-1871. Record of Surveys, Vol. 3, Page 59, Deputy County Surveyor T. J. Brown notes "Elm 22" dia. corner tree now almost gone." 4) 01-01-1969. Ingham County Road Commission Corner Grid Sheet calls for "stone on P. (?), anch. post West 30.7 feet, anch. post East 30.6 feet." (Continued on back) B Description of corner evidence found and/or method applied in restoring or reestablishing comer: Found axie shaft over stone in monument box in Elfart Road opposite fence line East and tree line West. Replaced axie with standard Ingham County Remonumentation rod and cap. C Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic): Found nail and tag 11370 in S. side Power Pole N46"E 80.87 feet Set nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and 13 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet	monumented recovered found as expressed below	
A Description of original monument and accessories and/or subsequent restoration: 1) 12-28-1826 U. S. Public Land Survey Field Notes, Deputy Surveyor Musgrove Evans "marked the 1/4 Sec. Cor. on an Elm 22" dia." 2) 12-08-1840 Record of Surveys, Vol. 1, Page 67, County Surveyor Anson Jackson notes "Corner Tree, 22" Elm." 3) 12-16-1871 Record of Surveys, Vol. 3, Page 59, Deputy County Surveyor T. J. Brown notes "Elm 22" dia. corner tree now almost gone. 4) 01-01-1969 Ingham County Road Commission Corner Grid Sheet calls for "stone on P. (?), anch. post West 30.7 feet, anch. post East 30.6 feet." (Continued on back) B Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found axle shaft over stone in monument box in Elfert Road opposite fence line East and tree line West. Replaced axie with standard Ingham County Remonumentation rod and cap. C Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic): Found nail and tag 11370 in S. side Power Pole N46"E 80.87 feet Set nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet	NOTE: Not more than 2 comers, all in the same town and range, may be recorded	
A Description of original monument and accessories and/or subsequent restoration: 1) 12-28-1826 U. S. Public Land Survey Field Notes, Deputy Surveyor Musgrove Evans "marked the 1/4 Sec. Cor. on an Elm 22" dia. 2) 12-08-1840 Record of Surveys. Vol. 1, Page 67, County Surveyor Anson Jackson notes "Corner Tree, 22" Elm." 3) 12-16-1871 Record of Surveys, Vol. 3, Page 59, Deputy County Surveyor T. J. Brown notes "Elm 22" dia. corner tree now almost gone. 4) 01-01-1969: Ingham County Road Commission Corner Grid Sheet calls for "stone on P. (?), anch. post West 30.7 feet, anch. post East 30.6 feet." (Continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found axle shaft over stone in monument box in Elfert Road opposite fence line East and tree line West. Replaced axle with standard Ingham County Remonumentation rod and cap. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic): Found nail and tag 11370 in S. side 14" Box Elder S74"E 38.62 feet NE Corner of House Foundation S76"W 94.55 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet	on this certificate.	
1) 12-28-1826 U. S. Public Land Survey Field Notes, Deputy Surveyor Musgrove Evans "marked the 1/4 Sec. Cor. on an Elm 22" dia." 2) 12-08-1840 Record of Surveys, Vol. 1, Page 67, County Surveyor Anson Jackson notes "Corner Tree, 22" Elm." 3) 12-15-1871 Record of Surveys, Vol. 3, Page 59, Deputy County Surveyor T. J. Brown notes "Elm 22" dia. corner tree now almost gone." 4) 01-01-1969: Ingham County Road Commission Corner Grid Sheet calls for "stone on P. (?), anch. post West 30.7 feet, anch. post East 30.6 feet." (Continued on back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found axle shaft over stone in monument box in Eifert Road opposite fence line East and tree line West. Replaced axle with standard Ingham County Remonumentation rod and cap. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic): Found nail and tag 11370 in S. side Power Pole N46"E 80.87 feet Set nail and tag 11370 in S. side 14" Box Elder S74"E 38.62 feet NE Corner of House Foundation S76"W 94.55 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet Found nail and tag 11370 in S. side Power Pole S87"W 43.58 feet		* *
Evans "marked the 1/4 Sec. Cor. on an Elm 22" dia." 2) 12-08-1840 Record of Surveys, Vol. 1, Page 67, County Surveyor Anson Jackson notes "Corner Tree, 22" Elm." 3) 12-16-1871 Record of Surveys, Vol. 3, Page 59, Deputy County Surveyor T. J. Brown notes "Elm 22" dia. corner tree now almost gone." 4) 01-01-1969: Ingham County Road Commission Corner Grid Sheet calls for "stone on P. (?), anch. post West 30.7 feet, anch. post East 30.6 feet." (Continued on back) B Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found axle shaft over stone in monument box in Eifert Road opposite fence line East and tree line West. Replaced axle with standard Ingham County Remonumentation rod and cap. C Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic): Found nail and tag 11370 in S. side Power Pole N46°E 80.87 feet Set nail and tag 11370 in S. side 14" Box Elder S74"E 38.82 feet Found nail and tag 11370 in S. side Power Pole S87°W 43.68 feet Found nail and tag 11370 in S. side Power Pole S87°W 43.68 feet Found nail and tag 11370 in S. side Power Pole S87°W 43.68 feet Found nail and tag 11370 in S. side Power Pole S87°W 43.68 feet Found 1/2" iron rod and cap 30090 N85°W 32.96 feet	A Description of original monument and accessories and/or subsequent restoration:	
Tree, 22" Elni." 3) 12-16-1871. Record of Surveys. Vol. 3, Page 59. Deputy County Surveyor T. J. Brown notes "Elm 22" dia. corner tree now almost gone." 4) 01-01-1969. Ingham County Road Commission Corner Grid Sheet calls for "stone on P. (?), anch. post West 30.7 feet, anch. post East 30.6 feet." (Continued on back) B Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found axle shaft over stone in monument box in Eifert Road opposite fence line East and tree line West. Replaced axle with standard Ingham County Remonumentation rod and cap. C Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic): Found nail and tag 11370 in S. side Power Pole N46°E 80.87 feet Set nail and tag 11370 in S. side 14" Box Elder S74°E 38.62 feet NE Corner of House Foundation S76°W 94.55 feet Found nail and tag 11370 in S. side Power Pole S87°W 43.58 feet Found 1/2" iron rod and cap 30090 N85°W 32.96 feet	1) 12-28-1826 U.S. Public Land Survey Field Notes, Deputy Surveyor Musgrove Evans "marked the 1/4 Sec. Cor. on an Elm 22" dia."	
almost gone. 4) 01-01-1969: Ingham County Road Commission Corner Grid Sheet calls for "stone on P. (?), anch. post West 30.7 feet, anch. post East 30.6 feet." (Continued on back) B Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found axle shaft over stone in monument box in Eifert Road opposite fence line East and tree line West. Replaced axie with standard Ingham County Remonumentation rod and cap. C Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic): Found nail and tag 11370 in S. side Power Pole N46"E 80.87 feet Set nail and tag 11370 in S. side 14" Box Elder S74"E 38.62 feet NO. STEADMAN LAND STEADMAN LAND SURVEYOR NO. 11370 11370 11370	2) 12-08-1840 Record of Surveys, Vol. 1, Page 67, County Surveyor Anson Jacks Tree, 22" Elm."	on notes "Corner
anch. post East 30.6 feet." (Continued on back) B Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found axle shaft over stone in monument box in Eifert Road opposite fence line East and tree line West. Replaced axle with standard Ingham County Remonumentation rod and cap. C Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic): Found nail and tag 11370 in S. side Power Pole N46°E 80.87 feet Set nail and tag 11370 in S. side 14" Box Elder S74°E 38.62 feet NE Corner of House Foundation S76°W 94.55 feet Found nail and tag 11370 in S. side Power Pole S87°W 43.58 feet Found 1/2" iron rod and cap 30090 N85°W 32.96 feet	3) 12-16-1871 Record of Surveys, Vol. 3, Page 59, Deputy County Surveyor T. J. almost gone."	Brown notes "Elm 22" dia. corner tree now
Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found axle shaft over stone in monument box in Eifert Road opposite fence line East and tree line West. Replaced axle with standard Ingham County Remonumentation rod and cap. C Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic): Found nail and tag 11370 in S. side Power Pole N46°E 80.87 feet Set nail and tag 11370 in S. side 14" Box Elder S74°E 38.62 feet NE Corner of House Foundation S76°W 94.55 feet Found nail and tag 11370 in S. side Power Pole S87°W 43.58 feet Found 1/2" iron rod and cap 30090 N85°W 32.96 feet	4) 01-01-1969; Ingham County Road Commission Corner Grid Sheet calls for "storanch, post East 30.6 feet."	ne on P. (?), anch. post West 30.7 feet,
Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found axle shaft over stone in monument box in Eifert Road opposite fence line East and tree line West. Replaced axle with standard Ingham County Remonumentation rod and cap. C Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic): Found nail and tag 11370 in S. side Power Pole N46°E 80.87 feet Set nail and tag 11370 in S. side 14" Box Elder S74°E 38.62 feet NE Corner of House Foundation S76°W 94.55 feet Found nail and tag 11370 in S. side Power Pole S87°W 43.58 feet Found 1/2" iron rod and cap 30090 N85°W 32.96 feet	(Continued on back)	
Found axle shaft over stone in monument box in Eifert Road opposite fence line East and tree line West. Replaced axle with standard Ingham County Remonumentation rod and cap. C Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic): Found nail and tag 11370 in S. side Power Pole N46°E 80.87 feet Set nail and tag 11370 in S. side 14" Box Elder S74°E 38.62 feet NE Corner of House Foundation S76°W 94.55 feet Found nail and tag 11370 in S. side Power Pole S87°W 43.58 feet Found 1/2" iron rod and cap 30090 N85°W 32.96 feet	(Continued on back)	
C Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic): Found nail and tag 11370 in S. side Power Pole N46°E 80.87 feet Set nail and tag 11370 in S. side 14" Box Elder S74°E 38.62 feet NE Corner of House Foundation S76°W 94.55 feet Found nail and tag 11370 in S. side Power Pole S87°W 43.58 feet Found 1/2" iron rod and cap 30090 N85°W 32.96 feet	B Description of corner evidence found and/or method applied in restoring or reestablishing of	orner:
Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic): Found nail and tag 11370 in S. side Power Pole N46°E 80.87 feet Set nail and tag 11370 in S. side 14" Box Elder S74°E 38.62 feet NE Corner of House Foundation S76°W 94.55 feet Found nail and tag 11370 in S. side Power Pole S87°W 43.58 feet Found 1/2" iron rod and cap 30090 N85°W 32.96 feet	Found axle shaft over stone in monument box in Eifert Road opposite fence line Eastandard Ingham County Remonumentation rod and cap.	ast and tree line West. Replaced axle with
Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic): Found nail and tag 11370 in S. side Power Pole N46°E 80.87 feet Set nail and tag 11370 in S. side 14" Box Elder S74°E 38.62 feet NE Corner of House Foundation S76°W 94.55 feet Found nail and tag 11370 in S. side Power Pole S87°W 43.58 feet Found 1/2" iron rod and cap 30090 N85°W 32.96 feet		
and took the following witnesses (bearings are magnetic): Found nail and tag 11370 in S. side Power Pole N46°E 80.87 feet Set nail and tag 11370 in S. side 14" Box Elder S74°E 38.62 feet NE Corner of House Foundation S76°W 94.55 feet Found nail and tag 11370 in S. side Power Pole S87°W 43.58 feet Found 1/2" iron rod and cap 30090 N85°W 32.96 feet	C. Description of monument for corner and accessories established to perpetuate locating the	position of the corner:
Found nail and tag 11370 in S. side Power Pole N46°E 80.87 feet Set nail and tag 11370 in S. side 14" Box Elder S74°E 38.62 feet NE Corner of House Foundation S76°W 94.55 feet Found nail and tag 11370 in S. side Power Pole S87°W 43.58 feet Found 1/2" iron rod and cap 30090 N85°W 32.96 feet SIEADMAN LAND SURVEYOR NO. 11370	Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box and took the following witnesses (bearings are magnetic):	E OF MICHIGA
Found 1/2" iron rod and cap 30090 N85°W 32.96 feet	Set nail and tag 11370 in S. side 14" Box Elder S74°E 38.62 feet NE Corner of House Foundation S76°W 94.55 feet	STEADMAN LAND SURVEYOR
Signed by Date October 26, 1996	Found 1/2" iron rod and cap 30090 N85°W 32.96 feet	(f) (f)
Signed by Date October 26, 1996	D. D. Williams	MINIMAN SUL
	Signed by Kickacol W. Steadiscan Date_	October 26, 1996
Surveyor's Michigan License No. 11370		

G-12 T3N, R2W

Part A Continued

- 5) 4 02 1973 Land Corner Recordation Certificate (Rec. 4-05-73, L2-P411), R. M. Lester, L.P.S. 18998 found 3/8" Y. 5/8" rectangular bar in centerline Eifert Road on fencelines East and West, nail and tag in N. side 12" twin maple West 61, 46 feet, nail and tag in E. side 30" Maple. North 130 70 feet, nail and tag in W. side 10" Pine SE 55 09 feet."
- 6) 4 04-1973 Certified Survey Map (Rec. 5-11-73: L1-P718), R. M. Lester found a 3/8" bar and repeats the witnesses given in Item 5 above. He also gives a distance of 2650-96 feet to H-12.
- 7) 9 06 1973 Land Corner Recordation Certificate (Rec. 1-08-79, L5-P129), R. W. Steadman, L.P.S. 11370 found the iron bar called for In Item 5 above, and dug hole. Below was an iron axle shaft over a large pointed stone with small stones, broken tile and crockery around. Raised axle shaft to surface to replace iron bar, and set monument box, utility pole NE 80 79 feet, utility pole WSW 43 65 feet, NW corner of house SE 85.45 feet.
- 8) 9-06-1973 Certified Survey Map (Rec. 3-07-79, L1-P1141), R. W. Steadman "found 3/8" bar over axel, removed bar, raised axel, set mon, box, power pole NE 80.79 feet, power pole WSW 43.65 feet, NW cor, house SE 85.45 feet
- 9) 12-04-1974 Certified Survey Map (Rec. 2-18-75, L2-P299), R. M. Lester calls for the W. 1/4 Cor. Sec. 34, T3N, R2W and gives the same witnesses as Item 5 above. He also give distances of 2639 67 feet to G-13 and 2650.96 feet to H-12.
- 10) 2-02-1978 Certified Survey Map (Rec. 3-10-78, L3-P252), A. C. Williams, L.P.S. 21275 notes "W. 1/4 Cor. Sec. 34, T3N, R2W, Liber 2-Pg. 411."
- 11) June 1978 Certified Survey Map (Rec. 7-19-78, L3-P441), R. M. Lester notes: "W. 1/4 Cor. Sec. 34, T3N, R2W, Fd. 3/4" bolt" and lists the same witnesses as given in Item 5 above. He also gives the same distances as in Item 9 above.
- C/L Eifert Road on East-West fence; found N & T in N. side 20" Twin Maple West 61.33 feet, found N & T in S. side Power Pole S85°W 43.56 feet, found N & T in W. side 18" Pine S45"W 55.05 feet, found N & T in SE side Power Pole N45°E 80.86 feet, found bar and cap West 32.00 feet. He also gives distances of 2650.72 feet to H-12 and 2639.98 feet to G-13.
- 13) 10-26-1990 Certified Survey Map (Rec. 12-26-90, L6-P611), D. R. Lohr, L.P.S. 30090 notes "E. 1/4 Cor. Sec. 33, T3N, R2W, L5-P129; found iron in mon. box as witnessed" and lists the witnesses given in Item 7 above. He also gives a distance of 2640.14 feet to G-13.
- 14) 4-10-1992 Certified Survey Map (Rec. 4-12-93, L6-P1134), Ron Helsel, L.P.S. 18994 notes "E. 1/4 Cor. Section 33, T3N, R2W, L5-P129."

CEPT No 33030 CRNR 9.00 MSSR 2.00 Total 11.00

		RNER RECORDATION CERTIFICAT juirement of Act 74, Mich. P.A. 197		9 Page 65	
or corbers in			[-1]	.ED	
NGHAM CQUINTY Delhi Township	Located In	Corner Code #	96004	43563 6 10:59:21 OF DEEDS	
Public Land Survey	T 3N_R 2W	G-13	Paula	OF DEEDS Johnson COUNTY, MI	
	T R R		\$ (401 mm)	Control	
Property Controlling S S	T R				· ·
Miscellaneous S Property in Sec S	T R T R T R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R T R R R T R R R T R R R T R R R T R R R R R R R		Register of Deed	is Stamp & File Numl	ıber ⁽
			register of book	o camp a charten	
Lot No Recorded Plat					
Puyate Claims					
					•
Richard W. Steadman, in a field survey of P.A. 74, Michigan P.A. of 1970, the corneration regulations and rules therefore as requitates Department of the Interior, Bureau on the corner points mentioned in lines of the discourse or by accommented recovered found as expressed.	r points mentioned in pred in the current r if Land Management 3, 4 and 5 above v r a Decree of a C	in lines 1 and 2 above were in conformance manual of survey instructions of the United t or by a decree of a Court of Law and for vere in conformance with the rules of the			
IOTE: Not more than 2 comers, all in t	the same town and	i mage may be recorded			
on this certificate.	are sering to this seri	a rainge, may no rainada			
					i
		and the second of the second			i.,
Description of original monument a	and accessories a	ind/or subsequent restoration:			: :
N40" E 28 links a	, cor. to Secs. 3 and 6" Beech N	3 and 34 from which 7" Beech 72°W 20 links."			
2) 12-08-1840 Record of Sun	veys, Vol. 1, Pa	ge 67. County Surveyor Anson Jacks	son notes the U.S. w	vilnesses.	
3). 12-16-1871. Record of Sur- identified by a	veys, Vol. 3, Pa lignment from to	ge 59. Deputy County Surveyor T. J. vo known points South."	Brown calls for "a po	ost or stone properl	ly
(Continued on back)					
3. Description of corner evidence for	und and/or metho	d applied in restoring or reestablishing	corner:		
Found iron axle shaft in monus sandstone. Axle was 0.3 feet cap.	ment box, remo north of point of	ved axle and dug in bottom of box. stone. Replaced axle with standard	Found pointed stone I Ingham County Rer	with broken brick a nonumentation rod	and I and
C. Description of monument for corn	er and accessorio	es established to perpetuate locating the	e position of the corner:		
Set 3/4" smooth iron rod and care magnetic):	ap stamped "P.	A. 345 PS 11370" in monument box	and took the following	ng witnesses (beari	ings
SW Corner, Foundation of Hou NE Corner, Foundation of Hou SE Corner, Foundation of Hou Found nail and tag 21565 in S Found nail and shiner in NE sid Found nail and shiner in S. sid Found nail and tag 25832 in E Set 3/4" iron and cap stamped N85"W 19.71 feet (G-1.7)	use S57°W 129. use N48°W 107. E side Telephor de Wood Post S7 de 24" Oak N63° side 30" Cherr d "P. A. 345 PS T2N, R2W)	32 feet 03 feet ne Pole S27°E 32.00 feet 79°W 54.66 feet W 86.56 feet y S56°W 131.58 feet 11370" over stone in monument box		S RICHARD W. STEADMAN LAND SURVEYOR NO. 11370 AND SUR	STATE NO.
$A \cdot A \cdot$, 1	······································	and the second of the second o		
Signed by Difficulting	WATER	Line	Date October 26 1		
Signed by Dika-1'	W. Stua	Line	Date October 26, 1		

G-13, T3N, R2W

Part A - Continued

- 4). 01-01-1969: Ingham County Road Commission Corner Grid Sheet calls for stone and brick; anch. post NE 42.3 feet, anch. Post SW 56.7 feet, 15" Elm NW 55.5 feet.
- 5). 04-02-1973: Land Corner Recordation Certificate (Rec. 5-11-73, L2-P413), R. M. Lester, L.P.S. 18998 "set 1/2" bar on townline at recorded falling from found NW corner of Section 3, T2N, R2W; nail and tag in S. side 30" Oak WNW 86.98 feet, nail and tag in E. side 12" Cherry NW 101.85 feet, nail and tag in E. side 15" Apple SW 131.03 feet.
- 6. 04-04-1973: Certified Survey Map (Rec. 5-11-73, L1-P718), R. M. Lester calls for the same monument and witnesses as Item 5 above. He also gives a distance of 2657.47 feet to H-13.
- 7). 08-07-1974: Certified Survey Map (Rec. 11-21-74, L2-P173), R. M. Lester calls for the same monument and witnesses as Item 5 above, and gives the same distance as Item 6 above.
- 8). 12-13-1974: Certified Survey Map (Rec. 2-18-75, L2-P299), R. M. Lester calls for the same witnesses as Item 5 above, and gives distances of 2657.48 feet to H-13 and 2639.67 feet to G-12.
- 9). 02-02-1978: Certified Survey Map (Rec. 3-01-78, L3-P252), A. C. Williams, L.P.S. 21275 notes "SW Cor. Sec. 34, T3N, R2W, Liber 2-Pg. 413."
- 10). June 1978: Certified Survey Map (Rec. 7-19-78, L3-P441), M. R. Dyer, L.P.S. 21565 calls for the same monument and witnesses as Item 5 above, and gives the same distances as Item 8 above.
- 11). 02-01-1988: Certified Survey Map (Rec. 7-02-90, L6-P233), L. A. Bryan, L.P.S. 25832 "found PK Nail 12 feet East of C/L Eifert Road in C/L Nichols Road; found nail and tag in S. side 30" Oak N60°W 86.95 feet, set nail and tag in E. side 24" Apple S30°W 131.03 feet, found nail and tag in NE side Power Pole S30°E 31.3 feet. He also gives distance of 2657.62 feet to H-13 and 2639.98 feet to G-12.
- 12). 10-26-1990: Certified Survey Map (Rec. 12-26-90, L6-P611), D. R. Lohr, L.P.S. 30090 "found PK Nail as per witnesses; N & T in S. side 30" Oak WNW 86.98 feet, N & T in 15" Apple (Cherry) SW 131.03 feet, SE Corner Foundation N65°E ____(?). He also gives a distance of 2640.14 feet to G-12.
- 13). 08-31-1994: Certified Survey Map (Rec. 11-15-94, L7-386), Ron Helsel, L.P.S. 18994 "found axle shaft surrounded by rocks, red brick, and sandstone 19.7 feet East from G-1, T2N, R2W. He also gives a distance of 2657.80 feet to H-13.

Reat No 33030 CRNR 9.00 MSSR 2.00 Total 11.00

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Liber

9 Page

103

For corners in	EII ED
INGHAM COUNTY Located In: Corner Code # Aurelius Township	960045752 12/02/1996 09:31:40 REGISTER OF DEEDS
1. Public Land Survey T 2N R 2W G-1	Paula Johnson INGIOM COUNTY, MI
Total Reserved to the state of	
T R	legister of Deeds Stamp & File Number
4. Lot No, Recorded Plat	
2	6 5 4 3 2 =1
and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:	10 11 12 13 16 15 14 -13 15 19 20 22 23 -24
on and continued.	. 30 29
A. Description of original monument and accessories amilia subsequent restoration.	31 juni 25 juni 35-juni 25-juni 36-juni
1). 1826: U. S. Public Land Survey Field Notes, Deputy Surveyor Harvey Parke "at 80.63 chains intersect N. Bdry. 30 links (19.80 feet) W. of post, set post, corner to Secs. 3 and 4 from which bears 8" Beech S64°E 47 links and 8" W. Ash S22°W 10-1/2 links."	
 05-10-1840: Record of Surveys, Vol. 1, Page 42, County Surveyor Anson Jac the U. S. witnesses. 	ckson used this corner and notes
3). 01-12-1844: Record of Surveys, Vol. 1, Page 99, County Surveyor Anson Jagain notes the U. S. witnesses.	ckson again used this corner and
(Continued on back)	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
About 1 foot deep in monument box, found large stone. Raised location of stone standard Ingham County Remonumentation rod and cap and packed asphalt are 2656.83 feet to H-1 and 2696.24 feet to G-2.	e with an 8" long piece of ound it for stability. Measured
C. Description of monument for corner and accessories established to perpetuate locating the position	on of the comer:
Set 3/4" smooth iron rod and cap stamped "P. A. 345 PS 11370" in monument box over stone and took the following witnesses (bearings are magnetic):	OF MICHIGATION
Found nail and tag (illegible) in S. side 24" Oak N58°W 68.36 feet Found nail and tag 25832 in E. side 30" Cherry S16°W 126.24 feet NE Corner of House Foundation S51°W 114.32 feet SW Corner of House Foundation N62°E 67.35 feet Set 3/4" iron rod and cap stamped "P. A. 345 PS 11370, 0.3 feet north of stone in monument box S85°E 19.71 feet (G-13, T3N, R2W)	STEADMAN LAND SURVEYOR NO. 11370 AND SUR
Signed by Kirkard W. Steadman Date Nover	nber 2, 1996
Surveyor's Michigan License No. 11370	
FORM APPROVED BY INCHIGAN	STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

G-1, T2N, R2W

Part A - Continued

- 4). 01-01-1969: County Road Commission Corner Grid Sheet calls for a stone and brick; 15" Elm NW 41.8 feet, anchor post SW 40.5 feet, anchor post NE 57.4 feet.
- b). 02-13-1973. Land Corner Recordation Certificate (Rec. 2-15-73, L2-P349), L. J. Hendryx, L.P.S. 3276 states "in 1945 a pointed stone was witnessed: NE cor. House SW 114.45 feet, center of 18" Oak NW 69.2 feet, SW cor. Store NE 72.65 feet, set #4 iron at surface from old witnesses; NE cor. House SW 114.45 feet, center of 18" Oak NW 69.2 feet, SW cor. House NE 72.65 feet."
- 6). 02-13-1973: Certified Survey Map (Rec. 2-15-73, L1-P630), L. J. Hendryx notes the NW Corner, Sec. 3, T2N, R2W and calls for a "pointed stone, #4 iron at surface."
- 7). 04-02-1973: Land Corner Recordation Certificate for G-13, T3N, R2W (Rec. 5-11-73, L2-P413), R. M. Lester, L.P.S. 18998 "set 1/2" bar (G-13) on townline recorded falling from found NW Corner Sec. 3, T2N, R2W (G-1)."
- 8). 04-04-1973: Certified Survey Map (Rec. 5-11-73, L1-P718), R. M. Lester notes "NW Cor. Sec. 3, T2N, R2W, found 1/2" bar" 19.8 feet West of G-13, T3N, R2W.
- 9). 08-31-1994: Certified Survey Map (Rec. 11-15-94, L7-P386), Ron Helsel, L.P.S. 18994
 "found plow point surrounded by rocks, red brick, and sandstone at a depth of 1
 foot, approximately 1.4 feet south from the C/L Nichols Road and 7.4 feet west
 from the C/L Eifert Road (set collar with lid over plow point). Found axle shaft
 surrounded by rocks, red brick, and sandstone at G-13, T3N, R2W East 19.70
 feet, found nail and tag (no ID.) in S. side 24" Oak N60°W 68.36 feet, found nail
 and tag 25832 (L. A. Bryan) in E. side 18" Cherry S10°W 126.10 feet, NE
 corner of House S40°W 114.31 feet, SW corner of House #506 N55°E 67.35
 feet." He also gives a distance of 2656 90 feet to H-3

INGHAM COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For Corners in Located In: Corner Code #	
1. Public Land Survey T_3N_R 2W F-12	
CENTER 1/4 CORNER TR_	•
SECTION 33 T R B: 12 P: 184 12/6/05 12:06 PM	Pages: 2
DELHI TOWNSHIP T R 2005-065034 LAND COUNTY, Michigan	ST. CO.
2. Property Controlling S T R	
in Section S T R	Vanis .
Register of Deeds Stamp	& File Number
3. Miscellaneous S T R	
ABCDEFG	HIJKLM
4. Lot No, Recorded Plat	
5. Private Claims 3	3 - 2 - 1 -
4 - 7 + 8 + 9 +	10 11 12-
I, <u>Brian Reynolds</u> , in a field survey on <u>SEPTEMBER 23, 2005</u> , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in	1 1 1 1
conformance with regulations and rules therefore as required in the current manual of suggestions and rules therefore as required in the current manual of suggestions.	15 - 14 - 13 -
of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of	22 22 24
Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules	22 - 23 - 24
of the missingari board of Land Surveyors of by a Decree of a Court of Law; established,	27 - 26 - 25
11 - - - - - - - - -	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	34 - 35 - 36
A. Description of original monument and accessories and/or subsequent restoration:	
SEE PAGE TWO FOR HISTORICAL SUMMARY	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
FOUND 3/4" REBAR WITH CAP No. 30090 (LOHR) AS DESCRIBED IN ITEMS No. 5 THROUGH 9 OF PAI	RT "A".
TRAVERSED ALL OF SECTION 33, TYING IN FOUND MONUMENTATION THROUGHOUT. TRAVERSE IN IRON AS FOUND TO BE ON A DIRECT LINE FROM F-11 TO F-13, 1.53 FEET SOUTH OF A DIRECT LINE TO G-12.	REVEALED
10 G-12. ACCEPTED INON AS REPRESENTING THE PROPER LOCATION OF THE SUBJECT CENTER	OF SECTION
LEFT 3/4" REROD IN PLACE, SET STANDARD INGHAM COUNTY ALUMINUM CAP STAMPED "31602" WITNESSED AS DESCRIBED BELOW	ON IRON,
WINESSED AS DESCRIBED BELOW	
	•
C. Deposition of managements	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	
WITNESSES TO STANDARD 3/4" IRON WITH ALUMINUM CAP STAMPED "31602"	•
FOUND NAIL & TAG No. 18994 IN THE WEST SIDE OF A 40" WILLOW N25°E 13.49 FEET	•
FOUND NAIL & TAG No. 28414 IN THE NORTH SIDE OF AN 8" OAK FAST 9.37 FEET	
FOUND NAIL & TAG No. 28414 IN THE EAST SIDE OF AN 8" OAK SOUTHEAST CORNER OF A 1.2' X 1.2' CONCRETE POST S10°W 2.81 FEET N30°W 27.63 FEET	_
SOUTHEAST CORNER OF A 1.2' X 1.2' CONCRETE POST N30°W 27.63 FEET	'
net for the second seco	
and the second s	The state of the s
	MOLOS TO
P.A. 345 INGHAM 2011	ANU
() LEED APPROVICE I	RVEYOR
10/10/2005 M	NO /2 /
	- A September 1
	W C S "
Signed by Date October 17, 2005	
Surveyor's Michigan License No 31602 Date October 17, 2005 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SUR	RVEYORS IAN 28 4074

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS. JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JANUARY, 1983 REVISED OCTOBER 1995

A. Description of original monument and accessories and/or subsequent restoration: T3N, R2W, F-12, CONTINUED

- CENTER OF SECTION NOT MONUMENTED BY THE GENERAL LAND OFFICE SURVEY.
- 2. A SURVEY OF MUCH OF THE SOUTH 1/2 OF SECTION 33 BY COUNTY SURVEYOR ANSON JACKSON, DATED DECEMBER 8, 1840, RECORDED IN BOOK 4, PAGE 68, NO MONUMENT SPECIFIED, WITNESSED BY, "B. ASH 5 IN S55 1/2W 10 LKS"

 B. ASH 8 IN N18 1/4W 12 LKS..."
- 3. A SURVEY OF THE SOUTHWEST 1/4 AND THE WEST 1/2 OF THE NORTHEAST 1/4 OF SECTION 33 BY COUNTY SURVEYOR ANSON JACKSON, DATED DECEMBER 12, 1854, RECORDED IN BOOK 4, PAGE 380, NO MONUMENT SPECIFIED, WITNESSED BY, "B. ASH 8 N18 1/4W 12 Do. 5 S55 1/2W 10 .."

4. NOTHING ON ROAD COMMISSION WITNESS MAP.

7.

ACT 132 SURVEY BY BEERY & ASSOCIATES, INC, SIGNED BY DAVID R. LOHR, P.S. 30090, LIBER 6, PAGES 611, 612 & 613, RECORDED DECEMBER 26, 1990 "CENTER OF SEC. 33, T3N, R2W—SET 5/8" X 40" REBAR AT INTERSECTION OF 1/4 LINES, 6' NO. OF ANCHOR POST REMAINS, ON DITCH BANK SET N&T 6" MAPLE WEST 43.60' SW COR. 12" CONC. POST N30°W 28.20 SET N&T 8" WH. OAK S80°E 9.56' SET N&T 8" ELM S25°E 27.70' "F-12 TO G-12 IS SHOWN AS S89°53'51"E 2664.51'; F-13 TO F-12 IS SHOWN AS N00°44'40"W 2639.47'; F-12 TO F-11 IS SHOWN AS N00°44'40"W 2638.26'; F-12 TO E-12 IS SHOWN AS N89°53'51"W 2650.82'.

F-12 TO F-11 IS SHOWN AS N00°44'40"W 2638.26'; F-12 TO E-12 IS SHOWN AS N89°53'51"W 2650.82'.

ACT 132 SURVEY BY ACCOLADE, INC, SIGNED BY RON HELSEL, P.S. 18994, LIBER 6, PAGE 876,

RECORDED DECEMBER 9, 1991 "CENTER OF SEC. 33, T3N, R2W FD. 3/4" REBAR ON EXTENSION OF

C/L DRAINAGE DITCH TO WEST SET N & T S/SIDE 10" ELM, S85°E, 9.70'

SET N & T S/SIDE 6" ELM, N45°E, 1.5' SET N & T S/SIDE 40" WILLOW, N25°E, 13.90'

DRAINAGE DITCH TO SOUTH, EAST 12'...."

E-12 TO F-12 IS SHOWN AS S89°14.36"E 2647.50'.

LAND CORNER RECORDATION CERTIFICATE, LIBER 7, PAGE 241, RECORDED DECEMBER 9, 1991, RON HELSEL, P.S. 18994, PART A: "NO CORNER SET." PART B: "FOUND 3/4" REBAR ON EXTENSION OF DRAINAGE DITCH WEST CORNER FOUND TO BE IN CLOSE ACCORD WITH THE INTERSECTION OF E-W & N-S (?) LINES AS TRAVERSED. CORNER APPARENTLY USED IN A BEERY & ASSOC. SURVEY IN THE SE 1/4 OF SECTION."

PART C: "3/4" REBAR N & T S/SIDE 10" ELM, S85°E, 9.70'

N & T S/SIDE 6" ELM, N45°E, 1.5'

N & T S/SIDE 40" WILLOW, N25°E, 13.90'

C/L OF DRAINAGE DITCH TO SOUTH EAST 12'± "

8. ACT 132 SURVEY BY WOLVERINE ENGINEERS & SURVEYORS, INC, SIGNED BY MAURICE H. MAHIEU, P.S. 28414, LIBER 8, PAGES 407 & 408, RECORDED JANUARY 19, 1999 "CENTER OF SECTION 33, T3N, R2W, DELHI TOWNSHIP, INGHAM COUNTY, MICHIGAN FOUND 3/4" REROD ON SE CORNER DITCH WITNESSES: N&T #18994 W. SIDE 40" WILLOW, N25°E 13.75' N&T #28414 N. SIDE 8" OAK, EAST 9.37' N&T #28414 E. SIDE 8" OAK, S10°W, 2.75' SE. CORNER 1.2' X 1.2' CONC. FENCE POST, N20°W 27.68' F-11 TO F-12 IS SHOWN AS S00°01'50"E 2638.36'; F-12 TO E-12 IS SHOWN AS N89°15.06"W 2647.50'.

TWO ACT 132 SURVEYS BY WOLVERINE ENGINEERS & SURVEYORS, INC, SIGNED BY MAURICE H.
MAHIEU, P.S. 28414, LIBER 8, PAGE 712, RECORDED MAY 12, 2000 AND LIBER 8, 891, RECORDED JULY
25, 2001, "CENTER OF SECTION 33, T3N, R2W, DELHI TOWNSHIP, INGHAM COUNTY, MICHIGAN
FOUND 3/4" REROD ON SE CORNER DITCH WITNESSES:

N&T #18994 W. SIDE 40" WILLOW, N25°E 13.75' N&T #28414 N. SIDE 8" OAK, EAST 9.37' N&T #28414 E. SIDE 8" OAK, S10°W, 2.75' SE. CORNER 1.2' X 1.2' CONC. FENCE POST, N82°W 14.75' "F-12 TO F-13 IS SHOWN AS S00°10'13"E 2639.22'; E-12 TO F-12 IS SHOWN AS S89°15'06"E 2647.50'.

10. ACT 132 SURVEY BY FRED WHITE ENGINEERING COMPANY, INC, SIGNED BY FRED N. WHITE, P.S. 12034, LIBER 8, PAGE 1224, RECORDED SEPTEMBER 22, 2003 "CENTER OF SECTION 33, T3N, R2W" NO WITNESSES DESCRIBED. F-12 TO F-11 IS SHOWN AS N00°46'06"W 2638.54'.

BRIAN EVHOUS SURVEYOR NO 3160

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

4. Lot No Recorded Plat 5. Private Claims 6. Private Claims 7. Private Claims 8. Private Claims 9. Priv						
1. Public Land Survey SOUTH 147 CORNER SECTION 33 TR B112 F188 SECTION 33 TR REGISter of Deeds Stamp & File Number Property Controlling ST RESISTER OF Deeds Stamp & File Number 2. Property Controlling ST RESISTER OF Deeds Stamp & File Number 3. Miscellaneous ST RESISTER OF Deeds Stamp & File Number 4. Lot No. Recorded Plat 5. Private Claims 1. Dean Recorded Pl	INGHAM	Located In:	Corner Code #			
DELHI TOWNSHIP 2. Property Controlling S. T. R. 3. Miscellaneous S. T. R. 4. Lot No. Accorded Plat S. Private Claims Register of Deeds Stamp & File Number 4. Lot No. Accorded Plat S. Private Claims Register of Deeds Stamp & File Number 4. Lot No. Accorded Plat S. Private Claims S. T. R. 4. Lot No. Accorded Plat S. Private Claims S. T. R. A B C D E F G H I J K L M S. PA 74, Minipain PA of 1970, the currer points mentioned in lines 1 and 2 above were in conformance with the plate of the littlenic Number of Land Stampane of the Current manual of survey instructions of the United PA 74, Minipain PA of 1970, the currer points mentioned in lines 1 and 2 above were in conformance with little conteme in the littlenic Number of Land Sturveyon on 19 aborter of 2 current of by a derive of 2 colour 1, Law adolf 8 A Description of circle in Littlenic Number of Land Sturveyon on 19 aborter of 2 current of Land Sturveyon on 19 aborter of 2 current of Land Sturveyon on 19 aborter of 2 current of Land Sturveyon on 19 aborter of 2 current of Land Sturveyon on 19 aborter of 2 current of Land Sturveyon on 19 aborter of 2 current of Land Sturveyon on 19 aborter of 2 current of Land Sturveyon on 19 aborter of 2 current of Land Sturveyon on 19 aborter of 2 current of Land Sturveyon on 19 aborter of 2 current of Land Sturveyon on 19 aborter of 2 current of Land Sturveyon on 19 aborter of 2 current of Land Sturveyon on 19 aborter of 2 current of Land Sturveyon Current of Land Sturveyon on 19 aborter of 2 current of Land Sturveyon on 19 aborter of 2 current of Land Sturveyon on 19 aborter of 19 aborter of 2 current of Land Sturveyon on 19 aborter of 2 current of Land Sturveyon on 19 aborter of 2 current of Land Sturveyon on 19 aborter of 2 current of 19 aborte	Public Land Survey SOUTH 1/4 CORNER		<u>F-13</u>			
In Section S T R Register of Deads Stamp & File Number 3. Miscellaneous S T R R 4. Lot No Recorded Plat 5. Private Claims 4. Lot No Recorded Plat 5. Private Claims 6. Bidar Remotis, in a field survey on OCTOBER 7, 2005, do hereby certify that under requirements of PA 74, Michigair PA of 1970, the comer points mentioned in hises 1 and 2 above were in conformance of the particle of the private		TR TR	B:12 P 2005-0650 Paula Joh	:185 12/6 235 LAND COENEES		PM Pages: 2
3. Miscellaneous S_T_R_ 4. Lot No_Recorded Piat 5. Private Claims 6. Private Claims 6. Private Claims 6. Private Claims 6. P.A. 74. Michigan P.A. of 1970, the comer points mendioned is lines 1 and 2 above were in conformance with requirements and trust tentions are required in the current inmus of Javany instructions of the United States Department of the Indexto, Bureau of the Indexto, Bureau of Land Management or by a decree of a Count of Law anotor but the corner points manchined in ass 5,4, and a above were in conformance with the rules of Land Gurveyors or by a Deciene of a Count of Law anotor but the corner points manchined in ass 5,4, and a above were in conformance with the rules of Land Gurveyors or by a Deciene of a Count of Law anotor but the corner points manchined in ass. 5,4, and a above were in conformance with the rules of the substitution of the conformance of Land Gurveyors or by a Deciene of a Count of Law, established, re-established. 7. Private Claims 7. Private Claims 8. 199 20 2 21 22 23 24 14 15 15 15 15 15 15 15 15 15 15 15 15 15		T R T R		1		
4. Lot No				Register	of Deeds Stam	o & File Number
4. Lot No Recorded Plat 5. Private Claims 7. Refundation in a field survey on OCTOBER 7, 2005, do hereby certify that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with requisitions and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior Busines of 1 and 1	3. Miscellaneous S	T R		Λ.		
I. Brian Remolds, in a field survey on GCTOBERT, 2005, do hereby certify that under requirements of PA-74, Michigan PA of 1970, the coner points mentioned in lines 1 and 2 above were in conformance with regulations are required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law analor that the corner points mentioned in lines 3, 4, and 5 shows were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, monumented, re-monumented, re-monumented, re-monumented, re-monumented, re-monumented, re-monumented, re-monumented, re-monumented, recovered, flound as expressed below. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 1. GENERAL LAND OFFICE DEPUTY SURVEYOR JOHN MULLETT, MAY 13, 1827, "40.00 SET A 1/4 POST FW A Be, 5 IN, NTS 1/2W 24 LKS Do, 8 IN, NTZE 37 LKS" 2. A SURVEY OF MUCH OF THE SOUTH 1/2 OF SECTION 33 BY COUNTY SURVEYOR ANSON JACKSON, DATED DECEMBER 8, 1940, REDGREED AND SECTION 33 BY COUNTY SURVEYOR ANSON JACKSON, DATED DECEMBER 8, 1940, REDGREED AND SECTION 33 BY COUNTY SURVEYOR ANSON JACKSON, DATED DECEMBER 8, 1940, REDGREED AND SECTION 33 BY COUNTY SURVEYOR ANSON JACKSON, DATED DECEMBER 12, 1954, RECORDED IN BOOK 4, PAGE 380, NO MONUMENT SPECIFIED, WITNESSED BY, "BEECH 5 IN 1752 B LKS" 3. A SURVEY OF THE SOUTHWEST 114 MAD THE WEST 112 OF THE NOTHHEAST 1/4 OF SECTION 33 BY COUNTY SURVEYOR ANSON JACKSON, DATED DECEMBER 12, 1954, RECORDED IN BOOK 4, PAGE 380, NO MONUMENT SPECIFIED, WITNESSED BY, "BEECH 5 IN 1754W 24 L." 4. NOTHING ON ROAD COMMISSION WITNESS MAP. SEEP AGE TWO FOR CONTINUATION OF HISTORICAL SUMMARY 5. Description of corner evidence found and/or method applied in restoring or restablishing corner. FOUND A" X 39" CONCRETE MONUMENT IN A MONUMENT IN A MONUMENT BY A WITNESSED AS DESCRIBED BELOW BY SURVEYOR LESTER, ITEM No. 6 OF PART "A". THAT RECORDING DID NOT S				2 -	6 - 5 - 4 -	
with regulations and rules therefore as recipited in the current manage of survey instructions of the United States Department of the Interior, Bureau of Land Management of the Jose decree of a Count of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors of by a Decree of a Count of Law, established, monumented, recovered, found as expressed below. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A Describtion of orional monument and accessories and/or subsequent restoration: GENERAL LAND OFFICE DEPUTY SURVEYOR JOHN MULLETT, MAY 13, 1827, "40.00 SET A 1/4 POST FW A Be. 5 IN. N75 1/2W 24 LKS Do. 8 IN. N72E 37 LKS." A SURVEY OF MUCH OF THE SOUTH 1/2 OF SECTION 33 BY COUNTY SURVEYOR ANSON JACKSON, DATED DECEMBER 9, 1840, RECORDED IN BOOK 4, PAGE 58, NO MONUMENT SPECIFIED, WITHERSED BY, "BEECH 5 IN N72W 24 LKS BEECH 5 IN N72W 31 LKS" 3. A SURVEY OF THE SOUTHWEST 1/4 AND THE WEST 1/2 OF THE NORTHEAST 1/4 OF SECTION 33 BY COUNTY SURVEYOR ANSON JACKSON, DATED DECEMBER 12, 1854, RECORDED IN BOOK 4, PAGE 380, NO MONUMENT SPECIFIED, WITHERSED BY, "BEECH 5 N75 1/2W 24" 4. NOTHING ON ROAD COMMISSION WITHESS MAP. SEE PAGE TWO FOR CONTINUATION OF HISTORICAL SUMMARY B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND 4" X 36" CONCRETE MONUMENT IN A MONUMENT BOX 3" BELOW BITUMINOUS SURFACE CONSISTENT WITH 1979 REMONUMENT AND BOX, EXCAVATED AND FOUND SEVERAL LARGE FIECES O FBICK, AND SEVERAL PIECES OF BROKEN CONCRETE, SOME OF WHICH HAD WITH 1979 REMONUMENT AND BOX, EXCAVATED AND FOUND SEVERAL LARGE FIECES OF BRICK, AND SEVERAL PIECES OF BROKEN CONCRETE, SOME OF WITH HAD BOX, EXCAVATED AND FOUND AND ALL & TAG NO. 18998 IN THE WEST SIDE OF A POWER POLE NAZ 151° 31.60" FOUND NAIL & TAG NO. 18998 IN THE WEST SIDE OF A POWER POLE NAZ 151° 31.60" FOUND NAIL & TAG NO. 18998 IN THE WEST SIDE OF A POWER POLE NAZ 151°	I, <u>Brian Reynolds</u> , in a field survey on <u>C</u>	OCTOBER 7, 2005, do he	ereby certify that under require	ements of 5	7 + 8 + 9 +	10 11 12
that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyor by a Decree of a Count of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 10	with regulations and rules therefore as a States Department of the Interior, Burea	required in the current ma au of Land Management	inual of survey instructions of or by a decree of a Court of La	the United 7		
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 11	that the corner points mentioned in lines Michigan Board of Land Surveyors or b	s 3, 4, and 5 above were y a Decree of a Court of i	in conformance with the rules _aw; established, re-establishe	of the 9		
A. Description of original monument and accessories and/or subsequent restoration: 1. GENERAL LAND OFFICE DEPUTY SURVEYOR JOHN MULLETT, MAY 13, 1827, "40.00 SET A 1/4 POST FW A Be. 5 IN. N75 1/2W 24 LKS Do. 8 IN. N72E 37 LKS" 2. A SURVEY OF MUCH OF THE SOUTH 12 OF SECTION 33 BY COUNTY SURVEYOR ANSON JACKSON, DATED DECEMBER 8, 1840, RECORDED IN BOOK 4, PAGE 68, NO MONUMENT SPECIFIED, WITNESSED BY, "BEECH 5 IN N75W 24 LKS BEECH 8 IN N72E 39 LKS" 3. A SURVEY OF THE SOUTHWEST 1/4 AND THE WEST 1/2 OF THE NORTHEAST 1/4 OF SECTION 33 BY COUNTY SURVEYOR ANSON JACKSON, DATED DECEMBER 12, 1854, RECORDED IN BOOK 4, PAGE 380, NO MONUMENT SPECIFIED, WITNESSED BY, "BEECH 5 IN 75 1/2W 24" 4. NOTHING ON ROAD COMMISSION WITNESS MAP. SEE PAGE TWO FOR CONTINUATION OF HISTORICAL SUMMARY B. Description of corner evidence found and/or method applied in restoring or reestabilishing corner: FOUND 4" X 36" CONCRETE MONUMENT IN A MONUMENT BOX 3" BELOW BITUMINOUS SURFACE CONSISTENT WITH 1979 REMONUMENTATION BY SURVEYOR LESTER, ITEM No. 6 OF PART "A". THAT RECORDING DID NOT DESCRIBE AN EXTENSIVE EXCAVATION. REMOVED CONCRETE MONUMENT AND BOX, EXCAVATED AND FOUND SEVERAL LARGE PIECES OF BRICK, AND SEVERAL PIECES OF BROKEN CONCRETE, SOME OF WHICH HAD WITSE MEST REINFORGING, AROUND AND BELOW WHERE THE HE CONCRETE MONUMENT HAD BEEN. ACCEPTED COLLATERAL EVIDENCE AS CONFIRMING THE LOCATION OF CONCRETE MONUMENT AS FOUND. REINSTALLED MONUMENT BOX, REPLACED CONCRETE MONUMENT WITH STANDARD STEEL FORM PIN AND ALUMINUM CAP, WITNESSED TO 3/4" X 24" STEEL FORM PIN WITH ALUMINUM CAP STAMPED "31.60" FOUND NAIL 8 TAG No. 18998 IN THE WEST SIDE OF A N 8" POST NAZ 15" 31.60" FOUND NAIL 8 TAG NO. 18998 IN THE WEST SIDE OF A N 8" POST NORTH 26.92" 2" SOUTH OF CENTER OF EAST — WEST BITUMINOUS ROADWAY. Date October 17, 2005				11 —		
1. GENERAL LAND OFFICE DEPUTY SURVEYOR JOHN MULLETT, MAY 13, 1827, "40.00 SET A 1/4 POST FW A Be. 5 IN. N75 1/2W 24 LKS De. 8 IN. N72E 37 LKS" 2. A SURVEY OF MUCH OF THE SOUTH 1/2 OF SECTION 33 BY COUNTY SURVEYOR ANSON JACKSON, DATED DECEMBER 8, 1840, RECORDED IN BOOK 4, PAGE 68, NO MONUMENT SPECIFIED, WITNESSED BY, "BEECH 5 IN N75W 24 LKS BEECH 8 IN N72E 39 LKS" 3. A SURVEY OF THE SOUTHWEST 1/4 AND THE WEST 1/2 OF THE NORTHEAST 1/4 OF SECTION 33 BY COUNTY SURVEYOR ANSON JACKSON, DATED DECEMBER 12, 1854, RECORDED IN BOOK 4, PAGE 380, NO MONUMENT SPECIFIED, WITNESSED BY, "BEECH 5 N75 1/2W 24" 4. NOTHING ON ROAD COMMISSION WITNESS MAP. SEE PAGE TWO FOR CONTINUATION OF HISTORICAL SUMMARY B. DESCRIPTION OF CONTINUATION OF CONTINUA				13		7 9 9
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND 4" X 36" CONCRETE MONUMENT IN A MONUMENT BOX 3" BELOW BITUMINOUS SURFACE CONSISTENT WITH 1979 REMONUMENTATION BY SURVEYOR LESTER, ITEM No. 6 OF PART "A". THAT RECORDING DID NOT DESCRIBE AN EXTENSIVE EXCAVATION. REMOVED CONCRETE MONUMENT AND BOX, EXCAVATED AND FOUND SEVERAL LARGE PIECES OF BRICK, AND SEVERAL PIECES OF BROKEN CONCRETE, SOME OF WHICH HAD WIRE MESH REINFORCING, AROUND AND BELOW WHERE THE CONCRETE MONUMENT HAD BEEN. ACCEPTED COLLATERAL EVIDENCE AS CONFIRMING THE LOCATION OF CONCRETE MONUMENT AS FOUND. REINSTALLED MONUMENT BOX, REPLACED CONCRETE MONUMENT WITH STANDARD STEEL FORM PIN AND ALUMINUM CAP, WITNESSED AS DESCRIBED BELOW. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: WITNESSES TO 3/4" X 24" STEEL FORM PIN WITH ALUMINUM CAP STAMPED "31602" FOUND NAIL & TAG NO. 18998 IN THE WEST SIDE OF A POWER POLE NAZ 151° 31.64' FOUND NAIL & TAG NO. 18998 IN THE WEST SIDE OF A POWER POLE NAZ 15° 31.60' FOUND NAIL & TAG NO. 18998 IN THE EAST SIDE OF A N8" POST NORTH 26.92' 2' SOUTH OF CENTER OF EAST – WEST BITUMINOUS ROADWAY. Signed by Date October 17, 2005	 GENERAL LAND OFFICE Be. 5 IN. N75 1/2W 24 L A SURVEY OF MUCH OF DECEMBER 8, 1840, REC "BEECH 5 IN N75W 24 A SURVEY OF THE SOUT SURVEYOR ANSON JAC SPECIFIED, WITNESSED 	E DEPUTY SURVEYO KS Do. 8 IN. N THE SOUTH 1/2 OF CORDED IN BOOK 4, LKS BE THWEST 1/4 AND TH KSON, DATED DECE BY, "BEECH	R JOHN MULLETT, MAY 72E 37 LKS" SECTION 33 BY COUNTY PAGE 68, NO MONUMEN ECH 8 IN N72E 39 LKS. E WEST 1/2 OF THE NOR MBER 12, 1854, RECORI 5 N75 1/2W 24"	13, 1827, "40.00 SURVEYOR AND IT SPECIFIED, W "	SON JACKSON, I	DATED
WITH 1979 REMONUMENT ATTON BY SURVEYOR LESTER, ITEM No. 6 OF PART "A". THAT RECORDING DID NOT DESCRIBE AN EXTENSIVE EXCAVATION. REMOVED CONCRETE MONUMENT AND BOX, EXCAVATED AND FOUND SEVERAL LARGE PIECES OF BRICK, AND SEVERAL PIECES OF BROKEN CONCRETE, SOME OF WHICH HAD WIRE MESH REINFORCING, AROUND AND BELOW WHERE THE CONCRETE MONUMENT HAD BEEN. ACCEPTED COLLATERAL EVIDENCE AS CONFIRMING THE LOCATION OF CONCRETE MONUMENT AS FOUND. REINSTALLED MONUMENT BOX, REPLACED CONCRETE MONUMENT WITH STANDARD STEEL FORM PIN AND ALUMINUM CAP, WITNESSED AS DESCRIBED BELOW. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: WITNESSES TO 3/4" X 24" STEEL FORM PIN WITH ALUMINUM CAP STAMPED "31602" FOUND NAIL & TAG NO. 18998 IN THE WEST SIDE OF A POWER POLE NAZ 151" 31.64' FOUND NAIL & TAG NO. 18998 IN THE WEST SIDE OF A POWER POLE NAZ 151" 31.64' FOUND NAIL & TAG NO. 18998 IN THE EAST SIDE OF A POWER POLE NAZ 163" 33.83' FOUND NAIL & TAG NO. 18998 IN THE EAST SIDE OF A POWER POLE NAZ 163" 33.83' FOUND NAIL & TAG NO. 18998 IN THE EAST SIDE OF A POWER POLE NAZ 163" 33.83' FOUND NAIL & TAG NO. 18998 IN THE EAST SIDE OF AN 8" POST NORTH 26.92' 2' SOUTH OF CENTER OF EAST – WEST BITUMINOUS ROADWAY. Date October 17, 2005					RY	
FOUND NAIL & TAG No. 18998 IN THE WEST SIDE OF A POWER POLE NAZ 151° 31.64' FOUND NAIL & TAG No. 18998 IN THE WEST SIDE OF AN 8" POST NAZ 15° 31.60' FOUND NAIL & TAG No. 18998 IN THE EAST SIDE OF A POWER POLE NAZ 03° 33.83' FOUND NAIL & TAG No. 18998 IN THE EAST SIDE OF AN 8" POST NORTH 26.92' 2' SOUTH OF CENTER OF EAST – WEST BITUMINOUS ROADWAY. P.A. 345 INGHAM COUNTY PEER APPROVED 10/18/2005 NC Signed by Signed by Date October 17, 2005	WITH 1979 REMONUMENTATI DESCRIBE AN EXTENSIVE EX SEVERAL LARGE PIECES OF WIRE MESH REINFORCING, A COLLATERAL EVIDENCE AS O MONUMENT BOX, REPLACED WITNESSED AS DESCRIBED I	MONUMENT IN A MON BY SURVEYOR CAVATION. REMOMENT BRICK, AND SEVEROUND AND BELOCONFIRMING THE CONCRETE MONUBELOW.	IONUMENT BOX 3" BE R LESTER, ITEM No. 6 OVED CONCRETE MOI ERAL PIECES OF BRO OW WHERE THE CONC LOCATION OF CONCE JMENT WITH STANDA	LOW BITUMING OF PART "A". NUMENT AND E KEN CONCRET CRETE MONUM RETE MONUME RD STEEL FOR	THAT RECORD BOX, EXCAVAT E, SOME OF W ENT HAD BEEN NT AS FOUND. RM PIN AND AL	ING DID NOT ED AND FOUND HICH HAD I. ACCEPTED
P.A. 345 INGHAM COUNTY PEER APPROVED 10 /18/2005 NC Surveyor's Michigan License No. 21000	FOUND NAIL & TAG No. 18998 FOUND NAIL & TAG No. 18998 FOUND NAIL & TAG No. 18998 FOUND NAIL & TAG No. 18998	EEL FORM PIN WIT IN THE WEST SID IN THE EAST SID IN THE EAST SIDI	H ALUMINUM CAP ST E OF A POWER POLE E OF AN 8" POST NA E OF A POWER POLE E OF AN 8" POST NOR	AMPED "31602 NAZ 151° 31.6 Z 15° 31.60' NAZ 03° 33.83	" 4'	
P.A. 345 INGHAM COUNTY PEER APPROVED 10 /18/2005 NC Surveyor's Michigan License No. 21000 Date October 17, 2005		÷,			% ~ \	/ ~ 3
Signed by Date October 17, 2005						A STATE OF THE STA
Signed by Date October 17, 2005			P.A. 345 ING	HAM COUNTY	05 M	STEEL STORY
Surveyor's Michigan License M. 24000 Date October 17, 2005			PEER APPROV	ED 10/18/00		
Surveyor's Michigan License M. 24000 Date October 17, 2005	(1 / 1 / 1 / h	\sim				
Surveyor's Michigan License M. 24000 Date October 17, 2005	Signed by			0-1-1		
	Surveyor's Michigan License No	31602				RVEYORS, JAN. 28, 1971

PAGE ONE

REVISED MAY 14, 1975 REVISED JANUARY, 1983 REVISED OCTOBER 1995

- A. Description of original monument and accessories and/or subsequent restoration: T3N, R2W, F-13, CONTINUED
- REGARDING CORRESPONDING CLOSING CORNER F-1, T2N R2W, LAND CORNER RECORDATION CERTIFICATE, LIBER 4, PAGE 376, RECORDED SEPTEMBER 19, 1978 BY RONNIE M. LESTER, P. S. No. 18998, PART A: "NO RECORD OF CORNER BEING ESTABLISHED IN ORIGINAL GOVERNMENT SURVEY. CORNER ESTABLISHED IN A SURVEY BY A. JACKSON, COUNTY SURVEYOR, DATED MAY, 1840 (V.1. P.42)" PART B: "EXCAVATED HOLE 10.2' X 7.8' TO AN AVERAGE DEPTH OF 3.6' SOUTH OF AND INCLUDING CENTERLINE OF NICHOLS ROAD AND ON EXTENDED POLE LINE TO THE SOUTH. FOUND 1" X 2.5' GAS PIPE JUST BELOW ASPHALT SURFACE, LOCATED \pm 2.0' SOUTH OF CENTERLINE NICHOLS ROAD AND ON EXTENDED POLE LINE TO THE SOUTH. FURTHER EXCAVATION REVEALED VAROIUS STONES AROUND AND BENEATH THE GAS PIPE. ACCEPTED GAS PIPE AS CORNER AS IT IS SIMILAR TO OTHER MONUMENTATION FOUND IN THE AREA AND IT IS IN ACCORD WITH ADJACACENT OCCUPATION. MEASURED EAST ± 26.45' TO GAS PIPE AT APPARENT LOCATION OF F-13, DELHI TWP., T3N-R2W. EXCAVATION CONDUCTED BY INGHAM COUNTY SURVEY AND REMONUMENTATION PROJECT CREW." PART C: "N 1/4 CORNER, SECTION 4, SET 4" X 36" CONCRETE MONUMENT WITH 1/2" X 38" REROD WITH CAP #18998, ANDCONCRETE COLLAR WITH COVER IN LOCATION OF GAS PIPE DESCRIBED ABOVE: NAIL & TAG, #18998, SOUTH SIDE 30" WALNUT, WEST, 636,66'...'

NAIL & TAG, #18998, EAST SIDE FENCE CORNER POST, NE 36.61'

NAIL & TAG, #18998, SOUTH SIDE 32" OAK, EAST, 584.77

NAIL & TAG, #18998, WEST SIDE TELEPHONE POLE, SOUTH, 28.30'

2" GAS PIPE (F-13, T3N-R2W), UNRECORDED CORNER, EAST, 26.45' "

LAND CORNER RECORDATION CERTIFICATE, LIBER 5, PAGE 312, RECORDED SEPTEMBER 19, 1979 BY RONNIE M. LESTER, P. S. No. 18998, PART A: "POST SET IN ORIGINAL GOVERNMENT SURVEY BY MUSGROVE EVANS DATED BETWEEN DEC. 24, 1826 AND JAN. 8, 1827. CORNER REFERRED TO IN SUBSEQUENT SURVEYS BY A. JACKSON, COUNTY SURVEYOR, DEC. 8, 1840 (V.1, P.67) AND DEC. 12, 1854 (V.2, P.227)." PART B: "DURING INVESTIGATION FOUND 2" GAS PIPE ± 2.5' SOUTH OF THE CENTERLINE OF NICHOLS ROAD AND ON FENCE LINE TO THE NORTH. MEASURED WEST \pm 26.34' TO F-1 AURELIUS TWP. GAS PIPE MATCHES OCCUPATION, PREVIOUS MONUMENTATION FOUND IN AREA AND IN CLOSE ACCORD WITH G.L.O. DISTANCES EAST AND WEST. ACCEPTED GAS PIPE AS LOCATION OF CORNER AS PERPETUATED. INVESTIGATION CONDUCTED BY INGHAM COUNTY SURVEY AND REMONUMENTATION PROJECT CREW."

PART C: "S 1/4 CORNER, SECTION 33, T3N-R2W SET 4" X 36" CONCRETE MONUMENT WITH 1/2" X 38" REROD AND CAP #18998 WITH CONCRETE COLLAR AND COVER IN LOCATION OF 2" GAS PIPE DESCRIBED ABOVE:

NAIL & TAG, #18998, EAST SIDE 5" WOOD FENCE POST, NNW, 26.82'

NAIL & TAG, #18998, SOUTHWEST SIDE SMALL ELM, SE, 38.92'

NAIL & TAG, #18998, NORTH SIDE POWER POLE, SW 38.94'

SOUTHEAST CORNER OF TIN SHED 2" ABOVE GROUND, NNE, 60.42'

CONCRETE MONUMENT F-1 AURELIUS TWP., T2N-R2W, WEST, 26.34' "

ACT 132 SURVEY BY BEERY & ASSOCIATES, INC, SIGNED BY DAVID R. LOHR, P.S. 30090, LIBER 6, PAGES 611, 612 & 7. 613, RECORDED DECEMBER 26, 1990 "S 1/4 COR. SEC. 33, T3N, R2W L.5, PG. 312 FOUND MON. IN BOX AS N&T IN P. POLE SW 39.24' SE COR. SHED NNE 60.42' PER WITNESSES MON. IN BOX WEST 26.34' N&T FENCE POST NNW 26.82'...." G-13 TO F-13 IS SHOWN AS N89°52'48"W 2653.33'; F-13 TO F-12 IS SHOWN AS N00°44'40"W 2639.47';

E-13 TO F-13 IS SHOWN AS N89°54'56"W 2655.19'.

ACT 132 SURVEY BY WOLVERINE ENGINEERS & SURVEYORS, INC, SIGNED BY MAURICE H. MAHIEU, P.S. 28414, LIBER 8, PAGE 712, RECORDED MAY 12, 2000 "S 1/4 CORNER, SEC. 33, T3N, R2W, DELHI TWP. FOUND 1/2" IRON ROD CONC. MONUMENT IN MONUMENT BOX, 2'± SOUTH OF C/L NICHOLS ROAD WITNESSES: N&T #18998 W. SIDE UTILITY POLE S 33°E N&T #18998 E. SIDE WOOD FENCE CORNER POST, N3°W. N&T #18998 W. SIDE WOOD FENCE POST, N28°E, N&T #28414 W. SIDE 10" THORN APPLE TREE, S3°W " F-12 TO F-13 IS SHOWN AS S00°10'13"E 2639.22'; E-13 TO F-13 IS SHOWN AS S89°16'20"E 2654.94'.

ACT 132 SURVEY BY WOLVERINE ENGINEERS & SURVEYORS, INC, SIGNED BY MAURICE H. MAHIEU, P.S. 28414, LIBER 9. 8, PAGE 891, RECORDED JULY 25, 2001 "S 1/4 CORNER, SEC. 33, T3N, R2W, DELHI TWP. FOUND 1/2" IRON ROD CONC. MONUMENT IN MONUMENT BOX, 2'± SOUTH OF CENTERLINE NICHOLS ROAD WITNESSED BY: N&T #18998 W. SIDE UTILITY POLE S 33°E N&T #18998 E. SIDE WOOD FENCE CORNER POST, N3°W. 26.82'

N&T #18993 W. SIDE WOOD FENCE POST, N28°E, N&T #28414 W. SIDE 10" THORN APPLE TREE, S3°W " F-12 TO F-13 IS SHOWN AS S00°10'13"E 2639.22'; F-13 TO E-13 IS SHOWN AS N89°16'20"W 2654.94'.

THREE ACT 132 SURVEYS BY POLARIS SURVEYING CO., SIGNED BY RONNIE M. LESTER, P.S. 18998, LIBER 8, PAGES 10. 914, 915, & 916 RECORDED SEPTEMBER 6, 2001 "SOUTH 1/4 CORNER, SECTION 33, T3N, R2W, 1/2" BAR IN CONCRETE MONUMENT. LIBER 5, PAGE 312. WITNESSED BY:

NAIL &TAG #18998 WEST SIDE U. POLE MAG. AZ. 151°, 31.66' NAIL &TAG #18998 EAST SIDE U. POLE MAG. AZ. 03°, 33.72' NORTHWEST CORNER HOUSE #5245 MAG. AZ. 164°, 116.63'

CONCRETE MONUMENT AT F-1, AURELIUS, WEST, 26.40' G-13 TO F-13 IS SHOWN AS N89°53'50"W 2653.23'. ACT 132 SURVEY BY WOLVERINE ENGINEERS & SURVEYORS, INC, SIGNED BY MAURICE H. MAHIEU, P.S. 28414, LIBER . 11. 8, PAGE 968, RECORDED MARCH 14, 2002 "SOUTH 1/4 COR., SEC. 33, T3N, R2W, DELHI TWP. **FND 1/2" IRON** ROD CONC. MON. IN MON. BOX, 2'± SOUTH OF CENTERLINE NICHOLS ROAD WITNESSES:

123


N&T UTILITY POLE, SW 39.24'

SE CORNER SHED, NNE. 60.42'

MON. IN BOX, WEST 28.34'

N&T FENCE POST, NNW 26.82' "

F-13 TO E-13 IS SHOWN AS N89°16'20"W 2654.94';



INGHAM COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

			·			
For Corners in INGHAM	Located In:	Corner Code	: #			
(county) 1. Public Land Survey CORNER COMMON	T <u>3N</u> R <u>2W</u> TR	<u>E-13</u>				
TO SECTIONS 32 & 33 ON TOWN LINE	TR	-	B:12 P:186	12/6/05	12:06 PM	Pages: 2
DELHI TOWNSHIP	1R	· - · · · · · · · · · · · · · · · · · ·	- Paula Johnson,	AND CORNERS Receiptingham County, Mic	t #3839 higan	STATE OF THE PARTY
	T R T R	**				
in Section S	T R					Mari
10				Register of Dee	ds Stamp & F	ile Number
3. Miscellaneous S	T R					1.
				ABCD	EFGH	IJKLM
4. Lot No, Recorded Plant	at			2 6 5		
5. Private Claims_	<u> </u>			3		7 7 1 7
				4 - 7 - 8	9 - 10-	+11-12-
I, <u>Brian Reynolds</u> , in a field survey on <u>Or</u>	ctober 31, 2005, do he	reby certify that un	der requirements of	P.A. 5		
74, Michigan P.A. of 1970, the corner poregulations and rules therefore as require	oints mentioned in lines	s 1 and 2 above we	re in conformance v	0 10 17	16 -15	14-13-
States Department of the Interior, Burea	u of Land Managemen	it or by a decree of	a Court of Law and	/or 7		
that the corner points mentioned in lines	3, 4, and 5 above were	e in conformance v	vith the rules of the	8 - 19 - 20	21-22-	+ 23 24
Michigan Board of Land Surveyors or by	/ a Decree of a Court o	f Law; established,	re-established,	9	28 - 27	26 25
monumented, re-monumented, recovered	a, found as expressed	below.		11 1		20 25
NOTE: Not more than 2 corners, all in th	e same town and rang	e, may be recorded	d on this certificate.	12 31 32	33 - 34	35 36
A. Description of original monument	and accessories an	d/or subsequent	restoration:	13		- h
	SEE PA	GE TWO FOR O	CORNER HISTOR	₹Y		
B. Description of corner evidence for FOUND 3/16" X 8" BOAT SPIKE IN ONONDAGA ROAD. EXCAVATED FOUND NOTHING. SET 1/2" X 18" No. 7 OF PART "A", THE IRON FOWAS FOUND AND VERY WELL DOTEST, THE GOVERNMENT SURVED COUMENTED CLOSING CORNEGOVERNMENT DISTANCE EAST BITS OF SHATTERED GLASS, BRENOVE THE TRUE CORNER POSISERVE AS A PROPERTY CONTROTHROUGH CORRESPONDING E-1 REMONUMENTATION IRON AND CONTROTHE	N MONUMENT BOX INTERIOR OF BOX " REBAR WITH "RE DUND COULD NOT OCUMENTED IN 19 EY CALLS FOR 35.6 R. EXCAVATED AI OF THE CLOSING OR RICK, AND CHINA A ITION. DISREGARI OLLING CORNER. I, 35.64 FEET FURT CAP, WITNESSED	CON CENTERLII C, ENCOUNTER EYNOLDS 31602 BE RECONCILE 178. THE MEASI 64 FEET. THE E N 18" DIAMETER CORNER AND 1 LT 20" BELOW CO DED THE EARLI ESTABLISHED THER EAST. INS AS DESCRIBED	NE OF NICHOLS ED CLAY AT 24" " CAP IN PLACE URED DISTANCE BOAT SPIKE FOU R HOLE THROUG .7 FEET SOUTH GRADE. ACCEP ER FOUND BOA CORNER POSIT STALLED MONU BELOW.	ROAD AND ALONG CONTINUED TO F CORRESPONDING CL E BETWEEN MONU JND WAS 1.7 FEET GH 8" OF BITUMING OF THE FIRST MO TED FOUND EVIDE AT SPIKE, LEFT IRC ION BY EXTENDING MENT BOX AND ST	INAL DEPTH OF AS DETAILED LOSING CORN MENTS AS FOUR AT THE NUMENT BOXINGE AS SUFFININ MONUMER ALINE FROM A LINE FROM ANDARD	OF 48", D IN ITEM ER THAT DUND IS 32.55 HE WELL- FOUND ICIENT TO
C. Description of monument for corn	er and accessories	established to pe	rpetuate locating	the position of the co	orner	
E-13	•	\$	PROPERTY CON	TROLLING CORNE	R	
WITNESSES TO 3/4" X 24" STEEL WITH ALUMINUM CAP STAMPED IN MONUMENT BOX	"31602"		WITNESSES TO N MONUMENT E	1/2" X 18" REBAR BOX		
SET N&T (REYNOLDS 31602) IN S	W SIDE OF	5	SET N&T (REYNO	OLDS 31602) IN SW	SIDE OF	
POWER POLE N37°W 5	9.40 FEET			POLE N34°W 56.1		
FD. N&T No. 28414 IN THE EAST S		F	D. N&T No. 284	14 IN THE EAST SI	DE OF	
POWER POLE \$47°W 10 SET N&T (REYNOLDS 31602) IN S	05.88 FEET			POLE S45°W 105.		
24" WALNUT N80°E 89.				DLDS 31602) IN S S NUT N83°E 92.13		
SET N&T (REYNOLDS 31602) IN W	/ SIDE OF	٠ .		DLDS 31602) IN W S		
38" WALNUT N33°E 58			38" WAL	NUT N36°E 58.16	FEET ,	en er er en en er
PROPERTY CONTROLLING CORN TO D-13 IS N89°40'01"W 2657.72'	IER N61°W 3.57'	T	O TRUE CORNE	R E-13 S61°E 3.57	11 September 1	10 Sec. 1
TO F-13 IS \$89°19'06"E 2651.87'					A Service Control of the Control of	
TO E-12 IS N00°06'22"W 2641.61'	. * 				12/ us	State to A
				GHAM COUNTY		1 4.16
			PEER APPROV	/ED 11/22/2005		mark n /
				p		Sim 18 3
					Mary of James	San James San
Signed by Surveyor's Michigan Linears Ve			Date N	ovember 3, 2005	A SECTION AND ADDRESS OF THE PERSON AND ADDR	

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS. JAN. 28, 1971

31602

Surveyor's Michigan License No.

A. Description of original monument and accessories and/or subsequent restoration: T3N R2W E-13 CONTINUED

- 1. GENERAL LAND OFFICE DEPUTY SURVEYOR JOHN MULLETT, MAY 13TH, 1825, "...80.00 SET POST COR. TO SECS 32 & 33 FW Be 12 IN. N35E 57 LKS Do. 6" N61W 30 LKS...."
- 2. A SURVEY OF THE SOUTHWEST 1/4 AND THE WEST 1/2 OF THE NORTHEAST 1/4 OF SECTION 33 BY COUNTY SURVEYOR ANSON JACKSON, DATED DECEMBER 12, 1854, RECORDED IN BOOK 4, PAGE 380, NO MONUMENT SPECIFIED, WITNESSED BY, "...D O 6 N61W 30 MAPLE 12 S34E 15 .."
- 3. A SURVEY OF MOST OF SECTION 32 BY T. J. BROWN, COUNTY SURVEYOR, DATED JUNE 15, 1875, COUNTY SURVEYOR BOOK 2, PAGE 128, THE SUBJECT CORNER IS LABELED "21" ON THE PLAT, AND IS DESCRIBED AS FOLLOWS, "A STONE..." THE PLAT DOES NOT SHOW DISTANCES TO OTHER CORNERS.
- 4. NOTHING ON ROAD COMMISSION WITNESS MAP.
- 5. ACT 132 SURVEY BY BOSS ENGINEERING COMPANY, SIGNED BY OSCAR BOSS, P.S. 13574, LIBER 1, PAGE 925 & 926, RECORDED SEPTEMBER 17, 1973, "S. E. COR. SEC. 32, T3N, R2W" NO WITNESSES DESCRIBED. E-12 TO E-13 SHOWN AS S0°21'40"W 2640.05'; E-13 TO D-13 SHOWN AS N89°21'11"W 2654.54'.
- LAND CORNER RECORDATION CERTIFICATE, LIBER 3, PAGE 93, RECORDED APRIL 25, 1974, BY OSCAR BOSS, P. S. No. 13574, PART A: "UNKNOWN" PART B: "IRON FD." PART C: "SE CORNER N.14°E. 70.18 NAIL S/S TELE POLE S.8°E. 69.15 NAIL W/S UTILITY POLE N.71°E. 93.02 NAIL S/S BOX ELDER"
- 7. REGARDING CORRESPONDING CLOSING CORNER E-1 T2N R2W, LAND CORNER RECORDATION CERTIFICATE, LIBER 4, PAGE 333, RECORDED SEPTEMBER 5, 1978, BY RONNIE M. LESTER, P. S. No. 18998, PART A: "POST SET BY MUSGROVE EVANS IN ORIGINAL GOVERNMENT SURVEY BETWEEN DEC. 24, 1826 JAN. 8, 1827. CORNER IDENTIFIED AS STONE BY T.J. BROWN, COUNTY SURVEYOR, IN SURVEY DATED MAY 3, 1874 (V.3, P.52). CORNER IDENTIFIED AS BUGGY AXLE BY R. J. ROBB, COUNTY SURVEYOR, IN SURVEY DATED 1912 (V.2, P.79 COPY)"
 - PART B: "EXCAVATED HOLE 20.6' X 8' TO AN AVERAGE DEPTH OF 2.7' IN CENTERLINE OF NICHOLS ROAD AND WEST OF CENTERLINE OF ONONDAGA ROAD. FOUND 1/2" BOAT SPIKE IN CENTERLINE OF NICHOLS ROAD AND 13.5'± WEST OF THE CENERLINE OF ONONDAGA ROAD. FOUND 1" X 21" BUGGY AXLE IN UPRIGHT POSITION SURROUNDED BY 5 LARGE ROCKS, 2' BELOW SURFACE, 35'± WEST OF EXTENDED PHYSICAL CENTERLINE OF ONONDAGA ROAD TO NORTH AND ON PHYSICAL CENTERLINE OF NICHOLS ROAD. ACCEPTED BUGGY AXLE AS CORNER DESCRIBED BY R. J. ROBB IN SURVEY DATED 1912. FALLING RECORDED TO BE 35.64' IN G.L.O. MEASURED 32.64' TO 1/2" BAR E-13, DELHI TWP., T3N-R2W AS RECORDED IN L.3, P.93, (PA 74) EXCAVATION CONDUCTED BY INGHAM COUNTY SURVEY AND REMONUMENTATION PROJECT CREW."
 - PART C: "NORTHWEST CORNER, SECTION 4, T2N-R2W, SET 4" X 36" CONCRETE MONUMENT WITH 1/2" X 38" REROD WITH CAP #18998, AND CONCRETE COLLAR WITH COVER AT LOCATION OF BUGGY AXLE DESCRIBED ABOVE: NAIL & TAG, #18998, SOUTH SIDE 18" MAPLE, WNW. 152.94'
 - FOUND P.K. NAIL, NORTHWEST SIDE 36" WALNUT, NE, 81.90'
 - FOUND P.K. NAIL, SOUTHEAST SIDE POWER POLE, NE, 86.98'
 - FOUND P.K. NAIL, NORTHEAST SIDE POWER POLE, SSE, 100.23'
 - 1/2" BAR, E-13, DELHI TWP., T3N-R2W, EAST, 32.64'
- S 1/4 CORNER, SECTION 32, DELHI TWP., CONCRETE MONUMENT IN MONUMENT BOX, EAST, 40.07'......"

 8. ACT 132 SURVEY BY FRED WHITE ENGINEERING COMPANY, INC, SIGNED BY DOUGLAS K. RICHARDSON, P.S. 31603, LIBER 5, PAGE 305, RECORDED OCTOBER 6, 1987 "EAST 1/4 CORNER SEC. 32, T3N, R2W (FOUND IRON) NAIL IN S. SIDE OF TEL. POLE, N14°E, 70.20' NAIL & TAG IN W. SIDE UTILITY POLE, S08°E, 93.00' NAIL & TAG IN S. SIDE OF 20" WALNUT, N71°E, 82.68' " E-12 TO E-13 IS SHOWN AS S00°03'40"E 2640.14'.
- 9. LAND CORNER RECORDATION CERTIFICATE, LIBER 6, PAGE 360, RECORDED FEBRUARY 19, 1988, BY DOUGLAS K. RICHARDSON, P.S. #31603, PART A: "FOUND IRON RECORDED IN LIBER 3 ON PAGE 93." PART B: "FOUND IRON RECORDED IN LIBER 3 ON PAGE 93." PART C: "FOUND IRON RECORDED IN LIBER 3 ON PAGE 93 NAIL IN S. SIDE TEL. POLE. N14°E, 70.20' NAIL AND TAG W. SIDE UTILITY POLE, S08°E, 93.00' NAIL AND TAG S. SIDE 20" WALNUT, N71°E, 82.68' "
- 10. ACT 132 SURVEY BY BEERY & ASSOCIATES, INC, SIGNED BY DAVID R. LOHR, P.S. 30090, LIBER 6, PAGES 611, 612 & 613, RECORDED DECEMBER 26, 1990 "SW COR. SEC. 33, T3N, R2W" NO WITNESSES DESCRIBED. E-13 TO F-13 IS SHOWN AS N89°54'56"W 2655.19'; E-13 TO E-12 IS SHOWN AS N00°38'58"W 2640.25'.
- THREE ACT 132 SURVEYS BY WOLVERINE ENGINEERS & SURVEYORS, INC, SIGNED BY MAURICE H. MAHIEU, P.S. 28414, LIBER 8, PAGE 712, RECORDED MAY 12, 2000; LIBER 8, PAGE 891, RECORDED JULY 25, 2001; AND LIBER 8, PAGE 968, RECORDED MARCH 14, 2002 "SW CORNER, SEC. 33, T3N, R2W, DELHI TWP. FOUND BOAT SPIKE IN MONUMENT BOX WITNESSES: PK NAIL W. SIDE 32" WALNUT, N32°E 58.10'
 PK NAIL SE SIDE UTILITY POLE, N39°W 55.65' N&T #28414 S. SIDE 18" WALNUT, N70°E, 68.90'
 N&T #28414 E. SIDE UTILITY POLE, S39°W 105.15' "
 - E-13 TO E-12 IS SHOWN AS N00°00'30"E 2640.07'; E-13 TO F-13 IS SHOWN AS S89°16'20"E 2654.94'.
- ACT 132 SURVEY BY KEBS, INC, SIGNED BY ANTHONY BUMSTEAD, P.S. 41095, LIBER 9, PAGE 136, RECORDED JANUARY 3, 2005, "SOUTHEST (SIC) CORNER SEC. 32, T3N, R2W FOUND 1/2" BAR IN MONUMENT BOX FOUND NAIL & TAG #28414 IN SOUTHEAST SIDE OF POWER POLE, S20°W, 105.16' SOUTHEAST CORNER OF HOUSE #5506, N45°W, 116.90'

FOUND PK NAIL SOUTHEAST SIDE OF LIGHT POLE, N40°W, 55.60'

SET NAIL & TAG IN SOUTH SIDE OF 20" WALNUT, N80°E, 92.14' "

E-12 TO E-13 IS SHOWN AS S00°01'22"E 2640.04'; E-13 TO D-13 IS SHOWN AS N89°43'09"W 2654.55'.

NAS N89°43'09"W 2654.55'.

WAR

REYNOLUS

AURVEYOL

NO

3160

INGHAM COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For Corners in Lo	cated In: Corne	Code#			
<u>INGHAM</u>	,				
(county)	•	. [
1. Public Land Survey T_1/4 CORNER COMMON T	3N R 2W E-1	2			
TO SECTIONS 32 & 33	R				
DELHI TOWNSHIP T	R	B:12 P:219	12/12/05	8.20 AM	
1_	R	2005-065959 LAND Paula Johnson, In	COENEES deceipt	8:29 AM #4012	Pages: 2
2. Property Controlling S T	R	I HAMBA INABI NA HON BROWNE WAS	Mitalija arbijaka masimi a	ilian Ilaan	E BER
in Section S T			OL 1901 KUB MAN 1940 BUSA MIN BY	H	
		· 1	Pagistar of Dan	d= 0t= 0 t	
2 Miggallana		· ·	Register of Deed	us Stamp & I	<u>-ile Number</u>
3. Miscellaneous ST_	R	<u> </u>			
			ABCD	EFGH	IJKL
4. Lot No, Recorded Plat	· .				1 1
5. Private Claims			2 - 6 - 5	7 4 7 3	
LB: -		***	4 - 7 - 8		
I, Brian Reynolds, in a field survey on Octobe	r 18, 2005, do hereby certify	that under requirements of	- 1 1 T	+ 9 + 10-	- 11 - 12 -
The corner po	ints mentioned in lines 1 and	2 obove !	6 -18 17-	-1615-	
required the rate as required the restriction as required	30 IN the current manual of ea	Digital in admirable as a City of the City	7	16 15 -	14-13-
States Department of the Interior, Bureau of L that the corner points mentioned in lines 3, 4,	and Management or bya dec	ree of a Court of Law and/or	8 - 19 - 20-	21 22-	22 24
Michigan Board of Land Surveyors or by a De	cree of a Court of Lawrence	ance with the rules of the	9 20	21 22	23 - 24-
monumented, re-monumented, recovered, for	and as expressed below	lisned, re-established,	10 - 30 - 29 -	2827-	26 25
			11 1 1	20 21	2625-
NOTE: Not more than 2 corners, all in the san	ne town and range, may be re	corded on this cortificate		33 34-	25 20
			13	33 - 34 -	35 - 36 -
A. Description of original monument and	accessories and/or subse	quent restoration:			
1. GENERAL LAND OFFICE DEP FW (FROM WHICH) A W	1.O. 6 IN. N83E 16 LKS	ROVE EVANS, JANUARY	1827, "40.00 \$	SET 1/4 SEC.	POST
2. A SURVEY OF THE SOUTHWE	EST 1/4 AND THE WEST	Be. 4 IN. S	62W 22 LKS"		
	N, DATED DECEMBER 1	2. 1854. RECORDED IN B	1/4 OF SECTION	33 BY COUN	ITY
SPECIFIED, WITNESSED BY,	" BEECH 4 S62W	22"	OOK 4, PAGE 38	u, no monui	MENT
s s	•	TINUATION OF CORNER	NIETODY		
B. Description of corner evidence found a	nd/or method applied in re	estoring or reestablishing o	omer		
				CAVATED A	2' Y 2' HOLE
THROUGH THREE LAYERS OF BITUMI BRICK. EXPANDED THE HOLE 2 FEET	NOUS AND COMPACTE	D ROAD GRAVEL, TO A	DEPTH OF 2 FEE	T, FOUND A	PIECE OF
BRICK. EXPANDED THE HOLE 2 FEET ORANGE SQUARE AROUND A BOAT S	PIKE APOUT 4 5 555	SECOND BITUMINOUS	ROAD SURFACE	FOUND A P	AINTED
THROUGH THE THIRD BITUMINOUS SI	IREACE TO FIND STON	TILET OF THE FOUND R	AILROAD SPIKE.	EXCAVATE	D FURTHER
FOUND BOAT SPIKE, DISREGARDED	RAII BOAD SPIKE ACC	EDTED DONOR, CROCKE	RY AND CHINA,	DIRECTLY B	ELOW THE
POSITION BY ROAD COMMISSION RE	PI ACED STONE METH	TI IED FOUND STONE A	12 PERPETUATIO	N OF CORN	ER .
WITNESSED AS DESCRIBED BELOW. PROPERTY CONTROLLING CORNER, V	SET 1/2" CAPPED IRON	AT PREVIOUS BALLBOA	AND CAP, RESE	L WONNWEN	т вох,
PROPERTY CONTROLLING CORNER, V	WITNESSED AS DESCRI	BED BELOW	D SPIKE POSITIO	ON TO SERVE	E AS A
C. Description of monument for corner and E-12 WITNESSES TO 3/4" X 24" STEEL	d accessories established	to perpetuate locating the	position of the corr	er.	
		PROPERTY CONTRO	LLING CORNER	içi.	
ALUMINUM CAP STAMPED "31602" IN FD N&T No. 28414 IN N SIDE 10" OAK C	MONUMENT BOX	WITNESSES TO 1/2"	CAPPED IRON N	o. 31602	
FD N&T No. 17624 IN N SIDE OF POWER	PROFESSE 31.80	FD N&T No. 28414 IN	N SIDE 10" OAK	CLUSTER N	88°E 30.56'
TO PK IN THE N SIDE OF 30" OAK W	FST 27 94'	FU N&I NO. 17624 IN	N SIDE OF POW	ER POLE FA	ST 28 28'
1/2" CAPPED IRON N83°55'E 1.23'	LO1 27.54	LO LAW IN THE USE	DE OF 30" OAK 1	NEST 29.18'	
ROAD CENTERLINE EAST 2'±		E-12 REMON IRON IN	IBOX S83°55'W	1.23'	
TO F-12 IS S89°16'03"E 2648.47'				artist and a second second	***
TO E-13 IS S00°06'22"E 2641.61' TO D-12 IS N89°58'09"W 2660.89'			يجدا والمتاريخ	TA DI MICH	A Comment
TO E-11 IS N00°02'17"E 2648.18'			A A A A A A A A A A A A A A A A A A A	BRIAN	No. of Manager
2040.10	P.A.	345 INGHAM COUNTY		REYNOLDS	1 "
	PEER A	PPROVED 11/22/200	15 N	LAND	* 1
	4	110120 117 00/200	二一十十	BURVEYOR	
			1 -1	NO. 31602	101
(1/1)/	1 .			31002	A 1 4
1(51/	()		The same of the sa	OLABDEN	N. V. Barrell
Signed by				The state of the s	•••
Surveyor's Michigan License No	31602	December 1, 200	05		
, simsingan Flocinge MO	31602	FORM APPROVED BY MIC	CUICAN STATE DO LEE -		_:

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS. JAN. 28, 1971

- A. Description of original monument and accessories and/or subsequent restoration: T3N, R2W, E-12, CONTINUED
- 3. A SURVEY OF MOST OF SECTION 32 BY T. J. BROWN, COUNTY SURVEYOR, DATED JUNE 15, 1875, COUNTY SURVEYOR BOOK 2, PAGE 128, THE SUBJECT CORNER IS LABELED "11" ON THE PLAT, AND IS DESCRIBED AS FOLLOWS, "A POST NO TREES..." THE PLAT SHOWS DISTANCES TO E-11 OF 39.90 CHAINS (2633.40'), TO D-12 40.14 CHAINS (2649.24')
- 4. FROM THE ROAD COMMISSION WITNESS MAP, "..STONE, BRICK, CROCKERY 19" OAK N.W. 41.0' 7" OAK E. 26.9' 5" OAK W. 54.4'...." NO NAME OR DATES
- 5. TWO ACT 132 SURVEYS BY POLARIS ASSOCIATES, INC, SIGNED BY RONNIE M. LESTER, P.S. 18998, LIBER 1, PAGES 32 & 33, RECORDED AUGUST 3, 1971, AND LIBER 1, PAGES 729 & 730, RECORDED MAY 11, 1973, W 1/4 COR. SEC. 33, T3N, R2W "FOUND RAILROAD SPIKE WITNESSES TO U. S. PUBLIC LAND SURVEY CORNERS:
 NAIL & TAG IN CORNER POST EAST, 28.23' NAIL & TAG IN POWER POLE ESE, 28.42'
 NAIL & TAG IN CORNER POST WEST 28.64' "
 E-12 TO E-11 SHOWN AS N0°01'23"E 2649.05'.
- 6. LAND CORNER RECORDATION CERTIFICATE, LIBER 1, PAGE 133, RECORDED AUGUST 26, 1971, BY GARY D. LESTER, P. S. No. 17624, PART A: "ORIGINAL CORNER AND ACCESSORIES OBLITERATED."
 PART B: "FOUND RAIL ROAD SPIKE IN ONONDAGA ROAD CORNER LOCATION SUPPORTED BY OLD FENCE WEST AND FIELD MEASUREMENT NORTH IN CLOSE ACCORD WITH ORIGINAL GOVERNMENT MEASUREMENTS."
 PART C: "RAIL ROAD SPIKE IN CENTER-LINE ONONDAGA ROAD W 1/4 CORNER, SECTION 33, T3N, R2W NAIL & TAG IN CORNER POST EAST, 28.23' NAIL & TAG IN POWER POLE ESE, 28.42'
 NAIL & TAG IN CORNER POST WEST, 28.64' "
- ACT 132 SURVEY BY BOSS ENGINEERING COMPANY, SIGNED BY OSCAR BOSS, P.S. 13574, LIBER 1, PAGE 925 & 926, RECORDED SEPTEMBER 17, 1973, "E. 1/4 COR. SEC. 32, T3N, R2W" NO WITNESSES DESCRIBED.
 C-12 TO E-12 SHOWN AS S89°38'45"E 5322.24'; E-12 TO E-13 SHOWN AS S0°21'40"W 2640.05'.
- 8. ACT 132 SURVEY BY FRED WHITE ENGINEERING COMPANY, SIGNED BY RON HELSEL, P.S. 18994, LIBER 1, PAGES 1020-1021, DATED OCTOBER 22, 1973, "EAST 1/4 CORNER, SECTION 32, T3N, R2W, LIBER 1, PAGE 133) FND. R.R. SPIKE. WITNESSES: EAST 28.23 FT. NAÎL & TAG IN CORNER POST ESE 28.42 FT. NAIL & TAG IN POWER POLE WEST 28.64 FT. NAIL & TAG IN CORNER POST" E-12 TO E-11 IS SHOWN AS NORTH 2648.95'.
- 9. THREE ACT 132 SURVEYS BY POLARIS ASSOCIATES, INC, SIGNED BY RONNIE M. LESTER, P.S. 18998, LIBER 3, PAGES 50 AND 51, RECORDED SEPTEMBER 26, 1977 AND LIBER 3, PAGES 333 & 334, RECORDED MAY 30, 1978 AND LIBER 3, PAGES 351-356, RECORDED MAY 30, 1978 "EAST 1/4 COR. SEC. 32, T3N, R2W FD. RAILROAD SPIKE, REC. L1 P 133 WITNESSES TO U.S. PUBLIC LAND CORNERS: NAIL & TAG IN CORNER POST, EAST, 28.23' NAIL & TAG IN POWER POLE, E.S.E., 28.42' NAIL & TAG IN CORNER POST, WEST, 28.64' "D-12 TO E-12 IS SHOWN AS N89°59'46"E 2661.56'; E-12 TO E-11 IS SHOWN AS (NO BEARING) 2653.51'.
- 10. ACT 132 SURVEY BY FRED WHITE ENGINEERING COMPANY, INC, SIGNED BY DOUGLAS K. RICHARDSON, P.S. 31603, LIBER 5, PAGE 305, RECORDED OCTOBER 6, 1987 "EAST 1/4 CORNER SEC. 32, T3N, R2W (FOUND RR SPIKE) NAIL & TAG IN CORNER POST, EAST, 28.23' NAIL & TAG IN POWER POLE, ESE, 28.39' NAIL & TAG W SIDE OF 20" OAK, WEST 28.92' NAIL & TAG W SIDE OAK CLUSTER, N40°E, 47.97' "

 C-12 TO E-12 IS SHOWN AS S89°47'23"E 5332.20'; E-12 TO E-13 IS SHOWN AS S00°03'40"E 2640.14'.
- 11. ACT 132 SURVEY BY FRED WHITE ENGINEERING COMPANY, INC, SIGNED BY DOUGLAS K. RICHARDSON, P.S. 31603, LIBER 5, PAGES 323 & 324, RECORDED OCTOBER 6, 1987 "E 1/4 CORNER SEC. 32, T3N, R2W (L1 P 133)" NO WITNESSES DESCRIBED. E-11 TO E-12 IS SHOWN AS SOUTH 2648.95'.
- 12. LAND CORNER RECORDATION CERTIFICATE, LIBER 6, PAGE 360, RECORDED FEBRUARY 19, 1988, BY DOUGLAS K. RICHARDSON, P.S. #31603, PART A: "FOUND R.R. SPIKE RECORDED IN LIBER 1 ON PAGE 133." PART B: "FOUND R.R. SPIKE RECORDED IN LIBER 1 ON PAGE 133." PART C: "FOUND R.R. SPIKE RECORDED IN LIBER 1 ON PAGE 133. N&T IN CORNER POST, EAST, 28.23' N&T IN POWER POLE, ESE, 28.39' N&T N. SIDE OF 20" OAK, WEST, 28.92' N&T W. SIDE OAK CLUSTER, N40°E, 47.97' "
- 13. ACT 132 SURVEY BY BEERY & ASSOCIATES, INC, SIGNED BY DAVID R. LOHR, P.S. 30090, LIBER 6, PAGES 611, 612 & 613, RECORDED DECEMBER 26, 1990 "W 1/4 COR. SEC. 33, T3N, R2W L6, PG. 360" NO WITNESSES DESCRIBED. F-12 TO E-12 IS SHOWN AS N89°53'51"W 2650.82'; E-13 TO E-12 IS SHOWN AS N00°38'58"W 2640.25'.
- 14. ACT 132 SURVEY BY ACCOLADE, INC, SIGNED BY RON HELSEL, P.S. 18994, LIBER 6, PAGE 876, RECORDED DECEMBER 9, 1991 "W 1/4 COR. SEC. 33, T3N, R2W L.1, P.133, P.K. NAIL 1' WEST OF C/L ONONDAGA ROAD ON FENCE LINE TO WEST. FD. N & T GUY POLE EAST, 28.42' SET N & T N/SIDE 24" OAK, WEST 28.77' SET N & T E/SIDE WOOD F. POST, N40°W, 50.64' SET N & T W/SIDE QUAD 20" OAK, N45°E, 48.11' " E-12 TO E-11 IS SHOWN AS N00°01'23"E 2647.99'; E-12 TO F-12 IS SHOWN AS S89°14.36"E 2647.50'.
- TWO ACT 132 SURVEYS BY WOLVERINE ENGINEERS & SURVEYORS, INC, SIGNED BY MAURICE H. MAHIEU, P.S. 28414, LIBER 8, PAGES 407 & 408, RECORDED JANUARY 19, 1999 AND LIBER 8, PAGE 712, RECORDED MAY 12, 2000 "WEST 1/4 CORNER SECTION 33, T3N, R2W, DELHI TOWNSHIP, INGHAM COUNTY, MICHIGAN FOUND RAILROAD SPIKE WITNESSES:

N&T #28414 N. SIDE (5) 10" OAKS, N70°E 30.67' N&T #17624 N. SIDE TELE. POLE, EAST 28.41' N&T #28414 W. SIDE QUAD. OAK, N35°E, 47.96' PK NAIL N. SIDE 32" OAK, WEST 29.05' " E-12 TO E-11 IS SHOWN AS N00°01'23"E 2647.84'; F-12 TO E-12 IS SHOWN AS N89°15'06"W 2647.50'; E-13 TO E-12 N00°00'30"E 2640.07'.

16. ACT 132 SURVEY BY KEBS, INC, SIGNED BY ANTHONY BUMSTEAD, P.S. 41095, LIBER 9, PAGE 136, RECORDED JANUARY 3, 2005, "EAST 1/4 CORNER SECTION 32, T3N, R2W FOUND RAILROAD SPIKE IN MONUMENT BOX IN C/L OF ROAD FOUND NAIL & TAG #28414 IN NORTHWEST SIDE OF 10" TWIN OAK, N85°E, 30.60' FOUND NAIL & TAG #28414 IN NORTH SIDE OF POWER POLE, EAST, 28.29' FOUND PK NAIL SOUTH SIDE OF 20" OAK, WEST, 29.16'

FOUND NAIL & TAG IN SEST (SIC) SIDE OF OAK CLUSTER, N40°E, 47.85' "
E-11 TO E-12 IS SHOWN AS SOUTH 2648'; E-12 TO E-13 IS SHOWN AS S00°01'22"E 2640,04'

22"E 2640.04