MAY 10 8 50 AM 34

For corners in	riling Require	ement of Act 74, Mich. P.		REGISTER OF	DEEDS
Ingham (County)	Located In:	Corner Code ##		THORAM COUN	TY. WICH!
Public Land Survey	T <u>4N</u> R <u>2W</u> T R T R	<u>I-1</u>			
2. Property Controlling	S T R				
in Section	S R				
3. Miscellaneous	S T R		Register of De	eeds Stamp &	File Number
Property in Sec.	S T R	L			
4. Lot No, Rec 5. Private Claims			A B	CDEFG	нјјкцм
5. Filvate Claims			2 6	54	-3 1 2 1 -1
			3		Ī
•			4 _ 7		_101112
Larry A. Bryan	in a field survey on Apri	il 11 19 94	5		
do hereby certify that under requi	rements of P.A. 74, Michigan P.A.	of 1970, the corner points menti	oned 6		
in lines 1 and 2 above were in c	-		_1 1	1 1	-15-14-13-13-1
current manual of survey instruct Management or by a decree of a C		· · · · · · · · · · · · · · · · · · ·			
above were in conformance with			19	20 21	-222324
Court of Law; established, re-	established, monumented, re-r	monumented, recovered, foun	d as		
expressed below:			10 -30-	29 28	-272625
NOTE: Not more than 4 cor	ners, all in the same town a	nd range, may be recorded	11	 	
on this certificate.			12 -31-	32 33	-3'43'53'6

Description of original monument and accessories and/or subsequent restoration:

I-1,

1. Corner set in Original Government Survey by Musgrove Evans, Deputy Surveyor, on February 14, 1827. "Int. North boundary 10 lks East of post and set post for corner Secs 2 and 3".

W. Ash 16 in. S14 1/2W 29 lks

B. Oak 14 in. S47E 55 lks

(Continued on Back)

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - I-1, Investigation at this corner revealed a 5/8" bar in a monument box 2.2' West of the centerline of Wood Road on a fence line East. All of the witnesses listed in items #4 and #6 were not found with the exception of the Southeast corner, Section 34, T5N, R2W, West 6.65'. Three of the witnesses listed in item #7 were found with the distances noted in part "C" below. Accepted 5/8" bar in monument box as the perpetuated location of I-2.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - T4N-R2W

Found 5/8" bar in monument box as noted above.

Found nail & tag #16053 in South side utility pole, S85°E, 37.31'.

Southwest corner brick light base pedestal, S35°E, 62.13'.

Northeast corner brick Granger sign, N70°W, 56.35'.

Found 5/8" bar in monument box, Southeast corner Section 34, T5N, R2W, West, 6.65'.

Surveyor's Michigan License No. 25832

LARRY A BRYAN SURVEYOR Censed LAND

Date 4-15-94

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

P.A. 345 INGHAM COUNTY PEER APPROVED 4/13/94 M

- 2. Corner identified in a survey by T.J. Brown, County Surveyor, on November 19, 1874 (vol. 2, page 115 County Surveyor Records) and on September 28, 1875 (vol. 2, page 129 County Surveyor Records) as "a post from which a Butternut 14 in. diameter bears S11°E 209 1/2 lks and a Butternut 10 in. diameter bears N67°W 62 2/3 lks".
- 3. Corner referred to in a resurvey of Lansing Township by R.J. Robb, County Surveyor, in August and September of 1909 (vol. 3, page 218 and 219 County Surveyor Records) and identified as a "cement post 3" square on top, 4" square on bottom and 2.5 feet long, witnessed by Maple 10" S-W 50', Butternut N-W 35', row of Maples on East side is 35' East of line".
- 4. Corner identified by C.E. Smith, survey chief Michigan State Highway Department, January 1965, on Government Monument Witness Form 280, as "1/2" iron 1" below black top in the west lane of Wood street, witnesses S65E 23.29 P.Pole, S32W 49.90 24" Maple, S63W 34.14 T.Pole".
- 5. Corner identified as 1/2 inch iron with witnesses listed in item #4 on Ingham County Road Commission grid map revised January, 1972.
- 6. Corner recorded by Fred N. White P.S. #12034 on 3/8/72 in Liber 1 of Corners, Page 415 Ingham County Records and on 3/7/74 in Liber 3 of Corners, Page 61 Ingham County Records as "Found 1/2" iron 2.2' West of centerline Wood street. Verified by witnesses from M.S.D.H. records by C.E. Smith". Witnessed by: Power pole S65°E 23.29', 24" Maple S32°W 49.90', Tel. pole S63°W 34.14', SE Cor. Sec. 34, T5N, R2W, West 6.65'.
- 7. Corner recorded by James E. Stephens P.S. #16053 on July 31, 1991 in Liber 7 of Corners, Page 235 Ingham County Records as "found 1/2 inch iron" in location of item #6. Witnessed by survey tags nailed to: East side utility pole N20°W 111.26 feet, South side of utility pole S85°E 37.32 feet, NE corner of brick Granger sign N85W 56.53 feet, SW corner of brick light pedistal S35°W 62.17 feet.
- 8. Corner referred to by Ronnie M. Lester P.S. #18998 on August 2, 1972 and recorded in Liber 2 of Corners Page 473 and 474 Clinton County Records and by Maurice H. Mahieu P.S. #28414 on September 6, 1984 and recorded in Liber 2 of Corners Page 531 Clinton County Records as having found 1/2 inch bar 6.66 feet East of I-13, Southeast Corner Section 34, T5N, R2W, Dewitt Township, Clinton County Michigan.
- 9. Corner shown on a survey by Fred N. White P.S. #12034, dated February 14, 1972 and recorded in Liber 1 of Surveys, Page 294 Ingham County Records as having found 1/2 inch bar with witnesses listed in item #6.
- 10. Corner shown on a survey by Fred N. White P.S. #12034 dated September 28, 1976 and recorded in Liber 2 of Surveys, Page 958 and 959 Ingham County Records. No monument or witnesses given, but referencing item #6.
- 11. Corner shown on a survey by James A. Porter P.S. #19003 dated May 19, 1983 and recorded in Liber 4, of Surveys, Page 737 and 738 Ingham County Records, with no monument or witnesses given.
- 12. Corner shown on a survey by James E. Stephens P.S. #16053 dated August 1, 1991 and recorded in Liber 6 of Surveys, Page 776 and 777 Ingham County Records as having found 1/2 inch bar with witnesses given in item #7.

Nov 29 9 29 AM '94

В

10

12

or corners in	Lansing	Twp.	Filing Requirement of Act 74,	Mic

REGISTER OF DEEDS 3 & Ochnion MICHS

			A CONTRACT OF THE PARTY OF THE
Ingham (County)	Located In:	Corner Code 🚁	THEHAM COUNTY MICH
Public Land Survey	т <u>4N г 2W</u>	1-2	
	T R		
	T R		
	T R		
2. Property Controlling	S T R		
in Section	S T R		
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		

Lot No. , Recorded Plat 5. Private Claims _

Larry A. Bryan, in a field survey on ... October 13 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

I-2.

1. Corner set in Original Government Survey by Musgrove Evans, Deputy Surveyor, on February 14, 1827. Post set for corner Sug. 12 in. S20W 19 lks.
Iron'w'd. 4 in. N77E 21 lks.

(Continued on Back)

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - I-2, Investigation at this corner revealed a 1/2" bar and cap #16053 tone foot west of the centerline of Wood street. The Southeast corner of a block house #2909 Wood street N51°48'W 32.70' and the Northeast corner of house #2733 Wood street N57°36'W 91.55' were found from item #9, #18 and #19. A 1/2" bar West 32.70' was found from item #18, along with a nail and tag found in the South side of a 52" Oak N80°E 43.79', which agrees with witnesses from item #5, and in the Northeast side power pole N45°W 41.56' from item #19. Excavated hole 2.0' x 2.0' centered on found 1/2" bar and cap #16053. Found bolt spike 0.20' below asphalt surface from item #9, #15 and #18.

(Continued on Back)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" bar with cap stamped P.A. 345 #25832 in monument box. Found Southeast corner of block house #2909, N51°48'W, 88.45.

Found Northeast corner of house #2733, S57°36'W, 91.55'. Found 1/2' bar, West, 32.70'

Found nail & tag in Northeast side power pole, N30°W, 41.56'. Found nail & tag #16053 in the South side 52" Oak, N40°E, 43.79'.

Top Northwest corner of a concrete corner post, N80°E, 34.62'. Centerline of 4" well, S65°W, 101 31'.

Signed by 25832 Surveyor's Michigan License No.

OF MICHE LABBY A BRYAN LAND SUNVEYOR Contract No. 1000

Date 1/-23-94

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

P.A. 345 INGHAM COUNTY PEER APPROVED 11/08/94 N

PART "A" CONTINUED

- 2. Corner identified in a survey by T.J. Brown, County Surveyor, on November 19, 1874 (vol. 2, page 115 County Surveyor Records) and on September 28, 1875 (vol. 2, page 129 County Surveyor Records) as "a post from which a Butternut 14 in. diameter bears S11°E 209 1/2 lks and a Butternut 10 in. diameter bears N67°W 62 2/3 lks".
- 3. Corner identified in a survey by A.P. Drake, County Surveyor, on December 22, 1881 (vol. 2, page 203 County Surveyor Records) as "a post from which a Swamp Oak 10 N68 1/3E 68 lks and a B. Walnut 9 S16E 202 3/4 lks".
- 4. Corner identified in a survey by John McCreary, County Surveyor, on May 30 and 31, 1890 (vol. 2, page 237 County Surveyor Records) as "a gas pipe and brick from which a Sugar 24 N43E 78lks and a Butternut 12 N78E 54 lks".
- 5. Corner referred to in a resurvey of Lansing Township by R.J. Robb, County Surveyor, in August and September of 1909 (vol. 3, page 218 and 219 County Surveyor Records) and identified a "cement post 3" square on top, 4" square on bottom and 2.5 feet long, witnessed by R. Oak N-W 35', S. Oak N-E 42.8'".
- 6. Corner identified as stone and pipe witnessed to: Iron East 34.55', 8" Elm S.E. 38.1, 14" Elm S.W. 49.3' on Ingham County Road Commission grid map, revised January, 1972.
- 7. Corner shown in the private records of Laverne J. Hendryx on County Surveyors Record form for Section 2, T4N, R2W as a gear and pipe on top of stone, with witnesses as listed in item #6.
- 8. Corner shown on a unrecorded survey by E.J. McCombs, of Consumers Power Company, drawing No. S-F 17553 dated July, 1971, as a 3/4" iron bar 0.8'W. of Pvt. centerline witnessed to: Nail and washer in P. pole N30°W 41.75', Nail and washer in 48" Oak N70°E 43.75', N.W. corner of conc. fence post E. 34.65'.
- 9. Corner recorded by Clyde K. Stephens P.S. #3829 on July 28, 1971 in Liber 1 of Corners, Page 129 Ingham County Records as "found boat spike at the E 1/4 corner of the section line road (Wood Street). Also on a projection of two old farm fences east and west. This corner as identified herewith has been used and accepted in its present location in excess of 25 years to our knowlege", witnessed to SE. corner of concrete block house #2909 N51°48'W 88.48 feet, NE. corner of a 1-story frame house #2733 S57°36'W 91.50 feet, NW corner of a 1 1/2 story brick house #2810 S63°06'E 123.01 feet.
- 10. Corner shown on a survey by Clyde K. Stephens P.S. #3829, dated July 26, 1971, recorded in Liber 1 of Surveys, Page 47 and 48, and on March 2, 1972, recorded in Liber 1 of Surveys, Page 327 Ingham County Records as having found a boat spike with witnesses listed in item #9.
- 11. Corner shown on a survey by Fred N. White P.S. #12034, dated February 14, 1972, recorded in Liber 1 of Surveys, Page 294 Ingham County Records as having found boat spike with witnesses listed in item #9.
- 12. Corner shown on a survey by James E. Stephens P.S. #16053 dated June 30, 1972, recorded in Liber 1 of Surveys, Page 390 and on December 12, 1972, recorded in Liber 1 of Surveys, Page 581 and 582 Ingham County Records, with no monument or witnesses shown, but referencing item #9.
- 13. Corner shown on a survey by Ron Helsel P.S. #18994 dated December 5, 1973, recorded in Liber 1 of Surveys, Page 1102 Ingham County Records as having found boat spike with witnesses listed in item #9.
- 14. Corner shown on a survey by James E. Stephens P.S. #16053 dated December 27, 1974, recorded in Liber 2 of Surveys, Page 272 through 275 Ingham County Records, with no monument or witnesses shown, but referencing item #9.

I-2 Lansing Twp. Continued

PART "A" CONTINUED

- 15. Corner shown on a survey by Fred N. White P.S. #12034 dated September 28, 1976, recorded in Liber 2 of Surveys, Page 958 and 959 Ingham County Records, with no monument or witnesses given, but referencing item #9.
- 16. Corner shown on a survey by James A. Porter P.S. #19003 dated February 14, 1977, recorded in Liber 3, of Surveys, Page 214 and 215 Ingham County Records and on October 14, 1977 recorded in Liber 3 of Surveys, Page 1208 Ingham County Records, with no monument or witnesses given but indicating that the corner had been previously recorded.
- 17. Corner shown on a survey by James A. Porter P.S. #19003 dated May 19, 1983 and recorded in Liber 4, of Surveys, Page 737 and 738 Ingham County Records, with no monument or witnesses given.
- 18. Corner shown on a survey by Larry A. Bryan P.S. #25832 dated April 27, 1989, recorded in Liber 5 of Surveys, Page 1263 and 1264 Ingham County Records and September 27, 1989, recorded in Liber 6, of Surveys, Page 105 and 106 Ingham County Records as having found boat spike 1' West of centerline of Wood Road on fence line East & West, with the following witnesses: Southeast corner concrete block house #2909 N50°W, 88.48', Northeast corner one story frame house #2733 S60°W, 91.51', found 1/2" bar West 32.70.
- 19. Corner shown on a survey by James E. Stephens P.S. #16053 dated August 1, 1991 and recorded in Liber 6 of Surveys, Page 776 and 777 Ingham County Records as having found 1/2 inch diameter steel rod witnessed by survey tags nailed to: Utility pole N45°W 41.58 feet, South side of 58" Oak tree N80°E 43.83 feet, SE corner of concrete block house #2909 N51°48'W 88.48 feet, NE corner of a frame house #2733 S57°36'W 91.50 feet.

PART "B" CONTINUED

Continued excavation to a depth of 1.3' and found 3/4" pipe 0.80'long lying flat in another asphalt surface. Continued excavation for another 0.5' and found gear from axle shaft on top of ± 0.3 'x ± 0.8 'x ± 1.0 ' stone from item #6 and #7. It appears that the gear was used to hold the 3/4" pipe vertical over high point of stone. The location of the 1/2" bar and cap #16053 falls on Southwesterly part of the high point of the stone. Accepted position of 1/2" bar and cap #16053 as the perpetuated location of I-2 and replaced with 3/4" bar with cap stamped P.A. 345 #25832 in monument box.



Jan d. Byn 11-23-94

Nev 29 9 30 AM 94

For corners in Lansing Twp.

....., Recorded Plat ___

Filing Requirement of Act 74, Mich. P.A. 1970

REGISTER OF DEEDS

	Ingham (County)	Located In:	Corner Code :##	THEHAM COUNTY. MICHE
1.	Public Land Survey	T 4N R 2W	1-3	·
		T R	1888 Million	
		T R		
		T R		
2.	Property Controlling	S T R		
	in Section	S T R		
3.	Miscellaneous	S T R		Pagister of Danda Stamp & File Number
	Property in Sec.	S T R		Register of Deeds Stamp & File Numbe

Larry A. Bryan, in a field survey on October 13, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10

A. Description of original monument and accessories and/or subsequent restoration:

5. Private Claims

1. Corner set in Original Government Survey by Musgrove Evans, Deputy Surveyor, on February 13, 1827. Post set for corner to sections 2, 3, 10 and 11. Sug. 12 in. S58E 13 lks. Lynn 10 in. N65W 20 lks.

(Continued on Back)

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - I-3, Investigation at this corner revealed in 1/2" bar in the centerline of Wood and David streets, with all three witnesses from item #7 found and noted in part "C" below. A nail and brass tag in the Southwest side of a power pole, S60°E 29.14' was found from item #8 along with a nail and tag #30897 in the Northwest side of a power pole, S58°28 W 41.96' and a storm sewer manhole, N40°E 39.10' from item #11. Found 1" pipe Southwest corner Bancroft Hills and Northwest corner Groesbeck Hills Subdivision No.10, East 50.00'. Found pinched pipe Southeast corner of Supervisor's Plat of Ideal Garden Farms N45°W 46.75'. Excavated hole 1.0'x1.0' centered on 1/2" bar to a depth of 2.0' and found old monument box with 1/2" diameter hole in the center of the top.

(Continued on Back)

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - I-3, T4N, R2W
 Set 3/4" bar with cap stamped P.A. 345 #25832 in monument box. Southeast corner of brick building, N41°26'W, 112.17'. Northwest corner of brick duplex #2004 Wood street, N51°34'E. 115.02'. Northwest corner of garage to #1918 Wood street, S76°55'W, 87.16'. Found nail & tag #30897 in Northwest side power pole, S58°28'W, 39.39'. Found nail & brass tag in Southwest side power pole, S69°E, 29.14'. Centerline storm sewer manhole, N40°E, 39.10'.

Surveyor's Michigan License No. 25832

OF MICHIGA LARRY A. BRYAN LAND SURVEYOR SEO LAND OU No.

*

-82

Date 1/-23-94

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

P.A. 345 INGHAM COUNTY PEER APPROVED 4/13/94 ML

- 2. Corner identified in a survey by A.P. Drake, County Surveyor, on December 22, 1881 (vol. 2, page 203 County Surveyor Records) as "a stone to be set from which a Maple 10 N66W 53 1/2 lks and a Elm 5 S78 1/2W 54 1/2 lks".
- 3. Corner referred to in a survey by John McCreary, County Surveyor, on May 30 and 31, 1890 (vol. 2, page 237 County Surveyor Records) with no monument or witnesses given.
- 4. Corner referred to in a resurvey of Lansing Township by R.J. Robb, County Surveyor, in August and September of 1909 (vol. 3, page 218 and 219 County Surveyor Records) and identified as a "cement post 3" square on top, 4" square on bottom and 2.5 feet long, witnessed by Ash 6" N-E 38', Bitternut 20" N-E 33.4'".
- 5. Corner identified in a resurvey of Lansing Township, from a document found in the dossier for I-3 Lansing Township, Ingham County Remonumentation Project, labeled "Horn Notes". This document describes the monumentation and witnesses listed in 1, 2, and 4 above along with the following: "Recovered the concrete post set by Robb and set a standard 1921 monument. The references do not agree with those given by Robb. There was found a tree 23 feet East, and an old fence line running East which agrees with information given by A.N. Bateman who used the corner in platting one acre tracts to the West". Witnessed to: 8" Hickory S60°20'W 31.00' blaze and nail, 5" Elm N41°15'W 48.10' blaze and nail, 14" Bitternut N88°15'E 23.03' blaze and nail.
- 6. Corner referenced in the private records of Laverne J. Hendryx on County Surveyors Record form for Section 2, T4N, R2W, with no monument given and one witness to a concrete monument 33' East.
- 7. Corner recorded by James E. Stephens P.S. #16053 on February 8, 1973 in Liber 2 of Corners, Page 351 Ingham County Records and shown on a survey dated December 12, 1972, recorded in Liber 1 of Surveys, Page 581 and 582 Ingham County Records as "a 1/2 inch iron rod found in the centerline of the two section line roads (David Street and Wood Street)". Witnessed to: N41°26'W 112.07 feet to the SE corner of a 1 story brick office building, N51°34'E 115.06 feet to the NW corner of the foundation of a duplex house, S76°55'E 87.23 feet the the NW corner of the garage foundation of a 2 story frame house. The bearing of the section line North of the corner was N0°16'10"E from the plat of Bancroft Hills.
- 8. Corner recorded by James A. Porter P.S. #19003 on February 20, 1973 in Liber 2 of Corners, Page 363, and on March 31, 1973 in Liber 2 of Corners, Page 417 Ingham County Records and shown on a survey dated February 19, 1973, recorded in Liber 2 of Surveys, Page 217, on February 14, 1977, recorded in Liber 3, of Surveys, Page 214 and 215 and on October 14, 1977 recorded in Liber 3 of Surveys, Page 1208 Ingham County Records as "from plats of Groesbeck Hills and Bancroft Hills found 1/2" iron in Wood Street and David Street intersection". Witnessed to: Bolt Head on Power Pole N49°30'W 43.92 feet, Brass Tag and Nail in Power Pole S58°28'W 41.96 feet, Brass Tag and Nail in Power Pole S69°00'E 29.17 feet.
- 9. Corner shown on a survey by Ron Helsel P.S. #18994 dated December 5, 1973, recorded in Liber 1 of Surveys Page 1102 Ingham County Records, listing the monument and witnesses for item #8.
- 10. Corner shown on a survey by Mark W. Witalec P.S. #30897 dated December 28, 1987. recorded in Liber 5 of Surveys, Page 461 through 464 Ingham County Records, as 1/2" iron at Wood St. David St. intersection. Witnessed to: S.E. 29.12' Nail and Brass Tag S.W. side P.P., S.W. 39.35' P.K. and tag #30897 N.W. side Util. P., W.N.W. 77.25' P.K. and tag #30897 S.Side 6" Wood Marker Post, N.E. 39.10' to centerline Sewer M.H. Cover.

11. Corner referred to in Recorded Subdivision Plats: Bancroft Hills, Clyde K. Stephens P.S. #3829, October 11, 1963, Liber 25 of Plats, Page 18; Bancroft Hills No.1, Clyde K. Stephens P.S. #3829, August 23, 1965, Liber 26 of Plats, Page 24; Bancroft Hills No.2, James E. Stephens P.S. #16053, April 4, 1972, Liber 31 of Plats, Page 2; Bancroft Hills No.3, James E. Stephens P.S. #16953, December 7, 1973, Liber 32 of Plats, Page 18; Supervisor's Plat of Groesbeck Hills, Laverne J. Hendryx P.S. #3276, December 30, 1954, Liber 18 of Plats, Page 15; Groesbeck Hills Subdivision No.8, Laverne J. Hendryx P.S. #3276, February 7, 1962, Liber 24 of Plats, Page 1; Groesbeck Hills Subdivision No.10, Clyde K. Stephens P.S. #3829, October 11, 1965, Liber 25 of Plats, Page 13; Groesbeck Hills Subdivision No.11, Clyde K. Stephens P.S. #3829, December 16, 1965, Liber 26 of Plats, Page 39; Supervisor's Plat of Ideal Garden Farms, Francis N. Bateman P.S. #1479, June 12, 1934, Liber 12 of Plats, Page 36.

PART "B" CONTINUED

Witnesses listed above fall in center hole of monument box. Removed top of monument box and found 5/8" bar in cement 8" in diameter. 5/8" bar lines up with center hole in top. Accepted 5/8" bar in cement as the perpetuated location of I-3, raised location and replaced with a 3/4" bar and cap stamped P.A. 345 #25832 in monument box.

LARRY A.
BUT AND
SURVEYOR
NO.
25832

Lund. Brun 11-23-94

> P.A. 345 INGHAM COUNTY PEER APPROVED 4/13/94

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MAY 10 8 50 AM *94

Fo	r corners in		
_I	ngham (County)	Located In:	Corner Code ##
1.	Public Land Survey	T 4N R 2W	J-1
		<u>T</u> <u>B</u>	
		T R	
		T R	
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	S T R	
	Property in Sec.	S T R	

REGISTER OF DEEDS Panis Do linson THEHAM COUNTY MICH

Register of Deeds Stamp & File Number

4. Lot No. ___ . Recorded Plat _ 5. Private Claims

I, Larry A. Bryan , in a field survey on March 10 , 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration: J-1,
 - 1. Corner not set in Original Government Survey.
 - 2. Corner identified in a survey by T.J. Brown, County Surveyor, on November 19, 1874 (vol. 2, Page 115 County Surveyor Records) as "a post from which a Beech 11 in. diameter bears S39 1/2W 33 1/8 lks, and a Sugar 10 in diameter bears N49W 13 lks".
- (Continued on Back)

 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J-1, Investigation at this corner revealed a copperweld in monument box 9.58' West of the West edge of South bound lane of U.S. 127. A nail and tag #18998 was found in top of a guard rail post N20°W 23.10', and in top of a guard rail post South 21.45' along with a copperweld in monument box, J-13 Dewitt Township, West 9.42'as listed in item #6. Measured 2623.44' to K-1 Lansing Township and 2635.41' to K-13 Dewitt Township. Accepted copperweld in monument box as the perpetuated location of J-1.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

T4N-R2W

Found copperweld in monument box as noted above.

Found nail & tag #18998 in top of guard rail post, N20°W, 23.10'. Found nail & tag #18998 in top of guard rail post, South, 21.45'.

Center of "+" in station 910+00 stamped in West edge of South bound

U.S.127, N40°E, 15.00'. Center of "+" in station 909+70 stamped in West edge of South bound U.S. 127, S35°E, 22.51'.

MICHIG

Surveyor's Michigan License No. 25832

LARRY A. BRYAN LAND

SED LAND SU

SURVEYOR

25832

Date 4-15-94

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

P.A. 345 INGHAM COUNTY

PEER APPROVED 4/13/94 ML

2611

REVISED MAY 14, 1975 REVISED JAN., 1983

- 3. Corner referred to in a resurvey of Lansing Township by R.J. Robb, County Surveyor, in August and September 1909 (vol. 3, Page 218 and 219 County Surveyor Records) and identified as a "cement post 3" square at top and 4" square on bottom and 2.5 feet long, witnessed by Elm 30" S-W no distance given".
- 4. Corner identified by C.E. Smith, survey chief Michigan State Highway Department, January 1965, on Government Monument Witness Form 280 as "one inch pipe", witnessed to: S62E 36.56 14" twin Basswood.

S81E 13.59 13" Hick.

S19E 23.78 17" Oak.

- 5. Corner identified as 1 inch pipe with witnesses shown in item #4 on Ingham County Road Commission grid map, revised January, 1972 .
- 6. Corner recorded by Ronnie M. Lester P.S. #18998 on February 5, 1980 in Liber 6 of Corners, Page 53 Ingham County Records, as having found copperweld in monument box ±9.42 feet East of J-13 Dewitt Township, T5N, R2W, on tree/fence line East and West, and ±10.0 feet West of West edge of Southbound lane of US 127. Accepted copperweld in monument box and witnessed to:

Nail and Tag, #18998, top of wooden guard rail post, NNW, 23.10'. Nail and tag, #18998, top of wooden guard rail post, South, 21.43'. East side of the West leg of sign Post, WNW, 10.17'. West edge of concrete lane on Southbound US 127, East, 9.58'. Copperweld in monument box, J-13, Dewitt Twp., T5N, R2W, West 9.42'.

- 7. Corner referenced by Ronnie M. Lester P.S. #18998 on February 5, 1980 and recorded in Liber 2 of Corners, Page 287 Clinton County Records as having found copperweld in monument box 9.42 feet East of J-13, South 1/4 corner of Section 35, T5N, R2W, Dewitt Township, Clinton County, Michigan.
- 8. Corner shown on a survey by Douglas K. Richardson P.S. #31603 on March 12, 1987 and recorded in Liber 3 of Surveys, Page 89 and 90, Clinton County Records as having found a copperweld in monument box and listing witnesses in item #6.

MAY 10 8 51 AM '94

For corners in	Filing Requirement of Act 74, Mich. P.A. 1970				REGISTER OF DEEDS					
Ingham (County)	Located	d In:	Corner Code ##		DA. TNGHA	M COUN	énsor [Y.M]	ch/	,	
Public Land Survey	T T	I R <u>2W</u> R R	J-2							
Property Controlling in Section	S T S T	R								
Miscellaneous Property in Sec.	S T S T	R		Registe	er of Deeds	Stamp	& File	Num	nber	,
4. Lot No, F 5. Private Claims	Recorded Plat			2 3	A B C C) E F	G H	<u> </u>	K	_ L _ N
I. Larry A. Bryan do hereby certify that under rein lines 1 and 2 above were in current manual of survey instr Management or by a decree of above were in conformance wi	quirements of P.A. 74 in conformance with fuctions of the United a Court of Law and/o	I, Michigan P.A. o regulations and d States Departi or that the corner	of 1970, the corner points mend rules therefore as required ment of the Interior, Bureau of points mentioned in lines 3.	ntioned 6 I in the 7 A and 5		16	15-	14		-13-

on this certificate.
 A. Description of original monument and accessories and/or subsequent restoration:
 J-2,

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

Court of Law; established, re-established, monumented, re-monumented, recovered, found as

- 1. Corner not set in Original Government Survey.
- 2. Corner identified in a survey by T.J. Brown, County Surveyor, on November 19, 1874 (vol. 2, page 115 County Surveyors Records) as "a post from which a Elm 11 in. diameter bears S78W 35 1/2 lks and a Elm 7 in. diameter bears N31 3/4W 40 lks".
- (Continued on Back)

 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - J-2, Investigation at this corner revealed a 18" square concrete post with a 1 1/4" steel pipe in the center ±342' West of U.S. 127 right of way fence. A nail and tag #16053 in the North side of a 30" Hickory, S20°E 113.16' and a 24" Oak, no tag visible, West ±92.5' as noted in item #6. Accepted concrete post with 1 1/4' pipe as the perpetuated location of J-2.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-2, T4N-R2W
Found 18" square concrete post with 1 1/4" pipe in center as noted above.
Found nail & tag #16053 in the North side 30" Hickory, S20°E, 113.16'.
Set nail & tag #25832 in the South side 20" Willow East 79.03'.
Set nail & tag #25832 in the North side 12" Elm, S80°W, 31.62'.
Set nail & tag #25832 in the North side 24" Oak, West, 92.47'.
Found bar and cap #16053, East 336.03'.

Signed by LAND LAND SURVEYOR No. 25832 No. 25832 LAND SURVEYOR NO. 25832 LAND SURVEYOR NO. 25832

Date 4-15-94

P.A. 345 INGHAM COUNTY

REVISED MAY 14, 1975
REVISED JAN., 1983

PEER APPROVED 4/13/94

expressed below:

- 3. Corner identified in a survey by A.P. Drake, County Surveyor, on December 22, 1881 (vol. 2, page 203 County Surveyor Records) as "a post from which a Elm 11 in. diameter bears S78W 351/2 lks and a Elm 7 in. diameter bears N31 3/4W 40 lks".
- 4. Corner identified in a survey by John McCreary, County Surveyor, on May 30 and 31, 1890 (vol. 2, page 237 County Surveyor Records) as "a stone and iron, Sugar 16 N1 1/2W 19 1/2 lks, Maple 12 N61 1/2E 47 lks".
- 5. Corner identified by Clifford Smith, survey chief Michigan State Highway Department, February, 1965, on Government Monument Witness Form 280 as "found 15 inch square concrete post with 2 inch pipe in center for the center of section 2 Lansing twp. Ingham County" witnessed to: 27" Elm S05W 13.20', 22" Elm S29W 14.20', 11" Elm N82W 19.92'.
- 6. Corner recorded by James E. Stephens P.S. #16053 on May 19, 1977 in Liber 4 of Corners, Page 62 Ingham County Records as "a 18" square corner fence post with a 1 1/4" pipe in the center was found at the intersection of four old fences", witnessed to Survey tag #16053 nailed to the North side of a 24" Oak tree, West 91.46 feet, Survey tag #16053 nailed to the East side of a 24" Hickory tree, South 116.92 feet, Survey tag nailed to the Northeast side of a 30" Hickory tree S40°E 113.08 feet.
- 7. Corner shown on a survey by James E. Stephens P.S. #16053 dated June 18, 1987, recorded in Liber 5 of Surveys, Page 232 and 233 Ingham County Records and on August 31, 1989, recorded in Liber 5 of Surveys, Page 1152 through 1159 Ingham County Records, with the same monument and witnesses as listed in item #6.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich. P.A. 1970

MAY 10 8 51 AM '94

1. Public Land Survey T 4N R 2W J-3 T R T R T R T R T R T R T R T R T R T	C D E F G H J K L S S S S S S S S S S S S S S S S S S
1. Public Land Survey 1. Public Land Survey 1. R 1. R 1. R 1. R 2. Property Controlling 2. Property Controlling 3. Miscellaneous 5. T 6. R 6. T 7. R 7. R 7. R 8. R 9. Register of Reg	REHAM COUNTY, MICH.
1. Public Land Survey T 4N R 2W J-3 T R T R T R T R T R T R T R T R T R T	eeds Stamp & File Number
2. Property Controlling in Section S T R R 3. Miscellaneous S T R R 4. Lot No. Recorded Plat 5. Private Claims 1. Larry A. Bryan in a field survey on March 15 6. Private Claims 1. Larry A. Bryan in a field survey on March 15 7. In the corresponding that under requirements of PA. 74, Michigan PA. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with requisitions and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with requisitions mentioned in lines 3, 4 and 5 above were in conformance with requisitions and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law and/or that the corner points mentioned in lines 4 and 10 above were in conformance with requirements and 10 above were of a Court of Law and/or that the corner points mentioned in lines 4 and 10 above were in conformance with	
3. Miscellaneous S T R R R Register of Property in Sec. S T R R R Register of Property in Sec. S T R R R Register of Recorded Plat R R Recorded Plat R R Recorded Plat R R R R R R R R R R R R R R R R R R R	
Property in Sec. S T R	
4. Lot No	C D E F G H J K L
5. Private Claims 1. Larry A. Bryan in a field survey on March 15 19 94 194 195 196 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-3, 1. Corner set in Original Government Survey by Musgrove Deputy Surveyor, on February 13, 1827. Set 1/4 post at average distance on true line from which Beech, 9 in. N7W 28 lks. Lynn 18 in. S2W 19 lks. (Continued on Back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-3, Investigation at this corner revealed a 1" pipe ins concrete monument along East side of a chain link fence. #18998 found in the East side of a power pole S10°W 9.28 side of a 24" Walnut N80°E 25.97' as noted in item #9.	C D E F G H J K L
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-3, 1. Corner set in Original Government Survey by Musgrove Deputy Surveyor, on February 13, 1827. Set 1/4 post at average distance on true line from which Beech, 9 in. N7W 28 lks. Lynn 18 in. S2W 19 lks. (Continued on Back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-3, Investigation at this corner revealed a 1" pipe ins concrete monument along East side of a chain link fence. #18998 found in the East side of a power pole S10°W 9.28 side of a 24" Walnut N80°E 25.97' as noted in item #9.	8 9 10 11 12 13 14 13 20 21 22 23 24
I Larry A. Bryan in a field survey on March 15 19 94 5 19 19 19 19 19 19 19 19 19 19 19 19 19	5 4 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-3, 1. Corner set in Original Government Survey by Musgrove Deputy Surveyor, on February 13, 1827. Set 1/4 post at average distance on true line from which Beech, 9 in. N7W 28 lks. Lynn 18 in. S2W 19 lks. (Continued on Back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-3, Investigation at this corner revealed a 1" pipe ins concrete monument along East side of a chain link fence. #18998 found in the East side of a power pole S10°W 9.28 side of a 24" Walnut N80°E 25.97' as noted in item #9.	8 9 10 11 12 12 12 13 14 15 14 15 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-3, 1. Corner set in Original Government Survey by Musgrove Deputy Surveyor, on February 13, 1827. Set 1/4 post at average distance on true line from which Beech, 9 in. N7W 28 lks. Lynn 18 in. S2W 19 lks. (Continued on Back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-3, Investigation at this corner revealed a 1" pipe ins concrete monument along East side of a chain link fence. #18998 found in the East side of a power pole S10°W 9.28 side of a 24" Walnut N80°E 25.97' as noted in item #9.	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-3, 1. Corner set in Original Government Survey by Musgrove Deputy Surveyor, on February 13, 1827. Set 1/4 post at average distance on true line from which Beech, 9 in. N7W 28 lks. Lynn 18 in. S2W 19 lks. (Continued on Back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-3, Investigation at this corner revealed a 1" pipe ins concrete monument along East side of a chain link fence. #18998 found in the East side of a power pole S10°W 9.28 side of a 24" Walnut N80°E 25.97' as noted in item #9.	
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-3, 1. Corner set in Original Government Survey by Musgrove Deputy Surveyor, on February 13, 1827. Set 1/4 post at average distance on true line from which Beech, 9 in. N7W 28 lks. Lynn 18 in. S2W 19 lks. (Continued on Back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-3, Investigation at this corner revealed a 1" pipe ins concrete monument along East side of a chain link fence. #18998 found in the East side of a power pole S10°W 9.28 side of a 24" Walnut N80°E 25.97' as noted in item #9.	20 21 22 23 24
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned dinlines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-3, 1. Corner set in Original Government Survey by Musgrove Deputy Surveyor, on February 13, 1827. Set 1/4 post at average distance on true line from which Beech, 9 in. N7W 28 lks. Lynn 18 in. S2W 19 lks. (Continued on Back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-3, Investigation at this corner revealed a 1" pipe ins concrete monument along East side of a chain link fence. #18998 found in the East side of a power pole S10°W 9.28 side of a 24" Walnut N80°E 25.97' as noted in item #9.	20 - 21 - 22 - 23 - 24
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-3, 1. Corner set in Original Government Survey by Musgrove Deputy Surveyor, on February 13, 1827. Set 1/4 post at average distance on true line from which Beech, 9 in. N7W 28 lks. Lynn 18 in. S2W 19 lks. (Continued on Back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-3, Investigation at this corner revealed a 1" pipe ins concrete monument along East side of a chain link fence. #18998 found in the East side of a power pole S10°W 9.28 side of a 24" Walnut N80°E 25.97' as noted in item #9.	20 21 22 23 2
Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-3, 1. Corner set in Original Government Survey by Musgrove Deputy Surveyor, on February 13, 1827. Set 1/4 post at average distance on true line from which Beech, 9 in. N7W 28 lks. Lynn 18 in. S2W 19 lks. (Continued on Back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-3, Investigation at this corner revealed a 1" pipe ins concrete monument along East side of a chain link fence. #18998 found in the East side of a power pole S10°W 9.28 side of a 24" Walnut N80°E 25.97' as noted in item #9.	-
expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-3, 1. Corner set in Original Government Survey by Musgrove Deputy Surveyor, on February 13, 1827. Set 1/4 post at average distance on true line from which Beech, 9 in. N7W 28 lks. Lynn 18 in. S2W 19 lks. (Continued on Back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-3, Investigation at this corner revealed a 1" pipe ins concrete monument along East side of a chain link fence. #18998 found in the East side of a power pole S10°W 9.28 side of a 24" Walnut N80°E 25.97' as noted in item #9.	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-3, 1. Corner set in Original Government Survey by Musgrove Deputy Surveyor, on February 13, 1827. Set 1/4 post at average distance on true line from which Beech, 9 in. N7W 28 lks. Lynn 18 in. S2W 19 lks. (Continued on Back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-3, Investigation at this corner revealed a 1" pipe ins concrete monument along East side of a chain link fence. #18998 found in the East side of a power pole S10°W 9.28 side of a 24" Walnut N80°E 25.97' as noted in item #9.	
on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-3, 1. Corner set in Original Government Survey by Musgrove Deputy Surveyor, on February 13, 1827. Set 1/4 post at average distance on true line from which Beech, 9 in. N7W 28 lks. Lynn 18 in. S2W 19 lks. (Continued on Back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-3, Investigation at this corner revealed a 1" pipe ins concrete monument along East side of a chain link fence. #18998 found in the East side of a power pole S10°W 9.28 side of a 24" Walnut N80°E 25.97' as noted in item #9.	
A. Description of original monument and accessories and/or subsequent restoration: J-3, 1. Corner set in Original Government Survey by Musgrove Deputy Surveyor, on February 13, 1827. Set 1/4 post at average distance on true line from which Beech, 9 in. N7W 28 lks. Lynn 18 in. S2W 19 lks. (Continued on Back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-3, Investigation at this corner revealed a 1" pipe ins concrete monument along East side of a chain link fence. #18998 found in the East side of a power pole S10°W 9.28 side of a 24" Walnut N80°E 25.97' as noted in item #9.	
 A. Description of original monument and accessories and/or subsequent restoration: J-3, 1. Corner set in Original Government Survey by Musgrove Deputy Surveyor, on February 13, 1827. Set 1/4 post at average distance on true line from which Beech, 9 in. N7W 28 lks. Lynn 18 in. S2W 19 lks. (Continued on Back) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-3, Investigation at this corner revealed a 1" pipe ins concrete monument along East side of a chain link fence. #18998 found in the East side of a power pole S10°W 9.28 side of a 24" Walnut N80°E 25.97' as noted in item #9. 	32 33 34 35 36
witness to the Southeast corner of house #2808 Tulane N3 M.S.D.H. nail and tag in the East side of a power pole S found as noted in item #6. Found 5/8" bar in concrete m corner Lot 99 plat of Somerset, West 136.5' rec. 136.25' in concrete monument, Northeast corner Kimberly Park, Kimbert 169.6' rec. 169.25'. Accepted 1" pipe in concrete	de a 3" diameter A nail and tag and the South lso from item #9 °E 102.69'. A 0°W 9.51' was nument, Southwest Found 1/2" bar berly Downs No.6,
C. Description of monument for corner and accessories established to perpetuate locating the position J-3, T4N-R2W Found 1" pipe in concrete monument as noted above. Found nail & tag #18998 in East side of power pole, S10° Found M.S.H.D. nail & tag in East side of power pole, S1 Found nail & tag #18998 in South side of 24" Walnut, N80 Centerline of 2" steel fence post, North, 1.27'. Centerline of 2" steel fence post, South, 0.55'. Southeast corner house #2808 Tulane, N35°E, 102.69'. Southwest corner concrete porch to house #2808 Tulane, N	

Surveyor's Michigan License No. _

- 2. Corner identified in a survey by A.P. Drake, County Surveyor, on December 22, 1881 (vol. 2, page 203 County Surveyors Records) as "a post from which a sugar 24 S41 1/2W 41 1/2 lks.
- 3. Corner identified in a survey by R.J. Robb, County Surveyor, on January 27, 1909 (vol. 2, Page 264 County Surveyors Records) and on January 29, 1909 (vol. 5, Page 55 County Surveyors Records) as a post with no witnesses given.
- 4. Corner referred to in a resurvey of Lansing Township by R.J. Robb, County Surveyor, in August and September of 1909 (vol. 3, page 218 and 219 County Surveyor Records) and identified a "cement post 3" square on top, 4" square on bottom and 2.5 feet long, between three anchor posts".
- 5. Corner shown in the private records of Laverne J. Hendryx on County Surveyors Record form for Section 2, T4N, R2W as a concrete monument with no witnesses or date given.
- 6. Corner identified by C.E. Smith, survey chief Michigan State Highway Department, January, 1965, on Government Monument Witness Form 280, as a 3" concrete monument with 1" iron pipe for N1/4 corner Section 11, witness: Due East 26.32 14" Wal., N38W 2.81 4" Maple, S10W 9.37 P.Pole.
- 7. Corner identified as a 3" concrete monument with 1" pipe with witnesses listed as in #6 above on Ingham County Road Commission grid map, revised January, 1972.
- 8. Corner recorded by Ronnie M. Lester P.S. #18998 on January 31, 1980 in Liber 6 of Corners, Page 52 Ingham County Records as "found 3" diameter concrete monument with 1 inch pipe 1.4 feet above ground ± 169 feet West of a concrete plat monument for Kimberly Downs #6, witnesses in close accord with those on MDSH form 280, 1965. Witnessed to: SE corner concrete foundation of house #2808, NE, 102.69', Nail and tag #18998, south side Walnut, East, 25.97', nail and tag #18998, east side power pole, South, 9.24', Nail and tag #18998, south side multi 4" Maple, West, 3.95'.
- 9. Corner referred to in Recorded Subdivision Plats: Irish Gardens, James E. Stephens P.S. #16053, September 3, 1982, Liber 38 of Plats, Page 27 and 28; Irish Gardens No. 2, James E. Stephens P.S. #16053, May 17, 1988, Liber 43 of Plats, Page 12 and 13; Kimberly Downs No. 3, Clyde K. Stephens P.S. #3829, March 11, 1965, Liber 27, page 4; Kimberly Downs No. 4, Clyde K. Stephens P.S. #3829, December 12, 1966, Liber 27, page 41; Kimberly Downs No. 6, James E. Stephens P.S. #16053, July 27, 1972, Liber 31, page 16; Somerset, Clyde K. Stephens P.S. #3829, October 11, 1963, Liber 25 of Plats, Page 15; Somerset No. 1, Clyde K. Stephens P.S. #3829, January 6, 1965, Liber 26 of Plats, Page 1, Somerset No. 2, Clyde K. Stephens P.S. #3829, August 10, 1965, Liber 26 of Plats, Page 23.

Nov 29 9 30 AH 194

Fo	r corners in Lansing	g Twp.	riing Requi	rement of Act 74, witch.	P.A. 1970	Æ	GistLi	. OF D	EEDS	3		
	[ngham		Located In:	Corner Code =14			Take to	Dr. de	7,120°			
	(County)		44			TN	CHAN C	CUNT	Y. MIC	CH.		
1.	Public Land Survey		T 4N R 2W	K-1								
			T R									
			, T R		·	•						
			TR									
2.	Property Controlling											
	in Section			- Action of developments in the continues realistic distribution of the continues of the co								
3.	Miscellaneous				Regist	er of De	eds Sta	mp &	File	Numb	er	
	Property in Sec.	S	T R		L							
٠.												
					····	А В	DE	F G	н	ı J	K L	М
5.	Private Claims							T	Ţ			
	4				2	6-1	- 5 - 1 -	1-1-	- 3 ·	2 	 	
					, j			+-+	\top		1	
					. 4	`} ? 	- - -	9	-10	1,1		<u></u>
				ruary 23 19 _9		· 		++	-	┝╾┼╾	╂╾╂	-
				of 1970, the corner points men nd rules therefore as required		18	17	-16	-15	14		3
			•	rtment of the Interior, Bureau o	_			$\downarrow \downarrow$			4-4	
	•		·	er points mentioned in lines 3, 4			_20	21	22	23-		4
	9		•	of Land Surveyors or by a Decr			Ĭ	11	Ĭ	LÏ.	لل	
	ourt of Law; established, pressed below:	re-establish	ied, monumented, re-	monumented, recovered, fou	ind as		20	20	-27-	26-		s
			l lu Alua aama Accorr					20-			T i	,
INC	zie: Not more than 4 (Jorners, all	i in tile same town a	ind range, may be recorded	יי נ	\rightarrow						

- Description of original monument and accessories and/or subsequent restoration: K-1,
 - 1. On Monday Feb. 12th, 1827, Musgrove Evans, U.S. Deputy Surveyor, going North between Sections 1 & 2 "Int. North Boundary 18 lks. West of Post" Set a Post cor. to Secs. 1 & 2 fw a
 - B. Ash 5 in S.76W. 265 lks
 - 6 " S. Oak S.82E. 450 "

(Continued on Back)

on this certificate.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - K-1, Investigation at this corner revealed a 1/2" bar in a concrete monument 11.95 feet West of 3/4" pinched pipe on extension of fence remains A nail and tag #16053 was found in the North side 6" Elm to the South. stump S70°W, 16.05' and in the West side of a 16" Elm stump N05°W, 27.72 as listed in item #6. Accepted 1/2" bar in concrete monument as the perpetuated location of K-1.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

T4N-R2W

Found 1/2" bar in concrete monument as noted above.

Found 3/4" pinched pipe, Southwest corner Section 36, T5N, R2W, East 11.95' Found nail & tag #16053 in North side 6" Elm stump, S70°W, 16.05'

Found nail & tag #16053 in West side 16" Elm stump, NO5°W, 27.72

Set nail & tag #25832 in West side 12" Box Elder, S30°E, 32.93'

Set nail & tag #25832 in North side 10" Poplar, S80°W, 45.33

Set nail & tag #25832 in East side 8" Ash, N60°W, 66.61'

25832 Surveyor's Michigan License No.

LARRY A BITYAN LEVD SURVEYOR No. 25832

Date //- 23-94

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

P.A. 345 INGHAM COUNTY PEER APPROVED _5/1/

Iron pipe East 11.88 feet

- 2. On Sept. 7, 1847, A. Jackson, County Surveyor, recorded corner with no monument noted witnessed by:
 Tam 16 N59-1/2E 22.53
 no other Tree
 (Vol.2 P.17 of County Surveyor Records)
- 3. On Nov. 19th, 1874, T.J. Brown, County Surveyor, recorded corner as a "Post" and noted that the bearing trees were gone, no witnesses given. (Vol.3 P.91 of County Surveyor Records)
- 4. Corner referred to in a resurvey of Lansing Township by R.J. Robb County Surveyor, in August and September of 1909 (vol. 3, page 218 and 219 County Surveyor Records) and identified as a "cement post 3" square on top, 4" square on bottom and 2.5 feet long, by an hor post of fence going South, Delta (Dewitt) post 18 lks East, set half way from adj. corners and on true line".
- 5. Marvin F. Fouty, P.S. #18989, recorded corner on 02/27/75 in Liber 2 of Surveys, Pages 308-309, as having found a 3/4" pipe witnessed by: Survey tag and nail South side 6" tree West 36.90' Survey tag and nail South side 6" tree East 24.39' Survey tag and nail East side 8" tree South 32.98'
- 6. James E. Stephens, P.S. #16053, recorded corner on 11/15/77 in Liber 4 of Corners, Page 108, and on 06/30/87 in Liber 5 of Surveys, Pages 232-233, as not finding the original monument or accessories and therefore setting a "concrete monument and cap 11.88' West of iron pipe which identifies the SW corner of Section 36, T5N, R2W. Set said monument on a projection of a line between the North 1/4 corner of Section 1 and the Southwest corner of Section 36, T5N, R2W." The concrete monument and cap were witnessed by: Survey tag #16053 set in the East side of an 8" Elm tree, N6°36'W, 27.70' Survey tag #16053 set in the South side of an 8" Elm tree, S89°34'E, 36.15' Survey tag #16053 set in the North side of an 8" Elm tree, N84°12'W, 25.05' Iron stake S89°50'12"E, 11.88' (from Liber 5 Pages 232-233 only)
- 7. James E. Stephens, P.S. #16053, recorded corner on 09/13/88 in Liber 6 of Corners, Page 391, as rod in concrete monument witnessed by tags nailed to:
 West side of 14" Elm tree North 27.71 feet
 North side of 6" Elm tree S85°W 16.07 feet
 NE side of 14" Elm tree S45°W 39.39 feet
- 8. Corner referred to in Recorded Subdivision Plats: The Crossings at Abbott Parkside, James E. Stephens P.S. #16053, January 18, 1991, Liber 46 of Plats, Page 24, 25 and 26; The Crossings at Abbott Parkside No.2, James E. Stephens P.S. #16053, March 12, 1993, Liber 48 of Plats, Page 3 and 4; The Crossings at Abbott Parkside No.3, James E. Stephens P.S. #16053, July 9, 1993, Liber 48 of Plats, Page 22 and 23.

MAY 10 8 51 AM '94

For corners in	Filing Require	REGISTER OF DEEDS Dina Dranson	
Ingham (County)	Located In:	Corner Code =##	THEHAM COUNTY, MICH.
Public Land Survey .	T <u>4N</u> R <u>2W</u> T R T R T R	K-2	
2. Property Controlling			
in Section	S T R		
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		
4. Lot No, R 5. Private Claims,	ecorded Plat		A B C D E F G H I J K L M
			2 6 5 4 3 2
			3
			4 7 - 12 9 - 10 - 11 - 12 - 12
	, in a field survey on <u>Febru</u>		
	quirements of P.A. 74, Michigan P.A. a conformance with regulations an		
	ections of the United States Depart		
	a Court of Law and/or that the corne		
	th the rules of the Michigan Board or e-established,monumented,re-r		
expressed below:	·	nonumented, recovered, tourid	10 30 29 28 27 26 25
NOTE: Not more than 4 co	orners, all in the same town ar	nd range, may be recorded	11
on this certificate.			12 31 32 34 35 36

- A. Description of original monument and accessories and/or subsequent restoration: K-2,
 - 1. On Monday Feb. 12th, 1827, Musgrove Evans, U.S. Deputy Surveyor, Set 1/4 Post fw

Sug. 11 N.64-1/2E.

Sug. 15 N.57W. 30

(Continued on Back)

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - K-2, Investigation at this corner revealed a 5/8" bar in a monument box 36.2' West of centerline of Coolidge Road. All of the witnesses listed in item #10 were found with the distances noted in part "C" below. No monumentation from Haver Acres Sub. No.1 was found due to construction. Accepted 5/8" bar in monument box as perpetuated location of K-2.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

T4N-R2W K-2.

Found 5/8" bar in monument box as noted above.

Found nail & tag #16053 in West side of a power pole, N05°E, 96.16'. Found nail & tag #16053 in West side of a 10" Cherry, East, 108.64'. Found nail & tag #16053 in West side of a power pole, S05°E. 163.84'.

Found P.K. nail in 2'diameter concrete light pole base, S70°E, 96.37'.

Centerline of a fire hydrant, N20°E, 232.30'. Centerline of the Northeast bolt in a 2' diameter concrete light pole

base, S45°W, 39.80'.

Signed by 25832 Surveyor's Michigan License No. .

OF MICHIG ARRY A BRYAN LAND SURVEYOR No 25832 LAND

Date 4-15-94

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

P.A. 345 INGHAM COUNTY PEER APPROVED 4/13/94 M

- 2. On Sept. 7, 1847, A. Jackson, County Surveyor, recorded corner with no monument noted witnessed by:
 Tam 7 South 12.50 lks.
 no other Tree (Vol.2 P.17 of County Surveyor Records)
- 3. On Nov. 19th, 1874, T.J. Brown, County Surveyor, recorded corner as a "Post" from which a Sugar 15 inches in diameter bears N.64-1/2E. 24 links distant. (Vol.3 P.91 of County Surveyor Records)
- 4. On Dec. 22nd, 1881, A.P. Drake, County Surveyor, recorded corner as a Black Walnut Stake with no bearing trees given. (Vol.3 P.185 of County Surveyor Records)
- 5. Corner referred to in a resurvey of Lansing Township by R.J. Robb County Surveyor in August and September, 1909 (vol. 3, page 218 and 219 County Surveyor Records) as a "cement post 3" square on top, 4" square on bottom and 2.5' long by two posts with one witness to a Ash N60°E 28'
- 6. Records of L.J. Hendryx, P.S. #3276, supplied by R. Helsel, P.S. #18994, record corner as a square concrete monument with no witnesses given and date unknown.
- 7. James E. Stephens, P.S. #16053, recorded corner on 11/29/73 in Liber 2 of Corners, Page 559, and on 10/28/80 in Liber 4 of Surveys, Page 149, and on 09/28/82 in Liber 4 of Surveys, Pages 578-584, as having found an old concrete monument in the intersection of a 3-way fence witnessed by: Survey tag in the SW side of a 10" Hickory tree, N14°21'E 19.05 feet Survey tag in the W. side of a 14" Wild Cherry tree, N85°11'E 8.54 feet Survey tag in the N. side of a 24" Oak tree, S9°40'E 11.91 feet The bearing of the Section line North of the corner is N0°37'20"W.
- 8. David L. Clifford, P.S. #25837, recorded corner on 04/06/82 in Liber 4 of Surveys, Page 524, calling only for L2, Pg.559.
- 9. Maurice H. Mahieu, P.S. #28414, recorded corner on 04/15/83 in Liber 4 of Surveys, Page 702, and on 07/07/83 in Liber 4 of Surveys, page 734, and on 11/19/84 in Liber 4 of Surveys, Page 946, with the same witnesses as listed in item #7.
- 10. James E. Stephens, P.S. #16053, recorded corner on 06/25/87 in Liber 6 of Corners, Page 337, and on 06/30/87 in Liber 5 of Surveys, Pages 232 233, and on 10/17/89 in Liber 5 of Surveys, Pages 1152-1159, stating the monument and its witnesses listed in item #7 were removed during road construction. A 5/8 inch iron rod in a monument box was found that was accepted as the re-established corner witnessed by: Nail and tag in the East side of a utility pole N5°E 96.33 feet, Nail and tag in the North side of a 10" Cherry tree East 108.70 feet, Chiseled "x" in top of concrete curb S45°E 12.52 feet, P.K. nail in concrete base of light pole S70°E 96.40 feet.
- 11. Douglas K. Richardson, P.S. #31603, recorded corner on 10/06/87 in Liber 5 of Surveys, Page 306, calling only for L2, Pg.559.
- 12. Maurice H. Mahieu, P.S. #28414, recorded corner on 10/27/87 in Liber 5 of Surveys, Pages 344-345, with the same witnesses as listed in item #10.
- 13. Corner referred to in Recorded Subdivision Plats: Haver Acres Sub. No.1, Laverne J. Handryx P.S. #3276, October 12, 1953, Liber 17 of Plats, Page 14; The Crossings at Abbott Parkside, James E. Stephens P.S. #16053, January 18, 1991, Liber 46 of Plats, Page 24, 25 and 26.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MAY 10 8 52 AH '94

For corners in	Filing Require	ment of Act 74, Mich. P.A. 197	KERIZIEN OF DEFEN
Ingham		6 6 4 4	Paris Drinson
(County)	Located In:	Corner Code ##	THEHAM COUNTY, MICH.
Public Land Survey	T <u>4N</u> R <u>2W</u> T R T R	K-3	
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R	F	Register of Deeds Stamp & File Number
4. Lot No , R	lecorded Plat		A B C D E F G H I J K L
5. Private Claims			2 6 5 4 3 2
		•	3
Tarry A Bryan	Febru	ary 28 , 19 94 ,	4 7 4 8 4 9 10 11 11 - 12-
do hereby certify that under rec in lines 1 and 2 above were in current manual of survey instru Management or by a decree of above were in conformance with	quirements of P.A. 74, Michigan P.A. of conformance with regulations and uctions of the United States Depart a Court of Law and/or that the corne the the rules of the Michigan Board of the rules of the Michigan Board of	of 1970, the corner points mentioned drules therefore as required in the ment of the Interior, Bureau of Land r points mentioned in lines 3, 4 and 5 f Land Surveyors or by a Decree of a nonumented, recovered, found as	5 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25
NOTE: Not more than 4 c on this certificate.	orners, all in the same town an	d range, may be recorded	11 12 31 32 33 34 35 36
K-3,	monument and accessories and		Donuty Survoyor
Set Post Cor Aspen 3 N.4	. to Secs. 1, 2, 1	Musgrove Evans, U.S. 1 & 12 fw an	Deputy Surveyor,
(Continued o	n Back)		
B. Description of corner e	evidence found and/or method a	applied in restoring or reestablish	ing corner:
monument box listed in it church light listed in it	±5.2' East of the em #7 was found, c standard, Northea em #12 and noted i	centerline of Cooli hiseled cross on top st, 59.10', along wi	bar and cap #19003 in dge Road. One witness of concrete base of th all the witnesses accepted 1/2" bar and cap of K-3.
			LARRY A. BRYAN LAND
C. Description of monume K-3, T4N-R2 Found 1/2" b Found chisel N44°24'W, 59	ed cross on top of	established to perpetuate locating in monument box as n concrete base of ch	the position of the correction
Found nail & Found nail & Found nail & Found nail & Northwest co Southeast co	tag #16053 in Nortag #16053 in Westag #16053 in Nortag #16053 in Sourner garage to hourner 4' high by 15 f Northeast bolt in	t side light guy pol th side utility pole thwest side utility se #1858 Coolidge Ro " wide brick sign, N	, S85°W, 58.75'. pole, N35°E 74.19'. ad, S70°E, 86.02'.
Signed by and	Syon 25000	Date 4-/5-	94
Surveyor's Michigan Licens	se No. <u>25832</u>	FORM A	PPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19 REVISED MAY 14, 19

- 2. On Dec. 22nd, 1881, A.P. Drake, County Surveyor, recorded corner as a Post found from the original surveys witnessed by: Cottonwood 18 N 3-1/2W, 34-1/4 links, Beech 24 S 27-1/2E, 6 links. (Vol.3, Page 185 of County Surveyor Records).
- 3. On Jan. 29, 1909, R.J. Robb, County Surveyor, recorded corner as a gas pipe with no witnesses given. (Vol.2 P.264 and Vol.5 P.55 of County Surveyor Records).
- 4. Corner referred to in a resurvey of Lansing Township by R.J. Robb, County Surveyor, in August and September of 1909 (vol. 3, page 218 and 219 County Surveyors Records) and identified as a "cement post 3" square on top and 4" square on bottom and 2.5 feet long, witnessed by Oak 3" N75°E 41', Ash 2" N50°E 45.5', Ash 2" N45°E 49.3'.
- 5. Records of L.J. Hendryx, P.S. #3276, supplied by R. Helsel, P.S. #18994, dated 1/25/51 record corner as a "Bolt to Surface" witnessed by: Oak 12" N75°E, 41.1, Maple 12" S55°E, 41.8, NW Cor. House S70°E, 66.4.
- 6. In Jan. 1965, C.E. Smith, Survey Chief for the Michigan State Highway Department, witnessed corner as a 1/2" iron in centerline of Coolidge Road witnessed by: 23" Maple N85W 34.50, 20" Maple S60E 43.36, 20" Oak N75E 42.84. (from corner witness records of MDOT)
- 7. James A. Porter, P.S. #19003, recorded corner on 03/01/72 in Liber 1 of Corners, Page 371, as having found a 1/4" reinforcing rod in Coolidge Road surface from the tie recorded on the original plat of Farwood Subdivision, Liber 29, Page 1, Ingham County Records, witnessed by: Chiseled cross on top conc. base of church light standard, N44°24'E, 59.10'Ex. Nail in blazed 20" Maple, N71°46'E, 42.80 feet, Nail with Brass tag in 21" Maple, S57°37'E, 43.00 feet, Nail with Brass tag in 24" Maple, N89°09'W, 34.32 feet.
- 8. James E. Stephens, P.S. #16053, recorded corner on 11/20/75 in Liber 2 of Surveys, Page 538, and on 05/14/76 in Liber 2 of Surveys, Page 698, and on 05/20/76 in Liber 2 of Surveys, Page 709, and on 10/20/76 in Liber 2 of Surveys, Page 927, as having found a 1/4" re-rod with the same witnesses as listed in item #7.
- 9. James E. Stephens, P.S. #16053, recorded corner on 10/28/80 in Liber 4 of Surveys, Page 148, and on 09/28/82 in Liber 4 of Surveys, Pages 578-584, as a rod found in the centerline Coolidge Road with the same witnesses as listed in item #7 minus the light standard.
- 10. James E. Stephens, P.S. #16053, recorded corner on 06/01/83 in Liber 4 of Surveys, Pages 724-728, as a 3/8" iron rod in Coolidge Road with the same witnesses as listed in item #7.
- 11. Maurice H. Mahieu, P.S. #28414, recorded corner on 07/07/83 in Liber 4 of Surveys, Page 734, and on 11/19/84 in Liber 4 of Surveys, Page 946, as having found an iron rod with the same witnesses as listed in item #7 minus the light standard.
- 12. Maurice H. Mahieu, P.S. #28414, recorded corner on 06/17/88 in Liber 6 of Corners, Page 376, as having found a 1/2" iron rod in monument box witnessed by: Nail and tag in NW side utility pole N45°E 40.29 feet, Nail and tag in West side Guy pole S25°E 76.47 feet, Nail and tag in North side utility pole S85°W 58.73 feet, Nail and tag in SW side utility pole N35°W 74.19 feet.
- 13. Corner referred to in Recorded Subdivision Plats: Farwood, Fred N. White P.S. #12034, April 22, 1968, Liber 29 of Plats, Page 1; Farwood North, Donald B. Emery P.E., April 8, 1971, Liber 30 of Plats, Page 21; Farwood South, Donald B. Emery P.E., April 5, 1972, Liber 31 of Plats, Page 3; Irish Gardens No.2, James E. Stephens P.S. #16053, May 17, 1988, Liber 38 of Plats, Page 27 and 28; Pinecrest No.3, Clyde K. Stephens P.S.#3829, February 24, 1965, Liber 26, Page 12 and 13; Pinecrest No.4, Clyde K. Stephens P.S. #3829, July 29, 1968, Liber 29, Page 5; Ramblewood, Clyde K. Stephens P.S. #3829, May 3, 1965, Liber 26 of Plats, Page 15 and 16.