

15

ESE 2000 Reman CONTRACT

LEZ

LEZ-15-45

L-10

Searched at APPARENT location of
CORNER and found 4" CONCRETE
Monument in concrete collar
Matching LESTER WITNESSES. ALUMINUM
Monument as per dictated by
R. Lester AND Camped w/
2 1/2" Aluminum Cap AND Set
Rings To Surface

C. 4" Conc Mon. w/ 2 1/2" Alum. Cap
STAMPED 25837 in Map Box
N5T 12034 N.S. Side U.P. EAST 53.66
N4T 25837 SW Side 29" Maple 53395 39.21
N1T 39100 S. Side R/L TE Corner N79°W 25.68
N5T 25837 E.S. Side 19" Ash N20°W 47.10

DLC
CFC

7650

21 July 00

15

LEZ-15-46

L-10

Searched at APPARENT location of
CORNER & found 1/2" Box & Cap #13574
@ ANCIENT Fence Corner Matching
1 Box WITNESS. Pulled Iron &
Cleared all fence from Area
and made Thorough Search for
McCreary's Iron. Could not find
Iron and accepted Box instead.
Fence corner as per dictation of
Corner and replaced it w/ 3/4"
Box & Alum Cap.

N1T 25837 E.S. Side 19" Maple N28°W 11.92
" " " " N18°W 22.45
" " " " N170°E 30.38'
" " " " E. " " 9" " 530°E 32.28'

17

M-6

LE 2-17-49

LE-2

DL C
SWN

770°

18 Aug 2000

17

M-5 LE 2-17-50

B. found Conc Mon w/ cap in Conc Collar. Accepted as per location of corner. Capped w/ Alum. Cap. 4 Set King To Surface

C.

NST 28414 Top conc 60/100 - N36E 31.92'

S45°E 31.92

S41°W 31.22

N37°W 32.82

3/4" Pipe in Mon Box South 109.38'

C. 4' Conc Mon w/ 2 1/4" Aluminum Cap

NST 25837 W. Side 16" Hike N19°E 121.80'

NST 28414 W. Side 17" Pipe S39°E 49.98'

SW Conc FDU Hse #2484 S35°E 78.29'

6 3/4" Steel Pipe FDU Post @ Ground S21°E 85.38'

N/T 28414 S. Side 21" Pipe N36°W 124'

Conc Mon. (AS T3N-R3E) South 97.05'

See LE 3-15 for Truv.

18

LE-2

M-4 LE2-18-51

3. Searched & Found Conc. Mound
Cap 9" W. of d. Wallace Rd.
on Fence Line West. Accepted
as Corner. Capped W/ Alum Cap

C. 4" Conc. Mon w/ 1/2" Rebar & Alum Cap

N 57 13998 NW Side 19" Tr. Cherry N 40° E 60.60'

N 57 25837 SW Side 25" Cherry 535° E 51.20'

↓ East Side 33" Oak 515° W 121.92'
S. Side For 104 N 81° W 21.08

See LE3-14 for Truv.

DL
BWN

770°

18 Aug 00

18

L-4 LE2-18-52

8. Searched at apparent location of
Corner and found 1/2" Bar & Cap #1702
at SW Side 3" Steel Pipe Anchor
Post. EXCAVATED 3' Dia hole and
Post and found old sleigh shoe.
lying in stones surrounding post.
Accepted sleigh shoe - 5' 12" RSC as
per junction of corner and replace
Bar w/ 1/4 3/4" x 24 Steel Bar &
Alum Cap

N 57 13037 NW Side 9" Elm N 53° E 14.50'

N 57 13037 W. Side 20" W. Ash East 27.92'

N 57 13037 SW Side 9" Ash N 58° W 13.95'

N 57 25837 E. Side 9" Cherry N 40° W 4.40'

See LE3-12 for Truv.

19				LE-2
K-4	LE2-19-58			
B. Searched at apparent location of corner and found 1/2" B&C 16053 on 28414 @ location. RETURNED LOT 3, 4, 5 & 6. Block 1 of Fisher's Addn. To Lakey Cor 22 Assessor's Plat Not a'd lots 6 & 7 of HANSEN'S. Unrecorded Plat and determined B&C was not perpetuation of corner in relationship To Plots. Dig 3' Dia Hole 3" Deep and found nothing more. Accepted B&C as perpetuation location of corner & replaced w/ STANDARD Bar & Cap				
NIT 25837	S. Side 20' Cornerwood	N84E 18.44'		
NIT 16053	E. Side 4th Pole	S04TH 15.36'		
NE. Cor Conc.	Block Bldg	S150W 08.00'		
NW Cor Conc	Block Bldg	S530W 99.42'		
NW Cor Lot 22	Asses. Plat (1" P. 1187W)	132.02'		
See LE3-10	For Trv.			

DE	Sum	TYPE	18 Aug 00 '19
K-5	LE2-19-54		
B. Searched at apparent location of corner. AND found 1" Gas Pipe on E curb Road 1' West of Fence line South Matching All of Burman's Road Comm's & Bosses WITNESSES. Accepted 1" Gas Pipe as corner and drove 3/4" Bar into it and placed Alum cap on Bar			
NIT 25837	W. Side 22" Maple	S110W 22.20'	
NIT 19834	NW Side 19" Maple	S500W 30.27'	
NIT 25837	NW Side 17" Maple	S680W 42.94'	
	NW Side 12" Oak	S740W 53.50'	
	NW Side 9" Oak	S780W 65.20'	
See LE3-07	For Trv.		

20			LE-2
M-8	LE-20-55		
B. Searched at APPARENT location of corner and found 1/2" Bar			
7' N. of d. VAN ORDEN Rd. on			
d. Wallace Rd. To N. EXCAVATED			
2 DIAMETER HOLE 18" DEEP AROUND			
Bar and found 3/4" Bolt WITH			
1" SQUARE Head beneath it surrounded			
By Broken Brick & Crockery. ACCEPTED			
Bolt as part of ruin of Corner and			
Set 3/4" x 24" Steel Bar with 2 1/4"			
Aluminum Cap. Above it.			
C. 3/4" x 24" Steel Bar w/ 2 1/4" Alum Cap.			
N 51° 19834 SE Side Tel Post 35-17-50 41.84'			
N 51° 25032 W Side 8" x 8" Wd. C. Post 144-29-59 43.24'			
1 1/4" Pipe w/ 3" Alum. Cap # 19834 179-25-86 101.83'			
PK in N. Side 28" Maple 299-11-34 43.43'			
SE Cor FDN. He # 746 Wallace 51-53-17 139.37'			
662.0-			
681.5 275-22-47			
1343.5-			
See Pg 29 For Trav.			

DC	SWN /	T70	21 Aug 00	20
4-8	LE-20-56			
B. Searched at apparent location of corner and found Bar Spike on d. VAN ORDEN Rd. matching Boss witness				
Bar Not Matching McCree's				
Remaining witness from 1897.				
Recovered 1" Bar (McCree's worn corner) at 1/8 corner to East				
and doubled distance from M-8				
To 1/8 corner to act search area				
41 North of Bar Spike Got Mo.				
Reading and EXCAVATED 3' Dia.				
16 1/2' Deep and found Bent				
3/4" Bar inside of 1 1/4" Gaspipe				
Accepted This and Set Standard				
Bar 5' Cap & Mon Bar Above.				
C. 3/4" x 24" Steel Bar 5' 2 1/4" Alum Cap.				
Mg 1011/3 Shiner NE Side 21" Maple Street 904'				
N 51° w Side 33" Maple 5130E 97.20				
N 51° Shiner E. Side 18" Walnut 532W 64.27				
N 51° Tag NE Side Tel Kiser Post N 55° W 38.12'				
Bar Spike (4-8) RECOVERED S 20° W 3.08'				
See Pg 24 For Trav.				

21

LEZ

DC
SUN

7:30

21 Aug 00

3

A

LEZ-21-57 (ED 1" Iron Bar @ 1/8 Cor.
3" Iron Corner)
BS LEZ-20-55 (M-8)
FS LEZ-21-58 (L-8?)

BS

0

FLD

180

Dist To

3555

FS 58

1342.09 1342.09

A

LEZ-21-59 (R.P. Set 10" 50k Edg. of where
100' NE of K-10
Set 1/2" Edg. S. EDM Frost
BS LEZ-21-60 (R.P. Set 1/2" Edg. S. EDM Frost
FS LEZ-15-46 (K-10 STAND. BCL

BS

180-00-29

FS

40-40-28

BS

180-00-24

FS

180-00-29 220-46-37 220-46-17

Dist To BS


FS

f


99.94

m

30.461



22				LE-2
A	LE2-21-60			
B5	LE2-16-48 (L-9			
F5	LE2-21-59			
B5	000-00-20			
	110-51-40	11051-20		
	180-20-12			
	290-51-22	11051-10	11051-15	
	60-20-30			
	351-12-02	110-51-32		
	240-20-36			
	351-11-37	110-51-01	11051-165	
			11051-16	
D.57 To	B5	F5		
		2770.19		
		844.354		



23

LE-2

LE2-24-60

LE2-16-48

LE2-23-61 (K-9) Sec 13 24
For Press.

BS 000-00-20

FS 180-57-19 180-56-59

BS 180-00-15

FS 000-57-13 180-56-58 180-56-585

BS 60-20-30

FS 241-17-35 180-57-05

BS 240-20-32

FS 61-17-30 180-56-58 180-57-015 180-57-00

D3+T0 BS FS

F 1333.82 1337.39

M 406.556 407.639


D&S

T.N.L

T750

21 Aug 00

23



24

LE-2

T LE2-16-48

B5 LE2-21-60

F5 LE2-20-56 (L-8)

F5 LE2-15-45 (L-10)

F5 LE2-16-47 (see pg 16)

B5D 000-00-20

S6D 85-27-37 85-27-17 ~

436 264-44-07 264-43-47 ~

47D 264-44-40 264-44-20 ~

B5R 180-00-24

S6R 265-27-44 85-27-17 ~ 85-27-17

43R 84-44-00 264-43-36 ~ 264-43-415

47R 84-44-33 264-44-09 ~ 264-44-145

B5D 60-20-80

S6D 145-47-52 85-27-22 ~

45D 325-04-20 264-43-50

B5R 240-20-51

S6R 325-47-52 85-27-21 85-27-215 85-27-19

45R 145-04-09 264-43-38 264-43-44 264-43-43

Dist to BS FS₅₆ FS₄₅ FS₄₇

F 1333.82 2644.05 2645.17 666.80

m 406.550 807.433 812.346 203.241

DL SWN

TNK

T75°

21 Aug 00

24

VAN OORDEN Rd

House Rd

Foster Rd

LINE

(47)

(45)

25

K-9 LE2-23-61

LE2

SEARCHED at apparent location of
CORNER and found 1/2" Bar & UNDERPASS
CAP 3 1/2 feet N. of & Frost Rd. on
Fence line to North, Traversed
NW Cor. Sec. 25 revealed a good
Preparation / relationship to
McCrearys 1885 Survey. EXAMINED
2' Diameter Hole 3' Deep and found
STONE Beneath Bar & Cap. ACCEPTED
STONE & Bar & Cap as proper location
of corner and Set Square B&C
Above in Plan Box

C. 3/4" X 2 1/2" Steel Bar 5 1/2" Alum Cap
N&T 25837 N Side Maple 5790± 78.00
N&T 24622 E Side Wm. Pole 5200 94.85
Top Most Point Large Boulder 5780 25.87
& SE Side 4" Spruce 5440W 41.60
& SE Side 4" Spruce 5630W 61.10

See Pg 23 for Trav.

DC

SWN

770

22 Aug 00 25

V-6 LE2-25-62

SEARCHED at Apparent location of corner
and found ANCHOR 3 1/4" Pipe w/ Plow
Share along Side 2' N. of & Townsend
Rd. on Fence line to South.
ACCEPTED Pipe as proper location of
corner and Set SQUARED B&C
over it.

3/4" B&C w/ 2 1/2" Alum Cap.
5' Edge 2" Angle Iron for Ground N&T 24.30
N&T 25837 W. Side 10" Walnut South 42.55
N&T 28414 N. Side 15" Walnut 560W/50.21
N&T 25837 E. Side 6" Locust NW 49W 36.86

See LE 3-05 for Trav.

26

L-6 LE2-26-63

Searched at apparent location of corner & found $\frac{1}{2}$ " Box & Cap # 13574 in old anchor Post Hole w/ Fences to North, East South & West. Accepted Box & Cap as Corner Based on Evidence of Historic Survey Work in Section. ~~Accepted~~ Replaced Box & Cap with Standard Mon. & Alum. Cap

LE-2

SW Cor 2" Angle Iron Fern Post

N15E

7.89

N1T 25837 N.S. side 20" AS4 S60E 12.27'

N5T 25837 S.E. Side 6" T_W AS4 S71W 22.07'

N5T 25837 W. Side 18" Ground N20W 26.66

26 SW

T750

22 Aug 00

26

M-7 LE2-26-64

Searched at apparent location of corner & found 1" Box 1.5'E. of W. Wallace Rd. Matching Boss & Bryan Witnesses. EXCAVATED 18" Dia. Hole 18" Deep Found Stone lying on side next to Box w/ Broken Brick & Crochery around. Accepted Box as perpetuator of corner (probably by McCreary in his 1897 Survey) and set Standard Box in Mon. Box in its place.

C. $\frac{3}{4}$ " x 24" Steel Box & Alum Cap in Mon. Box SW Cor Found AS4 2010 N51°E 80.13'

MDS4T Tag in S.S. side Tek Blk N77°E 30.05'

 $\frac{1}{2}$ " Box (A-7 T3V13E) South 100.48'

N1T 25837 E. Side 36" W. 1/4 S9°W 22.13'

 $\frac{1}{2}$ " Pipe N84°W 33.50'

N1T (w/ Roadside) E. Side 21" Oak N27°W 64.52'

27

LE-1 LE-2-27-15

LE-2

B. Searched at Apparent Location
of Corner and found 1" Pipe
in old Anchor Post Hole. Excavated
3' Dia. Hole 3' Deep and found
Wavy Fence Post Stakes. Accepted
1" Pipe as perpetuation of corner
and drove 3 1/4" Bor & Alum. Cap.
in side of it

N12 25837 SE Side 19" Oak N50E 61.52
N1T 9834 N3d. 29" Oak 56W 33.4
N1T 25832 N Side 17" Oak N75W 15.51
N1T 25837 E. Side 21" Board N50W 45.45

See LE-3-04 for Tray.

DC
CEE

1840

29 Aug 00

27

LE-1 LE-2-27-16

B. Searched

and found 1/2" B&C 13574 in
Ancient Anchor Post Hole 1.4' S. of
New 4" Steel Fence Post in Conc
Accepted 1/2" B&C as perpetuation of
corner

N12 25837 W. Side 21" Board N20E 30.30
E. Side 17" Board S50E 23.02
N. Side 27" Mobile West 45.45
W. Side 14" Ash N20W 15.26
S. FACE 4" Steel Post in Conc. North 1.20

28

L-5 LE2-28-67

LE2

B. Searched at apparent location of Corner and found $\frac{1}{2}$ " Bar in North fence line of Abandoned Road. Could not reconcile this location with Benjamin witnesses (they do not appear to be for this corner). Accepted Bar as perpetuation of corner and replaced with Standard Bar 5' Cap. Upon further consideration decided corner needed more work and placed on hold.

Witnesses to $\frac{1}{2}$ " Bar in fence

Ngt 25837 N. Side 7" Maple East 9.09'

S. Side 7" Maple S70E 12.28'

N. Side 36" Oak S75W 93.30'

Ngt 19834 S. Side 36" Maple West 64.50'


DL
CFE

1850

29 Aug 00

28

30				LE2
T	LE2-15.45 (L-10	4" Cont. Mon 3 Alum. Cap		
B5	LE2-16-48 (L-9	3/4" Box 1/2 A.C.		
F5	LE2-30-87 (AP Set 1/2" B&C 1' W of W. EOM	House Rd. B.S. 5' S. of STOP		
P50	000-00-20	Ahead sign on Top of Hill		
87D	180-20-39	180-20-19		
B5R	180-00-34			
87R	000-20-39	180-20-05 180-20-12		
B5D	000-00-18			
87D	180-20-35	180-20-17		
B5R	180-00-30			
87R	000-20-30	180-20-06 180-20-11.5 180-20-12		
D5RTD	B548	F587		
f	2605.07	2772.59		
m	812.314	668.303		



31

LE2..

π	87		
B5	45		
F5	LE2-04-15 (L+11	RECOV. 3/8" B&H.C.	
		IN MON BOJ	
B5D	000-00-20		
B5D	178-08-06	178-07-46	
B5R	180-00-17		
B5R	358-08-11	178-07-53	178-07-49.5
B5D	000-00-25		
B5D	178-08-06	178-07-41	
B5R	180-00-23		
B5R	358-08-13	178-07-50	178-07-45.5
Dist to	B545		F515
F	2192.59		456.89
m	668.303		139.261


OLC SWN

π NIK

7 150°


4 NOV 00

31



33			LE-2
Trav.			
T	LE2-16-48 (1-9		
BS	LE2-20-56 (1-8		
FS	LE2-33-88 (R.P. Temp. Pt. Field. Bean		
BS	000-00-21		
88	96-13-17 96-12-56		
BS	180-00-33		
88	276-13-26 96-12-53 96-12-545		
BS	600-00-26		
88	96-13-14 96-12-48		
BS	180-00-29		
88	276-13-26 96-12-57 96-12-525 96-12-535		
Dist To	BS	FS	
F	2649.09	2690.38	
m	807.445	820.031	
T	88		
BS	48		
FS	LE2-33-89 (M-4? See Pg 34		
BS	000-00-20		
89	102-15-17 102-14-57		
BS	180-00-23		
89	282-15-12 102-14-49 102-14-53		
Dist To	BS	FS	
F	2650.39	58.29	
m	820.032	17.766	


DL	SWN	TN/L	TSSO	4 NOV 00	33
T		88			
BS		48			
FS	LE2-33-90 (R.P. Temp. Pt. in Bean Field				
BS	000-00-19				
90	255-48-24	255-48-05			
BS	180-00-27				
90	75-48-32	255-48-05 255-48-05			
BS	000-00-17				
90	255-48-26	255-48-09			
BS	180-00-25				
90	75-48-34	255-48-09 255-48-09 255-48-07			
Dist To	BS	FS			
F	2690.39	892.99			
m	820.031	272.183			



34				LE-2
M-9	LE2-33-89			
FO 1 1/4" Pipe w/ 3" Alum. Cap Stamps				
M-9	19834	in N-S Fence line		
② Fence line from West Matching				
McCreary Distances To North-88				
4 West.				
1000	NST 25837	W.S. side 28" dia	503E	73.94'
1001	NST 25837	N.S. side 10" dia	510E	46.11'
1002	NST 25837	NW side 1/8" CTUD	543W	25.76'
1003	NST 25837	S. side 9" ASH	N 75° W	71.15'
CARSONITE Survey Marker Sign South 0.5'				
Measured	West	2703.35	To L-9	
	(McCreary 2700.06')			
Measured	North	2627.51	To M-8	
	(McCreary 2628.70')			
Measured	South	2659.26	To M-10	
	(McCreary 2655.84')			

DLC	N N.L	7350	4 Nov 00	34
SWN				
N	- 90			
AS	- 88			
ES	LE2-34-91	RP Set Temp. Pts in Beam		
BS	600-00-21			
91A	191-32-23	191-32-02		
BS	180-00-42			
91A	11-32-46	191-32-04	191-32-03	
BS	000-00-35			
91A	14-32-33	191-31-58		
BS	180-00-34			
91A	11-32-47	191-32-13	191-32-05	191-32-04
Dist To	BS88	FS 91		
C	892.98	1718.51		
M	272.182	523.803		

35					LE-2
Two.					
T		91			
B5		90			
FS	LEZ-35-24	92	A-10 Hand. Type 1/2" of		
35D	000-00-20		17022 Boss in old Arch.		
92D	170-43-59		1st Hole Surrounded By		
B5R	180-06-25		Broken Brick & Chockery		
42R	350-43-55	170-43-30	170-43-34.5'		
Dot to B590		FS92			
F	1718.51	102.84			
M	523.804	31.347			
Tied	100451005	Pts. on	E-W fence		
w/ SDR					
Set 98	4RT 109-35-52	Dot	11.18'		
Set 3/4" B3AL.					
100T NST	25837	N. Root	39" OAK 540°E	115.71'	
100B "	"	N. S. d.	6" OAK 530°E	34.48'	
100I "	"	NW Side	9" OAK 529°W	35.93'	
1010 "	"	N. Side	6" Hick 561°W	33.51'	
Set 3/4" Bar 1 Alum Cap	18'	Deep in	filled		
1/2" Bar 1 Cap # 7022	(A-B T3N, ESE) 504°48'42"E	9191'			



36

LE-2

ESE 2000 Remon Contract

ESE = ENGINEER Surveying & Engineering

DLG = Dave Crawford PS25837

CFE = Coe Emmons Survey Tech.

N/K = Nikon Total Station

B&C = 1/2" x 18" Smooth Box & Cap

28409 in less otherwise

NOTED

NST = 1 1/4" Alum. Tag & 20d Galv.

Spoke in less noted.

(Tag is #25837)

SWN = Sam Norde, Survey Tech

K-8 LE3-01-70

LE-3

DIC
CFC

7750


30 Aug 00

3. Searched at apparent location of
Corner and found 1/2" Bar & South
of 4 VAN OGDEN Rd on Fence
line North Matching Boss WITNESSES
EXCAVATED 18" Diameter Hole 18"
Deep and found that bar was
in middle of 4" Drain Tile standing
vertically in natural ground. Hooped
Tile & Bar as per function of corner
and replaced Bar with standard
Bar & Cap and Set new Bar.

C.

3/4" x 24" Steel Bar & Alum Cap	
NST 25837 E. S.D. RITE Bar N20E	37.38
NST 19834 E. Side 30" Maple S120W	72.33
NE Low Conc. Birch Hse #496	55.00
NST 25832 N. Side 28" Maple	58.00
1/2" Bar & Cap 25832 Byron	N20E 33.00

SEE Pg 2 FOR Trav.



DLC T-800
LSE T NIKONT

(10)

VAN DADEN RD.

(69)

HOUSE RD.

(58)

CUMMER RD.

(71)

Pine Trees


30 AUG 00

2

3

				LE3
A	LE3-02-71			
BS	LE2-29-69			
FS	LE3-03-72	RP SET 10:30 PM FLD TO (WEST Temp Pt)		
FS	LE3-03-73	RP SET 11:15 AM FLD TO (END OF BIT GUNNER TO NW CORNER BIT S OF RP SET TEMP IN FLD TO 15)		
FS	LE3-03-74	(WEST Temp Pt)		
BSD	000-00-20			
72D	75-42-53	75-42-33		
73D	180-03-12	180-02-52		
74D	301-25-54	301-25-34		
BS R	180-00-15			
R	255-42-44	75-42-29	75-42-31	
R	000-03-03	180-02-48	180-02-50	
R	121-25-56	301-25-41	301-25-375	
BS D	60-20-30			
D	136-03-08	75-42-38		
D	240-23-20	180-02-50		
D	001-46-06	301-25-36		
BS R	240-20-24			
R	316-02-54	75-42-32	75-42-35	75-42-33
R	60-23-07	180-02-43	180-02-46	180-02-48
R	181-46-03	301-25-39	301-25-375	301-25-375
DISTD	BS	FS72	FS73	FS74
FT	3306.85	756.59	2036.37	1286.96
m	1607.929	230.610	620.686	392.267

DL
LFE T NIKON
T-80
I-96
30 AUG 00
3



3

4

T LE3-03-74

BS LE3-02-71

~~BS LE3-04-75~~

FS LE2-27-65 (L-7)

BSD 180-00 00

D 172-25-59 172-25-39

BSR 180-00 00

R 352-20-05 172-25-59 172-25-49

BSD 180-20-30

D 232-40-17 172-25-47

BSR 240-20-21

R 52-40-25 172-26-04 172-25-55 172-25-52

DISTID BS FS


FT 1286.97 250.44

M 392.268 70.335

LE-3 DUC CEE TANKIN

T-80

30 AUG 80



	TRAIL		LE-3
Town			
π	LE3-03-73		
BS	LE3-02-71		
FS	LE3-05-75	(DP SET MARK NAIL 8' W. OF E)	
FS	LE2-25-62	(K-L)	
FS	LE3-05-76	(POL ON C/NET 73-75 SET EQUISPE TEMP) IN I-94 ROW	
BS D	000-00-20		
75 D	181-01-46	181-01-21 ✓	
02 D	95-22-40	95-22-24 ✓	
BS R	180-00-22		
75 R	001-01-33	181-01-11 ✓	181-01-18 S
02 R	275-22-48	95-22-24 ✓	95-22-26
BS D	00-20-30		
75 D	24-21-56	181-01-26 ✓	
02 D	155-42-56	95-22-24 ✓	
BS R	240-20-33		
75 R	101-21-44	181-01-11 ✓	181-01-18 S
02 R	335-42-54	95-22-21 ✓	95-22-26
DIST 10	BS	FS 75	FS 02
FT	2034.37	940.86	1324.86
M	620.687	292.870	403.817
			22.924

6

LE-3

T LE3-05-75

BS LE3-03-73

FS LE3-00-77

BS 000-00-20

P 178-46-29

BS 180-00-11

P 358-46-24 178-46-15 178-46-22

BS 100-20-30

P 239-00-30 178-46-06

BS 240-20-19

P 59-00-38 178-46-19 178-46-25 178-46-23

DIST 16 BS FS

FT 900.86 1081.93

M 292872 512.652

DL
LE T NILEON

T-78°

8 SEPT 00

6

Grub Rd.

GRANER Rd

A 75

W. 81 I-96

E. 81 I-96

THOUSAND Rd

73 A

7

LE3

LE3-06-77

BS LE3-05-75

FS LE3-07-78

FS LE2-19-54

FS LE3-07-79

BS 100-00-20

780 181-03-11

40 90-40-10

BS 180-00-11

780 001-03-08

40 270-40-11

BS 60-20-30

780 241-23-15

40 157-00-10

BS 240-20-20

780 61-23-14

40 337-00-10

BS 100-00-11

780 001-03-08

40 270-40-11

BS 60-20-30

780 241-23-15

40 157-00-10

BS 240-20-20

780 61-23-14

40 337-00-10

BS 100-00-11

780 001-03-08

RP SET MARKING & SIGNED NO 25837 SE

21'S OF & TOWN LN (SIGNED)

249'S

POL ON LINE 77-75 SET

NOT A NILE & BARNER RD 31' N AC N

SIGNED NO 25837

UNCLINE 44'S

249'S

181-02-51

90-39-50

181-02-54

90-40-00

181-02-54

90-39-51

181-02-54

90-39-53

181-02-54

90-39-51

181-02-54

90-39-51

181-02-54

90-39-51

181-02-54

90-39-51

181-02-54

90-39-51

181-02-54


90-39-51

DLC
LE3 T NILEON

T 78°

8 SEPT 00

7



9

LE-3

I LE3-08-80

BS LE3-07-78

FS LE3-09-82

20' FILL IN PIPE IN CANT.

BS 000-00-20

D 82-05-50 82-05-34

BS 180-00-18

R 202-05-47 82-05-29 82-05-325

BS 60-20-30

D 142-25-58 82-05-28

BS 240-20-28

R 322-25-54 82-05-20 82-05-27 82-05-30

DISTO BS FS

FT 1507.90 473.17


M 459.609 144.833

DLC
LE 7 NIKON

7:30

8 SEPT 00

9



10

LE-3


A	LE3-07-82				
B5	LE3-08-80				
FS	LE2-A-53	(K-4			
B50	000-00-20				
0	90-17-36	90-17-16			
B50	180-00-13				
0	270-17-21	90-17-08	90-17-12		
DISTO	B5	FS			
ET	475.17	132.08			
M1	144.833	40.257			

DLC
CFE X NIKUN

T-85°

10

83 SEPT 00



11

LE-3

X LE3-08-81

B5 LE3-07-78

FS LE3-1-83

FS LE3-1-84

B5 000-00-20

B3 178-19-25

B4 272-36-27

B5 180-00-13

B5 358-19-23

B5 92-36-30

B5 60-20-30

B3 238-39-37

B4 332-50-45

B5 290-20-24

B5 58-39-33

B5 152-56-42

B5 1332-58

B5 1324-88

B5 400.111

B5 403.823

B5 140.461

B5 178-19-09

B5 178-19-08

B5 178-19-08

B5 178-19-08

B5 178-19-08

B5 178-19-08


B5 178-19-08

BO SET 2" AT C 283407 75' N. 1" N. 1" E. 1" M
 (GROUND LINE ON 1/8 LINE FENCE)
 BO SET 50' 15' N. 1" N. 1" E. 1" M
 (3' E. OF E. WALL LINE) CHURCH EX. OFFIC.

DLC
CFC X NIKON

8 SEET 00

11



12

LE-3

RC
LE T NIKEN

T-85°

12
3 SEPT 00

T LE3-11-84

BS LE3-08-81

ES LE2-18-52 CL-4

BSD 600-00-20

D 132-34-57 132-34-37


BSQ 180-00-24

P 312-34-53 132-34-09 132-34-23

DISTIE BS ES

FT 526.51 71.67

M 100.482 21.844



13

LE-3

DL
CEE T NILON

13

LE3-11-83

BS LE3-08-81

FS LE3-13-85

BSD 100-00-20

P 184-53-49

BSR 180-00-13

R 004-53-51

BSD 100-20-30

P 245-13-54

BSR 240-00-17

R 14-14-00

BS

FS

ET 1324.88

M 403.524

AP SET TO BIC 23409 (2 E COM WALKIE)

TOP OF CURVE AT PRESS. WALKIE

184-53-29

184-53-38

184-53-35

184-53-32

184-53-31

184-53-30

184-53-29

184-53-28

184-53-27

184-53-26

184-53-25

184-53-24

184-53-23

184-53-22

184-53-21

184-53-20

184-53-19

184-53-18

184-53-17

184-53-16


184-53-15

184-53-14


184-53-13

184-53-12

184-53-11



14

[illegible]

15

LE-3

DL
LE T NILON

15
8 SEPT 00

LE2-18-51

LE3-13-85

LE2-17-50 (m-5)

100-00-20

178-17-20 178-17-00

180-00-05

358-17-14 178-17-09 178-17-045

238-37-28 178-16-58


240-20-18

58-37-20 178-17-08 178-17-03 178-17-04

DISTIC BS ES

FT 724.33 2445.37

M 214.680 826.310



16

LE-3

DL

T

16

8 SEP 00

X LE2-17-50

B5 LE2-18-51

FS LE3-16-80 (RP SET 4E B5C will describe Trav. in 2001)

B5D 000-00-20

D 180-00-01 179-59-41

B5R 180-00-14

R 359-59-58 179-59-44 179-59-425

B5D 00-20-30

D 240-19-52 179-59-22

B5R 240-20-23

R 00-19-45 179-59-22 179-59-22 179-59-32

DKIT6 B5 - FS

ET 2045.37 1639.80

M1 800.311 499.813

1/4 Line Fence

Wd Rd.

Rail road

0 50

886

W.Bd II-96

E.Bd II-96

17

LE 3

Ingham Co	Remedy Contract	2000
ESGER Surveying & Engineering	-	ESE
DAVE CLIFFORD	PS 25837	- DIC
COE EMANS	Surv. Tech	- CFE
Nikon Total Station	-	NIL
BSC	- Bar 3" Cap.	
SUN = Sam Norde	Surv. Tech	
BSC = 1/2" x 1/8" Smooth Bar 7 CAP		
28409 unless otherwise noted		
NT = 1 1/4" Alum. Tag PS 25835	\$200	
Grav. Spic unless otherwise		
NOTED		