

22

103

M-1

Field Investigation

M-1

Shomasse Co. C. I. Mon

N 1/2 S. Side 60' Ground

1/2" BGL "Landmark" 24622

N 1/2 S. Side Utility Pole

N 1/2 S. Side 6" X 6" Wood Post

90°

93°

828°

318°

137.36

32.73

261.18

51.48

DLC

ASQ T.N.K

770°

14 Jun 02

22

M-2

Field investigation of apparent location of corner revealed a 4" concrete monument 2' North of 2' East of 4" intersection of Kerning Ave and Seber Rd. on Fence Line To The West. A 1/2" Bor 3" Cap. #25832 Bryan" was found 3.0' South of monument. A 1/2" Bor 3" Cap #31603 was found 0.95' North of monument. This surveyor is positive that M-2 locate was used as A-2 Company in 1914 by Dunning and that monument has the proper position for corner.

Mon 1/2 keeps Tag SE Side 4th Rd N 30° E 49.53

1" I.D. Pipe 5505 40.85

N 1/2 28409 N. Side 8" Walnut 5505 40.85

N 1/2 28409 SW Side 14" Hick. 5505 40.85

23

M-3.

L03

Dec
JUL

1850

3 Aug 02

23

M-4

B. Field investigation of apparent location of corner revealed a 1/2" Bar in Conc Mon E.E. of d. Herring for Rd on Enc. Line West, 0.7' North of another conc. mark, at R-4 T4N R3E Accepted Mon. as perpetuation of corner based on 1999 excavation and capped it with 2 1/4 Alum. Cap.

C. 1/2" Bar in Conc Mon w/ 2 1/4" Alum Cap
 N57 28409 E. Side 5" Maple 515' W 8400'
 N57 28409 S. Side 5" Board 580' W 2962'
 N57 28409 N Side 6" Oak 1739' W 2115'
 N47 28409 N. Side 12" Oak 1500' W 2178'
 1/2" Bar in Conc Mon (AUTUMN 3E) 540' E 0.70

24 DLG JLC

19 Sep 02

10-3

L-1

B. Field investigation of apparent location of corner revealed a cast iron mon. (L-13 TSN, RECI 82 West of fence to South, A 1/2" Bar 3/4 Cap (Byron 35032) Was found 32.6' West of Fence to South. RECALCED Rayner's 1867 Survey and Set STANDARD Bar 3/4 Cap at N. END of Fence which has corner posts at Rayner's projected distance Short Dist To M-1 is APPROXIMATED TO Rayner's STANDARD 10 Deflection at East My Corner of Section 1

C					
NIT 28409 S.S. side	24" Iron Oak	N85°E	310.50		
NIT 28409 N.S. side	48" Oak	S85°E	180.07		
NIT 28409 NE Side	UTL Pole	S38°E	226.55		
NIT 28409 White Tag W.S. side	Iron Post	S30°E	35.05		
NIT 28409 E.S. side	To 14" Wbl.	S49°W	36.56		
CAST Iron Measurement (L-13 TSN RECI)	26.9°	81.76'			

DLG JLC

7980

14 Oct 02

24

L-2

B. Field investigation of apparent location of corner revealed a 6" Spike W/Cap 25032 on South Bank Drain on Fence line North and South. Traverse of Section revealed that Spike was 15.65' South of E-W 1/4 line. Set STANDARD 3/4" Bar 3/4 Alum Cap. on E-W 1/4 line on North-South line. Corner Falls in E. East-West Drain. Returned on 14 Oct 4 Set Mon in place of Spt 660 S. of Section 3/4" x 24" Bar w/ 3/4" Alum Cap on 2 1/4" Alum E. Post in E. Drain 15' E. of 15" E. end 5000 24.95 NIT 28409 N.S. side 15" E. end 5000 24.95 NIT 28409 S.S. side 15" E. end 5000 24.95 NIT 28409 W.S. side 36" Ground S. side 44.76 NIT 28409 W.S. side 36" Ground S. side 44.76 Spike 3/4" Cap 26.832 55.44 15.05 NIT 28409 N.S. side 24" Ground S. side 20.00 NIT 28409 S.S. side 15" E. end West 34.47 Mon. 15 15.6' S. 1.2' E. of intersection. 1/4 LINES

25

10-3

L-3

B. Field investigation at apparent location of corner revealed a $\frac{1}{2}$ " Bar Stap 25832 in East-West Fence 33' West of d Wolf Creek Drain. Measured East 24' - To Tangent of Drain & To South. as the Drain Survey calls for. Accepted Bar Stap as perpendicular of corner and replaced it with STAND BAR & Cap.

C.

$\frac{3}{4}$ " x 24" STEEL BAR & ALUM. CAP.
 NIT 28409 N.S. Side 1' Dia. Fence Post West 2.08
 2" Dia STEEL PIPE FENCE POST EAST 4.80
 NIT 28409 N.S. Side FENCE POST WEST 14.00
 NIT 25032 N.S. Side FENCE POST WEST 175.80
 NIT 25832 S. Side FENCE POST EAST 69.20

DUE

W.F.N. 1

7800

14 OCT 02 35

L-4

B. Field INVESTIGATION at apparent location of corner revealed a 3" STEEL POST in Conc. Base on Top Bank of Au E-W Drain 125 South and 10' East of an AXLE SHAFT. Fence Corner with Fence going West. At 3' Post 15 12 S & 6 E. of intersection $\frac{1}{4}$ Lines & The other corner is there also. did not Accept it as Cen. Sec. Set Center 12.25 N & 6.33 W. of 3" POST, which puts it 4' E. of AXLE SHAFT Fence Cor & On Fence To West

C. $\frac{3}{4}$ " x 24" STEEL BAR & ALUM. CAP.

d. W. Side 3" STEEL POST in Conc 535 E 1320
 & AXLE SHAFT FENCE COR 585 W 4.00
 NIT 28409 E. Side 8" RIDER N 20 W 10.65
 NIT 28409 N.S. Side 10" RIDER S 80 E 15.70
 INTERSECTION $\frac{1}{4}$ Lines SET $\frac{3}{4}$ " BAR & ALUM. CAP.

AXLE SHAFT - 12.25'

FENCE POST

3" STEEL POST

26 D.C. T650 OCT 14, 02

K-1

B. Field Investigation at opponent location of corner revealed a

1/2" I.D. Pipe on centerline located by

Matching all Boss with 5545.

Pipe is 98.76 East of EAST Iron

Monument at K-13 TSN/R2E

Further investigation revealed

Rebbs Beam Puller Blade

with a 1/2" B&C 24622 Next

to IT. 3' N80°W of 1/2" Pipe

EXCAVATED Both sites and

found no further indications

of corner. Accepted Beam

Puller Blade as perpetuation

of corner, & AMENDED POSITION.

TO STANDARD Line

C. 3/4" x 24" Bead Alum. Cap

NST 28409 N.E. Side 35" OAK 575°E 36.35'

NST 25832 East Side 14" OAK SOUTH 28.15'

NST 25832 East Side 23" OAK 535°W 29.05'

W4" x 4" Post N75°E 48.50'

W2" Pipe (K-1) As recorded L29.11' N40°E 3.31'

3/8" B&C & Beam Puller Blade (K-1) N40°W 3.31'

4" Co. I. Mon "K-13 TSN/R2E 509° & 2' W 96.61'

D.C. T750 3 Aug 02 26

K-2

B. Field Investigation at Apparent location of corner revealed a 1/2"

Bar & Cap 13574 on South Side of

Bridge, 13' S. of & Road & East

of & McCrea County Drain.

As this iron is not at fence

corner as called for in LCR

(There is no true corner anywhere

around here) Did not accept

position. Set corner on &

N-S Drain 33' S. of F.I. as called

for in Drain Description. Corner

falls 2' North of & Jacobs Rd.

C. 3/4" x 24" Steel Bar w/ 2 1/4" Alum. Cap

N.E. Cor Bridge Apartment N50°E 15.55'

NST 28409 S. Side 12" Twin Walnut N55°E 30.75'

S.E. Cor Bridge Apartment 540°E 19.10'

NST 28409 W. Side 15" Mult. Maple 510°W 23.38'

S.W. Cor Bridge Apartment 540°W 17.93'

N.W. Cor " " N50°W 16.05'

27

K-3

B. Field Investigation of apparent location of corner revealed a 1/2" BSC 25832 S.S. of & (Quar) Col by Rd on Accretion line to North. EXCAVATED 3' Diameter hole 3' Deep and found no further evidence of corner. Traverse to West Shows Box to B=10 same relationship to 1-3 & J-3 as Colkins had them in 1900. Accepted box as PRR restoration of corner and replaced W. th 3/4" Br. S.H.

C. 3/4" BSC Box of Alum Cap. N 18998 W. S. d. R.R. to Fence Post 25.62
 N 24022 S. S. d. Utl. Pole N 40E 32.95
 N 25832 N. S. d. Trip 12" Oak 568E 41.86
 N 25832 N. S. d. Dbl 14" Oak 545E 21.48
 N 25832 N. S. d. 20" Cottonwood 577W 91.40

DLC
NHR

7750

10 July 02

K-4

B. Field Investigation of apparent location of corner revealed a 1/2" Box BSC # 18998 (Fence) & West of West Edge B. at same in traverse Ed. A 3/4" Box in a Monument Box was found 0.60' NW of 1/2" BSC. EXCAVATED 3' D.R. hole 3' Deep and found stone under flake iron. Accepted stone & iron as representative of corner and replaced Box & Cap with STANDARD Box S.H. Set Mon. Box over Iron

C. 3/4" X 24" Steel Box of 2 1/4" Maple in Mon. Box.
 4 Trip 5" Maple N 65°E 87.40
 NW Cor. Lone Tree Post 581°E 51.83
 N 18988 NW S. d. Utl. Pole 536°W 117.55
 N 18334 W. S. d. Utl. Pole N 40°W 43.54

28

103

6 J-3

B. Field Investigation of apparent location of corner revealed a $\frac{1}{2}$ " Bar in Conc on Colby Rd. 15' West of E. corner Rd. @ Band. Accepted Mon. as perpetuation of corner and capped with standard Alum Cap.

Based on previous EXCAVATION

Set Mon Box 19 Sep 02

C.

NST 28409 E. Side Two 12" Alumg NOE 62.70
 " " " 12" Pine N150E 91.83
 " " S. Side 6" Pole N80E 61.19
 " " N. Side " " 553E 67.85
 NE Cor Conc Fnc. Post 548W 38.70
 S.E. Cor Fdw Hse N20W 63.85

DUE
MAR

T 750

10 July 02

28

I-3

B. Field Investigation of apparent location of corner revealed a $\frac{1}{2}$ " Bar in Conc. 2' South of E. Colby Road on Occupation Line to North of South. Accepted conc. Mon as perpetuation of corner based on previous excavation and capped it with standard Alum Cap.

C. Concrete monument with $\frac{1}{2}$ " Bar & $2\frac{1}{4}$ " Alum Cap stamped Indian County 23 355637
 NST 28409 S. Side 6" Quad Pole N85E 86.78
 " " " 2" Maple 5650E 59.32
 NW Cor Conc Cor Post 540E 31.82
 NST 28409 N. Side 2" Pole Post 570W & 4.25
 NST 28409 W. Side 8" Pole N11W 29.35

29

LO-3

K-1

Moved Standard Mon. To Position
of Bear Hitter Blade

DLG
CUM

7450

11 Nov 02

29

NST 2010⁹
N100E 4" x 4" Post

N110NE Side 3C" DAK

NST 2400E E. Side 14" DAK

NST 24032E Side 23" DAK

1/2" Pipe

Cost Iron Mon

N100E 47.09'

S150E 39.43'

South 31.50'

S30W 32.01'

S70E 2.51'

S87951' 38W 96.47'