

22

103

M-1

Field Investigation

M-1

Shawnee Co. C. I. Mon

N 1/2 W. Side 60' Ground

1/2" BqC "Landmark" 24022

N 1/2 E Side Utility Pole

N 1/2 E Side 6" X 6" Wood Post

9°

137.36

93°

32.73

228°

261.18

318°

51.48

DLC

770°

22

ASR T.N.K

14 Jun 02

M-2

Field investigation of a proposed location of corner revealed a 4" concrete monument 2' North of 2' East of 4" intersection being from and Suber Rd. on Force Line to The West, R 1/2" Box 3' Cap. #25832 Bryan" was found 3.0' South of monument. R 1/2" Box 3' Cap #31003 was found 0.95' North of monument. This surveyor is positive that M-2 lock was used as a 2' corner in 1914 by Dunning and that monument is the proper position for corner.

Mon 3' keels Tag SE Side Wm Rk N 30E 49.53
1" I.D. Pipe S 50E 40.185
N 1/2 28409 N Side 8" Walnut N 85W 38.02
N 1/2 28409 SW Side 14" Hick N 40W 61.30

23

M-3.

LO 3

DLC
JLL

7850

3 Aug 02

23

M-4

B. Field investigation of apparent location of corner revealed a 1/2" Bar in Conc. Mon. 2'E. of d. Huntington Rd. on Fire Line plat, 0.7' North of another conc. mark at R-4 T4N R3E Accepted Mon. as perpetuation of corner based on 1999 excavation and capped it with 2 1/4 Alum. Cap.

C. 1/2" Bar in Conc. Mon. w/ 2 1/4" Alum. Cap.
 OST 28409 E. Side 5" Maple S15°W 8400'
 N15T 28409 S. Side 5" Band S80°W 2962'
 N41T 28409 N Side 6" Oak N73°W 2115'
 N41T 28409 N.S. side 12" Oak N50°W 2178'
 1/2" Bar in Conc. Mon (A4T M3E) S 42° E 0.70

25

10-3

L-3

B. Field investigation at apparent location of corner revealed a $\frac{1}{2}$ " Bar Stake 25832 in East-West Fence 33' West of d Wolf Creek Drain. Measured East 24' - To Tangent of Drain & To South. as the Drain Survey calls for. Accepted Bar Stake as perpetuation of corner and replaced it with STAINLESS CORN.

C.

$\frac{3}{4}$ " x 24" STEEL BAR & ALUM. CORR.
 NIT 26409 N. Side 1' Dia FEN POST West 2.08
 2" Dia STEEL PIPE FEN POST East 4.85
 NIT 26409 N. Side FEN POST West 14.00
 NIT 25032 N. Side 1" Dia. Pole West 175.80
 NIT 25832 S. Side Fence Post East 69.20

DEC

WFM 1

7:00

14 OCT 02

25

L-4

B. Field INVESTIGATION at apparent location of corner revealed a 3" STEEL POST in Conc. Base on Top Bank of Au E-W Drain, 25 South and 10' East of an AXLE SHAFT. Fence Corner with Fence gains West As 3" POST 15 12 S & 6 E. of intersection $\frac{1}{4}$ Lines & The other Corn is there also. did not Accept it as Cen. Sec. Set Corner 12.25 N 63.33 W. of 3" POST, which puts it 4' E. of AXLE SHAFT Fence Cor & On Fence To West

A $\frac{3}{4}$ " x 24" STEEL BAR & ALUM. CORR.

d. W. Side 3" STEEL POST in Conc 535 E 13.20
 d. AXLE SHAFT FEN. COR 585 W 4.00
 NIT 26409 E. Side 8" AXLE N 20 W 10.65
 NIT 26409 N. Side 10" RIDER S 80 E 15.70
 INTERSECTION $\frac{1}{4}$ Lines Set $\frac{3}{4}$ " BAR & AL.

AXLE SHAFT - 12.25'

FENC. POST

3" STEEL POST

21

DLC T650
W5N OCT 14, 02

K-1

B Field Investigation of opponent
location of corner revealed a

1/2" I.D. Pipe on centerline located by Rd

Matching all Boss with 554's

Pipe is 98.76 East of East Iron

Monument at K-13 TSN/R22E

Further investigation revealed

Robbs Beam Puller Blade

with a 1/2" B&C 24622 Next

to IT 3' N80°W of 1/2" Pipe

EXCAVATED Both sides and

found no further indication

of corner. Accepted Beam

Puller Blade as perpetuation

of corner. Amended Position

TO STANDARD Line

C. 3/4" x 24" Steel Beam Alum Cap

NST 28409 N.E. Side 35" OAK 575°E 36.35'

NST 25832 East Side 14" OAK SOUTH 28.15'

NST 25832 East Side 23" OAK 535°W 29.05'

W4" x 4" Post N75°E 48.60'

W2" Pipe (K-1) As recorded L2g/M N40°E 3.34'

3/8" B&C Beam Puller Blade (K-1) N40°W 3.31'

4" Co I. Mon K-13 TSN/R22E 589° 52' W 96.61'

DLC
JNL

T750
3 Aug 02

26

K-2

B. Field Investigation of Opponent
location of corner revealed a 1/2"

Bar & Cap 13574 on South Side of

Bridge, 13' S. of & Road & East

of & McCreas County Drain.

As this man is not at Fence

Corner as called for in LCR

(There is no Fence Corner anywhere

around here) Did not accept

position. Set corner on &

N-S Drain 33' S. of F.I. as called

For in Drain Description. Corner

Falls 2' North of & Jacobs Rd.

C. 3/4" x 24" Steel Bar w/ 2 1/4" Alum Cap

N/E Cor Bridge Abutment N50E 15.55'

NST 28409 S. Side 12" Twin Walnut W55E 30.75'

S/E Cor Bridge Abutment 540E 19.10'

NST 28409 W. Side 15" White Maple S10W 23.38'

S/W Cor Bridge Abutment 540W 17.93'

N/W Cor " " N50W 16.05'

27

K-3

B. Field Investigation of apparent location of corner revealed a 1/2" B&C 25832 S.S. of & (ground) Col by Rd on Accretion line to North. EXCAVATED 3' Diameter hole 3' Deep and found no further evidence of corner. Traverse to West Shows B. to B=115 Same relationship to 1-3 & J-3 on Colkins had them in 1900. Accepted bar as Reproduction of corner and replaced with 3/4" B.S. AC

C. 3/4" B.S. 24" Bar S of Alum Cap. N5T 18998 W. S.S. of RR Tie Fence 25.62
 N5T 24622 S. S.S. of Line Pole N40E 37.95
 N5T 25832 N. S.S. of Trip. 12" OAK S68°E 41.86
 N5T 25832 N. S.S. of D6. 14" OAK S45°E 21.48
 N5T 25832 N. S.S. of 20" Cotwood S77°W 9.140

Dec
NHR

7750

10 July 02

K-4

B. Field investigation of apparent location of corner revealed a 1/2" Bar B&C # 18988 (fence) & West of West Edge B.T. at same in traverse Rd. A 3/4" Bar in Monument Box was found 0.60' NW of 1/2" B&C. EXCAVATED 3' D.R. hole 3' Deep and found stone under file like iron. Accepted stone & iron as reproduction of corner and replaced Bar & Cap with STANDARD Bar S AC Set Mar. Box over iron

C. 3/4" X 24" Steel Bar S of 2 1/4" Maple in Mon Box. N65°E 87.40
 A Trip 5" Maple N65°E 87.40
 NW Cor Lone Tree Post S89°E 51.83
 N9T 18988 NW S.S. of Hill Pole S36°W 117.55
 N5T 19834 W. S.S. of Hill Pole N49°W 45.54

28

L03

6 J-3

B. Field Investigation of apparent location of corner revealed a $\frac{1}{2}$ " Bar in Conc on Q Colby Rd. 15' West of E. corner Rd. @ Bend. Accepted Mon. as perpendicular of corner and capped with standard Alum Cap.

Based on previous EXCAVATION

Ser Mon Box 19 Sep 02

C.

NST 28409 E. Side Two 12" Alumg NOE 62.70
 " " " 12" Pine N150E 91.83
 " " S. Side 4" ALK Pole N800E 61.19
 " " " " " 553E 67.85
 NE Cor Conc FINE. Post 54" 38.70
 S.E. Cor F.W. Hse N209W 63.85

DUE
MAR

T 750

10 July 02

28

I-3

B. Field Investigation of apparent location of corner revealed a $\frac{1}{2}$ " Bar in Conc. 2' South of E. Colby Road on Decimation Line to North of Box 19. Accepted corner as perpendicular of corner. Based on previous excavation and capped it with standard Alum Cap.

C. Concrete monument with $\frac{1}{2}$ " Bar 2 1/4"
 Alum Cap Stripped Ingle County 23 7525037
 NST 28409 S. Side 6" Quad Maple N850E 86.78
 " " " 2 1/2" Maple 5650E 59.32
 NW Cor Conc Cor Post 54" 31.82
 NST 28409 N. Side 4" ALK Pole N800E 61.19
 NST 28409 W. Side 8" ALK Pole N119W 29.35

29

LO-3

K-1

MOVED STANDARDS Mon. To Position
of Bear Hitter Blade

NST 20709	NW Cor 4" x 4" Post	N70°E	47.09'
NST 10009	NE Side 3C" DAK	S15°E	39.43'
NST 4687	E. Side 14" DAK	South	31.50'
NST 25032	E. Side 23" DAK	S30°W	32.01'
1/2" Pipe		S72°E	2.51'
Cost Iron Mon		S87°S1'38"W	96.47'

DLC
C/M

7450

11 Nov 02

29