

Land Surveying & Related Services
P.O. Box 141, DeWitt, MI 48820
Phone 517-669-3640 Fax 517-669-6521

Description: LOCKE TWP


Description: 1/4 COR BETWEEN SEC. 33 & 34

Field Crew: _____ Date: 4/2/97

Computed:

Disk:

Job:



SEPT. 29, 1939

Dr. Henderson
Sept 29, '39.


NE 1/4 Sec 1

$N \frac{1}{2}$ $W \frac{1}{2}$ SE $\frac{1}{4}$ Dec 3
 T3 N R 2 E.

Double mast
new owner.

435605 4239204
3920404
309804
304920

$\begin{array}{r} 978 \\ \times 8965 \\ \hline 165 \\ 115945 \\ \hline 165 \\ 115945 \\ \hline 165 \\ 115945 \\ \hline 165 \\ 115945 \\ \hline \end{array}$	$\begin{array}{r} 11737 \\ \times 95 \\ \hline 51 \\ \hline 1883 \\ \hline 1894.5 \\ 1324.5 \\ \hline 1307.5 \end{array}$
---	---

$$\begin{array}{r} 2 \overline{) 6409.5} \\ \underline{3204.7} \\ 13.20 \end{array}$$
$$\begin{array}{r} 640940 \\ 56141 \\ 32047 \\ \hline 4230204P \end{array}$$


DID NOT FIND DRG. OR WIT.

④

CORNER EXCAVATION REPORT

TECH. SUP'R. R. LESTER TOWNSHIP LEROY
 COMPANY POLARIS CORNER CODE I-1
 FIELD SQUAD FLNT PAGE 1 OF 1 DATE 7-24-80

EXCAVATED AREA: 6x10 60 SQ. FT.; AVG. DEPTH 2.0 SURFACE ASP

ketch and describe roads, monuments found or set, and witnesses established:



EXC. EAST 6'x10' OF SITE. FOUND 1/2" REBAR
 NEAR SURFACE, REMOVED AND ONLY FOUND 11".
 LEAD PIPE 2' IN LENGTH. 1/2" REBAR WAS
 DRIVEN DOWN INSIDE PIPE. NO OTHER
 EVIDENCE FOUND.



FD PIPE


ALLEN PD

*we are
 finished
 with this
 corner - no
 evidence found to
 conflict with corner recorder
 in L2P525
 RL 8/6/80*

WEAVERVILLE

WITNESS FOR FIRE

PK NORTH 6.85,
 " SOUTH 2.91
 " WEST 10.71
 3-20-78; Fld. Form No. 4b



RESEARCH COMPLETED	date	Total	Total		
REMARKS					
NOTHSTINE NOTES		N.D.		MARTIN	LALONDE
FOLDER #1 PAGE 55		5	1	↓	↓
FOLDER #2 PAGE 44		6	2	↓	↓