

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Liber 9 Page 438

For corners in

INGHAM COUNTY
Meridian Township

Located In:

Corner Code #

1. Public Land Survey T 4N R 1W E-1
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

FILED

980061027
12/01/1998 10:31:04
REGISTER OF DEEDS
Paula Johnson
INGHAM COUNTY, MI

Register of Deeds Stamp & File Number

I, Larry A. Bryan, in a field survey on October 28, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1). 02-04-1827: U. S. Public Land Survey Field Notes, Deputy Surveyor Musgrove Evans "At 79.10 chains, intersected North boundary 37 links East of post, corner of Sections 32 & 33, T5N, R1W and set post, corner to Sections 4 & 5 from which: Aspen 6 in. S11W 31 lks., Aspen 5" S53E 11 lks."
- 2). 07-15-1847: Record of Surveys, Vol. 2, Page 13, County Surveyor Anson Jackson notes the U. S. witnesses: "Aspin 6 S12-1/2W 31 lks., do. 5 S53E 11 lks."
- 3). 05-09-1848: Record of Surveys, Vol. 2, Page 65, County Surveyor Anson Jackson again notes the U. S. witnesses: "Aspin 6 in. S_W 31 lks., do. 5 S53E 11 lks."
- 4). 12-23-1974: Land Corner Recordation Certificate for E-13, T5N, R1W (Rec. 2-27-75, L1-P907, Clinton County Records), M. F. Fouty, P.S. 18989, states "Found 3/4" pipe at the base of an old anchor post at intersection of old fencelines North, East and West. Records of eight area surveyors disclosed no additional evidence; tag and nail South side 16" tree ENE 2.55', tag and nail South side 6" tree WSW 5.02', tag and nail East side 8" Oak South 27.20'."

(Continued on back)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" iron bar and cap #18989 in good condition at Northeast base of 14" Ash with fence remnants running East and West as called for in Item 5 above, other witnesses gone. Accepted bar and cap as the best evidence of the location of this corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Left 1/2" iron bar and cap #18989 in place as found to mark the corner and took the following witnesses:

Found 3/4" iron pipe (E-13, T5N, R1W) West 24.52 feet (Rec. 37 lks. = 24.42')
Set nail and tag #25832 in North side 16" Ash S80°E 13.79 feet
Set nail and tag #25832 in East side 16" Ash N30°W 15.12 feet
Set nail and tag #25832 in East side 18" Hickory North 53.45 feet

Signed by Larry A. Bryan
Surveyor's Michigan License No. 25832

Date November 16, 1998



P.A. 345 INGHAM COUNTY
PEER APPROVED 11/19/98

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

E-1, T4N, R1W

Part A - Continued

- 5). 12-23-1974: Land Corner Recordation Certificate (Rec. 2-27-75, L3-P345), M. F. Fouty, P.S. 18989, states "Set 1/2" bar and cap on Township line at intersection of old fences South, East and West in close accord with original government measure. Records of eight area surveyors disclosed no additional evidence; tag and nail North side 14" tree ESE 13.70', tag and nail East side 14" tree NNW 15.60', tag and nail East side 14" tree South 0.95'."
- 6). 01-09-1975: Certified Survey Map (Rec. 02-27-75, L2-P312), M. F. Fouty, notes the same monument and witnesses as Item 4 above. He shows E-1, T4N, R1W East of E-13, T5N, R1W, but does not give the distance between them. He also gives a distance of 2662.38 feet from E-1 to D-1.
- 7). 03-14-1983: Certified Survey Map (Rec. 08-09-83, L4-P743), J. A. Porter, P.S. 19003 shows this corner, but gives no monument description nor witnesses. He shows E-1, T4N, R1W East of E-13, T5N, R1W, and gives 24.42 feet (37 lks.) as the distance between them. He also gives distances of 2713.46 feet from E-1 to F-1, and 2580.96 feet from E-1 to E-2 (Rec. 39.10 chains = 2580.6 feet).
- 8). 01-25-1988: Whitehills Woods, Liber 42 of Plats, Page 45, J. A. Porter notes "NE Corner, Section 5, T4N, R1W, Meridian Twp., Ingham Co., Mich." He also gives distances of 2661.25 feet from E-1 to D-1, and 2582.98 feet from E-1 to E-2 (Rec. 39.10 chains = 2580.6 feet).
- 9). 06-28-1988: Whitehills Lakes Subdivision No. 4, Liber 43 of Plats, Page 27, J. A. Porter notes "NE Corner, Section 5, T4N, R1W, Meridian Twp., Ingham Co., Mich." He also gives a distance of 2661.24 feet from E-1 to D-1.
- 10). 02-02-1990: Whitehills Woods No. 2, Liber 45 of Plats, Page 37, J. A. Porter notes "NW Corner, Section 4, T4N, R1W, Meridian Twp., Ingham Co., MI., Liber 3, Pg. 345". He also gives distances of 2661.25 feet from E-1 to D-1, 2582.98 feet from E-1 to E-2 (Rec. 39.10 chains = 2580.6 feet), and 2639.39 feet from E-1 to F-13, T5N, R1W.

INFORMATION
RECORDS
SECTION 5, T4N, R1W
MERIDIAN TWP., INGHAM CO., MICH.
1990/02/02
J. A. PORTER
P.S. 19003

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Liber 9 Page 440

For corners in

INGHAM COUNTY
Meridian Township

Located In:

Corner Code #

1. Public Land Survey T 4N R 1W E-2
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

FILED

980061028
12/01/1998 10:31:05
REGISTER OF DEEDS
Paula Johnson
INGHAM COUNTY, MI

Register of Deeds Stamp & File Number

I, Larry A. Bryan, in a field survey on October 28, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 02-04-1827: U. S. Public Land Survey Field Notes, Deputy Surveyor Musgrove Evans "set 1/4 Sec. Post from which 14" Aspen S24°W 35 links and 3" W. Oak S49°E 40 links.
- 07-15-1847: Record of Surveys, Vol. 2, Page 13, County Surveyor Anson Jackson notes the U. S. bearing trees for this corner.
- 05-09-1848: Record of Surveys, Vol. 2, Page 65, County Surveyor Anson Jackson again notes the U. S. bearing trees for this corner.
- 12-23-1974: Land Corner Recordation Certificate (Rec. 2-27-75, L3-347), M. F. Fouty, P.S. 18989, states "Set 1/2" bar and cap at fence intersection, fences North, South, and West. Measurements North and South in close accord with original government measure. Records of eight area Registered Land Surveyors disclosed no additional information of the corner. Tag and nail S. side 12" anchor post SE 0.50', tag and nail SW side 16" Poplar SE 23.85', Tag & nail S side 6" Oak E 24.80'."
- 01-09-1975: Certified Survey Map (Rec. 2-27-75, L2-P312), M. F. Fouty gives the same monument and witnesses as Item 4 above. He also gives a distance of 2701.07 feet from E-2 to D-2.

(Continued on back)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" iron bar with cap #18989 in good condition 0.3' West of wood anchor post as called for in Item A.4 above. Old fence wire running East, West, and South. Accepted bar and cap as the best evidence of the location of this corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Left 1/2" iron bar with cap #18989 in place as found to mark the corner and took the following witnesses:

Found nail and flagging Southeast side 16" Oak S45°E 23.73 feet
Found nail and tag #25832 west side Fence Post South 9.91 feet
Found nail and tag #25832 East side 30" Oak S05°W 51.96 feet
Found nail and tag #25832 Southwest side 12" Oak S40°E 36.01 feet
Set nail and tag #25832 South side 12" Ash N60°W 23.75 feet

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5	4			3		2		1	
3													
4	7			8	9			10		11		12	
5													
6	18			17	16			15		14		13	
7													
8	19			20	21			22		23		24	
9													
10	30			29	28			27		26		25	
11													
12	31			32	33			34		35		36	
13													

Signed by Larry A. Bryan

Date November 13, 1998

Surveyor's Michigan License No. 25832



P.A. 345 INGHAM COUNTY
PEER APPROVED 11/19/98

E-2, T4N, R1W

Part A - Continued

- 6). 12-20-1975: Certified Survey Map (Rec. 9-28-75, L3-542), F. N. White, P.S. 12034, notes "East 1/4 Corner Section 5, T4N, R1W, Liber 3, Pg. 347."
- 7). 12-30-1975: Certified Survey Map (Rec. 12-01-76, L2-P951), F. N. White notes "East 1/4 Corner Section 5, T4N, R1W, Liber 3, Pg. 347."
- 8). 03-14-1983: Certified Survey Maps (Rec. 8-09-83, L4-P743), J. A. Porter, P.S. 19003, shows this corner, but gives no monument description nor witnesses. He gives distances of 2662.83 feet from E-2 to F-2, and 2580.96 feet from E-2 to E-1 (Rec. 39.10 chains=2580.6 feet).
- 9). 02-11-1985: Whitehills Lakes Subdivision, Liber 39 of Plats, Page 13, J. A. Porter notes "E. 1/4 Corner Section 5, T4N, R1W, Meridian Township, Ingham County, Michigan".
- 10). 10-08-1986: Whitehills Lakes Subdivision No. 2, Liber 40 of Plats, Page 48, J. A. Porter notes "E. 1/4 Corner Section 5, T4N, R1W, Meridian Township, Ingham County, Mich." He also shows a distance of 2700.93 feet from E-2 to D-2.
- 11). 11-19-1986: Certified Survey Map (Rec. 5-12-94, L7-P183), L. A. Bryan, P.S. 25832, notes "East 1/4 Corner Section 5, T4N, R1W. Found 1/2" bar & cap #18989 West side corner post. Fences North, South, East & West, Liber 3, Page 347. Found nail & tag West side fence post, South, 9.86'; found nail & tag in South side 10" Elm, S85°W, 14.57'; found nail & tag Southwest side 18" Maple S45°E, 23.64'." He also shows a distance of 2699.64 feet from E-2 to D-2.
- 12). 09-01-1987: Whitehills Lakes Subdivision No. 3, Liber 42 of Plats, Page 19, J. A. Porter notes "E. 1/4 Corner Section 5, T4N, R1W, Meridian Township, Ingham County, Mich." He also shows a distance of 2700.93 feet from E-2 to D-2.
- 13). 01-25-1988: Whitehills Woods, Liber 42 of Plats, Page 45, J. A. Porter notes "E. 1/4 Corner Sec. 5, T4N, R1W, Meridian Twp., Ingham Co., Mich." He also shows a distance of 2582.98 feet from E-2 to E-1 (Rec. 39.10 chains=2580.6 feet)
- 14). 02-02-1990: Whitehills Woods No. 2, Liber 45 of Plats, Page 37, J. A. Porter notes "W. 1/4 Corner Section 4, T4N, R1W, Meridian Twp., Ingham Co., MI. Liber 3, Pg. 347." He also shows a distance of 2582.98 feet from E-2 to E-1 (Rec. 39.10 chains=2580.6 feet).
- 15). 10-08-1992: Whitehills Lakes No. 5, Liber 47 of Plats, Page 33, J. A. Porter notes "East 1/4 Corner Section 5, T4N, R1W, Meridian Twp., Ingham Co., Michigan, Liber 3, Page 347." He also shows distances of 2647.24 feet from E-2 to E-3, and 2700.93 feet from E-2 to D-2.

INCHON COTILLA AT
 1997 10/08/92
 RECEIVED DE DEEDS
 10/08/92 10:37:02
 10/08/92
 10/08/92
 10/08/92

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Liber

9 Page 442

For corners in

INGHAM COUNTY
Meridian Township

Located In:

Corner Code #

1. Public Land Survey T 4N R 1W E-3
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

FILED

980061029
12/01/1998 10:31:07
REGISTER OF DEEDS
Paula Johnson
INGHAM COUNTY, MI

Register of Deeds Stamp & File Number

I, Larry A. Bryan, in a field survey on October 28, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1). 02-04-1827: U. S. Public Land Survey Field Notes, Deputy Surveyor Musgrove Evans "set post, corner of Sections 4, 5, 8 & 9 from which B. Oak 22" S30°E 47 links and W. Oak 20" N28°E 14 links." The County Surveyor's copy of the U. S. Notes has a marginal note: S.E. Corner School House N53°W 153 lks. I find no mention of this corner in the County Surveyors Records.

2) Date Unknown: Old County Road Commission Corner Grid Sheet calls for "Pointed stone - axle shaft; SE Cor. Sch. Porch 59.0' N.W., Conc. Anch. Post 30.0' S., 30" Oak 87.67' WNW, Yew 58.72' N., Power Pole 49.94' WSW"

3). 12-20-1971: Land Corner Recordation Certificate (Rec.6-26-72, L1-587), J. E. Stephens, P.S. 16053, states "An iron bolt was found in a monument box in the centerline of the section line road (Lake Lansing Road) and on a projection of an old fence north of the corner; witnessed by survey tags in three utility poles: N65°43'W 106.28 feet, N37°54'W 53.23 feet, S82°12'W 176.20 feet."

(Continued on back)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron bolt in monument box 2.5' East of centerline Westbound Old Hwy. M-78/Business Route I-69 as called for in Item 3 above. Accepted bolt in monument box as the best evidence of the location of this corner, replaced it with a standard Ingham County Remonumentation bar and cap.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" smooth iron bar and 2-1/2" aluminum cap stamped "P. A. 345, 25832, Ingham County" in the monument box, and took the following witnesses:

Found nail and Stephens Engineering tag in South side Utility Pole N65°W 106.30 feet
Found nail and Stephens Engineering tag in Southwest side Utility Pole N40°W 53.35 feet
Found nail and tag #30087 in North side Utility Pole S80°W 184.33 feet
Found nail and tag #25832 in Southwest side Utility Pole S45°E 61.53 feet

P.A. 345 INGHAM COUNTY
PEER APPROVED 11/19/98



Signed by Larry A. Bryan
Surveyor's Michigan License No. 25832

Date November 18, 1998

E-3, T4N, R1W

Part A - Continued

- 4). 01-01-1972: County Road Commission Corner Grid Sheet calls for a monument box at this corner.
- 5). 10-08-1975: Certified Survey Map (Rec. 12-01-76, L2-P954), F. N. White, P.S. 12034 notes "SE Cor. Sec. 5, T4N, R1W (Liber 1, Pg. 587, I.C.R.)"
- 6). 12-20-1975: Certified Survey Map (Rec. 9-28-75, L3-542), F. N. White, P.S. 12034, notes "SE Cor. Sec. 5, T4N, R1W, (Liber 1, Pg. 587)."
- 7). 12-30-1975: Certified Survey Map (Rec. 12-01-76, L2-P951), F. N. White notes "SE Cor. Sec. 5, T4N, R1W, (Liber 1, Pg. 587)."
- 8). 03-09-1978: Certified Survey Map (Rec. 05-04-78, L3-P316), Ron Helsel, P.S. 18994 notes "SE Cor. Sec. 5, T4N, R1W, (Liber 1, Pg. 587)."
- 9). 03-07-1979: Certified Survey Map (Rec. 06-25-79, L3-P905), Ron Helsel notes "SE Cor. Sec. 5, T4N, R1W, (Liber 1, Pg. 587)."
- 10). 07-24-1980: Land Corner Recordation Certificate (Rec. 1-08-81, L6-134), H. L. Fluharty, P.S. 16223, states "Found spike in mon. box on E-W C/L of Lake Lansing Road & 2.5' E. of N-S C/L Southbound lanes; P.P. S15°E, 61.55', P.P. N38°W 53.20'."
- 11). 06-11-1981: Certified Survey Map (Rec. 07-29-81, L4-P345), F. N. White notes "SE Cor. Sec. 5, T4N, R1W, (Liber 1, Pg. 587)."
- 12). 03-14-1983: Certified Survey Maps (Rec. 8-09-83, L4-P743), J. A. Porter, P.S. 19003, shows this corner, but gives no monument description nor witnesses. He gives a distance of 2647.24 feet from E-3 to E-2.
- 13). 10-01-1987: Certified Survey Map (Rec. 01-14-88, L5-P390), H. J. Hanes, P.S. 5260 notes "SE Cor. Sec. 5", but gives no monument description nor witnesses.
- 14). 10-08-1992: Whitehills Lakes No. 5, Liber 47 of Plats, Page 33, J. A. Porter notes "SE Corner Section 5, T4N - R1W, Meridian Twp., Ingham Co., Michigan, Liber 6, Page 134." He also shows a distance of 2647.24 feet from E-3 to E-2.
- 15). 09-25-1997: Certified Survey Map (Rec. 06-30-98, L8-P254), T. L. Laakso, P.S. 30087 notes "Southeast Corner Section 5, T4N, R1W (E-3) recorded in Liber 6, P134. Found 1" iron in monument box. N65°E 128.14', Found nail and tag #25832, Northwest side guy pole for signals; S17°E 61.56', Found nail and shiner, Southwest side guy pole for signals; S79°W 184.26', Set nail and tag #30087, North side power pole; N38°W 53.39', set nail and tag #30087, South side guy pole for signals".
- 16). 03-05-1998: Land Corner Recordation Certificate (Rec. 05-05-98, L9-321), J. K. Autenrieth, P.S. 31588, states "E-3, T4N, R1W: Found bolt in monument box in centerline Lake Lansing Road and West bound M-78/Business I-69. Found nail and tag #16053 in South side utility pole, N65°W, 106.30'; found nail and tag #16053 in Southwest side utility pole, N40°W, 53.35'; found nail and tag #30067 in North side utility pole, S50°W, 184.33'; found nail and tag in Southwest side utility pole, S45°E, 61.53'."

INGHAM COUNTY
 LAND RECORDS
 VERIFIED BY DEED
 15/04/2009 10:11 AM
 00001051

44 50

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Meridian Township

INGHAM
(County)

Located In:

Corner Code #

1. Public Land Survey

T 4N R 1W

F-01

2. Property Controlling
in Section

S
S

T
T

R
R

3. Miscellaneous
Property in Sec.

S
S

T
T

R
R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Gilbert M. Barish, in a field survey on June 10, 2004 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1) Corner not set in original government survey
- 2) 15-July-1847 Corner was referenced by A. Jackson, County surveyor, in a survey for Thompson. Distance from the Center of section 4 to the North 1/4 corner, 156 rods (2,574 feet) at a bearing of N3/4W. Witnesses: W Oak 16 West 17-1/2 lks, DO 26 S16-3/4W 16-1/2 lks
- 3) No corner references in the Ingham County Grid Sheets

Continued on page 2:

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-01: Found 1/2" steel bar lying +/- 0.50 feet North of an existing east and west fence line.
NAZ 306°, 18.67', Found nail and tag #18989 (Marvin Fouty) in the Southwest face of a 30" White Oak
NAZ 293°, 28.71', Found James Stephens nail and tag #16053 in the South face of a 24" White Oak
NAZ 270°, 10.18', Found nail and tag #13039 (Arden Pierson) in the North face of an anchor post
NAZ 270°, 75.11' Found Standard Clinton County Remonumentation Bar and Cap #13039 (Arden Pierson)
NAZ 236°, 7.39', Found KEBS nail and tag in the South face of a 9" White Oak

Searched at the apparent location of the corner and found 1/2" steel bar (no cap) +/- 0.50 feet north of an existing east and west fence line. Set offsets to the found point and removed the 1/2" steel bar and excavated a 3 feet diameter circle to a depth of 2.5 feet. Did not recover any additional evidence pertaining to the corner location. Accepted the found 1/2" steel bar as a faithful perpetuation of the corner and set a 3/4" x 24" steel bar on the standard township line 0.29 feet south of the found 1/2" steel bar. The township line was established by Dwight Schofield on 08-Dec-1993 for the Clinton County Remonumentation program and the information pertaining to the line is recorded in Liber 4 Page 329 of Corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-01: Set standard Ingham County 3/4" X 24" smooth steel bar and cap stamped "P.A. 345, PS 47942" on the standard township line. The point lies 0.29 feet south of an existing 1/2" steel bar (now removed). This point is 0.20 feet north an east and west fence line.

NAZ 003°, 48.94', Set nail and tag #47942 (Barish) in the West face of a 22" White Oak
NAZ 306°, 18.67', Found nail and tag #18989 (Marvin Fouty) in the Southwest face of a 30" White Oak
NAZ 293°, 28.71', Found James Stephens nail and tag #16053 in the South face of a 24" White Oak
NAZ 270°, 10.18', Found nail and tag #13039 (Arden Pierson) in the North face of an anchor post
NAZ 162°, 29.45', Set nail and tag #47942 (Barish) in the West face of a 26" Burr Oak
NAZ 270°, 75.11' Found Standard Clinton County Remonumentation Bar and Cap #13039 (Arden Pierson)
NAZ 236°, 7.39', Found KEBS nail and tag in the South face of a 9" White Oak

Signed by Albert M. Barish
Surveyor's Michigan License No. 47942

Date 03-Nov-2004

P.A. 345 INGHAM COUNTY
PEER APPROVED 10/12/2004

Paula Johnson-
INGHAM COUNTY
REGISTER OF DEEDS
OFFICIAL SEAL



L-11 P-285

CRNR 17.00

2004-072553



2004-072553
Page: 1 of 2

11/30/2004 08:07 A

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													



Part "A" Continued - North 1/4 Corner of Section 4 (F01), T4N, R1W, Ingham County, MI

- 4) Land Corner Recordation Certificate by Marvin F. Fouty, P.S. #18989 on 30-Aug-1976 as recorded in Liber 3 page 612 of corners.
Part "A" states: N 1/4 corner of Section 4 not set in original government survey. Could find no record of corner being established by the County Surveyor. The corner has been occupied in the past by a 3/4" pipe used in several adjacent surveys.
Part "B" states: Set 1/2" bar and cap by retracement of deed lines from recent survey by Surveyor Clyde Stephens
Part "C" states: 1/2" bar and cap N 1/4 corner of Section 4, T.4N, R1W
Tag in fence corner post W 10.94'
Tag in 18" Oak NW 18.15'
Tag in 20" Walnut SE 30.03'
- 5) Corner referenced in a recorded survey by Marvin F. Fouty, P.S. #18989 in Liber 2, Page 867 on 22-July-1976. "N 1/4 cor. Sec. 4, T4N, R1W, Set 1/2" bar and cap"
Witnesses (brass tags):
Fence Cor. Post W 10.94'
18" Oak NW 18.15'
20" Walnut SE 30.03'
Measured 2585.16 from the North 1/4 corner to the Center of Section 4.
- 6) Corner referenced in a recorded survey by James A. Porter, P.S. #19003 in Liber 4, Pages 743-750 on 14-March-1983. No witnesses recorded. No identification of the corner type. Measures West, 75.18 feet to the South 1/4 corner of Section 33, T5N, R1W, Clinton County
- 7) Corner referenced in an unrecorded survey by Larry A Bryan, P.S. #25832 in Job Number 96-B-52484 on 20-Sept-1996. "North 1/4 corner, Section 4, T4N, R1W as recorded in Liber 3, Page 612, (Item 4 above) found 1/2" bar and cap #18989.
Witnesses (brass tags):
Found nail and tag south side of 24" Maple N60°E, 39.50
Found nail and tag south side of 14" Maple N45°E, 41.99
Found nail and tag #39100 (Terry Wiegman) south side of an 8" Elm N30°E, 29.50
Measured 2606.73' from the North 1/4 corner to the Northeast corner of Section 4.
- 8) Corner referenced in an unrecorded survey by Larry A Bryan, P.S. #25832 in Job Number 96-B-51727 on 11-June-1996. Same information as Item 7 above.
- 9) Corner referenced in an unrecorded survey by Larry A Bryan, P.S. #25832 in Job Number 96-B-51352 on 25-Apr-1996. Same information as Item 7 above.
- 10) Corner referenced in an unrecorded survey by Larry A Bryan, P.S. #25832 in Job Number 96-B-51200 on 08-Apr-1996. Same information as Item 7 above.
- 11) Corner referenced in an unrecorded survey by Larry A Bryan, P.S. #25832 in Job Number 96-B-50875 on 28-Feb-1996. Same information as Item 7 above.
- 12) Corner referenced in the plat of Whitehills Woods No. 5 by Larry A. Bryan, P.S. #25832 on 15-Dec-1998. Corner is noted on the plat as follows:
"North 1/4 Corner of section 4, T5N, R1W, Clinton County, MI as recorded in Liber 2, page 859." Measurements to the Center of Section 4 also listed as T5N, R1W, Clinton County Records from the North 1/4 corner of Section 4 is 2580.50 feet. Distance appears to be 5'+/- different than Marvin Fouty's measurements in Item 5 above.
- 13) Land Corner Recordation Certificate by Arden S. Pierson, P.S. #13039 on 08-Sept-1999 as recorded in Liber 4 page 329 of Corners, Clinton County Records for the South 1/4 corner of Section 33, T5N, R1W.
Part "C" states: Found Iron - East- 75.14 feet



2004-072553

Page: 2 of 2

11/30/2004 08:07 A

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Meridian Township

INGHAM
(County)

Located In:

Corner Code #

1. Public Land Survey

T 4N

R 1W

F-02

T

R

T

R

T

R

T

R

T

R

T

R

2. Property Controlling
in Section

S

T

R

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

S

T

R

Paula Johnson-
INGHAM COUNTY
REGISTER OF DEEDS
OFFICIAL SEAL



L-11 P-287

CRNR 17.00

2004-072554

2004-072554

Page: 1 of 2

11/30/2004 08:07 A

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Gilbert M. Barish, in a field survey on June 10, 2004 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1) Corner not set in original government survey
- 2) 15-July-1847 Corner was referenced by A. Jackson, County surveyor, in a survey for Thompson. Distance from the North 1/4 Corner to the Center of Section 4, 156 rods (2,574 feet) at a bearing of N3/4W. Distance from the Center of Section 4 to the West 1/4 corner, 159 rods (2623.5 feet) Witnesses: y Oak 10 N37E 33 lks, w oak 8 S7E 13 lks
- 3) Corner referenced in the Ingham County Road Commission Grid sheet dated 1969, noted as a "1-1/2" axle shaft" Witnesses:
12" Boxelder W. 87.08'
P.P. W.N.W. 13.35'
T.P. S.E. 28.70'

Continued on page 2:

P.A. 345 INGHAM COUNTY
PEER APPROVED 11/02/2004 RL

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-02: Found 1/2" steel bar 4.8 feet west of the existing centerline of Newton Road

Field investigation at the apparent location of the corner revealed a 1/2" steel bar (no cap). Set offsets to the found point and removed the 1/2" steel bar and excavated a 1.5 feet diameter circle to a depth of 2.0 feet. Did not recover any additional evidence pertaining to the corner location. Accepted the found 1/2" steel bar as the center of section and set a 3/4" x 24" steel bar and cap stamped "P.A. 345, PS 47942". The perpetuated location lies 2.02 feet South and 3.36 feet East of the mathematical intersection of Section 4.

Distances: (F2-G2) - 2644.64 (F2-F1) - 2586.93 (F2-E2) - 2661.99' (F2-F3) - 2645.74

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-02: Set standard Ingham County 3/4" X 24" smooth steel bar and cap stamped "P.A. 345, PS 47942" at the location of the found 1/2" steel bar. The point lies 4.8 feet west of the existing centerline of Newton Road and 8" below the gravel surface.

NAZ 343°, 87.44', Set nail and tag #47942 (Barish) in the Northeast face of an 8" silver maple
NAZ 301°, 41.12', Found KEBS nail and tag in the North face of a 4" quad Boxelder
NAZ 270°, 33.42', Found 1/2" steel bar and cap (illegible)
NAZ 259°, 41.02', Found KEBS nail and tag in the North face of a 6" Honey Locust
NAZ 222°, 64.41', Found KEBS nail and tag in the North face of a 6" Honey Locust
NAZ 197°, 98.46' Found Clyde Stephens nail and tag #3829 in the North face of a utility pole
NAZ 151°, 70.87', Found KEBS nail and tag in the Southwest face of a 6" Ash
NAZ 121°, 70.75', Found KEBS nail and tag in the Southwest face of a 10" Hickory
NAZ 90°, 32.95', Found 1/2" steel bar and cap #12034 (Fred White)
NAZ 352°, 189.68', Found Stephens nail and tag #16053 in the East face of a Utility Pole

Signed by Gilbert M. Barish

Date 03-Nov-2004

Surveyor's Michigan License No. 47942



Part "A" Continued – Center of Section 4 (F02), T4N, R1W, Ingham County, MI

- 4) Recorded Survey by James E. Stephens, P.S. #16053, Dated 30-December-1971 and recorded in Liber 1, Page 330 of Surveys, showing the bearing of the North and South $\frac{1}{4}$ line from the Center of Section 4 as S01°40'10"W
- 5) Land Corner Recordation Certificate by James E. Stephens, P.S. #16053 on 26-June-1972 as recorded in Liber 1 page 585 of corners.
- Part "A" states: The original monument was not found
- Part "B" states: A $\frac{3}{4}$ inch iron rod was found in the centerline of the $\frac{1}{4}$ line road (Newton Road) and on a projection of two farm fences east and west of the corner.
- Part "C" states: The $\frac{1}{4}$ inch iron rod found at the Center of Section was left in position with the following witnesses:
Survey tag in a 8 inch Box Elder N71°56'W 41.46 feet.
Survey tag in a 10 inch Box Elder S74°12'W 80.70 feet.
Survey tag in a utility pole S14°38'W 98.60 feet.
The bearing of the $\frac{1}{4}$ line south of the corner is S01°40'10"W
- 6) Recorded Survey by James E. Stephens, dated 21-August-1975 and recorded in Liber 2, page 537 of Surveys.
Measured 2646.0 feet from F2-F3
Found $\frac{3}{4}$ " Iron rod witnessed with survey tag nailed to:
East side Utility Pole N4°17'W 189.50'
West side 16" Hickory tree S88°E 95.30'
Utility Pole S14°38'W 98.60'
- 7) Land Corner Recordation Certificate by James E. Stephens, P.S. #16053 on 27-Aug-1975 as recorded in Liber 3 page 431 of corners.
- Part "A" states: The original monument was not set
- Part "B" states: This certificate is being filed to provide up-dated information on the previous filing recorded in Liber 1, page 585.
Two of the witnesses previously recorded were destroyed.
- Part "C" states: The $\frac{1}{4}$ inch solid iron rod found at the center of section was witnessed with the following:
Survey tag on the west side of a 16" Hickory Tree, S88°E, 95.30 feet
Survey tag on the North side of a utility pole, S14°38'W, 98.60 feet
Survey tag on the East side of a utility pole, N4°17'W, 189.50 feet
- 8) Recorded Survey by Marvin F. Fouty, P.S. #18989 dated 11-April-1976 and recorded in Liber 2, Page 727 of Surveys.
Measured (F2-G2) – 2645.14
Measured (F2-F3) – 2645.86
Center of Section 4, set $\frac{1}{2}$ " bar and cap #18989 from witnesses in Liber 3, page 431.
- 9) Corner referenced in a recorded survey by Marvin F. Fouty, P.S. #18989 on 22-July-1976 in Liber 2, Page 867 of Surveys.
Center of Sec. 4, T4N, R1W, $\frac{1}{2}$ " bar and cap, Liber 3, page 431.
Measured (F2-G2) – 2645.14
Measured (F2-F1) – **2285.16 (distance appears +/- 300 feet short of the accepted distance)**
- 10) Corner referenced in a recorded survey by James A Porter, P.S. #19003 dated 14-March-1983 in Liber 4, pages 743-750 of Surveys.
Measured (E2-F2) – 2662.83
Bearings based on Liber 2, page 537 of Surveys.
- 11) Unrecorded survey by Bryan Land Surveys, P.C., Larry Bryan, P.S. #25832 J.N. 92-B-39354 on 30-October-1992
Center of Section 4, T4N, R1W, as recorded in Liber 3, page 431
Found $\frac{1}{2}$ " bar 3' west of the centerline of Newman Road on fence East.
Found Stephens nail and tag north side of power pole, S15°W, 98.63'
Found Bar and cap #18989, West, 33.00'
Found Stephens nail and tag East side of power pole, N10°W, 189.60'
- 12) Unrecorded survey by Bryan Land Surveys, P.C., Larry Bryan, P.S. #25832 J.N. 97-B-54408 on 11-August-1997
Additional witnesses added for recovered Center of Section 4, T4N, R1W, as recorded in Liber 3, Page 431.
Set Nail and Tag #25832 North side 6" Mountain Ash, S75°W, 81.90'
Set Nail and Tag #25832 Southwest side of 5" Box Elder, S15°E, 71.05'

- 13) Corner referenced in the plat of Whitehills Woods No. 5 by Larry A. Bryan, P.S. #25832 on 15-December-1998. Corner is noted the plat as follows:
"Center of Section 4, T5N, R1W, Clinton County, MI as recorded in Liber 2, page 859." Measurements to the North $\frac{1}{4}$ corner of Section 4 also listed as T5N, R1W, Clinton County Records from the North $\frac{1}{4}$ corner of Section 4 is 2580.50 feet.

References to the Center of Section appear erroneous.

- 14) Corner referenced in the plat of Whitehills Woods No. 6 by Larry A. Bryan, P.S. #25832 on 13-June-2000. Corner is noted the plat as follows:
"Center of Section 4, T4N, R1W, Liber 9, page 341(records indicate that this Liber and page is the West $\frac{1}{4}$ corner of section 5, Bunker Hill Township)
X=13,105,658.978
Y=460,140.817
M.C.S. 83-94, South Zone
Standard Deviation X=0.03' Y=0.03'
CSF 0.9998642



2004-072554

Page: 2 of 2

11/30/2004 08:07 A

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Meridian Township

INGHAM
(County)

Located In:

Corner Code #

1. Public Land Survey

T 4N R 1W F-03

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Gilbert M. Barish, in a field survey on June 10, 2004 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F-03:

- 1) Corner originally set by Musgrove Evans in a GLO survey conducted in 1827. Page 68 of the Ingham County GLO notes.
"West on true line between Section 4 and 9 39.95ch (2636.70 feet) set 1/4 section post...on true line"
Witnesses: B.O. 12 in S28E 37lks
Elm 6" N18W 27 lks
- 2) Ingham County Road Commission Grid Sheet (no date) calls for:
1" Iron rod
13" Box Elder 51.20' NW
21" Maple 56.89' ENE
Power Pole 45.58' SSW

Continued on Sheet 2

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-03: Found 1/2" x 12" square bolt at the surface of the pavement in centerline of Lake Lansing Road.

Field investigation at the apparent location of the corner revealed a 1/2" X 12" square bolt at the surface of Lake Lansing Road. Excavated to a depth of 6" below the surface asphalt and found a Rail road spike. The 1/2" square bolt was bent at the 6" mark to fall closely over the top of the Rail Road Spike. Measurements indicate that the square bolt lies 0.05 feet west of the center of the rail road spike. Continued excavating to a depth of 12" to clear the existing asphalt road into clean fill sand. Excavated to a depth of 2.5 feet from the surface into clean fill sand in a 2' diameter circle. Did not recover additional evidence of the corner location. Accepted the location of the railroad spike as a faithful perpetuation of the original government corner and set a 3/4" x 24" steel bar and cap stamped "P.A. 345, PS 47942" in a monument box at the location of the found Rail road spike.

Measurements: (F3-G3) - 2651.70' (F3-F2) - 2645.74 (F3-E3) - 2649.59

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-03: Set standard Ingham County 3/4" X 24" smooth steel bar and cap stamped "P.A. 345, PS 47942" in a monument box at the location of the found Rail Road spike. The point lies in the centerline of Lake Lansing Road at the intersection of Newton Road.

NAZ 311°, 45.65', Found nail and tag #25832 (Larry Bryan) in the Southwest face of a service pole
NAZ 297°, 91.03', Found cut "X" in the top east arm of a fire hydrant
NAZ 223°, 47.13', Found Stephens Nail and Tag (#16053) in the North face of a utility pole
NAZ 192°, 33.63', Found KEBS nail and tag in the West face of a 6" Honey Locust
NAZ 112°, 92.68', Set nail and tag #47942 (Barish) in the North face of a 40" Oak
NAZ 030°, 67.91' Found nail and tag #25832 (Larry Bryan) in the West face of a twin 10" Apple

Signed by Gilbert M. Barish
Surveyor's Michigan License No. 47942

Date 03-Nov-2004

Paula Johnson-
INGHAM COUNTY
REGISTER OF DEEDS
OFFICIAL SEAL



L-11 P-289

CRNR 17.00

2004-072555

2004-072555

Page: 1 of 2

11/30/2004 08:07 A

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													



P.A. 345 INGHAM COUNTY
PEER APPROVED 11/02/2004

Part "A" continued – South 1/4 corner of Section 4, T4N, R1W, Ingham County, Michigan

- 3) Plat of Sleepy Hollow recorded by Fred N. White, P.S. #12034 on 09-Sept-1963. No information provided for this corner.
- 4) Ingham County Road Commission Grid Sheet, Dated 1971 calls for:
1" Iron
T.P. N.N.E. 73.01'
P.P. S.W. 47.70'
T.P. W.N.W. 100.57'
- 5) Land Corner Recordation Certificate by James E. Stephens, P.S. #16053 on 04-Jan-1972 as recorded in Liber 1 page 589 of corners.
Part "A" states: The original monument was not found
Part "B" states: A railroad spike was set in the centerline of the section line road (Lake Lansing road) and in the centerline of the 1/4 line road (Newton Road) from old witnesses. An Old axle shaft was found at the South 1/4 corner on August 22, 1966 and was witnessed by Stephens Engineering.
Part "C" states: The railroad spike set at the S 1/4 corner was witnessed with the following:
Survey tag in a 14 inch Box Elder N52°13'W 51.73'
Survey tag in a utility pole N62°45'E 54.75 feet.
Survey tag in a utility pole S38°54'W 47.18 feet.
The bearing of the section line west of the corner is N88°20'W.
The bearing of the 1/4 line north of the corner is N1°40'10"E
- 6) Corner referenced in a recorded survey by James E. Stephens in Liber 1, Page 330 of Surveys on 30-Dec-1971. "S 1/4 cor. Sec. 4, T4N, R1W, railroad spike"
Same witnesses as Item 5 above. Bearing along the South line of Section 4, N88°20'W. Bearing along the North-South 1/4 line is S01°40'10"W.
- 7) Corner referenced in a recorded survey by James E. Stephens in Liber 1, Page 447 of Surveys on 29-Sept-1972.
"South 1/4 corner sec. 4, T4N, R1W, Rec'd L.1, Pg. 589."
- 8) Corner referenced in a recorded survey by Fred N. White, P.S. #12034 in Liber 1, Page 504 of Surveys on 18-July-1972
"S 1/4 Cor. Sec. 4, T4N, R1W"
Railroad spike
Power Pole S38°54'W, 47.18'
14" Elder N52°13'W, 51.73'
21" Maple N62°45'E, 54.7'
Bearing F3-E3 N88°20'W
- 9) Corner referenced in a recorded survey by Fred N. White in Liber 1, Page 504 of Surveys on 18-July-1972.
Same information as item 8 above.
- 10) Corner referenced in a recorded survey by Richard W. Steadman, P.S. #11370 in Liber 1, Page 1151 of Surveys on 19-Nov-1973.
South 1/4 Corner – Sec. 4, T4N, R1W.
"Found railroad spike"
14" Box Elder – N.W.-51.73'
Power Pole – N.E.-54.75'
Power Pole-S.W.-47.18'
- 11) Corner referenced in a recorded survey by Marvin F. Fouty, P.S. #18989 in Liber 2, Page 310 of Surveys on 27-Feb-1975.
Found Railroad Spike as recorded in Liber 1, Page 589 of Corners (Item 5 above)
- 12) Corner referenced in a recorded survey by James E. Stephens in Liber 2, Page 537 of Surveys on 21-Aug-1975.
Found Railroad Spike witnessed with the same information as item 5 above. Measured (F3-F2) – 2646.0 feet
- 13) Corner referenced in a recorded survey by Marvin F. Fouty, P.S. #18989 in Liber 2, Page 727 of Surveys on 06-Apr-1976.
Found Railroad Spike as recorded in Liber 1, page 589 (item 5 above). Measured (F3-F2) – 2646.85 feet, (F3-G3) – 2651.98 feet
- 14) Corner referenced in a recorded survey by James A. Porter in Liber 4, Page 749 of Surveys on 03-Jan-1983.
No information pertaining to the found monumentation or witnesses provided.
- 15) Corner referenced in a recorded survey by Larry A. Bryan, P.S. #25832 in Liber 6, Page 178 of Surveys on 05-Feb-1988
Found Railroad Spike in centerline of Lake Lansing road and Newton road per Liber 1, Page 589 of Corners
Additional Witnesses: Northwest corner of basement to House #2245, S15°E, 112.12'
Set nail and tag Southwest side of Power pole, N45°W, 45.64'
- 16) Corner referenced in a recorded survey by Larry A. Bryan in Liber 6, Page 258 of Surveys, on 03-Feb-1988.
Same information as item 15 above.
- 17) Corner referenced in a recorded survey by Larry A. Bryan in Liber 6, Page 180 of Surveys, on 14-June-1988.
Same information as item 15 above.
- 18) Plat of Everett Farms as recorded by James A. Porter on 24-Apr-1989. No information pertaining to the corner provided.
- 19) Plat of Everett Farms No. 2 recorded by James A Porter on 31-Oct-1989. Corner references Liber 1, Page 589 (Item 5 above).
- 20) Plat of Everett Farms No. 3 recorded by James A. Porter on 09-Nov-1989. Same information as Item 19 above.
- 21) Plat of Everett Farms No. 5 recorded by Dwight Schofield, P.S. #34976 on 03-Mar-1993. Corner references Item 5 above.
- 22) Plat of Everett Hills recorded by Dwight Schofield, P.S. #34976 on 09-Feb-1994. Corner references Item 5 above.
- 23) Corner referenced in a recorded survey by Fred N. White in Liber 8, Page 1126 of Surveys on 25-Aug-2004.
No information pertaining to the found monumentation or witnesses provided.



2004-072555
Page: 2 of 2

11/30/2004 08:07 A

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Meridian Township

INGHAM
(County)

Located In:

Corner Code #

1. Public Land Survey

T 4N

R 1W

G-01

T

R

Paula Johnson-
INGHAM COUNTY
REGISTER OF DEEDS
OFFICIAL SEAL



L-11 P-279

CRNR 17.00

2004-072550

2. Property Controlling
in Section

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R



2004-072550
Page: 1 of 2

11/30/2004 08:07 A

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Gilbert M. Barish, in a field survey on June 10, 2004 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-01:

- 1) Original Corner set by Musgrove Evans in 1827
"Intersected N. Boundary 40 lks (26.4 feet) East of 1/4 post of Sec. 33 and 34,
T.5N, R.1W, and set post cor to Sec. 3 and 4 fw a
W.O. 10 in S32E 78lks
D.O. 24 in S44 1/2 W 58 lks
Measured (G1-G2) - 39.15 chains (2583.9')

Continued on Sheet 2

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-01: Found 1/2" steel bar in a low lying swampy area

Field investigation at the apparent location of the corner revealed a 1/2" X 18" steel bar 25.72 feet East of a Concrete Monument (G-13, Bath Township, Clinton County). Set offsets and removed the 1/2" steel bar. Excavated to a depth of 2.5' below the surface and did not recover additional evidence of the section corner. Intersecting the township line as established by Dwight Schofield, P.S. #34976 for the Clinton County Remonumentation program, and the East line of Section 4, Meridian Township as measured by Geodetic Designs (holding the found 1/2" steel bar for direction) indicated that the corner fell 1.88 feet south of the found 1/2" steel bar. Excavated 1.88 feet south and found 4"-6" cleaved stones piled 18" in diameter to a depth of 2.5 feet starting 4" below the surface of the ground. Remnants of an old fence were found lying at the surface of the ground. Additional holes dug within 4 feet of the found stone pile did not reveal stones of the size and type found. The area is swampy with heavy black, wet soils to a depth of 2 feet with wet gray clay lying below the 2-foot mark.

Accepted the found 1/2" steel bar as a faithful perpetuation of the original government corner and held the point for direction. Set 3/4" x 24" steel bar and cap stamped "P.A. 345, PS 47942" at the amended location on the standard township line at the intersection of the East line of section 4, Meridian Township at the location of the found stone mound. The corner was backfilled with surrounding soil and approximately 30 found stones. Replaced the 1/2" by 18" steel bar at the found location 1.88 feet north of the remonumented position. Measured (G1-G2) - 2588.72 (G1-F1) - 2606.34

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-01: Set 3/4" x 24" steel bar and cap stamped "P.A. 345, PS 47942" at the amended location on the standard township line at the intersection of the East line of section 4, Meridian Township at the location of the found stone mound. The corner was backfilled with surrounding soil and approximately 30 found stones. Found 1/2" by 18" steel bar 1.88 feet north of the amended remonumented position.

NAZ 045°, 40.73', Found KEBS (Keyes Engineering Bryan Surveys) nail and tag in the East face of a 24" Poplar
NAZ 082°, 55.22', Set nail and tag #47942 (Barish) in the West face of a 50" triple Willow
NAZ 154°, 49.15', Found nail and tag #39100 (Terry Wiegman) in the West face of an 18" Cherry
NAZ 195°, 25.88', Set nail and tag #47942 (Barish) in the North face of a 12" Oak
NAZ 270°, 25.67', Found a concrete monument (no cap) with a carsonite marker (G-13 Bath Township, Clinton County)

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													



Signed by

Gilbert M. Barish

Date

03-Nov-2004

P.A. 345 INGHAM COUNTY

PEER APPROVED 11/02/2004

Surveyor's Michigan License No.

47942

Part "A" continued – Northeast corner of section 4 (G-01) T4N, R1W, Ingham County, Michigan

- 2) Corner referenced in Ingham County Road Commission Grid Sheet (No date)
Axle Shaft
27" Elm 44.21' N.W.
23" Elm 59.82' N.N.W.
3" Elm 39.73' W
- 3) Corner referenced in a recorded survey by Ronnie M. Lester in Liber 1, Page 603-604 of Surveys on 6-Dec-1972.
Set 1/2" bar, NE Cor. Sec. 4, T4N, R1W
Witnesses:
Nail and tag in S.W. side triple 6" Willow, E.N.E., 56.42'
Nail and tag in West side 15" wild Cherry, S.E., 50.67'
Nail and tag in West side 10" Oak, South, 45.09'
- Measured (G01-G02) – 2590.40'
- 4) Land Corner Recordation Certificate by Ronnie M. Lester, P.S. #18998 on 16-Feb-1978 as recorded in Liber 4 page 146 of corners.
Part "A" states: Original monument and accessories obliterated.
Part "B" states: ICRC records call for axle shaft at North end of fence post with following witnesses: 27" Elm, N46°W, 44.21'; 23" elm, N20°W, 59.82'; S.W. corner Section 34, West 25.60' (1" Pipe). Found no axle. Elm trees gone. Set 1/2" bar and cap 25.60' East of found 3/4" pipe. Falls in fence line South.
Part "C" states: 1/2" bar and cap as described above.
Nail and tag in S.W. side triple 6" Willow, E.N.E.
3/4" pipe West, 25.60'
Nail and tag in West side 15" wild Cherry, S.E., 50.67'
Nail and tag in West side 10" Oak, South, 45.09'
- 5) Corner referenced in a recorded survey by Ronnie M. Lester in Liber 3, Page 547-548 of Surveys in Jul-1978.
Found 1/2" bar, NE Cor. Sec. 4, T4N, R1W
Witnesses: Same information as Item 3 above.
- 6) Corner referenced in a recorded survey by Fred N. White, P.S. #12034 in Liber 4, Pages 374 on 07-Aug-1981. Information provided is the same as Item 4 above. Measured (G01-G02) – 2590.40'
- 7) Corner referenced in a recorded survey by Fred N. White, P.S. #12034 in Liber 4, Pages 672-673 on 17-Nov-1982. Information provided is the same as Item 4 above. Measured (G01-G02) – 2590.40'
- 8) Corner referenced in a recorded survey by Fred N. White, P.S. #12034 in Liber 5, Page 8 on 13-Nov-1985. Information provided is the same as Item 4 above. Measured (G01-G02) – 2590.40'
- 9) Corner referenced in a recorded survey by Larry A. Bryan, P.S. #25832 in Liber 6, Pages 142-143 on 12-Jan-1988.
Northeast corner Section 4, T4N, R1W, Liber 4, Page 146.
Found 1/2" bar.
Found nail and tag #25832 West side 6" Box Elder, S20°E, 6.76'
Found nail and tag #25832 North side 6" Box Elder, East, 10.18'
Found nail and tag #25832 Northwest side 4" elm, S45°W, 17.86'
- 10) Corner referenced in an unrecorded survey by Larry A Bryan, P.S. #25832 in Job Number 92-B-39354 on 30-Oct-1992. Same information as Item 9 above. Measured (G01-G02) – 2590.60'
- 11) Corner referenced in an unrecorded survey by Larry A Bryan, P.S. #25832 in Job Number 96-B-52484 on 20-Sept-1996. " North 1/4 corner, Section 4, T4N, R1W as recorded in Liber 3, Page 612, (Item 4 above) found 1/2" bar and cap #18989.
Witnesses (brass tags):
Found nail and tag south side of 24" Maple N60°E, 39.50
Found nail and tag south side of 14" Maple N45°E, 41.99
Found nail and tag #39100 (Terry Wiegman) south side of an 8" Elm N30°E, 29.50
Measured 2606.73' from the North 1/4 corner to the Northeast corner of Section 4.
- 12) Corner referenced in an unrecorded survey by Larry A Bryan, P.S. #25832 in Job Number 96-B-51727 on 11-June-1996.
Northeast Corner Section 4, T4N, R1W, Liber 4, Page 146.
Found 1/2" Iron Bar in fence line South
Found 2" Brass Disk P.S. #34976, West 25.65'
Found nail and tag #39100 South side 24" Maple N60°E 39.49'
Found nail and tag #39100 South side 14" Maple N45°E 41.99'
Found nail and tag #39100 South side 8" Elm N30°E 29.50'
Found nail and tag #39100 West side 24" Walnut S15°E 50.72'
- 13) Corner referenced in an unrecorded survey by Larry A Bryan, P.S. #25832 in Job Number 96-B-51352 on 25-Apr-1996. Same information as Item 9 above.
- 14) Corner referenced in an unrecorded survey by Larry A Bryan, P.S. #25832 in Job Number 96-B-51200 on 08-Apr-1996. Same information as Item 9 above. Measured (G01-F01) – 2606.73'
- 15) Corner referenced in an unrecorded survey by Larry A Bryan, P.S. #25832 in Job Number 96-B-50875 on 28-Feb-1996. Same information as Item 9 above.
- 16) Corner referenced in an unrecorded survey by Larry A Bryan, in Job Number 97-B-54408 on 11-Aug-1997. Same information as Item 9 above.



2004-072550

Page: 2 of 2

11/30/2004 08:07 A

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Meridian Township

INGHAM
(County)

Located In:

Corner Code #

1. Public Land Survey

T 4N

R 1W

G-02

2. Property Controlling
in Section

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Gilbert M. Barish, in a field survey on June 10, 2004 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-02:

- 1) Musgrove Evans set a 1/4 section corner post fw a during the original GLO survey in 1827.
Witnesses: W.O. 24in S35E 16lks
Hick 8 in S24W 30lks
- 2) Ingham County Road Commission Grid Sheet dated January, 1972 calls for:
Axle Shaft
5" Iron Pipe E. 15.0'
14" Poplar E.S.E. 70.14'
16" Oak S. 4.35'
- 3) Corner referenced in a recorded survey by Ronnie M. Lester in Liber 1, Page 603-604 of Surveys on 6-Dec-1972.
Found Axle Shaft, E 1/4 Cor. Sec. 4, T4N, R1W
Witnesses:
Centerline 5" iron post, East, 15.30'
Nail and tag in N.E. side 36" Poplar, S.E., 70.05'
Nail and tag in North side 28" ash, West, 62.40'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-02: Found 3" Axle Shaft at the base of a fence anchor post. Accepted the corner as a faithful perpetuation of the original government corner. Soft welded an Ingham County Remonumentation aluminum cap stamped "P.A. 345, PS 47942" to the found axle shaft

Measured: (G2-G1) - 2588.72 (G2-F2) - 2644.64 (G2-G3) - 2634.09

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-02: Soft welded an aluminum cap stamped "P.A. 345, PS 47942" to the found axle shaft

NAZ 075°, 30.70', Found KEBS (Keyes Engineering Bryan Surveys) nail and tag in the Northwest face of a 12" Oak
NAZ 342°, 24.25', Found KEBS nail and tag in the West face of a 10" Oak
NAZ 295°, 36.45', Found KEBS nail and tag in the South face of an 8" Oak
NAZ 220°, 4.10', Found nail and tag #25832 (Larry Bryan) in the West face of a 40" Oak
NAZ 144°, 78.14', Set nail and tag #47942 (Barish) in the Southwest face of a 30" Cottonwood



L-11 P-281

CRNR 17.00

2004-072551

2004-072551

Page: 1 of 2

11/30/2004 08:07 A

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4	3		2		1		
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													



P.A. 345 INGHAM COUNTY
PEER APPROVED 11/02/2004 *me*

Signed by

Gilbert M. Barish

Date

03-Nov-2004

Surveyor's Michigan License No.

47942

Part "A" continued – West 1/4 corner of section 4 (G02), T4N, R1W, Ingham County, Michigan

- 4) Land Corner Recordation Certificate by Ronnie M. Lester, P.S. #18998 on 16-Feb-1978 as recorded in Liber 4 page 146 of corners.
Part "A" states: Original monument and accessories obliterated.
Part "B" states: ICRC records call for axle shaft with the following witnesses: 5" Iron pipe, East, 15.0'; 14" Poplar, E.S.E., 70.14'; 16" Oak, South 4.35'. Found Axle shaft at fence intersection.
Part "C" states: Found 3" gear with 1" shaft
Centerline 5" iron post, East, 15.30'
Nail and tag in N.E. side 36" Poplar, S.E., 70.05'
Nail and tag in North side 28" ash, West, 62.40'
- 5) Corner referenced in the plat of Crestwood Subdivision No. 1, by Sydney Bokavoy, P.S. #19828 on 19-Mar-1976. No information provided on the Corner. Bearing along the East-West 1/4 line of Section 3, T4N, R1W, is recorded as N89°51'15"E
- 6) Corner referenced in the plat of Crestwood Subdivision No. 2, by Marvin F. Fouty, P.S. #18989 on 9-July-1977. No information provided on the Corner. Bearing along the East-West 1/4 line of Section 3, T4N, R1W, is recorded as N89°54'07"E
- 7) Recorded Survey by Marvin F. Fouty, P.S. #18989 dated 11-April-1976 and recorded in Liber 2, Page 727 of Surveys. Measured (F2-G2) – 2645.14
East 1/4 Cor. Sec. 4, Found Axle Shaft, Liber 1 of Surveys, Page 603. Witnesses the same as Item 3 above.
- 8) Corner referenced in a recorded survey by Marvin F. Fouty, P.S. #18989 on 22-July-1976 in Liber 2, Page 867 of Surveys. East 1/4 Cor. Sec. 4., T4N, R1W, Axle Shaft, Liber 1 Certified Survey maps of Ingham County, Page 603. Measured (F2-G2) – 2645.14
- 9) Corner referenced in the plat of Crestwood Subdivision No. 3, by James E. Stephens, P.S. #16053 on 14-May-1979. No information provided on the Corner. Bearing along the East-West 1/4 line of Section 3, T4N, R1W, is recorded as N89°54'07"E
- 10) Corner referenced in a recorded survey by Fred N. White, P.S. #12034 in Liber 4, Pages 374 on 07-Aug-1981. Information provided is the same as Item 4 above. Measured (G01-G02) – 2590.40'
- 11) Corner referenced in a recorded survey by Fred N. White, P.S. #12034 in Liber 4, Pages 672-673 on 17-Nov-1982. Information provided is the same as Item 4 above. Measured (G01-G02) – 2590.40'
- 12) Corner referenced in the plat of Crestwood Subdivision No. 4, by Maurice Mahieu, P.S. #28414 on 13-June-1985. No information provided on the Corner. Bearing along the East-West 1/4 line of Section 3, T4N, R1W, is recorded as N89°53'22"E
- 13) Corner referenced in a recorded survey by Fred N. White, P.S. #12034 in Liber 5, Page 8 on 13-Nov-1985. Information provided is the same as Item 4 above.
- 14) Corner referenced in the plat of Pine Creek by Maurice Mahieu, P.S. #28414 on 26-Feb-1986. Information provided is the same as Item 4 above. Measured (G02-H02) – 2642.05'
- 15) Corner referenced in the plat of Crestwood Subdivision No. 5, by Maurice Mahieu, P.S. #28414 on 04-Mar-1986. No information provided on the Corner. Bearing along the East-West 1/4 line of Section 3, T4N, R1W, is recorded as N89°53'22"E
- 16) Corner referenced in a recorded survey by Larry A. Bryan, P.S. #25832 in Liber 6, Pages 142-143 on 12-Jan-1988. East 1/4 corner Section 4, T4N, R1W. Information provided is the same as Item 4 above.
- 17) Unrecorded survey by Bryan Land Surveys, P.C., Larry Bryan, P.S. #25832 J.N. 92-B-39354 on 30-October-1992
East 1/4 Corner 4, T4N, R1W, as recorded in Liber 4, page 146
Found Axle Shaft with gear at North side of fence post in fences East, West, and South.
C/L steel fence post East 15.33'
Set Nail and tag #25832 Northwest side 30" Oak S45°W 4.18'
Set Nail and tag #25832 West side 6" Oak N15°E 22.57'
Set Nail and tag #25832 North side 8" Cherry East 16.41'
Measured (G02-F02) – 2644.71'
- 18) Unrecorded survey by Bryan Land Surveys, P.C., Larry Bryan, P.S. #25832 J.N. 92-B-39354 on 30-October-1992
Center of Section 4, T4N, R1W, as recorded in Liber 3, Page 431. Witnesses are the same as Item 11 above.
- 19) Unrecorded survey by Bryan Land Surveys, P.C., Larry Bryan, P.S. #25832 J.N. 97-B-54408 on 11-August-1997
East 1/4 Corner 4, T4N, R1W, as recorded in Liber 4, page 146
Found Axle Shaft with gear at North side of fence post in fences East, West, and South.
C/L steel fence post East 15.33'
Found Nail and tag #25832 Northwest side 30" Oak S45°W 4.20'
Found Nail and tag #25832 West side 6" Oak N15°E 22.60'
Found Nail and tag #25832 North side 8" Cherry East 16.41'
Measured (G02-F02) – 2644.98'



2004-072551

Page: 2 of 2

11/30/2004 08:07 A

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Meridian Township

INGHAM
(County)

Located In:

Corner Code #

1. Public Land Survey

T 4N R 1W

G-03

2. Property Controlling
in Section

S T R
S T R
S T R

3. Miscellaneous
Property in Sec.

S T R
S T R
S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Gilbert M. Barish, in a field survey on June 10, 2004 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-03:

- 1) Musgrove Evans set a 1/4 section corner post to Sec. 3,4,9,and 10 fw a during the original GLO survey in 1827.
Witnesses: W.O. 14in S58E 40lks
Do 8 in N79W 35lks
- 2) Ingham County Road Commission Grid Sheet dated January, 1971 calls for:
1/2" Iron
12" Apple N.N.E. 40.23'
P.P. E.S.E. 83.95'
T.P. W.N.W. 68.72'
- 3) Plat of Lake O' The Hills as recorded by Robert J. Jagow, P.S. #6998 on 07-Feb-1967. No further information provided.

Continued on sheet 2

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-03: Found 1/2" X 24" steel bar (no cap) at the surface of Lake Lansing Road

Field investigation at the apparent location of the corner revealed a 1/2" steel bar at the surface of Lake Lansing Road. Offset the found 1/2" bar and excavated around the point in an 18" diameter to a depth of 24". The asphalt was about 6" deep with a hard pack gravel bed at the base of the asphalt. Did not recover any additional evidence as to the location of the section corner.

Accepted the found 1/2" steel bar as a faithful perpetuation of the corner and set a 3/4" x 24" steel bar and cap stamped "P.A. 345, PS 47942" in a monument box.

Measured: (G3-G2) - 2634.09 (G3-F3) - 2651.70

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-03: Set 3/4" x 24" steel bar and cap stamped "P.A. 345, PS 47942" in a monument box in the physical centerline of Lake Lansing Road.

NAZ 222°, 41.95', Found nail and tag #17741 (Gerald Gray) in the Southeast face of an 18" Red Pine
NAZ 159°, 37.28', Found nail and tag #17741 (Gerald Gray) in the Southwest face of an 18" Red Pine
NAZ 116°, 84.00', Set Mag nail and tag #47942 (Barish) below a found 16 penny nail in the Northeast face of a utility pole
NAZ 080°, 56.39', Set nail and tag #47942 (Barish) in the Southeast face of a 10" Elm
NAZ 012°, 82.85', Set nail and tag #47942 (Barish) in the West face of a 12" twin Elm

Signed by Gilbert M. Barish
Surveyor's Michigan License No. 47942

Date 03-Nov-2004

P.A. 345 INGHAM COUNTY
PEER APPROVED 11/02/2004 m

Paula Johnson-
INGHAM COUNTY
REGISTER OF DEEDS
OFFICIAL SEAL



L-11 P-283

CRNR 17.00

2004-072552

2004-072552

Page: 1 of 2

11/30/2004 08:07 A

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													



Part "A" continued – Southeast corner of Section 4 (G03), T4N, R1W, Ingham County, Michigan

- 4) Land Corner Recordation Certificate by Gary D. Lester, P.S. #17624 on 09-Aug-1971 as recorded in Liber 1 page 177 of corners.
Part "A" states: The original monument and accessories obliterated.
Part "B" states: Given witnesses by Ingham County Road Commission. Location supported by fence North and Location is called for in recorded plat of Lake O' The Hills Subdivision.
Part "C" states: Road Under Construction
Witnesses only for setting corners after construction completion.
Spike in 12" Apple, NNE, 40.23'
Spike in Power Pole, ESE, 83.95'
Spike in telephone pole, WNW, 68.72'
- 5) Corner referenced in a recorded survey by James E. Stephens in Liber 1, Page 447 of Surveys on 29-Sept-1972.
"S.E. corner sec. 4, T4N, R1W, Rec'd L.1, Pg. 177." (Item 4 above). No further information provided.
- 6) Corner referenced in a recorded survey by Marvin F. Fouty in Liber 2, Page 310 of Surveys on 27-Jan-1975. "NE Cor. Sec. 9, T4N, R1W, Fnd 1/2" Bar, Liber 1, Page 177" (Item 4 above)
Witnesses: PK nail in 12" Apple, NNE 40.32
PK nail in Power Pole ESE 83.99
Nail and tag N side utility pole WSW 104.78
- 7) Corner referenced in a recorded survey by Marvin F. Fouty, P.S. #18989 in Liber 2, Page 727 of Surveys on 06-Apr-1976.
Found 1/2" bar as recorded in Liber 1, page 177 (item 4 above). Measured (F3-G3) – 2651.98 feet, (G3-G2) – 2634.49'
- 8) Plat of Oak Grove Heights as recorded by Larry A. Bryan, P.S. #25832 on 12-Feb-1985. Corner references Liber 1, Page 177 (Item 4 above).



2004-072552
Page: 2 of 2

11/30/2004 08:07 A