

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

FILED

For corners in

Ingham  
(County)

Located In:

Corner Code M-4

- |                                    |                         |            |
|------------------------------------|-------------------------|------------|
| 1. Public Land Survey              | T <u>1N</u> R <u>1E</u> | <u>M-4</u> |
|                                    | T _____ R _____         | _____      |
|                                    | T _____ R _____         | _____      |
|                                    | T _____ R _____         | _____      |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____      |
|                                    | S _____ T _____ R _____ | _____      |
| 3. Miscellaneous Property in Sec.  | S _____ T _____ R _____ | _____      |

SEP 4 11 39 AM '92

REGISTER OF DEEDS

*Paul Johnson*  
 INGHAM COUNTY, MICH.

Register of Deeds Stamp &amp; File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

I, Maurice H. Mahieu, in a field survey on June 10, 19 92, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-4 Original Monument and Accessories Obliterated.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-4 Found 1/2" Iron Rod.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-4 East 1/4 Corner, Section 12, T1N, R1E, Bunkerhill Township, Ingham County, Michigan 1/2" Iron Rod

Witnessed By:

Nail &amp; Tag #28414, North side 32" Hickory, S 70° E 88.65'

Nail &amp; Tag #28414, North side 4" Oak, S 85° E 40.50'

West Edge Sign Post, S 30° E 34.60'

East Edge Sign Post, S 20° W 29.85'



Signed by

*Maurice H. Mahieu*

Date

7-13-92

Surveyor's Michigan License No.

28414

 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
 REVISED MAY 14, 1975  
 REVISED JAN., 1983

2436

T. 1N R. 2E

SOURCE:

LAND CORNER RECORDATION CERTIFICATE

TRANSCRIBED from ~~STOCKBRIDGE~~ on file at REMONUMENTATION OFFICE  
DUPLICATE

A-3

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 3 PG 117

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	6 T. 1 N. 2 E.	B-2, C-2, C-3
2. PROPERTY CONTROLLING IN SECTION	T. N. S. R. E.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Oscar Ross do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on November 16 19 73 established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law.

FILED

A. Description of original monument and accessories and/or subsequent restoration:

B-2 Unknown  
C-2 Unknown  
C-3 Unknown

APR 25 9 21 AM '74

REGISTER OF DEEDS  
Paul M. Smith  
INGHAM COUNTY, MICH.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

B-2 Set 1/2" Iron - fence intersection  
C-2 Set 1/2" Iron - fence intersection E-W  
C-3 found 1/2" Iron

C. Description of monuments for corner and accessories established to perpetuate locating the position of the corner:

B-2 Center Sec. 6,  
S. 05° E. 1.67 Nail W/S 36" Oak  
S. 02° E. 23.78 Nail W/S 12" Oak  
West 15.18 Nail W/S 6" Oak  
C-3 SE corner, Sec. 6,  
N. 75° W. 21.10 Nail S/S 40" Oak  
S. 70° E. 31.21 Nail S/S 14" Oak  
N. 15° E. 97.35 Nail W/S 10" Oak  
C-2 E 1/4 corner, Sec. 6,  
East 14.89 Nail S/S 14" Oak  
North 12.42 Nail E/S 10" Oak  
West 25.72 Nail S/S 12" Hickory

SIGNED BY Oscar Ross

DATE

4-10-74

SURVEYOR'S MICHIGAN REGISTRATION NO. 13574

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

DATE

APPROVED AND SIGNED BY

DATE

SURVEYOR'S MICHIGAN REGISTRATION NO.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

712

STOCKBRIDGE  
township

T 1 N, R 2 E

B-2  
corner code

1

attachment no.

p. 1 of 1

17-5

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in  
INGHAM  
(County)

Located In: STOCKBRIDGE TWP.  
Corner Code -#

MAR 4 12 58 PM '94

REGISTERED DEEDS  
INGHAM COUNTY, MICH.

1. Public Land Survey T 1N R 2E B-2  
T R  
T R  
T R  
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat  
5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6												
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12													
13													

i. RON HELSEL in a field survey on JAN. 13, 19 94  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration  
CORNER NOT SET IN ORIGINAL GOVERNMENT SURVEY. DID NOT FIND ANY SUBSEQUENT COUNTY SURVEYS REFERENCE TO THIS CORNER IN THE PUBLIC RECORDS. A C.R.C. RECORDED BY O. BOSS #13574 IN LIBER 3, PG. 117, DATED NOVEMBER 16, 1973 WAS DESCRIBED AS "SET 1/2" IRON-FENCE INTERSECTION" WITNESSES AS: S05°E, 1.67' NAIL W/S 36" OAK  
S02°E, 23.78' NAIL W/S 12" OAK  
WEST 15.18' NAIL N/S 6" OAK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
FOUND 1/2" BAR AND 2 REMAINING WITNESS TREES. REWITNESSED BAR.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
1/2" BAR AT FENCE INTERSECTION  
SET GALV NAIL & TAG #18994 NORTH/SIDE 44" OAK, EAST, 2.94'  
SET GALV NAIL & TAG #18994 NORTH/SIDE 12" ELM, N83°W, 3.95'  
SET GALV NAIL & TAG #18994 WEST/SIDE 44" OAK, S05°E, 1.67'  
SET GALV NAIL & TAG #18994 NORTH/SIDE 6" OAK, S85°W, 15.09'



Signed by Ron Helsel

Date FEB. 3, 1994

Surveyor's Michigan License No. 18994

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 8 PAGE 116

FILED

For corners in

INGHAM

(County)

Located In:

Corner Code: #

1. Public Land Survey

T 1N R 2E

B-3

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. Recorded Plat

5. Private Claims

MAR 4 12 58 PM '94

REGISTERED DEEDS

INGHAM COUNTY MICH.

Register of Deeds Stamp & File Number

I, RON HELSEL in a field survey on JANUARY 13 1993

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3	7	8	9	10	11	12							
4	16	17	18	19	20	21	22	23	24				
5	26	27	28	29	30	31	32	33	34				
6	35	36	37	38	39	40	41	42	43	44	45	46	47
7	48	49	50	51	52	53	54	55	56	57	58	59	60
8	61	62	63	64	65	66	67	68	69	70	71	72	73
9	74	75	76	77	78	79	80	81	82	83	84	85	86
10	87	88	89	90	91	92	93	94	95	96	97	98	99
11	100	101	102	103	104	105	106	107	108	109	110	111	112
12	113	114	115	116	117	118	119	120	121	122	123	124	125
13	126	127	128	129	130	131	132	133	134	135	136	137	138

A. Description of original monument and accessories and/or subsequent restoration:


ORIGINAL MONUMENT: POST SET BY U.S. DEPUTY SURVEYOR IN 1826. CORNER AND ORIGINAL WITNESSES ARE LOST. THERE WERE NO COUNTY SURVEYS REFERENCED TO THIS CORNER IN THE PUBLIC RECORDS.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND A 1" PIPE AT THE BASE OF A STEEL ANGLE IRON ANCHOR POST AT THE INTERSECTION OF FENCE LINES NORTH, WEST & EAST. EXCAVATED DOWN TO PILE OF FIELD STONES IN A LARGE CIRCLE.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1" PIPE AT BASE OF STEEL ANGLE IRON POST  
FOUND NAIL & TAG #28414 E/SIDE 14" ASH, S20°W, 26.70'  
SET GALV NAIL & TAG #18994 E/SIDE 14" ASH, SOUTH, 72.17'  
SET GALV NAIL & TAG #18994 E/SIDE 16" ASH, S25°E, 77.86'  
SET GALV NAIL & TAG #18994 S/SIDE 8" ELM, S80°E, 44.20'



Signed by

*Ron Helsel*

Date

FEB. 24, 1994

Surveyor's Michigan License No.

18994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN. 1983

2602

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

FILED

For corners in

INGHAM  
(County)

Located In:

Corner Code ##

1. Public Land Survey

T IN R 2E

B-3

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

MAR 4 12 58 PM '94

REGISTERED DEEDS

JAN 25 1994

INGHAM COUNTY MICH.

Register of Deeds Stamp &amp; File Number

I, RON HELSEL, in a field survey on 1-13- 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

ORIGINAL MONUMENT WAS A POST SET IN 1826 & ORIGINAL WITNESSES ARE LOST. DID NOT FIND ANY SUBSEQUENT COUNTY SURVEYS REFERENCED TO THIS CORNER.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND A 3/4" PIPE AT A STEEL ANGLE IRON ANCHOR POST, SET BY WOLVERINE ENGINEERING IN A SURVEY DATED JUNE 10, 1992, JOB #920552, DESCRIBED AS SET AT THE INTERSECTION OF N & E-W FENCE LINES. WITNESSED AS: N & T #28414, E/SIDE 15" ASH, S20°W, 26.75'  
N & T #28414, S/SIDE 4" ELM, N45°W, 3.30'

FOUND THE ASH TREE PER WOLVERINE'S FIELD NOTES & EXCAVATED 3'± BELOW THE PIPE DOWN TO FIELD STONES. STONES WERE IN AN IRREGULAR CIRCLE AROUND THE STEEL ANGLE IRON. MEASUREMENTS TO COR. C-3 AND PRORATED OCCUPATION WERE IN CLOSE ACCORD WITH THE G.L.O. MEASUREMENTS. ACCEPTED THE PIPE AS THE BEST AVAILABLE MARKER & EVIDENCE FOR THE GOVERNMENT CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" PIPE AT INTERSECTION OF E-W, AND NORTH FENCE LINES  
SET GALV. NAIL & TAG #18994 E/SIDE 14" ASH, SOUTH, 72.17'  
FOUND NAIL & TAG #28414 E/SIDE 14" ASH, S20°W, 26.70'  
SET GALV. NAIL & TAG #18994 E/SIDE 16" ASH, S25°E, 77.86'  
SET GALV. NAIL & TAG #18994 S/SIDE 8" ELM, S80°E, 44.20'



Signed by

*Ron Helsel*

Date

JAN. 25, 1994

Surveyor's Michigan License No.

18994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
 REVISED MAY 14, 1975  
 REVISED JAN. 1983

2603