


# RON HELSEL P.S.

Land Surveying & Related Services  
P.O. Box 141, DeWitt, MI 48820  
Phone 517-669-3640 Fax 517-669-6521

Client: Ing. Co. Remon  
Description: TEN, RIW  
Field Crew: HELSEL-LOHR Date: JULY 2005  
Computed: HELSEL  
Disk: 64-6 Job: SEC. 1 UENAY



| POINT # | NORTH      | EAST      |
|---------|------------|-----------|
| 1       | 20599.0925 | 4077.1266 |
| 2       | 20018.4207 | 9397.5149 |
| 3       | 17377.5895 | 9397.5242 |
| 4       | 20015.9063 | 4090.4276 |
| 5       | 17426.8356 | 6724.0323 |
| 6       | 12129.2083 | 9383.7876 |
| 7       | 12154.1415 | 6735.1716 |
| 8       | 20018.4471 | 6746.9252 |
| 9       | 12154.1415 | 6735.1716 |
| 10      | 20038.6406 | 1997.0709 |
| 11      | 18783.7814 | 4056.2125 |
| 12      | 20015.9788 | 4037.5434 |
| 13      | 20023.0309 | 1446.2052 |
| 14      | 17476.0944 | 4049.8313 |
| 15      | 18468.8034 | 6740.0356 |
| 16      | 17426.9197 | 6723.8108 |
| 17      | 14788.0721 | 6727.3445 |
| 18      | 14777.1350 | 8371.8381 |
| 19      | 12154.1225 | 6728.7645 |
| 20      | 14818.7627 | 5591.8792 |
| 21      | 14749.9827 | 9389.1758 |
| 22      | 14809.0634 | 4285.3351 |
| 23      | 14819.7674 | 4056.0849 |
| 24      | 12589.3955 | 4052.9439 |
| 25      | 12173.2883 | 4067.4529 |
| 26      | 11139.7481 | 4087.1082 |
| 27      | 9524.5051  | 4080.0416 |
| 28      | 9501.5310  | 6743.0678 |
| 29      | 8814.4082  | 6734.9368 |
| 30      | 7515.7287  | 6758.3183 |
| 31      | 7464.1389  | 7335.8386 |
| 32      | 6601.9274  | 6736.1548 |
| 33      | 6857.1207  | 6746.1713 |
| 34      | 5899.8043  | 6753.6080 |
| 35      | 5049.4362  | 6730.9451 |
| 36      | 4208.9411  | 6747.5938 |

VEVAY Twp T2N, R1W

SEC. 1

Inq Co. Remon

2005 RH

NE COR

E 1/2 COR

N 1/4 COR

NW COR

W 1/4 COR

COR

S 1/4 COR

SE COR

SW COR

MAP #1

on file at Ramon. OFFICE

Point  
ESE 51.3'  
Stump SSW 49.0'  
post NE 39.5'

This information was taken from the Alaiedon Twp. grid map, issued by the Ingham County Road Commission. Although it is not ment for Vevay Twp., the information is in accordance with a survey by G.E. States, County Surveyor, Oct. 1892. The witnesses given in the States survey match exactly the first two witnesses listed by the Road Commission records. This information is therefore assumed to be for Vevay Twp.

VEVAY  
township

T 2 N. R 1 W

4-1  
corner code

4  
attachment no.

p. 1 of 1

# T2N RIW VEVAY

found Aug 6/70  
 Ptd Stone 4 R.R.  
 SPIKE  
 Anchor Post 23.66W  
 " 29.18 E  
 12" diameter 99.55 RNE

2

0.55W  
 1.40W  
 1.96E


11

12

0.55W

14

13



INGHAM COUNTY ROAD COMMISSION

ALAIEDON