

V. H. V. Any

Ingham County

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

W. H. V. Any Center

1 10 535

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY Sec. 14 T. 2 N. R. 1 W.		I-6, J-6
2. PROPERTY CONTROLLING IN SECTION T. S. R. E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION T. S. R. E. W.		
4. LOT NO. RECORDED PLAT		
5. PRIVATE CLAIMS		

FILED

JUN 1 10 10 AM '72  
REGISTER OF DEEDS  
Mia Bill Humphrey  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

1. Ronnie M. Lester do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on April 10, 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- I-6, Original monument and accessories obliterated
- J-6, Original monument never set

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- I-6, Found 1/2" pinch pipe in Centerline of Ives Road and on fence line East measurement North & East in close accord with original measurement of F.J. Brown's measurement in 1874
- J-6, Center of Section set in 1874 by F.J. Brown, Ingham County Surveyor set post. Found fence intersection and set 1/2" bar. Measurements North, South, East and West in close accord with Brown's measurement in 1874

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- I-6, West 1/4 Corner Section 14, T2N, R1W  
1/2" pinch pipe Centerline of Ives Road & fence line East.  
Nail & Tag North side 10" hickory, WSW, 31.51'  
Nail & Tag South side corner post of fence East, E, 25.26'  
Nail & Tag SW side power pole, ESE, 36.24'
- J-6, Center Section 14, T2N, R1W  
1/2" bar at corner post, fences North, South, East and West  
Nail & Tag West side 8" maple, N, 8.35'  
Nail & Tag NW side 30" wild cherry, ENE, 5.53'  
Nail & Tag North side 30" maple, SW, 45.85'

SIGNED BY Ronnie M. Lester DATE April 24, 1972

SURVEYOR'S MICHIGAN REGISTRATION NO. 18908

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

Ingham County

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

NW corner N 1/4 sec 14

FILED 1 18 537

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY Sec. 14 T. 2 N. R. 1 W.		(1-5) J-5
2. PROPERTY CONTROLLING IN SECTION T. N. S. R. E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION T. N. S. R. E. W.		
4. LOT NO. RECORDED PLAT		
5. PRIVATE CLAIMS		

FILED

JAN 1 10 10 AM '72

REGISTER OF DEEDS  
Mia Bell Humphrey  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Ronnie M. Lester do hereby certify that under requirements of P.A. 74, Michigan P.A., of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on April 10, 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

I-5, J-5, Original monuments and accessories obliterated

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I-5, Set 1/2" bar on Centerline of Ives Road and fence line East  
Measurements North, South, East in close accord with original  
government measurements

J-5, F.J. Brown reset corner in 1874 - post. set 1/2" bar at found corner post.  
measurements East, West, and South to Center of Section as reestablished,  
were all in close accord with Brown's measurements in 1874.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-5, NW Corner Section 14, T2N, R1W  
1/2" bar Centerline of Ives Road and fence line East  
Nail & Tag South side root 30" maple, W, 20.93'  
Nail & Tag North side 36" maple, SW, 25.45'  
Nail & Tag South side 18" walnut, NE, 34.60'  
J-5, North 1/4 Corner Section 14, T2N, R1W  
1/2" bar at fence intersection - fences North, South East, West  
Nail & Tag SE side 18" cherry, WSW, 18.27'  
Nail & Tag West side 18" cherry, S, 16.98'  
Nail & Tag SW side 8" ash, ESE, 19.72'

SIGNED BY Ronnie M. Lester DATE April 11, 1972  
SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SE 1/4 Sec 16  
SE Cor Sec 16  
Vevay

**LAND CORNER RECORDATION CERTIFICATE**  
**FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970**

Section 16, T2N, R1W, Vevay Township, Ingham County, Michigan

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>16</u>	T. <u>2</u> N. <u>1</u> E. <u>1</u> W.	F-7 & G-7
2. PROPERTY CONTROLLING IN SECTION _____	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	_____
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

LIBER 3 PG 37

FILED

MAR 27 10 38 AM '74

REGISTER OF DEEDS  
*Paul M. Lewis*  
INGHAM COUNTY, MICH.  
REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Ron Helsel do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on March 8 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

F-7 - Original Corner & Witnesses Lost.

G-7 - Original Corner & Witnesses Lost.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

F-7 - Found 1" pipe 2" deep and 1.75' South of centerline Tomlinson Road. Iron on line with fence to South and in accord with G.L.O. measurements and abutting property descriptions.

G-7 - Found Boat Spike 4" under pavement 3' South of centerline Tomlinson Road on line with fence to North. Corner in close accord with abutting fences and G.L.O. measurements.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-7 - 1" Pipe

G-7 - Boat Spike

N & T - 16" Cherry Stump N45°W 39.32'	N & T - Power Pole S75°W 180.53'
N & T - Twin 14" Cherry Stump N10°W 26.11'	N & T - Power Pole S75°E 174.50'
P.K. Nail in Cor. Post S00°W 28.40'	N & T - 36" Sycamore N75°E 270.12'
	N & T - Cor. Post N02°W 64.57'

SIGNED BY Ron Helsel DATE 3-8-74

SURVEYOR'S MICHIGAN REGISTRATION NO. 18994

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

Form No. 101-M725  
PUBLISHED BY D. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS



N 1/4 pt Sec 10 Vevay  
S 1/4 pt Sec 10

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 3 PG 167

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	Sec. 10 T. 2 N. R. 1 W.	H-3, H-5
2. PROPERTY CONTROLLING IN SECTION	T. N. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

FILED

JUL 12 2 06 PM '74  
REGISTER OF DEEDS  
AND M. LESTER  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Ronnie M. Lester do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram-over) were, in a field survey on May 9, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

H-3, Witness trees remaining as recorded at the Ingham County Road Commission.  
H-5, Original monument and accessories lost.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

H-3, Found P.K. nail from old witnesses obtained from the Ingham County Road Commission and replaced with 1/2" bar on apparent centerline of Columbia Rd. and fenceline South.  
H-5, Set 1/2" bar and cap on line and 1/2 way between the SW corner and the SE corner of Section 10, on fence line and tree line East & West and 173'± East of physical centerline of Dexter Trail. Records of seven area surveyors revealed no additional evidence of this corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-3, N 1/4 Corner of Section 10, T2N, R1W  
SE Corner foundation existing house #1748, NNW, 105.19'  
Nail & tag East side 30" maple, North, 40.30'  
Nail & tag West side 26" maple, NE, 45.39'  
H-5, S 1/4 Corner of Section 10, T2N, R1W  
SE corner of existing house, NW, 85.65'  
Nail & tag South side 20" willow, West, 24.98'  
Nail & tag East side 12" maple, North, 44.70'

SIGNED BY Ronnie M. Lester DATE MAY 9 1974  
SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY  
APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

Form No. MLN725  
DOUGLASS BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION JAN. 1971  
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS



# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

USER

3 PG 616

FOR CORNERS OF-- LOCATED IN-- CORNER CODE NUMBER

1. PUBLIC LAND SURVEY E. 2N S. R. 1W 1. F-5, G-5, E-6, F-6

2. PROPERTY CONTROLLING IN SECTION 1. S. R. 1. W.

3. MISCELLANEOUS PROPERTY IN SECTION 1. S. R. 1. W.

4. LOT NO. RECORDED PLAT

5. PRIVATE CLAIMS

FILED

SEP 17 11 08 AM '78

REGISTER OF DEEDS  
*Carol M. Lewis*  
 INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, George M. Young, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above identified with circles on index code diagram were, in a field survey on 6/23 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 6/23 1976, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or by a Decree of a Court of Law:

A. Description of original monument and accessories and/or subsequent restoration:

- F-5 Original Corner & Accessories Not Found
- G-5 Original Corner & Accessories Not Found
- E-6 4" Cedar NE 10.63'  
 4" Cedar NNE 26.99'  
 Power Pole E 30.68'  
 Ingham County Road Comm. Reference
- F-6 Original Corner & Accessories Not Found



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- F-5 Found 3/4" Iron Pipe Set in Center of a small pile of stones
- G-5 Found 1/2" Re-rod next to rotted off Anchor Post
- E-6 Found 3/4" Iron in Monument Box
- F-6 Set 1/2" Re-rod with Cap @ intersection of E-W, N-S 1/4 lines

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- F-5 Nail & Washer in 24" Maple W 19.68'  
 Nail & Washer in 18" Maple N30°W 35.65'  
 Nail & Washer in 42" Oak N80°E 47.79'
- E-6 Nail & Washer in P.P. S70°E 32.51'  
 Nail & Washer in W Pole of Wickes Sign S30°E 81.15'  
 Fence Corner Post "W" 35.38'
- F-6 Nail & Washer in 8" Poplar N40°W 109.17'  
 Nail & Washer in 24" Box Elder "S" 44.98'  
 Nail in 30" Maple S 20° W 97.68'
- G-5 Nail & Cap in 4" Maple N 45° E 29.30'  
 Nail & Cap in 6" Poplar S 70° W 16.00'  
 Nail & Cap in 6" Ash "S" 23.10'

SIGNED BY *George M. Young*

DATE July 27, 1976

SURVEYOR'S MICHIGAN REGISTRATION NO. 17640

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ CHIEF OF SURVEY PARTY

DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_

MICHIGAN REGISTERED LAND SURVEYOR

DATE \_\_\_\_\_

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

USER

3 PG 618

FILED

SEP 17 11 08 AM '76

REGISTER OF DEEDS

Paul M. Lewis  
INGHAM COUNTY, MICH

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

FOR CORNERS OF-- LOCATED IN-- CORNER CODE NUMBER

1. PUBLIC LAND SURVEY 1 2N S. R. 1W G-6, H-6, H-7

2. PROPERTY CONTROLLING IN SECTION 1 S. R. 1W

3. MISCELLANEOUS PROPERTY IN SECTION 1 S. R. 1W

4. LOT NO. RECORDED PLAT

5. PRIVATE CLAIMS

1. George M. Young

Do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above, mentioned with circles on index code diagram - over were in a field survey on 6/23/76, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were in a field survey on 6/23/76, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or by a Decree of a Court of Law:

A. Description of original monument and accessories and subsequent restoration:

G-6 Original Corner & Accessories Not Found

H-6 Original Corner & Accessories Not Found

H-7 Original Corner & Accessories Not Found

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-6 Measured Mile between NE cor. & SE cor. Existing Anchor Post came close to splitting mile. Accepted Anchor Post as perpetuation of East 1/4 Post

H-6 Set 1/2" Re-rod with Cap at the Intersection of E-W, N-S 1/4 lines

H-7 Found 5/8" Re-rod 0.2' under asphalt

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-6 Nail & Cap in 24" Maple N 45° W 34.00'  
Nail & Cap in 12" Willow S 70° W 34.50'  
Nail & Cap in Twin 20" Maple S 05° 17.70'

H-6 Nail & Cap in 6" Ash N 05° W 19.85'  
Nail & Cap in 12" Scotch Pine N 20° E 28.05'  
Nail & Cap in 12" Scotch Pine N 45° E 31.12'

H-7 Nail in 36" Oak N 15° E 36.65'  
Nail in 36" Maple S 80° E 69.78'  
"PK" Nail in P.P. S 20° E 27.06'



SIGNED BY *George M. Young*

DATE July 27, 1976

SURVEYOR'S MICHIGAN REGISTRATION NO. 17640

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.

# LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT OF ACT 74, MICH. PA. 1971

FOR CORNERS OF:	LOCATED IN:	CORNER CODE NUMBER	FILE NO.
1. PUBLIC LAND SURVEY	1. 20 N. 1 W. 1	1-7	FILED
2. PROPERTY CONTROL ING IN SECTION	2. N. 1 W. 1		
3. MISCELLANEOUS PROPERTY IN SECTION	3. N. 1 W. 1		
4. FOR NO. RECORDED PLAT			
5. PRIVATE CLAIMS			

Oct 19 3 50 PM '78  
REGISTERED  
MICHIGAN  
RECORDATION

REGISTERED BY INDEX GROUP AND  
TOWNSHIP

I, Richard W. Steadman, do hereby certify that under appointment of F.A. of Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above were in a field survey on April 27, 1965 established or established, monumented, re-monumented, recovered or restored as expressed below and in accordance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 1, 2 and 3 above were, in a field survey on April 27, 1965 found, recovered, found or established or established as expressed below and in accordance with the rules of the Michigan State Board of Land Surveyors or by a Decree of a Court of law.

A. Description of original monument and accessories and in subsequent restoration:

Original Monument: wood post set by Harvey Parke, U.S. Deputy Surveyor in 1826; bearing trees: 9" Tamarac N19°E 150 lks. and 5" Tamarac S23°W 45 lks. In volume 3, Page 83, County Surveyor's Records, T. J. Brown, County Surveyor, notes this corner was lost and re-established by him May 30, 1874; "a stone 2 and a half feet long and tapering to about 3 inches square set small end up and top cross-marked, about even with the surface; the corner point from which a 11" Maple bears S84-1/4°W 231-2/3 lks."

B. Description of corner evidence found and/or method applied in restoring or re-establishing same:

Location of corner falls in former swampy area, now in road fill. Found no evidence of corner marker; re-established corner by double proportionate measure.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 1" Iron rod to mark the corner (falls 2 ft. West of C/L).

1978 Witnesses:	1/2" 28" Ash	S85°W	150.00 ft.
	Power pole	N45°W	55.76 ft.
	4" Elm	N18°E	63.28 ft.
	3" Wild Cherry	S35°E	26.60 ft.

SIGNED BY Richard W. Steadman DATE October 17, 1978

SURVEYOR'S MICHIGAN REGISTRATION NO. 11370


FOR STATE AND UNITED STATES AGENCIES

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. 1404

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, 1971  
MAY PLACE SKETCH ON BACK OR ATTACHED SHEET



VEVAY  
township

T 2N, R 1EW

I-7  
corner code attachment no.

0

p. 1 of 1

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

FILED

For corners in

Ingham  
 (County)

Located In:

Corner Code ==

- |                                    |                         |            |
|------------------------------------|-------------------------|------------|
| 1. Public Land Survey              | T <u>2N</u> R <u>1W</u> | <u>G-6</u> |
|                                    | T _____ R _____         | _____      |
|                                    | T _____ R _____         | _____      |
|                                    | T _____ R _____         | _____      |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____      |
|                                    | S _____ T _____ R _____ | _____      |
| 3. Miscellaneous Property in Sec.  | S _____ T _____ R _____ | _____      |
|                                    | S _____ T _____ R _____ | _____      |

FEB 21 3 20 PM '90  
 REGISTER OF DEEDS  
*Paula Johnson*  
 INGHAM COUNTY, MICH.

Register of Deeds Stamp &amp; File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_

I, James E. Stephens, in a field survey on February 19, 19 90, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

The original monument and accessories were not found.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

The anchor post identifying the  $\frac{1}{4}$  corner and the nails and caps called out as witnesses on the Land Corner Recordation in Liber 3, Page 618, had been obliterated. A  $\frac{1}{2}$ " diameter iron rod was found at the intersection of fences and two of the three trees were found which had been used previously as witnesses. The iron rod was accepted as perpetuating the location of the  $\frac{1}{4}$  corner as recorded.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

$\frac{1}{2}$ " diameter iron rod witnessed by tags nailed to:

West side Twin 18" Maple tree South 18.02 feet.  
 North side 12" Ash tree West 31.21 feet.  
 North side 14" Ash tree East 25.41 feet.  
 North side 24" Maple tree Northwest 33.73 feet.



Signed by

Date February 19, 1990

Surveyor's Michigan License No.

16053



**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

FILED

For corners in

Ingham  
(County)

Located In:

Corner Code ##

AUG 5 9 51 AM '91

REGISTER OF DEEDS

*Daniel J. Johnson*  
 INGHAM COUNTY, MICH.

- |                                    |                         |            |
|------------------------------------|-------------------------|------------|
| 1. Public Land Survey              | T <u>2N</u> R <u>1W</u> | <u>G-5</u> |
|                                    | T _____ R _____         | _____      |
|                                    | T _____ R _____         | _____      |
|                                    | T _____ R _____         | _____      |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____      |
|                                    | S _____ T _____ R _____ | _____      |
| 3. Miscellaneous                   | S _____ T _____ R _____ | _____      |
| Property in Sec.                   | S _____ T _____ R _____ | _____      |

Register of Deeds Stamp &amp; File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_

I, Maurice H. Mahieu, in a field survey on May 23, 19 91, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:

Original Monument and accessories obliterated


- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" Iron Rod, 40'± north of Kipp Road, in same location as corner recorded in Liber 3 of Land Corners, Page 616.

This corner is being re-recorded to update the witnesses

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

The 1/2" Iron Rod was left in position and witnessed by:  
 Nail and Tag #28414 N. Side 8" Poplar, N 85° E, 19.20 feet  
 Nail and Tag S. Side 24" Maple, N 80° E, 28.98 feet  
 Nail and Tag S. Side 12" Maple, N 50° E, 29.25 feet  
 Nail and Tag #28414 S. Side 10" Oak, N 50° E, 27.40 feet



Signed by Maurice H. Mahieu Date 6-24-91  
 Surveyor's Michigan License No. 28414