

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

NW CORNER SECTION 31, T2N, R1W, VEYAY TWP. LIBER 1 16 545

FILED

FOR CORNERS OF--

LOCATED IN--

CORNER CODE NUMBER

1. PUBLIC LAND SURVEY

2

S. R. 1

A-11

2. PROPERTY CONTROL-

ING IN SECTION

S. R. 1

3. MISCELLANEOUS

PROPERTY IN SECTION

S. R. 1

4. LOT NO. RECORDED PLAT

5. PRIVATE CLAIMS

JUN 26 10 32 AM '72

REGISTER OF DEEDS

Paul M. Lewis  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

1. Clyde K. Stephens

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram-over) were, in a field survey on June 15, 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on June 15, 1972, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:  
The original monument and accessories obliterated.

B. Description of corner evidence found and or method applied in restoring or re-establishing corner:  
A 3/4 inch iron pipe was set in the centerline of the two section line roads (Barnes Road and College Road), original dimension from the NE corner of Section 36 T2N, R2W, Aurelius Township.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
The 3/4 inch iron pipe set at the NE corner was witnessed with the following:  
Survey tag in the SW side of a utility pole N50°35'W 92.76 feet.  
Survey tag in the top of a fence post S83°40'W 50.36 feet.  
Survey tag in the top of a fence post S0°40'E 56.78 feet.  
N0°16'E 33.66 feet to a boat spike at the NE corner of Section 36, T2N, R2W.  
The bearing of the section line east of the corner is EAST.

SIGNED BY Clyde K. Stephens

DATE June 21, 1972

SURVEYOR'S MICHIGAN REGISTRATION NO. 3829


FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY \_\_\_\_\_ MICHIGAN REGISTERED LAND SURVEYOR

DATE



V/V/ary

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

N 1/4 CORNER SECTION 31, T2N, R1W,  
INGHAM COUNTY

LIBER 1 PG 547  
FILED.

FOR CORNERS OF: LOCATED IN: CORNER CODE NUMBER

1. PUBLIC LAND SURVEY T. 2 S. R. 1 B-11

2. PROPERTY CONTROLLING IN SECTION T. S. R.

3. MISCELLANEOUS PROPERTY IN SECTION T. S. R.

4. LOT NO. RECORDED PLAT

5. PRIVATE CLAIMS

JUN 26 10 33 AM '72

REGISTER OF DEEDS  
Clyde K. Stephens  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Clyde K. Stephens do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on June 5, 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:  
The original monument and accessories obliterated.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  
A railroad spike was set in the centerline of the section line road (Barnes Road) and on a line between the NE corner and the NW corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
The railroad spike set at the N 1/4 corner was witnessed with the following:

N43°42'W 121.90 feet to the SE corner of a 1 1/2 story frame house #3268.  
S65°29'E 107.19 feet to the northerly bolt of the NW leg of a transmission tower.  
Survey tag in the SE. side of a 30 inch Maple N31°45'E 32.46 feet.

SIGNED BY

Clyde K. Stephens

DATE June 21, 1972

SURVEYOR'S MICHIGAN REGISTRATION NO. 3829

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY


CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE



SURVEYOR'S MICHIGAN REGISTRATION NO.

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER

4 PG 37

FILED

FOR CORNERS OF—

LOCATED IN—

CORNER CODE NUMBER

1. PUBLIC LAND SURVEY 30 T. 2N S. R. 1W E. A-10, B-10

2. PROPERTY CONTROLL-  
ING IN SECTION T. S. R. E.

3. MISCELLANEOUS  
PROPERTY IN SECTION T. S. R. E.

4. LOT NO. RECORDED PLAT

5. PRIVATE CLAIMS

APR 29 3 29 PM '77

REGISTER OF DEEDS

Paul Johnson  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, George M. Young do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 4/18 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 4/18 1977, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

A-10 No record of corner being set

B-10 No record of corner being set

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-10 Set 1/2"x18" re-rod with cap mid-way between NW & SW corners and in accord with survey monuments found along East 1/4 line

B-10 Found 1/2" re-rod in line with North-South 1/4 line fence & in center of Rolf Road

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-10 #16 Nail in 15" Ash N 70° W 20.30'  
#16 Nail in 15" Ash S 10° W 73.50'  
#16 Nail in 20" Cherry N 45° E 44.79'  
Set 1/2"x18" Steel Re-rod with cap 0.1' under Road Surface

B-10 #16 Nail in 18" White Ash N 65° E 90.95'  
#16 Nail in 4" Pine S 05° W 45.35'  
#16 Nail in 12" Ash S 50° W 70.96'  
Found 1/2" Re-rod 0.2' under Road Surface



SIGNED BY George M. Young DATE April 20, 1977

SURVEYOR'S MICHIGAN REGISTRATION NO. 17640

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 17640

1047 Form No. 16-11735  
DOUGLASS & CO., ANN ARBOR, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970  
N.E. Cor. Sec 31, T2N, R1W, V184y Twp 15E2

4 16 191

FILED

FOR CORNERS OF--

LOCATED IN--

CORNER CODE NUMBER

1. PUBLIC LAND SURVEY	31	T.	2	N.	R.	1	W.	6-11
2. PROPERTY CONTROLLING IN SECTION		T.		N.	R.		W.	
3. MISCELLANEOUS PROPERTY IN SECTION		T.		N.	R.		W.	
4. LOT NO.	RECORDED PLAT							
5. PRIVATE CLAIMS								

APR 26 12 17 PM '78

REGISTER OF DEEDS

*Paula Johnson*  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Laverne J. Hendryx, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on Nov. 23, 1971, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

*Found iron*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

*Iron in 1st Barnes and T. H. R. Rd  
No. 1 40" Oak NNW 91.90  
Spr PP NW 57.30  
Spr Tol. pole NNE 76.74*

SIGNED BY Laverne J. Hendryx DATE Nov. 23/71


SURVEYOR'S MICHIGAN REGISTRATION NO. 3276

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_



FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
REVISED MAY 14, 1978

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY..... T. <u>2N</u> S. R. <u>1W</u> E. W.		A-8, A-9
2. PROPERTY CONTROL- ING IN SECTION..... T. N. S. R. E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION..... T. N. S. R. E. W.		
4. LOT NO. .... RECORDED PLAT .....		
5. PRIVATE CLAIMS .....		

LIBER 4 16 354

FILED

SEP 15 8 49 AM '78

REGISTER OF DEEDS

*Paula Johnson*  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, George M. Young, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 19, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on July 19, 1978, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

A-8 Corner not set in original public land survey.

A-9 Originally described monument, stone with tile, not evident.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-8 Found 1/2" pipe in monument box, 11.6' north of centerline of Lyons Road to East as per recordation, Liber 2, Page 313, West 1/4 corner.

A-9 Found capped monument in centerline College Road as indicated by Ingham County Remonumentation crew - Southwest section corner.

C. Description of monument for corner and accessories established to perpetuate locating the position:

A-8 Nail with Tag - 8" Elm SE 50.05'  
Nail with Tag - Power Pole WNW 55.33'  
P.K. Nail with ribbon - Power Pole SW 134.45'  
East 1/4 corner - Sec. 24, Aurelius Township - capped iron N 34.88'

A-9 Nail with Tag - R.L.S. 18998 - 12" Oak - SSE 102.71'  
Nail with Tag - R.L.S. 18998 - Fence Post NNE 50.28'  
U.S.C. & G.S. - Brass Cap on monument - marked "Sta. 17-0" NW 36.62"  
SE corner - Sec. 24 - Aurelius Township - capped monument at centerline  
Toles Road to West-North N 44.67'



SIGNED BY *George M. Young* DATE August 8, 1978

SURVEYOR'S MICHIGAN REGISTRATION NO. 17640 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

1318

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
REVISED MAY 14, 1978

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY----- T. <u>2N</u> S. <u>R. 1W</u> E.		<u>A-8, A-9</u>
2. PROPERTY CONTROLLING IN SECTION----- T. <u>      </u> N. <u>      </u> E.		
3. MISCELLANEOUS PROPERTY IN SECTION----- T. <u>      </u> S. <u>R.    </u> E.		
4. LOT NO.-----	RECORDED PLAT-----	
5. PRIVATE CLAIMS-----		

LIBER 4 16 354

FILED

SEP 15 8 49 AM '78

REGISTER OF DEEDS

*Paula Johnson*  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, George M. Young, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 19, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on July 19, 1978, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

A-8 Corner not set in original public land survey.

A-9 Originally described monument, stone with tile, not evident.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:


A-8 Found 1/2" pipe in monument box, 11.6' north of centerline of Lyons Road to East as per recordation, Liber 2, Page 313, West 1/4 corner.

A-9 Found capped monument in centerline College Road as indicated by Ingham County Remonumentation crew - Southwest section corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-8 Nail with Tag - 8" Elm SE 50.05'  
Nail with Tag - Power Pole NW 55.33'  
P.K. Nail with ribbon - Power Pole SW 134.45'  
East 1/4 corner - Sec. 24, Aurelius Township - capped iron N 34.88'

A-9 Nail with Tag - R.L.S. 18998 - 12" Oak - SSE 102.71'  
Nail with Tag - R.L.S. 18998 - Fence Post NNE 50.28'  
U.S.C. & G.S. - Brass Cap on monument - marked "Sta. 17-0" NW 36.62'  
SE corner - Sec. 24 - Aurelius Township - capped monument at centerline Toles Road to West-North N 44.67'



SIGNED BY George M. Young DATE August 8, 1978

SURVEYOR'S MICHIGAN REGISTRATION NO. 17640 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

1348

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
REVISED MAY 14, 1975

## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. <u>2</u> N. <u>1</u> E. <u>1</u> W.	<u>A-9</u>
2. PROPERTY CONTROLLING IN SECTION	T. <u>  </u> N. <u>  </u> S. <u>  </u> R. <u>  </u> E. <u>  </u> W. <u>  </u>	
3. MISCELLANEOUS PROPERTY IN SECTION	T. <u>  </u> N. <u>  </u> S. <u>  </u> R. <u>  </u> E. <u>  </u> W. <u>  </u>	
4. LOT NO. <u>  </u> , RECORDED PLAT <u>  </u>		
5. PRIVATE CLAIMS <u>  </u>		

USER

4 10 397

FILED

OCT 2 11 23 AM '78

REGISTER OF DEEDS

*Paul Johnson*  
 INGHAM COUNTY, MICH.  
 REGISTER OF DEEDS, STAMP AND  
 FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 18, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on   , 19  , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

## A. Description of original monument and accessories and/or subsequent restoration:

A-9

Post set by Harvey Parke in original government survey between February and March, 1826. Corner referred to in a survey by A. Jackson, County Surveyor, dated Dec. 23, 1857 (v.2, p.103).

Corner re-established as post, sleigh shoe and tile by W.A. Rowe, County Surveyor, in a survey dated March 29, 1897.

Corner identified as stone and tile by Wm. Barryman, County Surveyor, date unknown.

Corner identified as stone and tile by Ingham County Road Commission records in revised grid map, Jan. 1, 1972.

## B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-9

Excavated hole 6.4' x 7.8' to an average depth of 4.1' east of and including the centerline of College Road and + 49.7' south of the centerline of Toles Road. Found 3/4" pinched pipe at road surface, in centerline of College Road, + 40.0' south of M-9, T2N-R2W, Aurelius Twp. Found sleigh shoe surrounded by tile 2.9' below road surface, + 1.0' west of centerline of College Road, 44.70' south of M-9, T2N-R2W, Aurelius Twp. Accepted sleigh shoe and tile as corner described by W.A. Rowe in a survey noted above. Measured 44.70' north to M-9, T2N-R2W, Aurelius Twp. in close accord with G.L.O. falling distance of 44.88'

## C. Description of monument for corner and the method established to perpetuate locating the position of the corner:

A-9

Southwest Corner, Section 19, T2N-R1W

Set 4" x 36" concrete monument with 1/2" x 38" rerod with cap #18998 and concrete collar with cover at location of sleigh shoe described above:


Nail & tag, #18998, east side 24" Maple, NNW, 193.44'

Nail & tag, #18998, east side 22" Oak, SSE, 102.74'

Top center U.S. Geodetic Survey monument No. 17-0, NW, 44.66'

4" concrete monument with cap #18998, M-9, T2N-R2W, Aurelius Twp., North, 44.70'

SEE SKETCH ON OPPOSITE SIDE

SIGNED BY Ronnie M. LesterDATE 9/26/78SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

SIGNED BY

DATE

APPROVED AND SIGNED BY

DATE

LESTER  
LAND  
SURVEYOR  
1978

*Paul Johnson*  
 Director, Ingham County Survey and  
 Remonumentation Project

SURVEYOR'S MICHIGAN REGISTRATION NO. 17624

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
 REVISED MAY 14, 1978


MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

1387

Found Stone Pile

USER

4 10 398



2522624 \*000500 LK



## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF-- LOCATED IN-- CORNER CODE NUMBER

1. PUBLIC LAND SURVEY T. 2 N. R. 1 E. A-9

2. PROPERTY CONTROLLING IN SECTION T. S. R. E.

3. MISCELLANEOUS PROPERTY IN SECTION T. S. R. E.

4. LOT NO. , RECORDED PLAT

5. PRIVATE CLAIMS

LSEB

4 15 397

FILED

OCT 2 11 23 AM '78

REGISTER OF DEEDS

*Paul Johnson*  
 INGHAM COUNTY, MICH.  
 REGISTER OF DEEDS, STAMP AND  
 FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 18, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

## A. Description of original monument and accessories and/or subsequent restoration:

A-9

Post set by Harvey Parke in original government survey between February and March, 1826. Corner referred to in a survey by A. Jackson, County Surveyor, dated Dec. 23, 1857 (v.2, p.103).

Corner re-established as post, sleigh shoe and tile by W.A. Rowe, County Surveyor, in a survey dated March 29, 1897.

Corner identified as stone and tile by Wm. Barryman, County Surveyor, date unknown.

Corner identified as stone and tile by Ingham County Road Commission records in revised grid map, Jan. 1, 1972.

## B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-9

Excavated hole 6.4' x 7.8' to an average depth of 4.1' east of and including the centerline of College Road and + 49.7' south of the centerline of Toles Road. Found 3/4" pinched pipe at road surface, in centerline of College Road, + 40.0' south of M-9, T2N-R2W, Aurelius Twp. Found sleigh shoe surrounded by tile 2.9' below road surface, + 1.0' west of centerline of College Road, 44.70' south of M-9, T2N-R2W, Aurelius Twp. Accepted sleigh shoe and tile as corner described by W.A. Rowe in a survey noted above. Measured 44.70' north to M-9, T2N-R2W, Aurelius Twp. in close accord with G.L.O. falling distance of 44.88'

## C. Description of monument for corner and the steps established to perpetuate locating the position of the corner:

A-9

Southwest Corner, Section 19, T2N-R1W

Set 4" x 36" concrete monument with 3/4" x 38" rerod with cap #18998 and concrete collar with cover at location of sleigh shoe described above:


Nail & tag, #18998, east side 24" Maple, NNW, 193.44'

Nail & tag, #18998, east side 22" Oak, SSE, 102.74'

Top center U.S. Geodetic Survey monument No. 17-0, NW, 44.66'

4" concrete monument with cap #18998, M-9, T2N-R2W, Aurelius Twp., North, 44.70'

SEE SKETCH ON OPPOSITE SIDE

SIGNED BY Ronnie M. LesterDATE 9/26/78SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

SIGNED BY

DATE

APPROVED AND SIGNED BY

DATE

LESTER

Director, Ingham County Survey and

Remonumentation Project

SURVEYOR'S MICHIGAN REGISTRATION NO. 17624

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971

REVISED MAY 14, 1978

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

152 56 23

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. 2N N. S., R. 1W E. W.		C-9
2. PROPERTY CONTROLLING IN SECTION _____, T. _____ N. S., R. _____ E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____ N. S., R. _____ E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

FILED

OCT 18 4 00 PM '78

REGISTER OF DEEDS

*Paula Johnson*  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Richard W. Steadman, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October 7, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Original Monument: wood post set by Harvey Parke, U.S. Deputy Surveyor in 1826; bearing trees: 14" Beech N01°W 21 lks. and 9" Beech S25-1/2°W 10 lks. County Road Commission Records call for this corner to be marked by a 1" iron witnessed by: 26" Maple East 18.57 ft., 8" Elm S.W. 33.9 ft. (gone), 21" Maple N.N.W. 65.73 ft. I find no other reference to this corner in public records.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 1" iron rod in Tuttle Road opposite fences East and West.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Left 1" iron rod in place as found to mark the corner.

Witnesses: 26" Maple	East	18.57 ft.
21" Maple	N.N.W.	65.73 ft.
Anchor post	West	33.60 ft.

SIGNED BY Richard W. Steadman DATE October 13, 1978

SURVEYOR'S MICHIGAN REGISTRATION NO. 11370


(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_



1411

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

51 25

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 2N N. S. R. 1W E. W.	C-10
2. PROPERTY CONTROLLING IN SECTION	T. N. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

FILED

OCT 18 4 01 PM '78

REGISTER OF DEEDS

*Paula Johnson*

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Richard W. Steadman, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 11, 19 70, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Original Monument: wood post set by Harvey Parke, U.S. Deputy Surveyor in 1826; bearing trees: 10" Beech N85-1/2°W 21 lks. and 7" Beech S73°E 10 lks.

I find no further public record of this corner other than its use in a survey dated September 13, 1843 by Anson Jackson, County Surveyor, as recorded in Volume 1, Page 89, County Surveyor's Records.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found no evidence of the corner. Re-established corner by single proportionate measure. Location falls about 3 ft. West of the C/L of Tuttle Road and about on the C/L of Rolfe Road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 1/2" iron pipe to mark the corner.

Witnesses:	Telephone pole	N.E.	54.59 ft.
	Power pole	S.W.	40.55 ft.
	Telephone pole	S.E.	61.47 ft.

SIGNED BY Richard W. Steadman DATE October 13, 1978


SURVEYOR'S MICHIGAN REGISTRATION NO. 11370 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_



1413

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 23, 1971  
REVISED MAY 14, 1978

MAY PLACE SKETCH ON BACK OR ATTACH SHEET

## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF: LOCATED IN: CORNER CODE NUMBER

1. PUBLIC LAND SURVEY T. 2 N. R. 1 W. B-9

2. PROPERTY CONTROLLING IN SECTION T. N. S. R. E. W.

3. MISCELLANEOUS PROPERTY IN SECTION T. N. S. R. E. W.

4. LOT NO. , RECORDED PLAT

5. PRIVATE CLAIMS

5 PG 68

FILED

Nov 27 3 54 PM '78

REGISTER OF DEEDS

Paula Johnson

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 20, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

## B-9 Original monument and accessories obliterated

In March, 1897, W. A. Rowe, County Surveyor, Ingham County, calls for a post at the location of the corner.  
Milt Bailey, County Surveyor, called for a Post and Wire Fence. Date Unknown.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

## B-9 Set 1/2" Bar &amp; Cap at the Base of a Corner Post; fences East &amp; West, North &amp; South intersecting at corner post measure West, 2881.21', recorded G.L.O. 2869.68', Measure East 2647.45', recorded G.L.O. 2640.00'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-9 Set 1/2" Bar & Cap  
Nail & tag South side fence post, East, 12.86'  
Nail & tag NE side fence post, SE, 24.63'  
Nail & tag East side fence post, South, 20.08'  
Nail & tag North side 6" W. Cherry, West, 78.69'SIGNED BY Ronnie M. Lester DATE 11/22/78SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:


SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)



SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

1455

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

INGHAM COUNTY - VEWAY TWP.  
LAND CORNER RECORDATION CERTIFICATE  
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

1388 6 PC 140

FOR CORNERS OF --	LOCATED IN --	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T 2 N. R. 1 W.	B-11
2. PROPERTY CONTROLLED ING IN SECTION	N. S. R. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	N. S. R. W.	
4. LOT NO. RECORDED PLAT		
5. PRIVATE CLAIMS		

FILED

JAN 23 9 35 AM '81

REGISTER OF DEEDS  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on June 23, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on June 23, 1980, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- B-11 A. Description of original monument and accessories and/or subsequent restoration:  
Post set in original government survey by H. Parke, Feb. 28 - March 10, 1826. Old post, stone and brick found in a survey by W.A. Rowe, May 11, 1895, in Miscellaneous County Surveyor's field notes. Corner identified as a stone surrounded by brick in a survey by J. McCreary, December 3, 1898 (v.3, p.73). Corner referred to in Recorded Land Surveys by LaVerne Hendryx, RLS #3276, November 23, 1971 (L.1, p.167) and January 31, 1974 (L.2, p.208). Corner identified as a railroad spike in a Recorded Land Survey by Clyde K. Stevens, RLS #3829, May 6, 1972 (L.1, p.333). Corner recorded as a railroad spike set in the centerline of the section line road (Barnes Road) on line between NE and NW corner, by Clyde K. Stevens, RLS #3829, June 5, 1972 (L.1, p.547).
- B-11 B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  
Corner as recorded in L.1, p.547, is + 211' west of location as noted in original government notes and County Survey records dated in 1895. Excavated a 15' x 10' hole to an average depth of 2.5' on the centerline of Barnes Road at tree line north. No physical evidence found except pieces of broken tile. Corner set by placing on line between A-11 and C-11 at prorated G.L.O. distance. Corner falls + 6.0' south of the centerline of Barnes Road on east side of tree line north in area found pieces of tile. Measured east 2650.56'. Measured west 2875.20'.  
Excavation conducted by Ingham County Survey and Remonumentation Project crew.
- B-11 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
N $\frac{1}{2}$  Corner, Section 31, T2N-R1W  
Set 4" x 36" concrete monument with  $\frac{1}{2}$ " x 38" rerod and cap #18998 with concrete collar and cover in location described above:  
Nail & tag, #18998, north side power pole, WSW, 103.24'  
Nail & tag, #18998, southeast side 24" Maple, SW, 97.23'  
Nail & tag, #18998, east side 18" Walnut, North, 81.09'  
Nail & tag, #18998, southwest side power pole, North, 56.18'  
Railroad spike (recorded L.1, p.547), WNW, 211.33'


SIGNED BY Ronnie M. Lester DATE 1/22/81

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

SUBSTITUTE

SIGNED BY GARY D. [Signature] DATE 1/22/81  
APPROVED AND SIGNED BY [Signature]  
DIRECTOR, Ingham County Survey  
and Remonumentation Project

SURVEYOR'S MICHIGAN REGISTRATION NO. 17624



For corners in  
Ingham

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 6 PAGE 396

FILED

SEP 23 8 44 AM '88

REGISTER OF DEEDS

Phyllis Johnson  
INGHAM COUNTY, MICH.

Register of Deeds Stamp & File Number

	Located In:	Corner Code
1. Public Land Survey	T 2N R 1W	C-11
	T R	
	T R	
	T R	
2. Property Controlling In Section	S T R	
	S T R	
3. Miscellaneous Property In Sec.	S T R	
	S T R	
4. Lot No.	Recorded Plat	
5. Private Claims		

I, Ronnie M. Lester, in a field survey on September 15, 19 88, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.


	A	B	C	D	E	F	G	H	I	J	K	L	M
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

A. Description of original monument and accessories and/or subsequent restoration:

C-11 Original monument and accessories obliterated.  
This corner recorded Liber 4, Page 191 by L. Hendryx in April 1978 based on work performed Nov. 1971.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-11 No evidence of iron as called for in Liber 4, Page 191.  
Set 1/2" bar at location of Liber 4, Page 191 using two existing accessories.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-11 Set 1/2" bar at intersection of Barnes and Tuttle Roads.  
Found nail and white shiner in Northeast side utility pole, 328° az, 57.3'  
Found nail and white shiner in East side 48" oak, 350° az, 91.9' <sup>90°</sup>  
Set nail and tag in West side triple 8" oak, 173° az, 117.8' <sup>90°</sup>  
Set nail and tag in South side 20" oak, 82° az, 134.0' <sup>F7</sup>

Signed by Ronnie M. Lester  
Surveyor's Michigan License No. 18998

Date September 17, 1988

2142

55C

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 1971  
REVISED MAY 14, 1978  
REVISED JAN., 1983

396

144

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

FILED

For corners in

INGHAM

(County)

(VEVAY TWP.)

Located In:

Corner Code #

1. Public Land Survey

T 2N R 1W

A-11

2. Property Controlling  
In Section

S

T

R

3. Miscellaneous  
Property in Sec.


S

T

R

JAN 30 8 35 AM '88

REGISTER OF DEEDS

  
 INGHAM COUNTY, MICH.

Register of Deeds Stamp &amp; File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, Ronald L. Enger, in a field survey on July 26, 19 88, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

## A. Description of original monument and accessories and/or subsequent restoration:

A-11 Refer to Corner Recordation Certificate found in Liber 1, Page 545.

Monument is described as 3/4" Iron Pipe.

Witnesses: Utility Pole, N50.35W, 92.76'; Fence Post, S83.40W, 50.36'; Fence Post, S0.40E, 56.78'; Boat Spike (M-11, T2N, R2W), N0.16E, 33.66'.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-11 Found 3/4" Iron Pipe and proved it to be according to previous recordation by the Top of Fence Post in the SW quadrant, the Top of another Fence Post in the SW quadrant, the Power Pole in the NW quadrant, and the Boat Spike to the North at M-11, T2N, R2W. Accepted the 3/4" Iron Pipe as the corner position.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-11 3/4" Iron Pipe

Survey Tag in Top of Fence Post, S0°40'W, 56.78'

Survey Tag in Top of Fence Post, S83°40'W, 50.36'

Survey Tag in SW side of Power Pole, N50°35'W, 92.76'

Boat Spike (M-11, T2N, R2W), North, 33.74'

3/4" Iron Pipe monumenting A-11 is on the East boundary of T2N, R2W between M-11 and M-12.

Corner recovered for Superconducting Super Collider Project surveys.

Signed by



Date

25 Nov 88

Surveyor's Michigan License No. 28409

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
 REVISED MAY 14, 1975  
 REVISED JAN., 1983

2232

86 747

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in  
**INGHAM**

**FILED**

**JAN 30 8 35 AM '88**

**REGISTER OF DEEDS**  
*R. Johnson*  
**INGHAM COUNTY, MICH.**

Register of Deeds Stamp & File Number

	Located In:	Corner Code #/
1. Public Land Survey	T 2N R 1W	B-10
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec	S T R	
	S T R	
4. Lot No.	Recorded Plat	
5. Private Claims		

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	15	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, **Ronald L. Enger**, in a field survey on **September 15**, 19 **88** do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessions and/or subsequent restoration:


B-10 Corner previously recorded on April 29, 1977 in Liber 4, Page 37 by George M. Young, LS# 17640 as: Found  $\frac{1}{2}$ " Rerod with witnesses: 18" White Ash, N65E, 90.95'; 4" Pine, S05W, 45.35'; 12" Ash, S50W, 70.96'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

B-10 Found  $\frac{1}{2}$ " Rerod and proved it to be at corner position as previously recorded by the 18" White Ash (actually a Walnut, still 18") in the NE quadrant and the 12" Ash (Actually a Walnut, now 15") in the SW quadrant.

C. Description of monument for corner and accessions established to perpetuate locating the position of the corner.

B-10  $\frac{1}{2}$ " Rerod  
 Nail and Tag #18998 in North Side of 15" Walnut, 248NAZ, 71.0'  
 NE Corner Frame Garage #3265, 235NAZ, 105.4'  
 Nail and Tag in South Side of 18" Walnut, 80NAZ, 90.4'  
 NW Leg of Electrical Tower (3' off ground), 174NAZ, 49.1'  
 $\frac{1}{2}$ " Rerod is in centerline of Rolfe Road



Corner recovered for Superconducting Super Collider Project surveys.

Signed by *R. Enger*  
 Surveyor's Michigan License No. 28409

Date **28 Nov 88**

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
 REVISED MAY 14, 1975  
 REVISED JAN. 1982

2233



**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

FILED

For corners in

INGHAM

Located In:

Corner Code ##

JAN 30 8 35 AM '89

REGISTER OF DEEDS

INGHAM COUNTY, MICH.

Register of Deeds Stamp &amp; File Number

1. Public Land Survey	T	2N	R	1W	C-9
	T		R		
	T		R		
	T		R		
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Sec	S	T	R		
	S	T	R		
4. Lot No.					Recorded Plat
5. Private Claims					

	A	B	C	D	E	F	G	H	I	J	K	L	M
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

I, Ronald L. Enger, in a field survey on September 15, 1988 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-9 Refer to Corner Recordation Certificate found in Liber 5, Page 23.  
 Corner described as 1" Iron Rod.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-9 Found 1" Iron Rod and proved it to be at corner position as previously recorded by the 21" Maple bearing tree (now 36") in the NW quadrant, and the Anchor Post to the West.

C. Description of monument for corner and accessories established to perpetuate locating the position of corner:

C-9 1" Iron Rod  
 Nail and Tag on East side of 36" Maple, 340°NAZ, 65.7'  
 Nail and Tag # 11370 in South side of Anchor Post, 277°NAZ, 33.8'  
 Nail and Tag in West side of Twin 10" Box Elder, 177°NAZ, 148.4'  
 Nail and Tag in West Root of 40" Maple, 87°NAZ, 16.1'  
 Iron Rod is 1' below asphalt an centerline of Tuttle Road and on fence line to the West.

Corner recovered for Superconducting Super Collider Project surveys.

Signed by

*R. Enger*

Date 28 Nov 88

Surveyor's Michigan License No.

28409

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
 REVISED MAY 14, 1975  
 REVISED JAN. 1983

2236

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

FILED

For corners in

INGHAM

County

(VEVAY TWP.)

Located In:

Corner Code ##

JAN 30 8 35 AM '89

REGISTER OF DEEDS

*Paul Johnson*  
 INGHAM COUNTY, MICH.

Register of Deeds Stamp &amp; File Number

1. Public Land Survey

T 2N. R 1W

C-10

2. Property Controlling

S

T

R

in Section

S

T

R

3. Miscellaneous

S

T

R

Property in Sec.

S

T

R

4. Lot No.

Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	16	17	18	19	20	21	22	23	24				
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Ronald L. Enger, in a field survey on September 15, 1988, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below


NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-10 Refer to Corner Recordation Certificate found in Liber 5, Page 25.  
 Corner is described as a 1/2" Iron Pipe.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-10 Found 1/2" Iron Pipe and proved it to be at corner position as previously recorded by the Power Pole in the SW quadrant and the Telephone Pole in the SE quadrant.



C. Description of monument for corner and accessories established to perpetuate locating the position of

C-10 1/2" Iron Pipe

Nail and Tag # 11370 in NW side of Utility Pole, 230°NAZ, 40.4'

Nail and Tag # 11370 in NE side of Utility Pole, 120°NAZ, 61.5'

SW Corner of Brick House # 1693, S5°NAZ, 153.2' ✓

NW Corner of Brick House (# unknown), 128°NAZ, 142.5' ✓ 1761

Pipe is 3' West of centerline of Tuttle Road and on centerline of Rolfe Road

Corner recovered for Superconducting Super Collider Project surveys.

Signed by

Date 28 NOV 88

Surveyor's Michigan License No.

28409

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
 REVISED MAY 14, 1975  
 REVISED JAN. 1982

2237