

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Liber 9 Page 352

For corners in
VEVAY TOWNSHIP
INGHAM COUNTY

Located In:

Corner Code #

1. Public Land Survey

T 2N R 1W

K-12

2. Property Controlling
in Section

3. Miscellaneous
Property in Sec.

S T R

S T R

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Maurice H. Mahieu, in a field survey on September 24, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. ORIGINAL GLO CORNER WAS SET IN MAY/JUNE 1825, BY HERVEY PARKE, D.S.
"40.00 SET 1/4 SEC. POST FW 9 BEECH 8 IN. N78 1/2 W 16 LKS; W. OAK, 14", S
62 E 40 LKS NOTED IN BOOK 2, PAGE 25.

2. COUNTY SURVEYOR A. JACKSON V1, P93 NOTES BEECH 8 N 78 1/2 W 16 LKS; W.
OAK 14 S 62 E 40 LKS; SEPT. 6, 1845.

3. COUNTY SURVEYOR A. JACKSON L4A, P92 NOTES W. OAK 14 S62E 40; SEPT. 6, 1945.

4. COUNTY SURVEYOR A. JACKSON L4A, P51 NOTES W. OAK 20 N63W 21 LKS; FEB. 16, 1848.

5. COUNTY SURVEYOR A. JACKSON IN FOLDER SET #2 P.72B NOTES BEECH 8N 78 1/2 W 16 LINKS; W. OAK 14 S62E 40 LINKS;
NOVEMBER 7, 1856.

(CONTINUED ON BACK)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1" IRON ROD, ± 6' SOUTH OF S. EDGE OF TWO-TRACK DRIVEWAY, 1' WEST OF FALLEN DOWN NORTH-SOUTH FENCE. FOUND WITNESSES: NAIL & TAG # 18998 SOUTH SIDE 12" ASH, N70°E 63.33'; NAIL & TAG # 18998 EAST SIDE TWIN 8" POPLAR, S55°W 28.76'; NAIL & TAG #18998 SOUTH SIDE 10" CHERRY, N45°W, 51.65 FEET (TREE DEAD); NAIL & TAG #18994 WEST SIDE 12" QUADRUPLE ASH S85°E. 1" IRON ROD IN GOOD CONDITION, LEFT IN PLACE AND RE-WITNESSED. THE 1" IRON FOUND APPEARED TO BE IN THE SAME LOCATION AS IRON SET BY FRED WHITE, WHO SET IT IN LOCATION ESTABLISHED BY COUNTY SURVEYORS.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

FOUND 1" IRON ROD AND LEFT IN PLACE, ATTACHED PLASTIC CAP STAMPED "PA 345, PS 28414" TO TOP AND LEFT IN POSITION.
WITNESSED BY:

SET NAIL AND TAG #28414, EAST SIDE 10" TWIN POPLAR, S55°W, 29.56 FEET
SET NAIL AND TAG #28414, SOUTH SIDE 10" ASH, N60°W, 45.76 FEET
SET NAIL AND TAG #28414, WEST SIDE 8" TWIN CHERRY, N30°E 27.50 FEET
SET NAIL AND TAG #28414, NORTH SIDE 12" OAK, S45°E 35.53 FEET

Signed by Maurice H. Mahieu
Surveyor's Michigan License No. 28414

Date 9-17-98



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975

REVISED JAN, 1983
REVISED OCT., 1995

P.A. 345 INGHAM COUNTY
PEER APPROVED 8/11/98

A. (CONTINUED)

6. COUNTY SURVEYOR A. JACKSON IN L3, P1245 NOTES CHERRY 17 N 12E 40; MAPLE 10 N 84 ½ E 21; NOVEMBER 7, 1856.
7. LCRC RECORDED IN LIBER 3, PAGE 393 BY FRED WHITE P.S. #12034, IN JUNE 22, 1975 "FOUND ANCHOR POST ON LINE WITH FENCE EAST, SOUTH AND TREE ROW TO NORTH. SET ½" IRON BAR AT BASE OF WEST SIDE OF ANCHOR POST. CORNER IN ACCORD WITH G.L.O. DISTANCES. WITNESSES: NAIL & TAG 12" ASH, N 70° E 63.33'; NAIL AND TAG 8" TWIN POPLAR S 55° W 28.76'; NAIL AND TAG 10" WILD CHERRY N 45° W 51.65'.
8. AN ACT 132 SURVEY RECORDED IN LIBER 2, PAGE 366 ON JUNE 22, 1975 BY FRED WHITE PS #12034 MONUMENTATION AND WITNESSES SAME AS A-7.
9. AN ACT 132 SURVEY RECORDED IN LIBER 2, PAGE 999 ON JUNE 22, 1977 BY FRED WHITE PS #12034 MONUMENTATION AND WITNESSES SAME AS A-7.
10. AN ACT 132 SURVEY RECORDED IN LIBER 4, PAGE 231 ON FEBRUARY 27, 1981 BY FRED WHITE PS #12034 MONUMENTATION AND WITNESSES SAME AS A-7.
11. AN ACT 132 SURVEY RECORDED IN LIBER 4, PAGE 234 ON FEBRUARY 27, 1981 BY FRED WHITE PS #12034 MONUMENTATION AND WITNESSES SAME AS A-7.
12. AN ACT 132 SURVEY RECORDED IN LIBER 5, PAGE 47 ON SEPTEMBER 26, 1986 BY GEORGE YOUNG PS #17640. FOUND ANCHOR POST WITNESSES SAME AS A-7.
13. AN ACT 132 SURVEY RECORDED IN LIBER 5, PAGE 123 ON DECEMBER 12, 1986 BY RONNIE LESTER PS #18998. NO MONUMENTATION GIVEN. NAIL AND TAG 3" TWIN COTTONWOOD, SW 28.38'; NAIL AND TAG 10" CHERRY, NW, 50.95'; NAIL AND TAG 10" CHERRY, SE 10.15'; NAIL AND TAG 15" ASH, NE 63.56'; MEASURED 5301.02 TO I-12, 2653.21 TO K-11.
14. AN ACT 132 SURVEY RE-RECORDED IN LIBER 5, PAGE 1238 ON DECEMBER 11, 1989 BY MAURICE MAHIEU PS #28414. MONUMENTATION AND WITNESSES SAME AS A-12. MEASURED 5299.23 TO M-12.
15. AN ACT 132 SURVEY RE-RECORDED IN LIBER 6, PAGE 669 ON NOVEMBER 19, 1990 BY MAURICE MAHIEU PS #28414. MONUMENTATION AND WITNESSES SAME AS A-12. MEASURED 5299.23 TO M-12.
16. AN UNRECORDED SURVEY ON JUNE 16, 1994 BY LARRY BRYAN PS 25832 FOUND 1" BAR AT FENCE INTERSECTION, FENCES EAST-WEST AND SOUTH. FOUND NAIL & TAG SOUTH SIDE 24" ASH, N 70° E 63.33; FOUND NAIL & TAG NORTHEAST SIDE 10" CHERRY N 45° W 51.65'; FOUND NAIL & TAG EAST SIDE TWIN 12" POLAR S 55° W 28.76'; FOUND NAIL & TAG NORTH SIDE 10" CHERRY, S 75° E 10.17'. MEASURED 2653.25 TO K-11.
17. AN ACT 132 SURVEY RECORDED IN LIBER 7, PAGE 387 ON NOVEMBER 15, 1994 BY RON HELSEL, P.S. #18994 FOUND 1" BAR IN EAST-WEST FENCE LINE & FENCE TO SOUTH. FOUND NAIL AND TAG #18998 IN SOUTH SIDE OF 10" CHERRY, S85° E 9.90'; FOUND NAIL AND TAG #17640 IN SOUTH SIDE OF 10" CHERRY, S85° E, 10.15'; FOUND NAIL AND TAG #18998 IN EAST SIDE OF 10" TWIN POPLAR, S40° W 28.76'; SET NAIL AND TAG #18998 IN WEST SIDE OF 12" QUAD. ELM, SOUTH 22.07'; SET NAIL AND TAG #18998 IN EAST SIDE OF 6" CHERRY, N10° W, 21.84'.

Rept No	97035
CRNR	9.00
MSSR	2.00
Total	11.00

5/9-

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Liber

9 Page 286

For corners in
VEVAY TOWNSHIP
INGHAM COUNTY

Located In:

Corner Code #

FILED

970047751
12/02/1997 13:38:27
REGISTER OF DEEDS
Paula Johnson
INGHAM COUNTY, MI

1. Public Land Survey T 2N R 1W K-13
T R
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Maurice H. Mahieu, in a field survey on September 23, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. ORIGINAL GLO CORNER WAS SET BY JOHN MULLETT, D.S. IN MAY 1825 "80.00 SET POST COR. OF SECT. 35 & 36 FW B OAK 16 N86 1/2E 50; W. OAK 18 N19W 22"

2. COUNTY SURVEYOR A. JACKSON ON SEPT 6, 1845 SURVEYED THE SW 1/4 OF SECTION 36 AS NOTED IN BOOK 1, PAGE 92. NO MENTION OF CORNER MONUMENTATION. WITNESSES SAME AS A-1 WITH AN ADDITION OF HACK 8, S45W 64 (DRAKE).

3. COUNTY SURVEYOR A. JACKSON ON NOVEMBER, 1856 NOTES "HACK 8 S45W 64" THIS INFORMATION IS FROM 1980 REMON PROGRAM DOSSIER.

(SEE BACK FOR CONTINUANCE)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND IRON FENCE POST CENTERLINE OF PLAINS ROAD. FOUND WITNESSES: NAIL & TAG #28414, WEST SIDE DOUBLE 10" WALNUT, N50°E, 48.33'; NAIL & TAG #28414, NORTH SIDE 10" HICKORY, S65°W 33.75' (TREE DEAD); NAIL & TAG #28414, EAST SIDE 15" WALNUT N30°W, 40.89'. OTHER WITNESSES OBLITERATED. EXCAVATED FENCE 2'X2'X2.5' DEEP HOLE SURROUNDING FENCE POST. FOUND NO EVIDENCE OF ANY HISTORICAL MARKER OTHER THAN FENCE POST. OBSERVATION OF THE RELATIVE ELEVATION OF EXCAVATION AREA AND SURROUNDING LANDSCAPE SHOWED EVIDENCE OF PRIOR CUT AND SUBSEQUENT FILL ACTIVITIES. THEREFORE NO FURTHER EXCAVATION WAS PERFORMED. REPLACED FENCE POST WITH 3/4" IRON ROD AND CAP STAMPED "PA 345 PS 28414" AND SET MONUMENT BOX AND COVER OVER IT. THERE WAS NO OTHER EVIDENCE IN THE AREA TO SUGGEST A DIFFERENT POSITION FOR THIS CORNER AND THEREFORE ACCEPTED THE POSITION OF THE FENCE POST AS THE PERPETUATED LOCATION FOR THIS CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 3/4" x 24" IRON ROD WITH CAP STAMPED "PA345 PS28414" IN LOCATION OF FOUND FENCE POST. WITNESSED BY:
NAIL & TAG #28414, WEST SIDE DOUBLE 10" WALNUT, N50°E 48.32 FEET
NAIL & TAG #28414, EAST SIDE 15" WALNUT, N30°W, 40.83 FEET
NAIL & TAG #28414, NORTH SIDE POWER POLE, S60°E, 105.94 FEET
NAIL & TAG #28414, EAST SIDE 18" WALNUT, S58°W, 73.97 FEET
Found 1/2" rod in monument box (A-13, Leslie Twp.) N 85° W 73.15 feet

Signed by Maurice H. Mahieu
Surveyor's Michigan License No. 28414

Date 10-10-97



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975

77061 6 5986 581

REVISED JAN. 1993
REVISED OCT. 1995

P.A. 345 INGHAM COUNTY
PEER APPROVED 9/29/97 M

SECTION A CONTINUED:

4. LCRC IN LIBER 2, PAGE 321 RECORDED ON FEB. 6, 1973, BY RICHARD W. STEADMAN, P.S. #11370. "OPPOSITE FENCE LINE NORTH, FOUND STEEL FENCE POST "T" CROSS SECTION JUST BELOW ROAD SURFACE. LEFT ABOVE MONUMENTATION IN PLACE AND TOOK THE FOLLOWING WITNESSES:
NAIL & TAG IN SOUTHERLY TRUNK OF TWIN 12" OAK, NNE 39.38 FT.
NAIL & TAG IN 8" WALNUT; NW, 41.10 FT.
NAIL & TAG IN 48" OAK; WNW 84.11 FT."
5. AN ACT 132 SURVEY WAS RECORDED IN LIBER 1, PAGE 606 ON FEB. 8, 1973 BY RICHARD W. STEADMAN, P.S. #11370. MONUMENTATION AND WITNESSES SAME AS A-4
6. AN ACT 132 SURVEY WAS RECORDED IN LIBER 3, PAGE 475 ON AUG 16, 1978 BY AUSTIN WILLIAMS, P.S. #21275. NO MONUMENTATION WAS GIVEN. THE WITNESSES SAME AS A-4
7. AN ACT 132 SURVEY WAS RECORDED IN LIBER 3, PAGE 1073 ON NOV. 7, 1979 BY AUSTIN WILLIAMS, P.S. #21275. NO MONUMENTATION WAS GIVEN. THE WITNESSES SAME AS A-4.
8. AN ACT 132 SURVEY WAS RECORDED IN LIBER 5, PAGE 48 ON SEPT. 26, 1986 BY GEORGE YOUNG, P.S.#17640. MONUMENTATION AND WITNESSES SAME AS A-4.
9. AN ACT 132 SURVEY WAS RECORDED IN LIBER 5, PAGE 1179 ON OCT 18, 1989 BY RON HELSEL, P.S. #18994. ONLY REFERENCE TO CORNER WAS THE LIBER AND PAGE AS A-4.
10. AN ACT 132 SURVEY WAS RECORDED IN LIBER 5. Page 1242 and rerecorded in Liber 6, Page 673 on Dec. 11, 1989 and Mar 8, 1991 by this surveyor. Monumentation and witnesses for this corner same as A-4.
11. AN ACT 132 SURVEY WAS RECORDED IN LIBER 6, PAGE 323 ON AUG 9, 1990 BY THIS SURVEYOR. MONUMENTATION AND WITNESSES FOR THIS CORNER SAME AS A-4.
12. AN ACT 132 SURVEY WAS RECORDED LIBER 6, PAGE 548 ON NOV. 28, 1990 BY RON HELSEL, P.S. # 18994. "FOUND "T" FENCE POST; WITNESSED BY: SET NAIL AND TAG, TWIN 16" OAK, N5°E, 39.00'
FOUND NAIL & TAG, 10" WALNUT, N45°W 41.10'
SET NAIL & TAG, 8" WALNUT, N45°E, 48.62'
FOUND BAR AND CAP, NORTH, 33.00"
13. AN ACT 132 SURVEY WAS RECORDED IN LIBER 6, PAGE 1246 ON JULY 9, 1993 BY THIS SURVEYOR. "FOUND "T" BAR, WITNESSED BY:
N & T #28414 N. SIDE 10" HICKORY S65°W, 33.75'
N & T #28414 E. SIDE 15" WALNUT, N30°W, 40.89'
N & T #28414 E. SIDE 12" CHERRY, N10°E, 32.97'
N & T #28414 W. SIDE (2) 10" WALNUT, N50°W, 48.33'
14. AN ACT 132 SURVEY WAS RECORDED IN LIBER 7, PAGE 786 ON MAY 10, 1996 BY RONNIE M. LESTER P.S. #18998. " SOUTHWEST CORNER SECTION 36, T2N, R1W, VEYAY TWP. L2, PAGE 321. T BAR. CONCRETE MONUMENT AT K-1 LESLIE MAG. AZ. 278°, 73.06'; FOUND NAIL AND TAG #28414 WEST SIDE DOUBLE 10" WALNUT MAG. AZ. 57°, 48.42'; FOUND NAIL AND TAG #28414 NORTH SIDE 10 SHAGBARK MAG. AZ. 243°, 33.78'; FOUND NAIL AND TAG #28414 N.E. SIDE 12" WALNUT MAG. AZ. 332°, 40.89"

INVESTIGATION
BENTON JOHNSON
REGISTERED DEEDS
1510517331 73:38:51
2100-1127

FILED

1996 2 28 586

Liber 9 Page 354

For corners in VEVAY TOWNSHIP

INGHAM COUNTY

Located In:

Corner Code #

1. Public Land Survey

T 2N R 1W

L-12

2. Property Controlling In Section

S

T R

3. Miscellaneous

S

T R

Property in Sec.

S

T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims

I, Maurice H. Mahieu, in a field survey on September 24, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. Corner not set in original GLO survey.

2. County Surveyor A. Jackson in collection of various surveys Vol. 1 P.24 notes W. Oak 34 S11E 11 ½ Cherry 8 S 81 ½ E 19, Sept. 6, 1845.

3. County Surveyor A. Jackson Vol. 1, P.93 notes W. Oak 34 S 11E 11 ½ Cherry 8 S 81 ½ E 19, Sept. 6, 1845.

4. County Surveyor A. Jackson L4A, P92 notes Cherry 8 S 81 ½ E 19, Maple 12 N 84 ½ E 21, Sept. 6, 1845.

5. County Surveyor A. Jackson in Folder Set #2 P.72B notes W. Oak 34 S 11E 11 ½ links Cherry 8 S 81 ½ E 19 links, November 7, 1856.

6. County Surveyor A. Jackson L3, P124 notes W. Oak 34 S 11E 11 ½ Cherry 8 S 81 ½ E 19, November 7, 1856.

(Continued On Back)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" iron and cap #25832 0.5' West of North-South fence line and 0.5' North of East-West fence line. Found no witness tags. Accepted position of corner set by Surveyor Bryan as the perpetuated location set by previous County Surveyors. Pulled 1/2" iron rod and set 3/4" x 24" iron rod with aluminum P.A. 345 cap stamped "28414 - Ingham County". Measured 2644.81' to M-12; 2644.42' to L-11; 2648.73' to L-13; and 2648.32' to K-12.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 1/2" Iron rod with cap #25832, replaced with 3/4" x 24" iron rod and aluminum cap stamped #28414 Ingham County".

Witnessed by:

Set Nail and Tag #28414 North side 24" Oak, N 80° E, 7.99'

Set Nail and Tag #28414 South side Quadruple 10" Basswood, N 30° W, 21.02'

Set Nail and Tag #28414 West side 10" Hickory, South, 14.71'

Set Nail and Tag #28414 North side 12" Basswood, S 80° W 26.20'

Signed by *D. J. Jaurin*
Surveyor's Michigan License No. 28414

Date 9/22/98



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975

P.A. 345 INGHAM COUNTY

PEER APPROVED: 9/22/98

REVISED JAN, 1983
REVISED OCT, 1995

A. (CONTINUED)

7. Notes from miscellaneous Ingham County Survey records Bk #15 P.118, Oak post set in ground witnessed by stump of Oak as recorded in the survey made by Jackson. Made new witnesses: B. Oak 12 N 47 1/2° E 49 1/2'; DO 6 N 76° W 13'; December 22, 1899.
8. County Surveyor E. A. Calkins in Folder Set #2 Page 72A notes 12 B. Oak, N 47 1/2° E 49 1/2' links; 6 B. Oak, N 76° W 13 links, December 22- 23, 1899.
9. County Surveyor E. A. Calkins in L1, Page 6 notes found oak post with stump of witness made by Jackson at proper distance from which post bears B. Oak 12, N 47 1/2° E, 49 1/2' lks DO 6, N 76° W, 13 lks, December 22-23, 1899.
10. LCRC recorded in Liber 6, Page 269 by Larry Bryan PS #25832 in March 29, 1985 "Set 1/2" bar at base of corner post, fence lines North, South & East, West corner called for in Folder 2, Page 72A of the Ingham County Remonumentation records." Witnessess: set Nail & Tag North side 20" Oak N 80° E 7.45'; Set Nail & Tag North side 8" Ash, West, 13.44'; Set Nail & Tag Southeast side 8" Hickory, S 50° W, 12.00'.

Rcpt No	97035
CRMR	9.00
MSSR	2.00
Total	11.00

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Liber

9 Page

290

FILED

970047753
12/02/1997 13:38:30
REGISTER OF DEEDS
Paula Johnson
INGHAM COUNTY, MI

For corners in
VEVAY TOWNSHIP
INGHAM COUNTY

Located In:

Corner Code #

1. Public Land Survey

T 2N R 1W

M12

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Maurice H. Mahieu, in a field survey on September 22, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.


A. Description of original monument and accessories and/or subsequent restoration:
1. ORIGINAL GLO CORNER WAS SET IN MAY/JUNE 1825 BY JOSEPH WAMPLER, D.S
"40.00 Set 1/4 Sec. Post from which a W. Oak 14 N14W 11; Ash 13 S31W 27"

2. COUNTY SURVEYORS A. JACKSON IN 1845, A. JACKSON IN 1856, AND E. A. CALKINS IN 1899 ALL DID SURVEYS IN THE N.E. 1/4 OF SECTION 36 BUT NONE SHOWED ANY REFERENCE TO MONUMENTATION OR WITNESSES FOR THIS CORNER.

(See back for continuance)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
FOUND 1/2" IRON ROD IN CONCRETE MONUMENT IN THE CENTERLINE OF KELLY ROAD. KELLY ROAD HAS BEEN NEWLY WIDENED AND PAVED IN SEPTEMBER, 1997. ALL WITNESSES FROM A-3 WERE OBLITERATED AT TIME OF RECONSTRUCTION OF KELLY ROAD. 1/2" ROD AND MONUMENT ARE IN GOOD CONDITION. SET MONUMENT BOX OVER THE EXISTING IRON AND MONUMENT. LEFT IN PLACE AS THE MONUMENT IS THE CORRECT LOCATION FOR A LOST CORNER AS STATED IN LCRC LIBER 6, PAGE 69. Set cap #28414 on rod.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
1/2" IRON ROD IN CONCRETE MONUMENT WAS LEFT IN PLACE AND WITNESSES BY:
NAIL & TAG #28414, WEST SIDE UTILITY POLE N9°E, 212.53 FEET
NAIL & TAG #28414, EAST SIDE 12" HICKORY, N20°W, 74.33 FEET
NAIL & TAG #28414, EAST SIDE 10" ELM, S52°W 33.17 FEET
NAIL & TAG #28414, WEST SIDE UTILITY POLE, S19°E 74.75 FEET



Signed by Maurice H. Mahieu
Surveyor's Michigan License No. 28414

Date 10-10-97

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975

REVISED JAN. 1983
REVISED OCT. 1995

P.A. 345 INGHAM COUNTY
PEER APPROVED 9/25/97

M12 VEVAY
PAGE 2

SECTION A - CONTINUED

3. LCRC RECORDED IN LIBER 6, PAGE 69 BY RONNIE M. LESTER / GARY D. LESTER, P.S. 18998/17624 ON AUG. 4, 1980. CORNER WAS RECORDED AS PART OF THE 1979/80 CETA INGHAM COUNTY REMONUMENTATION PROGRAM. "EXCAVATED A HOLE 10'X10' TO AN AVERAGE DEPTH OF 3.0' ON THE CENTERLINE OF KELLY ROAD. FOUND BOARDS WITH NAILS AROUND NORTH AND SOUTH PERIMETER OF EXCAVATION SITE. APPEARS TO BE BROKEN FENCE LINE. FOUND PIECES OF FENCE $\pm 2'$ BELOW ROAD SURFACE. NO OTHER EVIDENCE FOUND. CORNER CONSIDERED LOST. SET CORNER MIDWAY AND ON LINE BETWEEN M-13 AND M-11. MEASURED NORTH AND SOUTH 2648.75. MEASURED SOUTH TO A-13, 1358.97'; MEASURED NORTH TO A-12, 1262.59'. MONUMENT FALLS 10.2' WEST OF EAST EDGE OF KELLY ROAD. EXCAVATION CONDUCTED BY INGHAM COUNTY SURVEY AND REMONUMENTATION PROJECT CREW. SET 4"X36" CONCRETE MONUMENT WITH 1/2"X36" REBROD AND CAP #18998 IN LOCATION DESCRIBED ABOVE. WITNESSED BY:

NAIL & TAG #18998, NORTHEAST SIDE 8" BASSWOOD, ESE, 22.87'

NAIL & TAG #18998, WEST SIDE 24" BASSWOOD, SE, 35.82'

NAIL & TAG #18998, SOUTHWEST SIDE 24" OAK, SOUTH, 92.68'

NAIL & TAG #18998, EAST SIDE 8" HICKORY, NORTH 74.21'

4. AN ACT 132 SURVEY RECORDED IN LIBER 5, PAGE 47 BY GEORGE M. YOUNG, P.S. #17640 ON SEPT. 9, 1986 USED CORNER ON SURVEY. THE MONUMENTATION AND WITNESSES ARE THE SAME AS A-3

5. AN ACT 132 SURVEY RECORDED IN LIBER 5, PAGE 1238 AND RERECORDED IN LIBER 6, PAGE 669 ON DECEMBER 11, 1989 AND MARCH 8, 1991 BY THIS SURVEYOR FOUND THE SAME MONUMENTATION AND WITNESSES AS A-3

INGHAM COUNTY, MI
REGISTERED DEED
1510517221 13:38:30
210041123

FILED

SEP 1991

SEP 1991

SEP 1991

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Liber 9 Page 288

FILED

970047752
12/02/1997 13:38:29
REGISTER OF DEEDS
Paula Johnson
INGHAM COUNTY, MI

For corners in
VEVAY TOWNSHIP
INGHAM COUNTY

Located In:

Corner Code #

- | | | | |
|-------------------------|---|-----------|------|
| 1. Public Land Survey | | T 2N R 1W | L-13 |
| | | T | R |
| | | T | R |
| | | T | R |
| 2. Property Controlling | S | T | R |
| in Section | S | T | R |
| 3. Miscellaneous | S | T | R |
| Property in Sec. | S | T | R |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Maurice H. Mahieu, in a field survey on September 22, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. ORIGINAL GLO CORNER WAS SET BY JOHN MULLETT D.S. IN MAY, 1825 " 40.00 SET 1/4 SEC. POST ; B. OAK 20, N88 1/2E 274; SUGAR 8 N89W 700"

2. COUNTY SURVEYOR A. JACKSON, ON SEPTEMBER 5 & 6, 1845 USED CORNER. RECORDED IN BOOK 4, PAGE 92. NO MONUMENTATION SHOWN, WITNESSED BY: B. OAK 20 N88 1/2E, 274; SUGAR 8 N89W 700

3. COUNTY SURVEYOR A. JACKSON, ON NOVEMBER 7, 1856. RECORDED IN BOOK1, PAGE 93, USED CORNER, GAVE NO INFORMATION ON MONUMENTATION. WITNESSES SAME AS A-1

CONTINUED ON BACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" IRON ROD WITH CAP #18998 IN PLAINS ROAD. FOUND NAIL & TAG#18998, WEST SIDE POWER POLE N75°E, 103.03 FEET. DISCUSSED CORNER WITH RONNIE M. LESTER P.S. 18998 AND DETERMINED THE LOCATION OF THE FOUND 1/2" ROD IS THE SAME POSITION AS THE MONUMENT SET IN 1980. THE ROAD HAS BEEN FILLED SINCE 1980 AND LARGE PONDS ARE ON EITHER SIDE OF THE ROAD. DID NOT EXCAVATE AREA DUE TO EVIDENCE OF PRIOR EXTENSIVE FILL ACTIVITIES. REPLACED 1/2" IRON ROD WITH 3/4"x24" IRON PIN WITH CAP STAMPED PA 345, PS #28414. THE LOCATION OF THIS CORNER IS THE PROPER POSITION BASED ON PREVIOUS RESTORATION OF THIS CORNER BY RONNIE M. LESTER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" x 24" IRON PIN SET IN PLACE OF 1/2"x18" ROD; WITNESSED BY:
NAIL & TAG #28414 N. SIDE 8" ELM S48°E, 200.60FEET
NAIL & TAG #28414, NORTHWEST SIDE UTILITY POLE N75°E, 103.27 FEET
3/4" CAPPED IRON PIN #28414 (L-1, LESLIE TWP) WEST 36.56 FEET
SOUTH EDGE "NO STOPPING, STANDING, PARKING" ROAD SIGN POST, S70°W, 45.65 FEET

Signed by Maurice H. Mahieu
Surveyor's Michigan License No. 28414

Date 10-10-97



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975

REVISED JAN, 1983

REVISED OCT., 1995

P.A. 345 INGHAM COUNTY
PEER APPROVED 9/25/97 *m*

2 b936 582

SECTION A CONTINUED

4. LCRC RECORDED IN LIBER 6, PAGE 121 BY RONNIE M. LESTER / GARY D. LESTER, P.S. #18998/17624 ON DEC. 8, 1980 RECORDED CORNER AS A PART OF CETA INGHAM COUNTY SURVEY AND REMONUMENTATION PROJECT OF 1980. "SECTION A: POST SET IN ORIGINAL GOVERNMENT SURVEY BY HARVEY PARKE, FEB. 28, MARCH 10, 1826. SECTION B: INVESTIGATION REVEALED EXCAVATION SITE TO BE FUTILE AND UNSAFE AS LOCATION OF CORNER LIES IN FILL AREA ACROSS A POND. CORNER CONSIDERED LOST. SET CORNER MIDWAY ON LINE BETWEEN K13 AND M13 VEWAY. LOCATION OF CORNER FALLS ± 2.5 ; NORTH OF CENTERLINE OF PLAINS ROAD, ± 29.5 ' EAST OF FENCE LINE SOUTH. MEASURED WEST 2643.6; TO K13 AND 2643.55 TO M-13 AND WEST 36.55' TO L-1 LESLIE TWP. INVESTIGATION CONDUCTED BY INGHAM COUNTY SURVEY AND REMONUMENTATION PROJECT CREW. SET 4"x36" CONCRETE MONUMENT WITH $\frac{1}{2}$ "x38" REROD AND CAP#18998 IN LOCATION DESCRIBED ABOVE, WITNESSED BY:

NAIL & TAG #18998, WEST SIDE POWER POLE NE, 103.03'
NAIL & TAG #18998, SOUTHWEST SIDE 8" ELM, NE 138.78'
NAIL & TAG #18998, NORTH EDGE ROAD SIGN, SW, 45.85'
NAIL & TAG #18998, EAST SIDE 10" TWIN ASH, SW, 40.65'
 $\frac{1}{2}$ " bar, L-1, Leslie Twp. T1N, R1W, West, 36.55'

5. An Act 132 survey recorded in Liber 5, Page 47, by George M. Young, P.S. #17640 on Sept. 9, 1986 used corner on survey. The monumentation and witnesses are the same as A-4.

6. An Act 132 survey recorded in Liber 5, Page 1238 and rerecorded in Liber 6, Page 669 on December 11, 1989 and March 8, 1991 by this surveyor found the same monumentation and witnesses as A-4

7. An Act 132 survey recorded in Liber 6, Page 1246 on July 9, 1993, by this surveyor indicated a 1"x36" rod was set. In subsequent research, and information obtained by Ronnie M. Lester, P.S. 18998, it was determined that the 1" rod was set 300 feet too far west from the proper position. The corner in A-4 was finally used as the corner.

INGHAM COUNTY MI
REGISTERED DEEDS
510517001 12:38:50
510021125

FILED

FILED 2 1986 588

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Liber

9 Page 280

For corners in
LESLIE TOWNSHIP
INGHAM COUNTY
(County)

Located In:

Corner Code #

FILED

970047748
12/02/1997 13:38:22
REGISTER OF DEEDS
Paula Johnson
INGHAM COUNTY, MI

1. Public Land Survey

T 1N R 1W M-1

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

M-13, T2N, R1W, Vevay Township

4. Lot No. , Recorded Plat

5. Private Claims

I, Maurice H. Mahieu, in a field survey on August 25, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. ORIGINAL GLO CORNER WAS SET IN MAY, 1825 BY JOSEPH WAMPLER, D.S. "80.00 SET POST COR. OF TOWNS 1 & 2 N, RANGE 1W; W. OAK 18 S79W 26; DO 11 N44W 22 1/2"

2. LCRC RECORDED IN LIBER 5, PAGE 53, BY RONNIE M. LESTER/GARY D. LESTER P.S. #'S 18998/17624 AS A PART OF THE 1978 INGHAM COUNTY SURVEY & REMONUMENTATION PROGRAM, EXCAVATED HOLE 10'X6' TO AN AVERAGE DEPTH OF 2.5 FEET AT THE INTERSECTION OF THE CENTERLINE OF KELLY AND PLAINS ROADS. FOUND LARGE, FLAT BROKEN SANDSTONE 1.6 FEET BELOW SURFACE, ABOVE BROKEN PIECE OF IRON MACHINERY SURROUNDED BY CROCKERY, 2.2 FEET BELOW SURFACE, +2.0 FEET NORTH OF CENTERLINE OF PLAINS ROAD AND ±1.0 FEET EAST OF CENTERLINE OF KELLY ROAD. ACCEPTED IRON AND CROCKERY AS CORNER. MEASURED ±2645 FEET SOUTH TO M-2, LESLIE TWP., T1N, R1W IN CLOSE ACCORD TO GLO MAP. SET 4"X36" CONCRETE MONUMENT WITH 1/2" X 28" ROD WITH CAP #18998 AND CONCRETE COLLAR WITH COVER AT LOCATION OF IRON DESCRIBED ABOVE:

NAIL & TAG #18998, SOUTHEAST SIDE 30" MAPLE, SSE 92.49'
NAIL & TAG #18998, SOUTHWEST SIDE 24" MAPLE, SE 49.86'
NAIL & TAG #18998, SOUTHWEST SIDE 15" WALNUT, SE, 48.26'
NAIL & TAG #18998, SOUTHWEST SIDE FENCE CORNER POST, NE, 34.78' (See other side)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
FOUND 1/2" IRON REBAR IN CONCRETE MONUMENT, 1.5' NORTH OF C/L PLAINS ROAD AND 3.5' WEST OF C/L KELLY ROAD. FOUND THE FOLLOWING WITNESSES: (NEW) NAIL & TAG #18998 N. SIDE 24" WALNUT, S56°E 47.91'; (OLD) NAIL & TAG #18998 S.W. SIDE 24" WALNUT, S56°E 48.27'; (NEW) NAIL & TAG W. SIDE 32" MAPLE, S24°E, 49.16'; C/L 36" MAPLE, S13°E 91.85'; (NEW) NAIL & TAG #18998 S. SIDE UTILITY POLE, N49°W, 40.94'. AREA HAS BEEN EXCAVATED IN PREVIOUS REMONUMENTATION PROGRAM AND NO ADDITIONAL EXCAVATION WAS PERFORMED. LEFT THE 1/2" REBAR IN CONCRETE MONUMENT IN PLACE, PLACED CAP #28414 ON REBAR, AND ACCEPTED AS THE PERPETUATED POSITION OF CORNER. THERE IS NO CONFLICTING EVIDENCE TO SUPPORT ANY DIFFERENT LOCATION FOR CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
1/2" REBAR WITH CAP #28414 WAS LEFT IN PLACE AND WITNESSED WITH THE FOLLOWING:

NAIL AND TAG #18998, SOUTH SIDE UTILITY POLE N49°W, 40.94 FEET
NAIL AND TAG #18998, NORTH SIDE 24" WALNUT, S56°E, 47.91 FEET
NAIL AND TAG WEST SIDE 32" MAPLE, S24°E, 49.16 FEET
NAIL AND TAG #28414, SOUTH SIDE 15" MAPLE, N64°E, 53.85 FEET



Signed by Maurice H. Mahieu DATE 10-10-97

Surveyor's Michigan License No. 28414

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN 28, 1971
REVISED MAY 14, 1975

REVISED JAN, 1983

P.A. 345 INGHAM COUNTY 2 b336 587
PEER APPROVED 9/25/97 AL

M-1 CONTINUED
PAGE 2

PART A:

3. ACT 132 SURVEY RECORDED IN LIBER 3, PAGE 1070 ON NOV. 7, 1979, BY AUSTIN C. WILLIAMS, P.S. 21275 CALLS FOR CORNER AS S.E. CORNER OF SECTION 36, T2N, R1W. NO MENTION OF CORNER MATERIAL.

WITNESSED BY: NAIL & TAG SW/S 30" MAPLE SSE 92.49'

NAIL & TAG SW/S 24" MAPLE SE 49.86'

NAIL & TAG SW/S 15" WALNUT SE 48.26'

4. ACT 132 SURVEY RECORDED IN LIBER 6, PAGE 196 ON JUNE 10, 1990, BY LARRY BRYAN, P.S. 25832, CALL FOR CORNER AS N.E. CORNER OF SECTION 1, T1N, R1W. FOUND BAR & CAP #18998 AT CENTERLINE OF PLAINS & KELLY ROADS, LIBER 5, PAGE 53; WITNESSED BY

FOUND NAIL & TAG #18998 SOUTHEAST SIDE FENCE POST, N45°E, 34.66'

FOUND NAIL & TAG #18998 SOUTHWEST SIDE 30" WALNUT S60°E, 48.26'

"+" STAMPED ON U.S.G.S. BENCHMARK MONUMENT, N45°W, 36.62'

5. ACT 132 SURVEY RECORDED IN LIBER 6, PAGE 524 ON NOV. 28, 1990, BY RON HELSEL, P.S. #18994 CALLS FOR CORNER AS S.E. CORNER OF SECTION 36, T2N, R1W, Refers to LCRC Liber 5, Page 53.



INDEXED COPY
REGISTER OF DEEDS
JAN 10 1991

FILED

1990

2 1990

580