

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICHIGAN P.A. 1970
W 1/4 corner, Section 6, T3N, R1E, Wheatfield Township
Ingham County

FOR CORNERS OF: LOCATED IN: CORNER CODE NUMBER
1. PUBLIC LAND SURVEY T. 3N. R. 1E. A-2
2. PROPERTY CONTROLLING IN SECTION
3. MISCELLANEOUS PROPERTY IN SECTION
4. LOT NO. RECORDED PLAT
5. PRIVATE CLAIMS

Nov 23 1 35 PM '76

REGISTER OF DEEDS

INGHAM COUNTY, MICH

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, James E. Stephens, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above identified with circles on index code diagram - over were, in a field survey on November 2, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 10, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law;

A. Description of original monument and accessories and/or subsequent restoration:
The original monument and accessories were not found.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
A 1 inch iron rod in a monument box was found in the centerline of Meridian Road on a projection of a fence line East of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
The 1 inch iron rod in a monument box found at the W 1/4 corner was left in position with the following witnesses;

Tag no. 11370 found on the North side of a 6" Oak tree, N43°50'E 37.90 feet.
Tag no. 11370 found on the North side of a 30" Oak tree, N89°13'E 29.86 feet.
Tag no. 11370 found on the SW side of a 24" Oak tree, N39°W 37.73 feet.

SIGNED BY: James E. Stephens DATE: November 3, 1976

SURVEYOR'S MICHIGAN REGISTRATION NO. 16053

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

DATE



LAND CORNER

FILING REQUIREMENT

FOR CORNERS OF: LOCATED
1. PUBLIC LAND SURVEY T. 3N. R. 1E. A-2
2. PROPERTY CONTROLLING IN SECTION
3. MISCELLANEOUS PROPERTY IN SECTION
4. LOT NO. RECORDED PLAT
5. PRIVATE CLAIMS

1. Marvin F. Fouty

the corner points mentioned in lines 1 and 2 above identified with circles on index code diagram - over were, in a field survey on November 2, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 10, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law;

A. Description of original monument and accessories and/or subsequent restoration:
The original monument and accessories were not found.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
A 1 inch iron rod in a monument box was found in the centerline of Meridian Road on a projection of a fence line East of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
The 1 inch iron rod in a monument box found at the W 1/4 corner was left in position with the following witnesses;

Tag no. 11370 found on the North side of a 6" Oak tree, N43°50'E 37.90 feet.
Tag no. 11370 found on the North side of a 30" Oak tree, N89°13'E 29.86 feet.
Tag no. 11370 found on the SW side of a 24" Oak tree, N39°W 37.73 feet.

SIGNED BY: James E. Stephens DATE: November 3, 1976

SURVEYOR'S MICHIGAN REGISTRATION NO. 16053

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

DATE

30 JUNE 70

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER

4 B 220

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 3 N. R. 1 E.	0-3
2. PROPERTY CONTROLLING IN SECTION	T. S. R. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

FILED

JUN 30 1 19 PM '78

REGISTER OF DEEDS

Dana Johnson

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Marvin F. Fouty, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 8-16, 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 8-16, 1973, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

8-3 Original monument and accessories obliterated.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

8-3 Found 1/2" iron bar in monument box in Linn Road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

8-3 NW corner Section 8, T3N, R1E, 1/2" bar in monument box. ✓
 Nail and Tag West side 3" Elm North 25.41' GONE
 Nail and Tag in Utility Pole ENE 86.09' 11370
 Nail and Tag in 3" Elm ESE 55.55' GONE

SIGNED BY Marvin Fouty DATE 6-26-78SURVEYOR'S MICHIGAN REGISTRATION NO. 18989

FOR STATE AND UNITED STATES AGENCIES:


SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)



SURVEYOR'S MICHIGAN REGISTRATION NO. _____

1217

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 3N S. R. 1E E. W.	A-2
2. PROPERTY CONTROLLING IN SECTION	T. N. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

LIBER 5 N 138
FILED

JAN 16 3 01 PM '79
REGISTER OF DEEDS
Paul Johnson
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Richard W. Steadman, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on April 26, 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on April 26, 1973, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

The County Surveyor customarily established closing quarter corners, since they were not included in the procedure for the United States Survey of the Public Lands; however, I find no surveys for this section in the Ingham County Surveyors Records.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found railroad spike in the center of Meridian Road opposite fenceline East; dug hole but found nothing.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced railroad spike with 3/4" iron pipe and set monument box.

Witnesses:	30" Oak	East	29.86 ft.
	5" Oak	N.E.	37.83 ft.
	24" Oak	N.W.	37.70 ft.

SIGNED BY Richard W. Steadman DATE January 10, 1979

SURVEYOR'S MICHIGAN REGISTRATION NO. 11370

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

DATE



16 JAN 79

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 3N S. R. 1E E. W.	C-2
2. PROPERTY CONTROLLING IN SECTION	T. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. E. W.	
4. LOT NO. _____	RECORDED PLAT _____	
5. PRIVATE CLAIMS _____		

LIBER 5 PG 140
FILED

JAN 16 3 01 PM '79

REGISTER OF DEEDS

Paula Johnson
INGHAM COUNTY, MICH.REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Richard W. Steadman, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on May 7, 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Original Monument: wood post set by Joseph Wampler, U.S. Deputy Surveyor in 1826; bearing trees: 11" Beech S34°E 16 lks. and 11" Beech N42°W 29 lks. I find no further mention of this corner in public records except for a marginal note on Page 72 of the Ingham County copy of the USPLS Field Notes: 6" Elm N67-1/2°E 62-1/2 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found no evidence of the corner other than an East-West fenceline. Found anchor post at the 1/8 post next East and at the center of the section next East. Projected this line West and set corner the same distance West of 1/8 post that 1/8 post is West of center of section. Corner falls in East-West fence.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2" iron drive shaft 4 ft. long with 6" bell end just above ground level to mark the corner.

Witnesses: 7" Basswood ✓	N.W.	7.73 ft.
14" Basswood ✓	W.S.W.	13.92 ft.
14" Oak	E.S.E.	35.85 ft.


SIGNED BY Richard W. Steadman DATE January 10, 1979SURVEYOR'S MICHIGAN REGISTRATION NO. 11370

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____



1527

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF— LOCATED IN— CORNER CODE NUMBER

1. PUBLIC LAND SURVEY T. 3 N. R. 1 E. A-3

2. PROPERTY CONTROLLING IN SECTION T. N. S. R. E. W.

3. MISCELLANEOUS PROPERTY IN SECTION T. N. S. R. E. W.

4. LOT NO. RECORDED PLAT

5. PRIVATE CLAIMS

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 9, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

A-3

Post set in original government survey by Joseph Wampler dated Feb.-March, 1826.

Corner identified as 3/4" iron pipe in Consumers Power records dated 1960, and in MDSHT Government Monument Witness Form 280, no date given.

Corner identified as iron in Jamestown Plat L.27, P.44-45 by Max Rogers, R.L.S. #6637 dated Jan. 6, 1967.

Corner identified as 3/4" pipe by Ingham County Road Commission records dated Jan. 1, 1969.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-3

Excavated a 10' x 16' hole to an average depth of 2.2', at the intersection of the centerlines of Linn and Meridian Roads. Found a 3/4" x 1.6' iron pipe with P.K. nail in center, in upright position, 1" below road surface, + 1.0' south of centerline of Linn Road and + 2.0' east of centerline of Meridian Road. Found railroad spike at road surface, + 4.0' west of centerline of Meridian Road and on centerline Linn Road. Accepted 3/4" iron pipe for corner as called for in surveys noted above. Measured + 2630' north to A-2. Measured + 635' east to C-3 in close accord to G.L.O. distance.

Excavation conducted by Ingham County Survey and Remonumentation Project crew.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-3

NW Corner, Section 7, T3N-R1E

Set 4" x 36" concrete monument with 1/2" x 38" rerod and cap #18998, with concrete collar and cover at location described above:

Found nail & tag, #11370, east side 30" Walnut, SW, 68.97' FD

3" iron anchor post at ground level, NE, 38.33' FD

Top northwest corner, 4" concrete Road Way marker, ESE, 81.56' FD

Nail & tag, #18998, west side 20" Box Elder, NE, 76.96' FD

SIGNED BY Ronnie M. Lester

DATE 3/5/79

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

XX

SIGNED BY

DATE

APPROVED AND SIGNED BY

DATE 3/16/79

CHIEF OF SURVEY PARTY

MICHIGAN REGISTERED LAND SURVEYOR

Director, Ingham County Survey and Remonumentation Project

SURVEYOR'S MICHIGAN REGISTRATION NO. 17624

