

SOURCE: CORNER RECORDATION CERTIFICATE

TRANSCRIBED from ORIGINAL on file at REGISTER OF DEEDS
DUPLICATE

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 4 PG 97

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY 36 T. 2N S. R. 2E		K-11, L-11
2. PROPERTY CONTROLLING IN SECTION		
3. MISCELLANEOUS PROPERTY IN SECTION		
4. LOT NO. RECORDED PLAT		
5. PRIVATE CLAIMS		

FILED

SEP 23 11 26 AM '77

REGISTER OF DEEDS
Ingham County, Mich.
Ingham County, Mich.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, George M. Young, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on May 28, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on May 28, 1977, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

K-11 NW Corner
14" White Oak, S77°E 1.57 lks or Ch
13" White Oak, N42 1/2°E 1.50 lks or Ch
Lost

L-11 N 1/4 Post
5" Black Oak N39°E 45 lks
7" Black Oak S82°E 65 lks
Lost

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

K-11 Set corner by double proportionate between west 1/4 post of Section 25 & 36 & North 1/4 posts of 35 & 36.

L-11 Dug 10' dia. hole found rotted of Anchor Post surrounded by stone accepted old post as perpetuation of original corner. Set 1/2"x24" re-rod with cap in middle.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-11 #16 Nail & Cap in 15" Ash N 75°E 106.42'
#16 Nail & Cap in 6" Elm S 45°W 18.92'
Railroad spike in 36" Oak S 50°E 142.28'
Set 1/2"x24" re-rod with cap 6' West of traveled c/l of Brogan Road.
L-11 #16 Nail & Cap in 36" Oak N05°W 14.57'
#16 Nail & Cap in Twin 24" Oak S30°W 49.60'
#16 Nail & Cap in Twin 12" Oak S89°W 49.11'
Set 1/2"x24" Re-rod in Middle of rotted anchor post.



SIGNED BY George M. Young DATE June 8, 1977

SURVEYOR'S MICHIGAN REGISTRATION NO. 17640

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 16, 1978

SOURCE: CORNER RECORDATION CERTIFICATE

TRANSCRIBED from ORIGINAL on file at REGISTER OF DEEDS
~~DUPLICATE~~

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970
LIBER 2 R 269

FOR CORNER OF:	LOCATED IN:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T 2 N. R. 2 E.	N-12
2. PROPERTY CONTROL LING IN SECTION	S. R. 1	
3. MISCELLANEOUS PROPERTY IN SECTION	S. R. 1	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

FILED
DEC 12 1972
REGISTER OF DEEDS
JAMES M. LINDSEY
JACKMAN COUNTY, MICH.
REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, George M. Young, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on Dec 24, 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1972, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and of subsequent restoration:
Original corner lost and obliterated.

B. Description of corner evidence found and of method applied in restoring or re-establishing corner:
Reestablished corner from old witnesses and from previous survey information which checked in same square with witnesses.

C. Description of monument for corner and accessories established to perpetuate location and position of the corner:
Set 1/2" iron rod capped.

45° 44.52' R.R. spk in 21" Oak
NE 50.90' R.R. spk in Telephone Pole
SE 53.04' R.R. spk in 21" Hickory
SE 43.43' center of U.S. 2nd. BM



SIGNED BY George M. Young

DATE Dec. 5, 1972

SURVEYOR'S MICHIGAN REGISTRATION NO. 1746
FOR STATE AND UNITED STATES AGENCIES

SIGNED BY

DATE

APPROVED AND SIGNED BY

DATE

SURVEYOR'S MICHIGAN REGISTRATION NO.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

SOURCE: CORNER RECORDATION CERTIFICATE

TRANSCRIBED from ORIGINAL on file at REGISTER OF DEEDS
~~DUPLICATE~~

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH.

FOR CORNERS OF: LOCATED IN: CORNER CODE NUMBER
1. PUBLIC LAND SURVEY 1. 2 N. R. 2 E. L-12
2. PROPERTY CONTROLLING IN SECTION 1 N. R. 1 E.
3. MISCELLANEOUS PROPERTY IN SECTION 1 N. R. 1 E.
4. LOT NO. RECORDED PLAT
5. PRIVATE CLAIMS

Filed
Dec 8 12 30 PM '72
REGISTER OF DEEDS
JAMES M. HAMIL
INGHAM COUNTY, MICH.
REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, George H. Young, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on Dec 4, 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1972, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
Original corner lost and obliterated,

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
Excavated roadway and found old cast iron rod in line with north and south quarter line fence,

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Set 1 1/2" iron rod capped,

SW 20.00' R.R. spk in 42" Oak,
WNW 60.35' R.R. spk in 42" Gycamore,
N 26.00' R.R. spk in Anchor Post,
ESE 64.59' R.R. spk in 24" Walnut.



SIGNED BY *George H. Young*
SURVEYOR'S MICHIGAN REGISTRATION NO. 17640

DATE Dec 8, 1972

FOR STATE AND UNITED STATES AGENTS

SIGNED BY _____

DATE

APPROVED AND SIGNED BY _____

DATE

SURVEYOR'S MICHIGAN REGISTRATION NO.

SOURCE:

CORNER RECORDATION CERTIFICATE

TRANSCRIBED from ORIGINAL on file at REGISTER OF DEEDS
DUPLICATE

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 3 PG 527

FOR CORNERS OF: LOCATED IN: CORNER CODE NUMBER

1. PUBLIC LAND SURVEY 25 1 2 EX 2 M-9, M-11

2. PROPERTY CONTROLING IN SECTION

3. MISCELLANEOUS PROPERTY IN SECTION

4. DATE NO. RECORDED DEED

5. PRIVATE CLAIMS

FILED

FEB 3 8 39 AM '78
REGISTER OF DEEDS
Ann Arbor, Mich.
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, **Oscar Boss**, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above identified with circles on index code diagram - over - were, in a field survey on **July 17**, **1974**, established, re-established, monumented, re-monumented, recovered or restored as expressed above and in conformity with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on **July 17**, **1974**, found, recovered, restored, established or re-established as expressed below and in conformity with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of Law:

A. Description of original monument and accessories and/or subsequent restoration:

M-9 Unknown
M-11 Unknown

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

M-9 1/2" Iron Pd.
M-11 1/2" Pipe Pd.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-9, Section 25
N. 34°W 22.85 nail fd NE/S 36" tree
N. 13°E 75.90 nail fd W/S 10" Hickory
S. 17°E 121.47 nail fd N/S dble trunk 40" tree

M-11, Section 25
S. 43°W 37.06 nail fd SE/S dble trunk tree
Due East 43.03 nail fd N/S 54" Oak
S. 30°E 78.03 nail set S/S 16" tree

SIGNED BY *Oscar Boss*

DATE 1-29-78

SURVEYOR'S MICHIGAN REGISTRATION NO. 13574

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE

SURVEYOR'S MICHIGAN REGISTRATION NO.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

926

Form No. 85 8726
INCORPORATED & CO., ANN ARBOR, MICH.

INGHAM COUNTY-WHITE OAK TWP.
LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY.....	T. <u>2</u> N. <u>2</u> E. <u>W</u> S. R. <u>2</u> W.	M-13
2. PROPERTY CONTROLLING IN SECTION.....	T. <u> </u> N. <u> </u> E. <u> </u> S. R. <u> </u> W. <u> </u>	
3. MISCELLANEOUS PROPERTY IN SECTION.....	T. <u> </u> N. <u> </u> E. <u> </u> S. R. <u> </u> W. <u> </u>	
4. LOT NO.	RECORDED PLAT.....	
5. PRIVATE CLAIMS		

LIBER 5 PG 237

FILED

APR 23 2 15 PM '79

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 15, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on , 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
M-13

Post set in original government survey by J. Wampler in November, 1825.
Corner identified as a post in a survey by T.J. Brown, County Surveyor, dated January, 1858 (v.2, p.329).

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
M-13

Excavated a hole 8' x 9' to an average depth of 4', east of the centerline of Kane Road and on a fence line to the west. Found a pointed rock (4" x 20") with sleigh shoe along its northwest side, + 5.0' east of the centerline of Kane Road and on fence line to the west and + 4.5' north of the fence line to the east. Measured north + 5335' to M-11 in close accord with T.J. Brown survey noted above. Accepted sleigh shoe for corner.
Excavation conducted by Ingham County Survey and Remonumentation Project crew.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
M-13

SE Corner, Section 36, T2N-R2E
Common Corner to T1N-R2E, T2N-R3E, and T1N-R3E
Set 4" x 36" concrete monument with 1/2" x 38" rerod with cap #18998 in location of sleigh shoe described above:
Nail & tag, #18998, north side 18" Oak, East, 212.32'
Nail & tag, #18998, east side 5" Red Cedar, SE, 28.71'
Nail & tag, #18998, northeast side 6" Corner Post, ESE, 20.95'
Nail & tag, #18998, southwest side 6" Wood Gate Post, WNW, 28.97'

SIGNED BY Ronnie M. Lester DATE April 4, 1979

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

SIGNED BY

CHIEF OF SURVEY PARTY

DATE


DATE 4-20-79

Director, Ingham County Survey and
Remonumentation Project

REGISTRATION NO. 17624

1620

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET



FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 22, 1971
REVISED MAY 14, 1975