

REMONUMENTATION
(K 03) SOUTHWEST CORNER SECTION 1, T4N-R1E, WILLIAMSTOWN TWP, INGHAM CO, MI.

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ingham

(County)

Located In:

Corner Code#

1. Public Land Survey

T 4 N R 1 E

K 03

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. Recorded Plat

5. Private Claims

B:12 P:230

12/15/05

11:14 AM

Pages: 2

2005-066836 LAND CORNERES Receipt #4196

Paula Johnson, Ingham County, Michigan



I, Ronald R. Harris, in a field survey on March 30, 2005
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore
as required in the current manual of survey instructions of the United States Department
of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the
corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the
Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1) MARCH 1826 CORNER SET BY DEPUTY SURVEYOR WAMPLER

Set post cor. Sect. 1, 2, 11 & 12

W.O. 17 in N5 1/2 E 14 1/2 lks

Dq 6 in N88W 9 lks

(2) SEPT. 1971 PA 74 LCRC, LIBER 1, PG 157 G.D. LESTER PS 17624

MONUMENT - found 1" pipe at fence intersection ACCESSORIES - nail and tag south side 24" maple tree E 12.96', nail and tag
north side 30" ash tree WSW 19.90', nail and tag west side 24" tamarack South 3.23'

SEE BACK OF SHEET

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1 1/2" pipe at the NE corner of a pointed stone, above ground and in wooded area, with fragments of fence lines west,
east and south. Excavated area and found no further evidence of corner position. I accepted the position of 1 1/2" pipe as the
establishment of the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:


Set standard Ingham County Remonumentation monument, being a 2 1/2" aluminium cap, marked PA 345 INGHAM COUNTY
and stamped "P.S. 41917", at position of found (removed) pipe.

S 85° E 13.08' set nail and tag (#41917) in south face 28" maple
WEST 20.37' set nail and tag (#41917) in south face 15" elm
S 10° W 3.22' set nail and tag (#41917) in west face 30" tamarack
S 50° E 32.01' set nail and tag (#41917) in northeast face 18" maple

N.05°00'23"W. 2,697.97' to K 02 (T4N-R1E)
S.03°59'56"E. 2,631.64' to K 04 (T4N-R1E)
N.88°43'14"E. 2,588.50' to L 03 (T4N-R1E)

Bearings and distances based upon G.P.S. Observations.

P.A. 345 INGHAM COUNTY
PEER APPROVED 10/18/2005 AL



Signed by

ROR Harris

Date

Nov. 30, 2005

Surveyor's Michigan License No.

41917

PART A - CONTINUED

(K 03) SOUTHWEST CORNER SECTION 1, T4N-R1E, WILLIAMSTOWN TWP, INGHAM CO, MI.

(3) SEPT. 1971 PA 132 SURVEY, LIBER 1, PGS 68-69 G.D. LESTER PS 17624

MONUMENT - same as #2 ACCESSORIES - same as #2 MEASUREMENTS - 2698.85' north to K-2

(4) SEPT. 1971 PA 132 SURVEY, LIBER 2, PG 486 R. HELSEL PS 18394

MONUMENT - same as #2 ACCESSORIES - same as #2 MEASUREMENTS - 2641.28' south to K-4

(5) JAN. 1980 PA 132 SURVEY, LIBER 3, PGS 1188-1191 R.M. LESTER PS 18998

MONUMENT - same as #2 ACCESSORIES - same as #2 MEASUREMENTS - 2698.85' north to K-2

(6) APR. 1983 PA 132 SURVEY, LIBER 4, PGS 1097-1098 M. FOUTY PS 18989

MONUMENT - same as #2 ACCESSORIES - same as #2 MEASUREMENTS - 2589.15' east to L-3

(7) OCT. 1987 PA 132 SURVEY, LIBER 5, PGS 321-322 D.K. RICHARDSON PS 31603

MONUMENT - same as #2 ACCESSORIES - same as #2 MEASUREMENTS - 2641.28' south to K-4

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Williamstown Township

INGHAM
(County)

Located in:

Corner Code #

1. Public Land Survey

T 4N R 1E K-4

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

B:13 P:40 11/30/06 1:35 PM Pages: 2
2006-059751 LAND CORNERS Receipt #20138
Paula Johnson, Ingham County, Michigan



Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Gilbert M. Barish, in a field survey on 6 June/12 Oct, 2006 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1) **March 13, 1826** - Corner originally set by Joseph Wampler in a GLO survey.
Page 26 of the Ingham County GLO notes.
Set post
17" White Oak N41 °W 14-1/2 lks
16" White Oak N22°E 15 lks
Set at 40.00 Chains North of the Southwest corner of Section 12

Continued on Sheet 2

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a PA 345 Disc and Cap #41917 in a monument box at this location. Notes contained in Ingham County Field Book "WM-2" as compiled by R. Harris, P.S. #41917 indicate the following: "Found 1/2" bar in monument box in centerline of Epley Rd."

Offset and removed the found bar and cap. Excavated the interior of the monument box to a depth of 3 feet. Materials removed from the monument box location consist of very clean yellow sand. Found no additional historical evidence. This location falls in a slight cut section. There appears to be a roadway cut to the north and a slight fill section to the south. Mature oak trees appear along an occupation line to the north and a mixture of oaks and black walnut trees are along what appears as an occupation line to the south.

Accepted the location of the found PA 345 cap and bar as the best available evidence of the original government corner location. Set a standard Ingham County bar and cap #47942 in a monument box in the centerline of Epley Road

Measurements: (K-4 to L-4) 2607.69 feet (K-4 to K-3) 2631.35 feet (K-4 to K-5) 2658.00 feet

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set standard Ingham County bar and cap stamped "P.A. 345, 47942" on a 3/4" steel bar in monument box in the centerline of Epley Road.

S 10° W, 31.30' Found nail and tag "#25832" in the West face of a 27" Oak
S 60° W, 38.90' Found nail and tag "41917" (Ron Harris, P.S.) in the Southeast face of 20" Elm
N 70° W, 75.00' Found nail and tag #25832 in the South face of a twin 36" Boxelder
N 80° E, 56.12' Found nail and tag #41917 (Ron Harris, P.S.) in the Southeast face of 28" Oak
N 10° E, 31.55' Found nail and tag #25832 in the East face of 42" Oak

P.A. 345 INGHAM COUNTY
PEER APPROVED 10/24/2006 *rm*

Signed by Gilbert M. Barish
Surveyor's Michigan License No. 47942

Date 11-NOV-2006



Part "A" continued – K-4,T4N,R1E, Ingham County, Michigan

- 2) **February 24, 1856** – Corner referenced by A. Jackson, County Surveyor as recorded in book 3 page 95 (Volume 2, Page 274) of the County surveyors notes.
Witnesses:
9" White Oak N20 3/4°W 60-1/2 lks
12" White Oak S37 2/3°E 96 lks
Measured distances:
(K-4 to L-4) – 157 rods 7 lks – 2595.12 feet
- 3) **2-August-1971** Land Corner Recordation Certificate by Fred N. White, P.S. #12034 as recorded in Liber 1 page 91 of corners.
Part "A" states: Set 1/2 mile post
17" White Oak N41°W 14.5 links
16" White Oak N22°E 15 links
Part "B" states: Found 5/8" iron bar
Verified by occupation line and surveys.
Part "C" states: Found 5/8" bar 1.0' south of centerline of Eply Road
Witnesses:
30" Oak North, 31.63'
18" Oak South, 31.34'
8" Box Elder SW, 38.97'
- 4) **30-July-1971** Corner referenced in a recorded survey by Fred N. White, P.S. #12034 as recorded in Liber 1, Pages 42 & 43 of surveys.
Found 5/8" iron bar (1 foot south of centerline of asphalt)
30" Oak North, 31.63'
18" Oak South, 31.34'
8" Box Elder SW, 38.97'
- 5) **09-July-1973** Corner referenced in a recorded survey by Marvin F. Fouty, P.S. #18989 as recorded in Liber 1 pages 916-919 of Surveys
Found 5/8" bar
Same witnesses as Item 4 above.
- 6) **14-August-1973** Corner referenced in a recorded survey by Marvin F. Fouty, P.S. #18989 as recorded in Liber 1 pages 1036 & 1037 of Surveys
Found 5/8" bar
Same witnesses as Item 4 above.
- 7) **10-June-1974** Corner referenced in a recorded survey by Marvin F. Fouty, P.S. #18989 as recorded in Liber 1 pages 1265-1268 of Surveys (This survey supersedes the survey recorded in Item 5 above)
Found 5/8" bar
Same witnesses as Item 4 above.
- 8) **29-August-1974** Corner referenced in a recorded survey by Ron Helsel, P.S. #18994 as recorded in Liber 2 page 144 of Surveys.
References Liber 1, Page 91 for witnesses.
- 9) **10-February-1975** Corner referenced in a recorded survey by Ron Helsel, P.S. #18994 as recorded in Liber 2 pages 358 & 359 of Surveys.
References Liber 1, Page 91 for witnesses.
- 10) **01-May-1975** Corner referenced in a recorded survey by Ron Helsel, P.S. #18994 as recorded in Liber 2 pages 363 & 364 of Surveys.
References Liber 1, Page 91 for witnesses.
- 11) **18-July-1975** Corner referenced in a recorded survey by Ron Helsel, P.S. #18994 as recorded in Liber 2 pages 485 & 486 of Surveys.
References Liber 1, Page 91 for witnesses.
- 12) **03-December-1976** Corner referenced in a recorded survey by Marvin F. Fouty, P.S. #18989 as recorded in Liber 2 pages 962 & 963 of Surveys (rerecorded survey, same as Liber 1, pages 1036 & 1037)
Found 5/8" bar
Same witnesses as Item 4 above.
- 13) **30-March-1978** Corner referenced in the CETA file by L. Bryan. Notes identify a found 5/8" pipe 1.32 feet south of the centerline of Eply Road, 0.40 feet below the surface of the roadway along a tree line north and south.
Set Nail and tag East side of a 30" Oak, North, 32.60'
Set Nail and tag West side of a 24" Oak, South, 30.88'
Set Nail and tag in the South side of a 10" Oak, N60°E, 55.68'

REMONUMENTATION
(K 05) SOUTHWEST CORNER SECTION 12, T4N-R1E, WILLIAMSTOWN TWP, INGHAM CO, MI.

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ingham

(County)

Located In:

Corner Code#

1. Public Land Survey

T 4 N R 1 E

K 05

2. Property Controlling
in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

B:12 P:234 12/27/05 8:49 AM Pages: 2
2005-068275 LAND CORNER RECEIPT #4532
Paula Johnson, Ingham County, Michigan



I, Ronald R. Harris, in a field survey on March 30, 2005
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore
as required in the current manual of survey instructions of the United States Department
of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the
corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the
Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1) MARCH 1826 CORNER SET BY DEPUTY SURVEYOR WAMPLER

Set post cor. Sect. 11,12,13 & 14

Ash 7 in N86W 12 lks

Do 17 S24E 7 lks

(2) JUNE 1972 PA 74 LCRC, LIBER 1, PG 553 C.K. STEPHENS PS 3829

MONUMENT - found 1/2" iron rod in the centerline of the two section line roads (Haslett & Williamston Roads) ACCESSORIES - survey
tag s. side 30" elm N42°11'W 42.35 ft., survey tag w. side 30" oak N77°29'E 131.47 ft., survey tag n. side utility pole S20°15'W
120.20 ft.

SEE BACK OF SHEET

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" solid bar in monument box in asphalt roadway, centerline Haslett Road and 1' ± east of centerline Williamston
Road. Also found a monument box filled with concrete 2.5' ± NW of 3/4" bar in mon. box. Removed bar and excavated down
through monument box. No further evidence was found for corner position. I accepted the position of 3/4" bar in monument
box as the establishment of the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:


Set standard Ingham County Remonumentation monument, being a 2 1/2" aluminium cap, marked PA 345 INGHAM COUNTY
and stamped "P.S. 41917", in monument box.

N 60° W 76.74' found nail and tag #18998 (R. Lester) south face 8" elm
N 45° E 53.60' set nail and tag #41917 west face wood post
S 50° E 68.60' found nail and tag #18998 (R. Lester) west face 24" elm
S 35° W 108.54' set nail and tag #41917 NW face 14" elm
NW'ly 2.5' monument box, filled with concrete
N 85° E 182.1' found nail and tag #18998 south side 12" shagbark hickory

N.04°27'41"W. 2,658.09' to K 04 (T4N-R1E)

N.88°58'29"E. 2,600.42' to L 05 (T4N-R1E)

Bearings and distances based upon G.P.S. Observations.



P.A. 345 INGHAM COUNTY

PEER APPROVED 10/18/2005 M

Signed by

R. R. Harris

Date

DEC. 01, 2005

Surveyor's Michigan License No.

41917

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

ADAPTED FOR WORD PROCESSING MARCH, 1993

PART A - CONTINUED

(K 05) SOUTHWEST CORNER SECTION 12, T4N-R1E, WILLIAMSTOWN TWP, INGHAM CO, MI.

(3) MAY 1989 PA 74 LCRC, LIBER 7, PG 124 L.A. BRYAN PS 25832

MONUMENT - set 1/2" bar and cap #25832 in centerline Williamston Road, 1.5' south of centerline Haslett Road

ACCESSORIES - set nail and tag #25832 NE side power pole S25°E 82.40', set nail and tag #25832 east side power pole S20°W 100.00', set nail and tag #25832 SW side power pole N40°W 46.00'

(4) JUNE 2002 PA 74 LCRC, LIBER 10, PGS 234-235 R.M. LESTER PS 18998

MONUMENT - set gear topped 1/2" bar at location described, will attempt to have Road Commission set monument box

ACCESSORIES - set galvanized nail and 1 1/2" aluminum tag stamped "PS 18998 WITNESS" west side new u. pole mag. AZ. 158° 81.27', found nail and tag #18998 south side 12" shagbark hickory mag. AZ. 86° 182.10', set galvanized nail and 1 1/2" aluminum tag stamped "PS 18998 WITNESS" west side 15" elm mag. AZ. 137° 68.55', set galvanized nail and 1 1/2" aluminum tag stamped "PS 18998 WITNESS" south side 10" oak mag. AZ. 303° 76.79', set galvanized nail and 1 1/2" aluminum tag stamped "PS 18998 WITNESS" south side telephone mag. AZ. 54° 53.66', 1/2" bar in monument box N45°W 3.12' MEASUREMENTS - east to L-5 2600.37'

(5) DEC. 1976 PA 132, LIBER 2, PG 962-963 M.F. FOUTY PS 18989

MONUMENT - same as # 2 ACCESSORIES - same as # 2 MEASUREMENTS - east to L-5 2601.16', north to K-4 2658.66

(6) MAR. 1978 INGHAM COUNTY REMONUMENTATION PROJECT

MONUMENT - found 1/2" iron bar according to L1-P553 ACCESSORIES - N20°E 66.91' set n&t east side 6" poplar, S60°E 69.25' set n&t west side 8" elm, S60°W 49.00' center of Haslett & Williamston Road *CORNER POSITION NOT REMONUMENTED*

(7) JUNE 1981 PA 132, LIBER 4, PG 312 M.F. FOUTY PS 18989

MONUMENT - same as # 2 ACCESSORIES - same as # 2

(8) AUG. 1990 PA 132, LIBER 6, PG 369-371 L.A. BRYAN PS 25832

MONUMENT - same as # 3 ACCESSORIES - same as # 3 MEASUREMENTS - north to K-4 2658.10'

(9) OCT. 1990 PA 132, LIBER 6, PG 435-438 R.M. LESTER PS 18998

MONUMENT - same as # 3 ACCESSORIES - fnd nail and tag #25832 NE side power pole 155° az. 82.4', fnd nail and tag #25832 east side power pole 198° az. 99.8', fnd nail and tag #25832 SW side power pole 320° az. 46.0', found nail and tag #18998 south side 12" shagbark hickory 85° az. 182.1', MEASUREMENTS - east to L-5 2600.37'

REMONUMENTATION
(L 03) SOUTH 1/4 CORNER SECTION 1, T4N-R1E, WILLIAMSTOWN TWP, INGHAM CO, MI.

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RE-FILED FOR PREVIOUS SURVEYOR BLUNDER IN SECTION C OF THIS CERTIFICATE IN REFERENCE TO THE CORNER AT L-2

For corners in Ingham (County)	Located In:	Corner Code#
1. Public Land Survey	T 4 N R 1 E	L 03
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous S Property in Sec.	T R	
	S T R	
4. Lot No.		Recorded Plat
5. Private Claims		

B:13 P:33 11/30/06 1:35 PM Pages: 2
2006-059744 LAND CORNERS Receipt #20138
Paula Johnson, Ingham County, Michigan



Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, GILBERT M. BARISH, in a field survey on October 4, 2006
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore
as required in the current manual of survey instructions of the United States Department
of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the
corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the
Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1) MARCH 1826 CORNER SET BY DEPUTY SURVEYOR WAMPLER

Set 1/4 Sec. Post at avg. dist.

W.O. 18 N12W 46
Do 18 N28W 36

(2) FEB 1846 COUNTY SURVEYOR VOL 2 PG 82 CS L.D. PRESTON

MONUMENT - no mention ACCESSORIES - Not described

SEE BACK OF SHEET

P.A. 345 INGHAM COUNTY
PEER APPROVED 10/18/2005 ✓
M

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" pipe with cap #11370 in center of east, west and south fence lines. Excavated and could not remove pipe, found no further
evidence of corner position. I accepted the position of 3/4" pipe as the establishment of the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found standard Ingham County Remonumentation monument, being a 2 1/2" aluminium cap, marked PA 345 INGHAM COUNTY and
stamped L-3, "P.S. 41917", inside found pipe.

S 35° E	3.38'	found nail and tag #39100 (T. Wiegman) west face 15" hickory
S 15° W	3.73'	found nail and tag #39100 (T. Wiegman) west face 48" oak
N 85° W	8.58'	found nail and tag #39100 (T. Wiegman) north face 8" cherry
NORTH	4.55'	found nail and tag #39100 (T. Wiegman) west face 8" elm

N.05°02'21"W. 2,644.39' to L 02 (T4N-R1E) 2,622.35' to found metal post (L 02 monumented center of Sec.)
S.04°21'12"E. 2,669.54' to L 04 (T4N-R1E) 2,652.47' to L 04
S.89°56'27"E. 2,573.59' to M 03 (T4N-R1E)
S.88°43'14"W. 2,588.50' to K 03 (T4N-R1E)

Bearings and distances based upon G.P.S. Observations.



Signed by Gilbert M. Barish

Date 11-NOV-2006

Surveyor's Michigan License No. 47942

PART A - CONTINUED

(L 03) SOUTH ¼ CORNER SECTION 1, T4N-R1E, WILLIAMSTOWN TWP, INGHAM CO, MI.

(3) 1856 COUNTY SURVEYOR VOL 2 PG 274 CS A. JACKSON

MONUMENT - no mention **ACCESSORIES -** 4" hickory N24°W 24½lks, 12" W. oak S55-2/3°W 102 lks

(4) 1889 COUNTY SURVEYOR VOL 3 PG 209 CS JOHN McCREARY

MONUMENT - stone **ACCESSORIES -** 12" hickory S86°W 25lks, 8" hickory S47°E 33lks

(5) MAR. 1973 PA 74 LCRC, LIBER 2, PG 375 R.W. STEADMAN PS 11370

MONUMENT - set ¾" iron pipe and cap at base of post **PART "B" -** The corner is now occupied by a wood anchor post. Dug at base of post, but found no stone as mentioned above. **ACCESSORIES -** nail and tag in 14" wild cherry WEST 26.23 ft., nail and tag in 28" oak SOUTH 4.40 ft., nail and tag in triple 8" hickory EAST 2.78'

(6) MAR. 1973 PA 132 SURVEY, LIBER 1, PGS 663 R.W. STEADMAN PS 11370

MONUMENT - same as #5 **ACCESSORIES -** same as #5

(7) JUNE 1974 PA 132 SURVEY, LIBER 1, PGS 1265-1268 M. FOUTY PS 18989

MONUMENT - fnd ½" bar and cap **ACCESSORIES -** same as #5 **MEASUREMENTS -** 5301.50' south to L-5

(8) APR. 1983 PA 132 SURVEY, LIBER 4, PGS 1097-1098 M. FOUTY PS 18989

MONUMENT - ¾" pipe and cap **ACCESSORIES -** same as #5 **MEASUREMENTS -** 2589.15' west to K-3, 2622.89 north to metal post

REMONUMENTATION
(L 03) SOUTH ¼ CORNER SECTION 1, T4N-R1E, WILLIAMSTOWN TWP, INGHAM CO, MI.

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ingham

(County)

Located In:

Corner Code#

1. Public Land Survey

T 4 N R 1 E

L 03

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. Recorded Plat

5. Private Claims

B:12 P:228

12/15/05

11:14 AM

Pages: 2

2005-066834 LAND CORNER#45 Receipt #4196
Paula Johnson, Ingham County, Michigan



I, Ronald R. Harris, in a field survey on March 30, 2005

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1) MARCH 1826 CORNER SET BY DEPUTY SURVEYOR WAMPLER

Set ¼ Sec. Post at avg. dist.

W.O. 18 N12W 46
Do 18 N28W 36

(2) FEB 1846 COUNTY SURVEYOR VOL 2 PG 82 CS L.D. PRESTON

MONUMENT - no mention ACCESSORIES - Not described

SEE BACK OF SHEET

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found ¾" pipe with cap #11370 in center of east, west and south fence lines. Excavated and could not remove pipe, found no further evidence of corner position. I accepted the position of ¾" pipe as the establishment of the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set standard Ingham County Remonumentation monument, being a 2 ½" aluminium cap, marked PA 345 INGHAM COUNTY and stamped L-3, "P.S. 41917", inside found pipe.

S 35° E 3.38' found nail and tag #39100 (T. Wiegman) west face 15" hickory
S 15° W 3.73' found nail and tag #39100 (T. Wiegman) west face 48" oak
N 85° W 8.58' found nail and tag #39100 (T. Wiegman) north face 8" cherry
NORTH 4.55' found nail and tag #39100 (T. Wiegman) west face 8" elm

N.05°02'21"W. 2,644.39' to L 02 (T4N-R1E)
S.04°21'12"E. 2,669.54' to L 04 (T4N-R1E)
S.89°56'27"E. 2,573.59' to M 03 (T4N-R1E)
S.88°43'14"W. 2,588.50' to K 03 (T4N-R1E)

N.05°03'33"W. 2,622.61' to found metal post

Bearings and distances based upon G.P.S. Observations.

P.A. 345 INGHAM COUNTY
PEER APPROVED 10/18/2005



Signed by

R. R. Harris

Date

Nov. 30, 2005

Surveyor's Michigan License No.

41917

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

ADAPTED FOR WORD PROCESSING MARCH, 1993

PART A - CONTINUED

(L 03) SOUTH ¼ CORNER SECTION 1, T4N-R1E, WILLIAMSTOWN TWP, INGHAM CO, MI.

(3) 1856 COUNTY SURVEYOR VOL 2 PG 274 CS A. JACKSON

MONUMENT - no mention ACCESSORIES - 4" hickory N24°W 24½lks, 12" W. oak S55-2/3°W 102 lks

(4) 1889 COUNTY SURVEYOR VOL 3 PG 209 CS JOHN McCREARY

MONUMENT - stone ACCESSORIES - 12" hickory S86°W 25lks, 8" hickory S47°E 33lks

(5) MAR. 1973 PA 74 LCRC, LIBER 2, PG 375 R.W. STEADMAN PS 11370

MONUMENT - set ¾" iron pipe and cap at base of post PART "B" - The corner is now occupied by a wood anchor post. Dug at base of post, but found no stone as mentioned above. ACCESSORIES - nail and tag in 14" wild cherry WEST 26.23 ft., nail and tag in 28" oak SOUTH 4.40 ft., nail and tag in triple 8" hickory EAST 2.78'

(6) MAR. 1973 PA 132 SURVEY, LIBER 1, PGS 663 R.W. STEADMAN PS 11370

MONUMENT - same as #5 ACCESSORIES - same as #5

(7) JUNE 1974 PA 132 SURVEY, LIBER 1, PGS 1265-1268 M. FOUTY PS 18989

MONUMENT - fnd ½" bar and cap ACCESSORIES - same as #5 MEASUREMENTS - 5301.50' south to L-5

(8) APR. 1983 PA 132 SURVEY, LIBER 4, PGS 1097-1098 M. FOUTY PS 18989

MONUMENT - ¾" pipe and cap ACCESSORIES - same as #5 MEASUREMENTS - 2589.15' west to K-3, 2622.89 north to metal post

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Williamstown Township

INGHAM
(County)

Located In:

Corner Code #

1. Public Land Survey

T 4N R 1E L-4

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Gilbert M. Barish, in a field survey on 6 June/ 30 Oct., 2006 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1) Corner not set in original GLO survey.
- 2) **24-February -1856** – Corner referenced by County Surveyor A. Jackson in Book 2, Page 95 (Vol. 2, P. 274) of county surveyors notes.
Witnesses:
Yellow Oak 9" S67°E 38 1/4 lks
Yellow Oak 8" N15°W 11 lks.
Measurements: (L-4 to L-3) 2641.98' (L-4 to K-4) 2595.12'

P.A. 345 INGHAM COUNTY
PEER APPROVED 10/24/2006

Continued on Sheet 2

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a PA 345 Cap #41917 on a 3/4" steel bar in a monument box at this location. Notes contained in Ingham County Field Book "WM-2" as compiled by R. Harris, P.S. #41917 indicate the following: "Found 0.5 rebar at surface of road, 3' +/- North of the centerline of Epley Rd."

The location Falls 1.51' East of a line between L-3 and L-5, also falls 24.30' North of a line between K-4 and M-4.

Found old anchor post (rotted off at the base) with circle of cleave stones around it, 25' south of found bar in monument box. Old post falls 0.74 feet south of a line between K-4 and M-4 and 0.39 feet east of a line between L-3 and L-5. The recovery of the anchor post remnants supports a locally accepted "1.5 Rod Rule" in which the position of various corners located within the county have anchor posts or other evidence located perpendicular to the corner at a distance of 1.5 Rods (24.75 feet) from the corner.

In addition, the notes contained in item 3 above by County Surveyor McCreary indicate that he observed the line between the corner at L-4 and the corners at L-3 and M-4. The notes do not show a distance to L-3, but do indicate a bearing. Bearings and distances are shown from L-4 to M-4.

Accepted the location as the best available evidence of the center of section per the items listed above in section A and set a standard Ingham County Cap on the found 3/4" steel bar in the monument box.

Measurements: (L-4 to M-4) – 2599.59' (L-4 to L-5) – 2649.37' (L-4 to L-3) – 2652.47' (L-4 to K-4) – 2607.69'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set standard Ingham County cap stamped "P.A. 345, 47942" on Found 5/8" bar in a monument box 3' +/- North of Epley Road.

N80°E, 65.13 feet Found Nail and Tag #41917 (Ron Harris, P.S.) in the South face of a power pole
N00°E, 31.64 feet Found Nail and Tag #41917 (Ron Harris, P.S.) in the West face of a 20" Oak
S43°E, 51.60 feet Found Nail and Tag #41917 (Ron Harris, P.S.) in the Northeast face of a 12" Oak
S59°W, 40.45 feet Found Nail and Tag #25832 (Larry Bryan, P.S.) in the North face of a twin 12" Oak

Signed by Gilbert M. Barish
Surveyor's Michigan License No. 47942

Date 11-NOV-2006

B:13 P:39 11/30/06 1:35 PM Pages: 2
2006-059750 LAND CORNERS Receipt #20138
Paula Johnson, Ingham County, Michigan



Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													



Part "A" continued – L-4, T4N, R1E, Ingham County, Michigan

- 3) **14-March-1889** – Corner referenced by County Surveyor John McCreary in Book 2, Page 224 of county surveyors notes.
Set Stone
Witnesses:
Red Oak 5" S26°W 42 1/2 lks
Red Oak 4" S64-1/2°E 105 lks.
Measurements: (L-4 to M-4) 2585.88'
- 4) **16-November-1977** – Ingham County Survey & Remonumentation Crew found a railroad spike. They excavated a 5' x 15' hole, 2' deep. No evidence of stone set by McCreary was found. Re-excavated on 20-Sept.-1978, 6' x 10' hole on fenceline north, no evidence was found. Re-excavated on 14-Nov.-1978, 9.5' x 6.5' hole adjacent to RR spike, no evidence found. Re-excavated on 8-Jan.-1979, no evidence was found and was deemed lost by Larry Bryan.
Witnesses:
North 27.20' N&T west side of fence post
S45°W 40.10' N&T east side of twin 10" Oak
S45°E 51.40' N&T west side of 4" Oak
South 62.45' Nail in east side of 7" Oak
- 5) **02-May-1979** Corner referenced in a recorded survey by Ron Helsel, P.S. #18994 as recorded in Liber 3 page 907 of Surveys.
No distances stated.
Center, Sec. 12, T4N, R1E
Fd. Railroad spike

S04°E 27.23' N&T 8" anchor post
S45°W 40.08' Twin 20" Oak
S40°E 51.44' 5" Oak
S15°W 27.73' 24" Triple Oak
- 6) **08-January-1979** Corner referenced in CETA files from notes by Bob Martin. An area 15 feet north and south by 5.5 feet east and west was excavated to a depth of 2.0 feet. Notes indicate that the found rail road spike falls 3 feet east of a fallen fence line to the north, and on line with a fence to the south. Numerous excavations occurred from the years of 1978 to 1979 in various locations and depths surrounding the corner with no historical evidence recovered. The files indicate that this corner is lost.
- 7) **03-May-1979** Land Corner Recordation Certificate by Ron Helsel, P.S. #18994 as recorded in Liber 5 page 251 of corners.
Part "A" states: M-4– Original Monument obliterated.

Part "B" states: M-4 – Found Railroad spike in centerline Eply Road and on line with fence South and 10 feet East of the centerline brush row North.

Part "C" states: M-4 – Center, Section 12
Same witnesses as in Item 5
- 8) **22-June-1985** Corner referenced in a recorded survey by Marvin F. Fouty, P.S. #18989 as recorded in Liber 4 page 1071 of Surveys.
No Witnesses listed.
Measurements (L-4 to L-5) 2649.11' (L-4 to M-4) 2600.30'.
- 9) **No Recorded subdivisions or Condominium documents found relating to this corner**

REMONUMENTATION
(L 05) SOUTH ¼ CORNER SECTION 12, T4N-R1E, WILLIAMSTOWN TWP, INGHAM CO, MI.

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RE-FILED FOR PREVIOUS SURVEYOR BLUNDER IN SECTION C OF THIS CERTIFICATE IN REFERENCE TO THE CORNER AT L-4

For corners in
Ingham
(County)

Located In: Corner Code#

1. Public Land Survey

T 4 N R 1 E

L 05

B:13 P:34 11/30/06 1:35 PM Pages: 2
2006-059745 LAND CORNERS Receipt #20138
Paula Johnson, Ingham County, Michigan



2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous S
Property in Sec.

T R
S T R

4. Lot No.

Recorded Plat

Register of Deeds Stamp & File Number

5. Private Claims

I, Gilbert M. Barish, in a field survey on October 06, 2006
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore
as required in the current manual of survey instructions of the United States Department
of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the
corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the
Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1) **MARCH 1826 CORNER SET BY DEPUTY SURVEYOR WAMPLER**

Set ¼ sec. post at avg. dist. West corrected betwn Sect. 12 & 13 from M05; 39.80 chains to
L05, 79.60 chains to K05.

W O 16 S12E 20 lks
W O 18 S12½E 50½ lks

(2) **MARCH 1889 COUNTY SURVEYOR VOL 2 PG 226 CS JOHN McCREARY**

MONUMENT - stone ACCESSORIES - WO 4" N84W 47 lks, Hick 4" S4E 90½ lks MEASUREMENTS - 157 rds 31 lks east to M-5
(2610.96')

SEE BACK OF SHEET

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found ¾" solid bar in monument box, 1± north of centerline Haslett Road. Removed bar and excavated down through monument
box. No further evidence was found for corner position. I accepted the position of bar in monument box as the establishment of the
corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set standard Ingham County Remonumentation monument, being a 2½" aluminium cap, marked PA 345 INGHAM COUNTY and
stamped "P.S. 41917", in monument box.

N 05° W 28.78' found nail and tag (#25832 - L. Bryan) SW face 50" oak
N 20° W 30.55' found nail and tag (#18998 - R. Lester) west face 10" oak
South 33.12' found capped iron (#18998) property corner
S 40° E 55.96' set nail and tag #41917 NE face 6" pine

N-04°24'12"W. 2,632.30' to L-04 (T4N-R1E) 2649.37' to the monumented Center of Sec. L 04
S-88°58'29"W. 2,600.42' to K 05 (T4N-R1E)
2617.39' to M 05

Bearings and distances based upon G.P.S. Observations.

P.A. 345 INGHAM COUNTY

PEER APPROVED 10/18/2005



Signed by Gilbert M. Barish

Date 11-NOV-2006

Surveyor's Michigan License No. 47942

PART A – CONTINUED

(L 05) SOUTH ¼ CORNER SECTION 12, T4N-R1E, WILLIAMSTOWN TWP, INGHAM CO, MI.

(3) NOV. 1973 PA 74 LCRC, LIBER 2, PG 603 M.F. FOUTY PS 18989

MONUMENT – found 5/8" bar in centerline Haslett Road on fence lines north and south. **ACCESSORIES** – tag & nail 24" twin oak North 28.90', tag & nail 20" hickory WSW 205.65', tag & nail utility pole SE 201.59'

(4) DEC. 1976 PA 132, LIBER 2, PG 962-963 M.F. FOUTY PS 18989

MONUMENT – same as # 3 **ACCESSORIES** – same as # 3 **MEASUREMENTS** – west to K-5 2601.16'

(5) MAR. 1978 INGHAM COUNTY REMONUMENTATION PROJECT

MONUMENT – fnd 5/8" bar according to L2-P603, 0.8'± north of centerline Haslett Road on fence lines north and south, 6" below grade.

ACCESSORIES – north 28.93' fnd nail & tag #18989 east side 24" twin oak, S45°E 201.59' fnd nail & tag #18989 northeast side power pole, S75°W 205.65' fnd. nail & tag #18989 north side 20" hickory

CORNER POSITION NOT REMONUMENTED

(6) JULY 1978 PA 132 SURVEY, LIBER 3, PGS 459 L.J. HENDRYX PS 3276

MONUMENT – no mention **ACCESSORIES** – Same as (4). **MEASUREMENTS** – east to M-5 2618.8'

(7) JUNE 1981 PA 132, LIBER 4, PG 312 M.F. FOUTY PS 18989

MONUMENT – same as # 3 **ACCESSORIES** – same as # 3

(8) OCT. 1990 PA 132 SURVEY, LIBER 6, PGS 435-438 R.M. LESTER PS 18998

MONUMENT – fnd. ¾" bar (L2-P603) **ACCESSORIES** – set nail and tag south side 10" poplar 298°AZ 66.5', set nail and tag west side 10" oak 340°AZ 30.6', found Fouty nail and tag north side 20" hickory 265°AZ 205.4', centerline gas riser pipe 245°AZ 54.1' **MEASUREMENTS** – west to K-5 2600.37'

(9) AUG. 1999 PA 132 SURVEY, LIBER 8, PGS 615-616 R.M. LESTER PS 18998

MONUMENT – ¾" bar in monument box **ACCESSORIES** – fnd. nail and tag south side 10" poplar 298°AZ 66.40', fnd. nail and tag west side 10" oak 340°AZ 30.59', found nail and tag (#25832 – L. Bryan) south side 30" oak 03°AZ 28.80', centerline gas riser pipe 245°AZ 54.13'. **MEASUREMENTS** – east to M-5 2617.52'

(10) OCT. 2002 PA 132 SURVEY, LIBER 8, PGS 1068-1072 R.M. LESTER PS 18998

MONUMENT – same as # 9 **ACCESSORIES** – Same as # 9. **MEASUREMENTS** – east to M-5 2617.52'

REMONUMENTATION
(L 05) SOUTH ¼ CORNER SECTION 12, T4N-R1E, WILLIAMSTOWN TWP, INGHAM CO, MI.

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ingham

(County)

Located In:

Corner Code#

1. Public Land Survey

T 4 N R 1 E

L 05

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

B:12 P:227

12/15/05

11:14 AM

Pages: 2

2005-066839 LAND CODE#5 Receipt #4196
Paula Johnson, Ingham County, Michigan



I, Ronald R. Harris, in a field survey on March 30, 2005

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1) MARCH 1826 CORNER SET BY DEPUTY SURVEYOR WAMPLER

Set ¼ sec. post at avg. dist. West corrected betwn Sect. 12 & 13 from M05; 39.80 chains to L05, 79.60 chains to K05.

W O 16 S12E 20 lks

W O 18 S12½E 50½ lks

(2) MARCH 1889 COUNTY SURVEYOR VOL 2 PG 226 CS JOHN McCREARY

MONUMENT - stone ACCESSORIES - WO 4" N84W 47 lks, Hick 4" S4E 90½ lks MEASUREMENTS - 157 rds 31 lks east to M-5 (2610.96')

SEE BACK OF SHEET

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found ¾" solid bar in monument box, 1'± north of centerline Haslett Road. Removed bar and excavated down through monument box. No further evidence was found for corner position. I accepted the position of bar in monument box as the establishment of the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set standard Ingham County Remonumentation monument, being a 2½" aluminium cap, marked PA 345 INGHAM COUNTY and stamped "P.S. 41917", in monument box.

N 05° W 28.78' found nail and tag (#25832 - L. Bryan) SW face 50" oak
N 20° W 30.55' found nail and tag (#18998 - R. Lester) west face 10" oak
South 33.12' found capped iron (#18998) property corner
S 40° E 55.96' set nail and tag #41917 NE face 6" pine

N.04°21'12"W. 2,632.30' to L 04 (T4N-R1E)

S.88°58'29"W. 2,600.42' to K 05 (T4N-R1E)

P.A. 345 INGHAM COUNTY
PEER APPROVED 10/18/2005

Bearings and distances based upon G.P.S. Observations.



Signed by

Date

Nov. 30, 2005

Surveyor's Michigan License No.

41917

PART A - CONTINUED

(L 05) SOUTH ¼ CORNER SECTION 12, T4N-R1E, WILLIAMSTOWN TWP, INGHAM CO, MI.

(3) NOV. 1973 PA 74 LCRC, LIBER 2, PG 603 M.F. FOUTY PS 18989

MONUMENT - found 5/8" bar in centerline Haslett Road on fence lines north and south. ACCESSORIES - tag & nail 24" twin oak North 28.90', tag & nail 20" hickory WSW 205.65', tag & nail utility pole SE 201.59'

(4) DEC. 1976 PA 132, LIBER 2, PG 962-963 M.F. FOUTY PS 18989

MONUMENT - same as # 3 ACCESSORIES - same as # 3 MEASUREMENTS - west to K-5 2601.16'

(5) MAR. 1978 INGHAM COUNTY REMONUMENTATION PROJECT

MONUMENT - fnd 5/8" bar according to L2-P603, 0.8' ± north of centerline Haslett Road on fence lines north and south, 6" below grade. ACCESSORIES - north 28.93' fnd nail & tag #18989 east side 24" twin oak, S45°E 201.59' fnd nail & tag #18989 northeast side power pole, S75°W 205.65' fnd. nail & tag #18989 north side 20" hickory

CORNER POSITION NOT REMONUMENTED

(6) JULY 1978 PA 132 SURVEY, LIBER 3, PGS 459 L.J. HENDRYX PS 3276

MONUMENT - no mention ACCESSORIES - Same as (4). MEASUREMENTS - east to M-5 2618.8'

(7) JUNE 1981 PA 132, LIBER 4, PG 312 M.F. FOUTY PS 18989

MONUMENT - same as # 3 ACCESSORIES - same as # 3

(8) OCT. 1990 PA 132 SURVEY, LIBER 6, PGS 435-438 R.M. LESTER PS 18998

MONUMENT - fnd. ¾" bar (L2-P603) ACCESSORIES - set nail and tag south side 10" poplar 298°AZ 66.5', set nail and tag west side 10" oak 340°AZ 30.6', found Fouty nail and tag north side 20" hickory 265°AZ 205.4', centerline gas riser pipe 245°AZ 54.1'

MEASUREMENTS - west to K-5 2600.37'

(9) AUG. 1999 PA 132 SURVEY, LIBER 8, PGS 615-616 R.M. LESTER PS 18998

MONUMENT - ¾" bar in monument box ACCESSORIES - fnd. nail and tag south side 10" poplar 298°AZ 66.40', fnd. nail and tag west side 10" oak 340°AZ 30.59', found nail and tag (#25832 - L. Bryan) south side 30" oak 03°AZ 28.80', centerline gas riser pipe 245°AZ 54.13'. MEASUREMENTS - east to M-5 2617.52'

(10) OCT. 2002 PA 132 SURVEY, LIBER 8, PGS 1068-1072 R.M. LESTER PS 18998

MONUMENT - same as # 9 ACCESSORIES - Same as # 9. MEASUREMENTS - east to M-5 2617.52'

REMONUMENTATION
(M 03) SOUTHEAST CORNER SECTION 1, T4N-R1E, WILLIAMSTOWN TWP, INGHAM CO, MI.

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Ingham
(County)

Located In: Corner Code#

1. Public Land Survey T 4 N R 1 E
T R
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. Recorded Plat
5. Private Claims

M 03

B:12 P:226

12/15/05

11:14 AM

Pages: 2

2005-066832 LAND CORNER RECEIPT #4196
Paula Johnson, Ingham County, Michigan



I, Ronald R. Harris, in a field survey on March 30, 2005
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore
as required in the current manual of survey instructions of the United States Department
of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the
corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the
Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1) MARCH 1826 CORNER SET BY DEPUTY SURVEYOR WAMPLER

Set p cor of 1 & 12

(4N-R2E int W bnd 5 lks S of p)

W O 10 N64W 82

W O 12 S57W 63

(2) FEB 1849 COUNTY SURVEYOR VOL 2 PG 82 CS L.D. PRESTON

MONUMENT - no mention ACCESSORIES - Not described.

SEE BACK OF SHEET

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found capped iron (unreadable) in a concrete monument, 0.5' ± west of centerline Shaftsbury Road. Monument matches call
for Ingham County Remonumentation Project of 1979. I accepted the position of concrete monument as the establishment of
the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set standard Ingham County Remonumentation 2½" aluminium cap, marked PA 345 INGHAM COUNTY and stamped, M-3,
"P.S. 41917", on top of concrete monument, in a monument box.

S 49° E 43.83' found nail & tag #18998 west face wood fence post
S 82° E 30.81' found nail & tag #18998 north face 38" maple
S 47° W 31.67' found nail & tag #39100 (T. Wiegman) north face power pole
N 39° E 41.65' found nail & tag (KEBS - Kyes Eng. / Bryan Surveying) NW face 40" oak
SOUTH 3.37' found capped iron (A-3, T4N-R2E)

N.05°03'15"W. 2,651.40' to M 02 (T4N-R1E)

S.04°55'52"E. 2,647.85' to M 04 (T4N-R1E)

N.89°56'27"W. 2,573.59' to L 03 (T4N-R1E)

Bearings and distances based upon G.P.S. Observations.



Signed by R. Harris

Date Nov. 30, 2005

Surveyor's Michigan License No. 41917

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

ADAPTED FOR WORD PROCESSING MARCH, 1993

P.A. 345 INGHAM COUNTY

PEER APPROVED 10/18/2005 RL

PART A - CONTINUED

(M 03) SOUTHEAST CORNER SECTION 1, T4N-R1E, WILLIAMSTOWN TWP, INGHAM CO, MI.

(3) MARCH 1889 COUNTY SURVEYOR VOL 3 PG 207 CS JOHN McCREARY

MONUMENT - gas pipe **ACCESSORIES** - Maple 2" S75E 47 links, W.O. 4" N43E 61 links

(4) MARCH 1889 COUNTY SURVEYOR VOL 3 PG 209 CS JOHN McCREARY

MONUMENT - gas pipe **ACCESSORIES** - Not described.

(5) JUNE 1979 PA 74 LCRC, LIBER 5, PG 242 RONNIE LESTER, PS 18998

MONUMENT - set 4" x 36" conc. monument over position of found 1" pipe **PART "B"** - Excavated a hole 2' x 2.8' to an average depth of 3.0' on the centerline of Shaftsbury Road and $\pm 2.0'$ north of fenceline to the east. Found 1" iron pipe on the centerline of Shaftsbury Road and $\pm 2.0'$ north of fenceline to the east. Set $\frac{1}{2}$ " bar on Nov. 9, 1977 until further measurements could be made. Measured south 3.3' to A-3 Locke Twp., T4N-R2E in close accord to G.L.O. falling distance. Measured $\pm 2675'$ south to M-4. Location of pipe also in close accord to witnesses as given in survey by J. McCreary. Accepted iron pipe for corner. Excavation conducted by Ingham County Survey and Remonumentation Project crew. **ACCESSORIES** - nail & tag #18998 SW corner fence post SE 43.70', nail & tag #18998 north side power pole WSW 31.74', nail & tag #18998 NW side 30" oak NE 41.04', nail & tag #18998 north side 24" maple ESE 30.82', conc. mon. A-3, Locke Twp., T4N-R2E, South 3.3'
MEASUREMENTS - south to M-4 2675' \pm

(6) MAR. 1980 PA 132 SURVEY, LIBER 3, PGS 1227-1228 A.C. WILLIAMS PS 21275

MONUMENT - no mention **ACCESSORIES** - Same as (4).

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Williamstown Township

INGHAM
(County)

Located In:

Corner Code #

1. Public Land Survey

T 4N R 1E M-4

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Gilbert M. Barish, in a field survey on 6 June / 30 Oct., 2006 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1) **April 1826** - Corner originally set by Joseph Wampler D.S. in a GLO survey. Page 21 of the Ingham County GLO notes. Set quarter post fw. Witnesses are illegible due to writing by John McCreary.

Continued on Sheet 2

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" bar & cap #28414 (M. Mahieu) as called out in Liber 8, P. 1007 (Item 9 above). This point appears to be in close accord to the location of the 1/2" bar found by Fred White, P.S. in Item A-4 above. Excavations occurred around this point in 1978 by the CETA program as indicated in Item 5 above and no further evidence was found. Notes from item 5 above indicate that Larry Bryan was skeptical of the iron recorded by Fred White and deemed this corner as lost in the CETA file.

Searched at 1/8th corner between M-5 and M-4 and found an old fenceline in good condition running to the West. Measured 1313.88 feet from M-5 (original stone was found by Ron Lester) to the fenceline as it would intersect the section line, County Surveyor called for a distance of 1314.04 feet to a set gas pipe. We did not find any evidence of the gas pipe as set by the county surveyor. This distance measured so close that we doubled over the distance and searched at a point 11 feet north of the found 1/2" bar & cap #28414. We excavated a 4' x 4' hole to a depth of 3 feet and found an 8" cleaved blue stone slightly leaning over. We measured 1313.76 feet from the 1/8th line to this stone which was in close accord to the distance measured by the County Surveyor of 1313.04 feet.

Accepted the location of the found stone in conjunction with the measurements along the section line to the 1/8th line fence and reestablished the obliterated corner at the location of the found stone. I feel this location is a faithful perpetuation of the government corner as established by Deputy Surveyor McCreary in Item 2 above.

Measurements (M-4 to M-3) 2662.10' (M-4 to M-5) 2627.63' (M-4 to L-4) 2599.59'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set standard Ingham County bar and cap stamped "P.A. 345, 47942" on a 3/4" steel bar in a monument box in the centerline of Shaftsbury Road.

S 79° E, 24.92' Top bolt on Telephone Pedestal
S 35° W, 47.65' Set Standard Ingham County nail and tag in the Northwest face of a utility pole
S 04° E, 10.54' Found 1/2" bar and cap #28414 (Property Controlling Corner)
N 74° W, 58.35' Found nail and tag #28414 in the South face of a 54" Oak
N 18° W, 124.76' Found nail and tag #28414 in the East face of a utility pole

Signed by Gilbert M. Barish

Date 11-NOV-2006

Surveyor's Michigan License No. 47942

P.A. 345 INGHAM COUNTY
PEER APPROVED 11/21/2006 RC

Property Controlling Corner (1/2" bar and cap #28414)
N&T N. side utility pole, S46°W, 39.26'
N&T #28414 S. side 48" Oak, N57°W, 62.70'
N&T #28414 E. side utility pole, N15°W, 134.96'
c/l bolt top of telephone box, N79°E, 24.44'

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													



Part "A" continued – M-4, T4N, R1E, Ingham County, Michigan

- 2) **14-March-1889** – Corner referenced by County Surveyor John McCreary on page 11 of the Ingham County GLO notes. Also shown in Book 2, Page 224 of county surveyor notes.
Set Gas Pipe for corner
Witness:
Maple 4", N10°E, 156 lks. (102.96')
Elm 8", S5°W, 199-1/2 lks. (131.67')
Measurements: M-4 to L-4 (2585.88') M-4 to M-3 (2632.74') M-4 to M-5 (2628.08')
- 3) **29-August-1974** Corner referenced in a recorded surveys by Ron Helsel, P.S. #18994 as recorded in Liber 2 page 144, Liber 2, Pages 358-359, Liber 2, Pages 485-486 of Surveys.
Calls out the East 1/4 Corner of Section 12 and references Liber 1, Page 91 (which only shows witnesses for K-4)
Measurement of 5208.03 feet from M-4 to K-4
- 4) **31-July-1978** Land Corner Recordation Certificate by Fred N. White, P.S. #12034 as recorded in Liber 4 page 316 of corners.
Part "A" states: M-4– Original Monument obliterated.

Part "B" states: M-4 – Found 1/2" rod

Part "C" states: M-4 –East 1/4 Corner, Section 12
N60°W 63.44' Nail & tag south side 34" oak
S45°W 39.14' Nail & tag east side power pole
N35°E 47.80' Nail & tag west side drain post
- 5) **November-1978** 6' x 6' hole, 2.5' deep excavated by Larry Bryan around 1/2" bar. No evidence of original corner was found.
Notes state that they are skeptical of the White iron.
- 6) **2-May-1979** Corner referenced in a recorded survey by Ron Helsel, P.S. #18994 as recorded in Liber 3 page 907 of Surveys.
Calls out the East 1/4 Corner of Section 12 and references Liber 4, Page 316
- 7) **20-June-1979** Corner referenced in a recorded survey by Larry Bryan, P.S. #25832 as recorded in Liber 3 page 931-933 of Surveys.

East 1/4 Cor., Sec. 12, T4N, R1E
Fd. 1/2" bar in centerline of road
Fd. Nail & tag South side 34" oak, N60°W, 63.44'
Fd. Nail & tag North side power pole, S45°W, 39.14'
Set 1/2" bar at West 1/4 corner Section 7, T4N, R2E, North 25.00'
- 8) **22-June-1985** Corner referenced in a recorded survey by Marvin F. Fouty, P.S. #18994 as recorded in Liber 4 page 1071 of Surveys.
Calls out the East 1/4 Corner of Section 12 and references Liber 4, Page 316
Measurement of 2600.30 feet from M-4 to L-4, Measurement of 2616.91 feet from M-4 to M-5
- 9) **15-February-2002** Corner referenced in a recorded survey by Maurice H. Mahieu, P.S. #28414 as recorded in Liber 8 page 1007 of Surveys.

East 1/4 Cor., Sec. 12, T4N, R1E
Set 1/2" bar and cap #28414, 0.5' East of c/l Shaftsbury Rd. & 1' South of c/l Epley Rd.
Witnesses:
N&T N. side utility pole S46°W 39.26'
N&T #28414 S. side 48" Oak N57°W 62.70'
N&T #28414 E. side utility pole N15°W 134.96'
c/l bolt top of telephone box N79°E 24.44'
Measurement of 2672.78 feet from M-4 to M-3
- 10) **No Recorded subdivisions or Condominium documents found relating to this corner**

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Williamstown Township

INGHAM
(County)

Located In:

Corner Code #

1. Public Land Survey

T 4N R 1E M-5

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R
S T R
S T R

B:13 P:41 11/30/06 1:35 PM Pages: 2
2006-059752 LAND CORNERS Receipt #20138
Paula Johnson, Ingham County, Michigan



4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

30 OCT 2006

I, Gilbert M. Barish, in a field survey on 6 June/30 June, 2006 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1) **March 1826** - Corner originally set by Joseph Wampler D.S. in a GLO survey.
Page 21 of the Ingham County GLO notes.
Set quarter post fw
Witnesses: White Oak 15 N73°W, 11.5 links (7.59')
White Oak 13 S41-1/2°W, 78 links (51.48')
Measurements: (M-5 to M-4) 40.00 ch. (M-5 to L-5) 40.00 ch.

P.A. 345 INGHAM COUNTY
PEER APPROVED 10/24/2006

Continued on Sheet 2

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a PA 345 Disc and Cap #41917 in a monument box at this location. Notes contained in Ingham County Field Book "WM-2" as compiled by R. Harris, P.S. #41917 indicate the following: "Found 1/2" rebar in monument box."

Searched location at M-5, found P.A. 345 bar & cap #41917 (Ron Harris) in monument box at the intersection of centerlines for Shaftsbury Road and Haslett Road. Witness to Ron Lester nail & tag (Item 8 Part A) did not match by 4 feet. Measured witness distance from Lester tag and observed a strong magnetic reading in the asphalt. Excavated location and found 1/2" bar encased in concrete 6" below the surface of the asphalt as recorded by Ron Lester in item 8 part A above. Removed Harris P.A. 345 cap from the property controlling corner to avoid confusion with the true remonumented location for M-5 (T4N, R1E) and A-5 (T4N, R2E).

Accepted the location of the 1/2" bar in concrete as a faithful perpetuation of the original government corner based on previous excavation and monument perpetuation by Mr. Ronnie Lester, P.S. in item A-8 above. Notes contained in item 2 part A above indicate that the corner for A-5 Locke Township (T4N, R2E) is a common corner with M-5 Williamston Township (T4N, R1E).

Measurements: (M-5 to M-4) -N 04-40-33 W, 2627.63 feet (M-5 to L-5) -S 89-46-59 W, 2617.39 feet

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Set standard Ingham County bar and cap stamped "P.A. 345, 47942" on 1/2" steel bar in concrete in monument box.

Corner falls 2.5' north of the centerline of Haslett Road and 4.5' west of the centerline of Shaftsbury Road.

S 47° W, 38.85' Found nail and tag "18998" in the North face of a Power Pole
S 47° W, 39.19' Found nail and tag "41917" in the West face of a Power Pole
N 05° W, 50.00' Found chiseled "X" in center of curb & gutter (North end)
S 36° E, 66.45' Found nail and tag #18998 in the Southwest face of a 28" Hickory
N 19° E, 50.79' Found chiseled "X" in center of curb & gutter (North end)
S 58° E, 4.04' Top of 5/8" bar in monument box set by Ron Harris

Property Controlling Corner:

S 51° W, 40.18' Found nail and tag "41917" in the Northwest face of a Power Pole
N 11° W, 52.79' Found chiseled "X" in center of curb & gutter (North end)
S 37° E, 62.76' Found nail and tag #18998 in the Southwest face of a 28" Hickory
N 13° E, 52.12' Found chiseled "X" in center of curb & gutter (North end)
N 58° W, 4.04' Top of 5/8" bar in monument box set by Ron Harris

Signed by

Gilbert M. Barish

Date

11-NOV-2006

Surveyor's Michigan License No. 47942

Part "A" continued – A-5, T4N, R2E, and M-5, T4N, R1E, Ingham County, Michigan

- 2) **March 1826** – A-5 Corner originally set by Joseph Wampler D.S. in a GLO survey.
Page 64 of the Ingham County GLO notes.
Intersect section line at post (A-5 Locke Twp.) and (M-5 Williamstown Twp.) are a common corner
Measurements: (A-5 to B-5) 22.66 ch.

- 3) **15-March-1889** – Corner referenced by County Surveyor John McCreary in V. 3, page 207 of county surveyors notes
Calls for a stone.
Witnesses:
Red Oak 18 N35°E 65 links (42.9')
Maple 3 N32-1/2°W 87.5 links (57.75')
Hickory 6 S42°E 100 links (66')
Measurements: (M-5 to L-5) 2610.96' (M-5 to M-4) 2628.12'

- 4) **1969** – Corner identified as a stone and boatspike on Ingham County Road Commission revised Grid map
Witnesses:
T.P. Northeast 44.34'
16" Hickory Southeast 62.05'
P.P. Southwest 41.51'

- 5) **26-July-1972** Land Corner Recordation Certificate by Clyde K. Stephens, P.S. #3829 as recorded in Liber 2 page 11 of corners.
(This certificate is for A-5 Only).
Part "A" states: A-5 – The original monument and accessories obliterated
Part "B" states: A-5 – The 1/2 inch iron rod was found in the centerline of two section line roads (Haslett Road and Shaftsbury Road).
Part "C" states: A-5 – The 1/2 inch iron rod was found at the NW corner was left in position with the following witnesses:
Survey tag in the S. Side of a utility pole N41°40'E, 44.15 feet
Survey tag in the N. Side of a 30" Hickory S42°16'E, 61.70 feet
Survey tag in the NE Side of a utility pole N42°56'W, 40.84 feet
The bearing of the Section line south of this corner is S06°01'E
The bearing of the Section line east of this corner is N89°48'E

- 6) **11-November-1977** Corner referenced in a recorded survey by LaVerne Hendryx, P.S. #3276 as recorded in Liber 3 page 459 of Surveys.

No Witnesses listed.

- 7) **20-June-1979** Corner referenced in a recorded survey by Larry A. Bryan, P.S. #25832 as recorded in Liber 3 pages 931-933 of Surveys.
Southwest corner of Section 7, T4N, R2E
Fd. 3/4" bar in the centerline of roads
Fd. Spike West side utility pole, N45°E, 44.73 feet
Fd. Stephens tag in the North side of a 30" Hickory, S45°E, 61.64 feet
Fd Stephens tag Northeast side power pole, S45°W, 40.82 feet

Measurements: A-5 to B-5 (1500.32 feet) A-5 to M-4 (2619.31 feet)

- 8) **13-September-1979** Land Corner Recordation Certificate by Ronnie M. Lester, P.S. #18998 as recorded in Liber 5 page 301 of corners.
Part "A" states: M-5 – Post set in original government survey by J. Wampler dated between March 3 and 13, 1826.
Corner identified as a stone in a survey by John McCreary, County Surveyor, Mar.. 14, 1889 (V.3, P.207)
Corner identified as a stone in the records of Wm. Berryman, County Surveyor, Date Unknown.
Corner identified as a stone and boatspike in the records of Ingham Co. Road Comm., revised grid map, 1969
Corner referred to in a recorded Land Survey by LaVerne Hendryx, Nov. 11, 1977 (L.3, P.459)
Part "B" states: M-5 – Excavated an 8' x 6' hole to an average depth of 4.0', mostly north of the intersection of the centerlines of Haslett and Shaftsbury Roads. Found boatspike recorded as A-5 Locke Twp., T4N-R2E at the intersection of the centerlines of Shaftsbury and Haslett Roads. Found wooden stake between two stones 2.5' below road surface +/- 2.0' north of the centerline of Haslett Road and +/- 3.5' west of the centerline of Shaftsbury Road. Found pointed stone surrounded by small stones and brick 3.7' below road surface directly beneath wooden stake. Accepted stone for corner as called for in a survey by J. McCreary, County Surveyor. Measured north +/- 2618' to M-4, south +/- 2688' to M-6 and west +/- 2617' to L-5. Excavation conducted by Ingham County Survey and Remonumentation Project crew.
Part "C" states: M-5 – NE Corner, Section 13, T4N-R1E
Set 4"x 36" concrete monument with 1/2" x 38" rerod and cap #18998 with concrete collar and cover in location of stone described above:
Nail and tag #18998, southwest side 24" Hickory, SE, 66.47'
Nail and tag #18998, northwest side 1" Hickory, SW, 66.46'
Nail and tag #18998, east side power pole, NNW, 127.83'
Boatspike recorded as A-5 Locke Twp., T4N-R2E, SSE, 4.09'
Top centerline buried cable box, NE 44.98'

- 9) **24-March-1980** Corner referenced in a recorded survey by Austin C. Williams, P.S. #21275 as recorded in Liber 3 page 1221 of Surveys.
Witnesses: SW Cor. Sect. 6, T4N, R2E, N43°E, 41.10' nail N. base 30" White Oak; S72°30'E, 29.97' nail N. base 24" Maple; S54°W, 31.82' nail N. base power pole. Section line distances not shown.

- 10) **22-June-1985** Corner referenced in a recorded survey by Marvin F. Fouty, P.S. #18989 as recorded in Liber 4 page 1071 of Surveys.
References Item 8 above for witnesses.

- 11) **09-April-1999** Corner referenced in a recorded survey by Ronnie M. Lester, P.S. #18998 as recorded in Liber 8 pages 616-616 of Surveys and in a separate survey recorded in Liber 8, pages 1068-1072 of surveys recorded in 26-August-2002
Liber 5, Page 301 Concrete Monument and cap over stone
Found Nail and tag #18998 S.W. side 24" Shagbark Mag.
Az. 144°, 66.60'
Found Nail and tag #18998 East side utility pole Mag. Az. 349°, 127.90'
Set galvanized nail and 1 1/4" brass tag stamped "18998 LESTER" North side utility pole mag az. 226°, 38.81'
Southwest corner entrance to school house mag. Az. 85°, 150.12'
1/2" bar S.E. 4.06'

2002 Witnesses:
Liber 5, Page 301 Concrete Monument and cap over stone
Set new Nail and tag #18998 S.W. side 24" Shagbark Mag.
Az. 144°, 66.58'
Found nail and tag stamped "18998" North side utility pole mag az. 225°, 38.80'
Set galvanized nail and 1 1/4" brass tag stamped "18998 LESTER" East side utility pole mag az. 354°, 202.20'
Set galvanized nail and 1 1/4" brass tag stamped "18998 LESTER" West side utility pole mag az. 175°, 206.70'
1/2" bar in monument box S.E. 4.06'