


4-13

Found $\frac{1}{2}$ " IRON ROD, PULLED
STERNMAN'S WITNESSED $\frac{1}{2}$ " IRON.
MUTTERED ALL 4 WITNESSES, PROCEEDED
TO DIG, FINDING A $\frac{1}{2}$ " IRON BAR.
CONTINUED DIGGING AND REMOVED
 $1\frac{1}{2}$ " BAR. FINDING NO OTHER
EVIDENCE OF MONUMENTATION.
REPAIRED WITH INSHAW CO. REMON
BAR & CAP. 0.3' EAST OF EAST
EDGE OF PAVEMENT OF ZIMMER RD.

85-KF 4-23-02

(71)



1-20	00-00-23	23	186.24
1-7	334-16-46		228.30
1-28	180-00-23	24	186.24
1-7	154-16-47		228.33
4	334-16-23.5		228.315
1-20	00-00-25	33	186.24
1-8	339-36-58		394.72
1-20	180-00-23	33	186.25
1-8	159-36-56		394.75
4	339-36-33		394.735

11-05-02
30° 24' N

I-12

GP.S.
TRAYE RCE

10-11-I-12

E, 1/4 Cor.

SEC 34

B50

0-00-30

10-17-

294.72

143-10-47

142.14

B50

180-00-32

10-14.5

294.72

323-10-44

10-12

142.13

mean

143° 10' - 15"

Dist

10 → 11

294.72'

11 → I-12

142.14'

10 =

SET PERMANENT

COLLECTOR

11 =

SET PERMANENT

(68)


I-12

85-JV

FD. INC # 18998 APPROXIMATELY
40' WEST OF WOOD LINE EAST
OF RESIDENCE # 680 OF RIVERWOOD
SUBDIVISION. FOUND EVIDENCE OF
THE OLD FENCE INTERSECTION SO
PROCEEDED TO LOOK FOR WITNESS.
FOUND ONLY ONE OF LESTERS
AND IT MATCHED. HEID LOCATION
+ DOG TO A DEPTH OF 24' IN
VERY UNSTABLE GROUND, FINDING
ONLY SOME OLD FENCE WIRE.
RESET REMOV IRON + CAP AT
LOCATION OF LESTERS ID-CMP.

11-05-02 OVERCAST 35°

(67)



11-11

DT/6

For 2000, more at 5. Rate of land
on the east. From running East.
They hit at perpendicular distance
according to G.D. Found no evidence
of original movement. Accepted
then as the best available
evidence, placed 1/2 in from E. corner
copy over from. Study of 4/103.

6/6/02

16

