

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

INGHAM

(County)

Located In:

Corner Code #

LANSING TOWNSHIP.

1. Public Land Survey

T 4N R 2W

A-5

2. Property Controlling in Section

S T R

3. Miscellaneous Property in Sec.

S T R

4. Lot No.

5. Private Claims



2001-060842

Page: 1 of 2
11/14/2001 08:20A

Paula Johnson
INGHAM COUNTY
REGISTER OF DEEDS

RECORDED

L-10 P-148

CRNR 11.00

2001-060842

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|----|----|----|----|----|---|---|---|---|---|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | 5 | 4 | 3 | 2 | 1 | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | 8 | 9 | 10 | 11 | 12 | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | 17 | 16 | 15 | 14 | 13 | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | 20 | 21 | 22 | 23 | 24 | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 | | | | | | | |
| 13 | | | | | | | | | | | | | |

I, DAVID R. LOHR, in a field survey on JUNE 16, 2001, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. CORNER SET BY MUSGROVE EVANS, U.S. DEPUTY SURVEYOR IN FEB., 1827.

"INT. W. BDY 34 LKS. (22.44') N. OF POST & SET A POST FOR THE COR. TO SEC. 7 & 18."

WITNESSED BY:

BEECH 27", N 72° E, 3 LKS. (1.98')

IRONWOOD 4", S 44° E, 22 LKS. (14.52')

NOTES SHOW DISTANCE EAST OF 44.66 CH. (2947.56)

2. CORNER REFERENCED IN SURVEY BY W.A. ROWE, COUNTY SURVEYOR, DATED OCT. 31, 1899, AND RECORDED IN BOOK 1, PAGE 2, COUNTY SURVEYORS RECORDS. CORNER SHOWN AS "#1" - "STONE SET 34 LKS NORTH FROM A STONE MARKING THE CORRESPONDING CORNER IN DELTA TOWNSHIP", NO WITNESSES GIVEN. SURVEY SHOWS DISTANCE EAST OF 45 CH. (2970')

3. CORNER REFERENCED IN RESURVEY OF LANSING TOWNSHIP, DATED 1909, AND RECORDED IN BOOK 5, PAGE 218, COUNTY SURVEYORS RECORDS, BY SURVEYOR R.J. ROBB, "ALL CORNERS ARE MARKED BY CEMENT POSTS 2.5' LONG - 3" SQUARE AT TOP - 4" SQUARE AT BOTTOM." "GOV BM ???, N-W 33.4' DELTA COR. SOUTH 22.4' "

CONTINUED ON BACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

SEARCHED AT APPARENT LOCATION OF CORNER AND FOUND 1" PIPE IN MONUMENT BOX ON C/L WAVERLY ROAD, 22.44' NORTH OF M-5, DELTA TWP. ATTEMPTED TO EXCAVATE INTERIOR OF MON. BOX BUT FOUND PIPE TO BE SET IN BIT. OR CONC. COULD NOT REMOVE PIPE OR SET STANDARD CAP ON IT. ACCEPTED LOCATION OF FOUND PIPE AS PER ITEMS A-8 THRU A-10. MEASURED NORTH 2635.23' TO A-4 LANSING TWP.; EAST 2968.94' TO B-5 LANSING TWP, EAST 5607.88' TO C-5 LANSING TWP. AND SOUTH 2640.35 TO A-6 LANSING TWP. AND 5273.49' TO A-7 LANSING TWP.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-5, T4N, R2W, LANSING TOWNSHIP, INGHAM COUNTY. FOUND 1" PIPE IN MON. BOX ON C/L WAVERLY ROAD.

WITNESSED BY:

FOUND MSHD NAIL & TAG IN NE/S UTILITY POLE, AZ. 145-13-15, 72.78'

NORTHERLY BOLT ON SIGN POST, AZ. 216-27-42, 88.64'

SURVEY C/L P.I. (1" IRON IN MON. BOX) AZ. 261-56-18, 82.66'

SOUTHEAST CORNER CONCRETE SIGN BASE, AZ. 319-21-11, 60.17'

SET N&T 30090, NW/S P. POLE, AZ. 26-25-14, 93.58'

TOP CENTER FIRE HYDRANT, AZ. 37-33-25, 68.23'

FOUND 1" BAR IN MONUMENT BOX, M-5 DELTA TWP., AZ. 180-22-30, 22.44'

TRAV. PT. DT2-24-12, (#4 BAR/CAP #30090) AZ. 30-37-24, 76.36

BEARINGS GIVEN ARE BASED ON TRAVERSE.



Signed by David R. Lohr

Date JUNE 18, 2001

Surveyor's Michigan License No. 30090

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT, 1995
ADAPTED FOR WORD PROCESSING JAN, 1999

P.A. 345 INGHAM COUNTY
PEER APPROVED 6/19/2001 re

A-5: LANSING TOWNSHIP, PART A CONTINUED:

4. CORNER REFERENCED IN UNDATED "NORTHSTINE NOTES" AS "30" X 3/4" PIPE, 3.1 FT. N. OF N. EDGE OF CONCRETE ON M-43 AT END OF BITUMINOUS CONC. AND BEG. OF CONC. 22.4 FT. N. OF SEC. COR. 12 & 13 EATON." NO OTHER WITNESSES GIVEN.
5. CORNER REFERENCED IN UNDATED MSHD ROW PLAN BOOK, PAGE 96. NO MENTION OF MONUMENT OR WITNESSES. PLAN SHOWS A DISTANCE EAST TO C-5 (LANSING TWP.) OF 5606.10', AND A DISTANCE SOUTH OF 22.53' TO M-5 DELTA TOWNSHIP, EATON COUNTY.
6. CORNER REFERENCED IN THE PLATS OF "EDGEMONT PARK AND EDGEMONT PARK NO. 3", DATED APRIL 12, 1948 AND APRIL 3, 1953, BY CLYDE K. STEPHENS, RLS #3829, AND RECORDED IN LIBER 14 OF PLATS, PAGE 42, AND LIBER 16 OF PLATS, PAGE 47. NO MENTION OF MONUMENT OR WITNESSES GIVEN. PLAT DRAWINGS SHOW A TOTAL DISTANCE EAST TO B-5 OF 2968.59.
7. CORNER REFERENCED IN UNDATED INGHAM COUNTY ROAD COMMISSION NOTES. "MON. BOX (ICRC 1965) NO MENTION OF MONUMENT. WITNESSED BY: P.P. SE, 64.03'
N. COR. BASE, STANDARD SIGN, SW, 70.20'
SW COR. BASE SUNOCO SIGN, NW, 77.70'
SE COR. BOTTOM OF A B & T SIGN, NE, 93.27'
8. CORNER REFERENCED ON MDOT FORM 280 CARD, BY DON FLUKE, SURVEY CHIEF, DATED 5/4/65.
"3/4 INCH SQUARE ROD IN CONCRETE PAVT. SECTION CORNER COMMON TO SECTIONS 7 & 18."
WITNESSED BY: N 35° E, 89.90' PK NAIL WITH REFERENCE CAP IN BIT DRIVE.
S 45° E, 118.40' PK NAIL WITH REFERENCE CAP IN BIT DRIVE TO GOLF COURSE.
S 60° W, 104.62' PK NAIL WITH REFERENCE CAP IN BIT DRIVE.
N 40° W, 91.83' PK NAIL WITH REFERENCE CAP IN BIT DRIVE.
9. CORNER REFERENCED ON MDOT FORM 280 CARD, BY ARDEN S. PIERSON, SURVEY CHIEF, DATED JAN. 1968.
"SW CORNER SECTION 7, SECTION CORNER COMMON TO SECTIONS 7 & 18, LANSING TOWNSHIP, INGHAM COUNTY.
3/4 INCH PIPE IN MON. BOX." WITNESSED BY:
TOP NUT, FIRE HYD. - N 40° E, 68.32'
SE CORNER CONCRETE SIGN BASE - N 35° W, 60.17'
CHIS. SQUARE ON NW COR. CONC. LIGHT BASE - S 55° W, 90.88'
REAR OF CARD SHOWS DISTANCE SOUTH OF 22.44' TO M-5 DELTA; SOUTH OF 2639.94' TO A-6 LANSING AND NORTH OF 2634.52 TO A-4 LANSING TWP.
10. CORNER REFERENCED IN LCRC DATED NOV. 9, 1979, BY RONNIE M. LESTER, RLS #18998, AND RECORDED IN LIBER 6, PAGE 6. PART B STATES: "DURING INVESTIGATION FOUND 3/4" PIPE IN MONUMENT BOX AT INTERSECTION OF THE CENTERLINES OF SAGINAW AND WAVERLY ROADS. ACCEPTED 3/4" PIPE IN MONUMENT BOX FOR CORNER AS CALLED FOR BY MSDHT FORM 280. RESEARCH CONDUCTED BY INGHAM COUNTY SURVEY AND REMONUMENTATION PROJECT STAFF."
PART C STATES: "NW CORNER SECTION 18, T4N, R2W, FOUND 3/4" PIPE IN MONUMENT BOX IN LOCATION DESCRIBED ABOVE." WITNESSED BY:
SE CORNER, AT THE BASE OF CONCRETE SIGN, NW, 60.17'
TOP NUT, FIRE HYD., NE, 68.32'
NAIL & TAG, #18998, NORTH SIDE 14" POWER POLE, SE, 72.82'
3/4" BAR IN MONUMENT BOX, M-5 DELTA TWP., T4N-R3W, EATON COUNTY, SOUTH, 22.40'
11. NO OTHER REFERENCES FOUND.



2001-060842
Page: 2 of 2
11/14/2001 08:20A

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
INGHAM

(County)

Located In:

Corner Code #

LANSING TOWNSHIP.

1. Public Land Survey

T 4N -R 2W

A-6

Paula Johnson
INGHAM COUNTY
REGISTER OF DEEDS
KEBS INCORPORATED

RECORDED

L-10 P-263

CRNR 11.00

2002-054414

2002-054414

Page: 1 of 2

09/04/2002 08:36

2. Property Controlling
in Section

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

S

T

R

4. Lot No. Recorded Plat

5. Private Claims

Register of Deeds Stamp & File Number

I, DAVID R. LOHR, PS

, in a field survey on JUNE 27, 2001,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
1. CORNER NOT SET IN GLO SURVEY.

2. CORNER REFERENCED IN SURVEY BY W.A. ROWE, COUNTY SURVEYOR, DATED OCT. 31, 1899, AND
RECORDED IN BOOK 1, PAGE 2, COUNTY SURVEYORS RECORDS. CORNER SHOWN AS "#8" - "STONE SET IN
PLACE OF OLD POST AND 37 1/2 LKS (24.75') NORTH OF STONE MARKING DELTA CORNER.",
WITNESSED BY:
SUGAR 4 IN., S 77 1/2 E, 118 LKS (77.88')
ELM, 10 IN., S 11 W, 66 LKS (43.56')
W. OAK, 10 IN., N 12 1/21/2 63 LKS (41.58')
SURVEY SHOWS DISTANCE EAST OF 44.97 (2968.02') TO B-6.

3. CORNER REFERENCED IN RESURVEY OF LANSING TOWNSHIP, DATED 1909, AND RECORDED IN BOOK 5, PAGE
218, COUNTY SURVEYORS RECORDS, BY SURVEYOR R.J. ROBB, "ALL CORNERS ARE MARKED BY CEMENT
POSTS 2.5' LONG - 3" SQUARE AT TOP - 4" SQUARE AT BOTTOM." WITNESSED BY:
SUGAR 4", S 77 1/2 E, 77.9',
DELTA COR. 37 1/2 LKS (24.75') SOUTH."

CONTINUED ON BACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
SEARCHED AT APPARENT LOCATION OF CORNER AND FOUND AN EMPTY MON. BOX AT WHAT APPEARED TO TO BE
A-6 LANSING TWP. COULD NOT POSITIVELY DETERMINE LOCATION OF THIS CORNER FROM WITNESSES.
TRAVERSED EAST AND TIED IN PLAT OF SUPERVISOR'S PLAT OF FARMINGTON NO. 2, BY E. W. TAPPEN,
(ITEM #A-5) CALCULATED LOCATION OF A-6 LANSING TWP. AND UPON INVERSING TO THIS CALCULATED
LOCATION, PICKED UP STRONG READING WITH METAL DETECTOR. UPON EXCAVATION AT THIS LOCATION,
FOUND 3/4" SOLID IRON BAR IN A MON. BOX, ABOUT 4" DEEP, COMPLETELY PAVED OVER. FOUND IRON BAR FALLS
7.09' WEST X 2.28' NORTH OF VISIBLE EMPTY MON. BOX. FOUND IRON FALLS 1.11' SOUTH X 0.93' WEST
OF THE COMPUTED LOCATION USING FOUND CONTROL FROM SUPERVISOR'S PLAT OF FARMINGTON NO. 2 (ITEM
#A-5) ACCEPTED LOCATION OF FOUND 3/4" BAR IN COVERED MON. BOX AS A-6 LANSING TWP. CUT 12" X 4"
DEEP CORE IN PAVEMENT AND RAISED MON. BOX TO GRADE. COULD NOT REMOVE FD. 3/4" BAR, SO SET
ORANGE PLASTIC PA 345 CAP #30090 ON IT. MEASURED NORTH 2640.35' TO A-5, SOUTH 2633.15 FT. TO
A-7 AND EAST 2667.70' TO B-6. CORNER FALLS ON STANDARD LINE.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
A-6, T4N, R2W, LANSING TOWNSHIP, INGHAM COUNTY. FOUND 3/4" SOLID IRON BAR IN MON. BOX ON C/L
WAVERLY ROAD AND MICHIGAN AVE. WITNESSED BY:

SET N/T #30090, N/S P. POLE, S 68° E, 90.60'

SET N/T #30090, N/S WOOD WALL, S 48° E, 58.60'

SET N/T #30090, W/S 20" APPLE, S 15° E, 83.60'

SET N/T #30090, E/S UTIL. POLE, S 27° W, 102.52'

NE CORNER CONC. PAD (SWITCHBOX), S 58° W, 62.80'

M-6, T4N, R3W, STANDARD REMON. BAR/CAP IN MON. BOX), SOUTH, 24.60'
BEARINGS GIVEN ARE MAGNETIC.



Signed by David R. Lohr

Date JUNE 3, 2002

Surveyor's Michigan License No. 30090

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995
ADAPTED FOR WORD PROCESSING JAN., 1999

P.A. 345 INGHAM COUNTY
PEER APPROVED 6/04/2002

A-6: LANSING TOWNSHIP, PART A CONTINUED:

4. CORNER REFERENCED IN ORIGINAL FIELD NOTES FROM MSHD DATED JULY, 1939, BY E.A. BELLENBAUM, SURVEY PARTY CHIEF. NOTES STATE: "W 1/4 CORNER SEC. 18, LANSING TWP., INGHAM CO. - STA. 105 + 88.65 - 3" SQ. CONC. POST, RAISED TO GRADE WITH 24" - 3/4" GAS PIPE." WITNESSED BY:
12" MAPLE, N 41 30 E, 81.11'
20" MAPLE, N 88 0' E, 76.13'
15" OAK, N 24 30' W, 70.70'
NOTES ALSO SHOW E 1/4 COR. SEC. 13, DELTA TWP. STA. 105 + 63.83 " STONE RAISED TO GRADE WITH 24" GAS PIPE. (0.7' LT RD. C/L)" (THIS WOULD RESULT IN A CLOSING DISTANCE OF 24.82')
5. CORNER REFERENCED IN THE PLAT OF "SUPERVISOR'S PLAT OF FARMINGTON NO. 2", DATED MAY 31, 1945 BY E.W. TAPPEN, REG. LAND SURVEYOR, AND RECORDED IN LIBER 13 OF PLATS, PAGE 45, INGHAM COUNTY RECORDS. NO MENTION OF MONUMENT OR WITNESSES GIVEN. PLAT DRAWING SHOWS A TOTAL DISTANCE EAST OF 1615.53' TO THE 1/8 LINE.
6. E-W 1/4 LINE REFERENCED IN THE PLAT OF "WESTWOOD VILLAGE NO. 1", DATED DEC. 5, 1952, BY E.W. TAPPEN, REG. LAND SURVEYOR, AND RECORDED IN LIBER 16 OF PLATS, PAGE 35, INGHAM COUNTY RECORDS. PLAT DRAWING SHOWS A DISTANCE WEST TO THE 1/8 LINE FROM B-6 OF APPROXIMATELY 1353.85'
7. CORNER REFERENCED IN UNDATED INGHAM COUNTY ROAD COMMISSION NOTES. "3" CONC. POST - PIPE." WITNESSED BY:
17" MAPLE, NE, 62.8'
18" MAPLE, ESE, 77.0'
20" OAK, NW, 50.48'
8. CORNER REFERENCED IN UNDATED "NORTHSTINE NOTES" AS "3" CONC. POST, 24" X 1/2" PIPE ON TOP" WITNESSED BY: 12" MAPLE, N 54 E, 62.80'
18" MAPLE, S 76 E, 77.0'
20" MAPLE, N 41 W, 50.48'
9. CORNER REFERENCED ON MDOT FORM 280 CARD, BY DON FLUKE, SURVEY CHIEF, DATED 5/4/65. "FOUND 1/2 INCH ROD 0.3' BELOW BIT. WEST 1/4 CORNER OF SECTION 18." WITNESSED BY: N 38° W, 58.97' 16" MAPLE
N 53° E, 56.01' FACE OF 2-1/4 INCH SIGN POST
S 22° E, 71.57' 26" OAK
S 24° W, 101.91' TELE. ANCHOR POLE
10. CORNER REFERENCED ON MDOT FORM 280 CARD, BY ARDEN S. PIERSON, SURVEY CHIEF, DATED JAN. 1968. "WEST 1/4 CORNER SECTION 18, LANSING TOWNSHIP, INGHAM COUNTY. 1/2 " IRON PIN FOUND" WITNESSED BY:
NW COR. BRK. BLDG. - S 40° E, 82.25'
TOP NUT, FIRE HYD. - S 55° E, 55.20'
TOP NUT, FIRE HYD. - N 35° W, 51.25'
REAR OF CARD SHOWS DISTANCE NORTH OF 2639.94' TO A-5 LANSING TOWNSHIP.
11. CORNER REFERENCED IN LCRC DATED NOV. 9, 1979, BY RONNIE M. LESTER, RLS #18998, AND RECORDED IN LIBER 6, PAGE 8. PART B STATES: "DURING INVESTIGATION FOUND 1/2" BAR IN MONUMENT BOX AT THE CENTERLINES OF MICHIGAN AVENUE AND WAVERLY ROAD. LOCATION OF 1/2" BAR IN CLOSE ACCORD WITH WITNESSES AS GIVEN IN MDSHT FORM 280, 1968. ACCEPTED 1/2" BAR FOR CORNER. RESEARCH CONDUCTED BY INGHAM COUNTY SURVEY AND REMONUMENTATION PROJECT STAFF." PART C STATES: "WEST 1/4 CORNER, SECTION 18, T4N-R2W. FOUND 1/2" BAR IN MONUMENT BOX IN LOCATION DESCRIBED ABOVE." WITNESSED BY:
NORTHWEST CORNER OF BRICK BUILDING, SE, 82.25'
TOP NUT FIRE HYD., SE, 55.20'
TOP NUT FIRE HYD., NW, 51.25'
NAIL & TAG, #18998, NORTH SIDE 10" POWER POLE, NE, 60.64'
APPARENT LOCATION OF M-6 DELTA TWP., T4N-R3W, EATON COUNTY, SOUTH, 24.60'
12. NO OTHER REFERENCES FOUND.



2002-054414

Page: 2 of 2

09/04/2002 08:36A

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
INGHAM

(County)

Located In:

Corner Code #

LANSING TOWNSHIP.

1. Public Land Survey

T 4N. R 2W

A-7

2. Property Controlling
in Section

S

T R

T R

T R

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

S

T R

4. Lot No. Recorded Plat

5. Private Claims



2002-054415

Page: 1 of 2

09/04/2002 08:36A

Register of Deeds Stamp & File Number

I, DAVID R. LOHR, PS

, in a field survey on JUNE 27, 2001,

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. CORNER SET BY MUSGROVE EVANS, U.S. DEPUTY SURVEYOR IN FEB., 1827.

"INT. W. BDY 41 LKS. (27.06') N. OF POST AND SET A POST COR. TO SEC. 18 & 19. fw"

WITNESSED BY: BEECH 15", N 51-1/2° E, 29 LKS. (19.14')

BEECH 16", S 21° E, 26 LKS. (17.16')

NOTES SHOW DISTANCE EAST OF 44.51 CH. (2937.66)

2. CORNER REFERENCED IN SURVEY BY W.A. ROWE, COUNTY SURVEYOR, DATED OCT. 31, 1899, AND RECORDED IN BOOK 1, PAGE 2, COUNTY SURVEYORS RECORDS. CORNER SHOWN AS "#4" - "IRON PIPE 3 FT. LONG SET IN PLACE OF OLD POST SET BY PRESTON f.w." WITNESSED BY:

N.W. CORNER OF SCHOOLHOUSE, S 37 E, 173-1/2 LKS (114.51')

EIM, 6 IN., N 63 E, 57 LKS (37.62')

DOUBLE OAK, 20 IN., N 84 W, 119 LKS (78.54')

SURVEY SHOWS DISTANCE EAST OF 44.69 (2949.54') TO B-7.

3. CORNER REFERENCED IN RESURVEY OF LANSING TOWNSHIP, DATED 1909, AND RECORDED IN BOOK 5, PAGE 218, COUNTY SURVEYORS RECORDS, BY SURVEYOR R.J. ROBB, "ALL CORNERS ARE MARKED BY CEMENT POSTS 2.5' LONG - 3" SQUARE AT TOP - 4" SQUARE AT BOTTOM." WITNESSED BY:

S.W. COR. HOUSE, N-E, 36.6'

B. OAK, 24", N-W, 72.8'

CONTINUED ON BACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

SEARCHED AT APPARENT LOCATION OF CORNER AND FOUND A MON BOX ON C/L WAVERLY AND ST. JOSEPH HIGHWAY EAST, 27.1' NORTH OF M-7 DELTA TWP. EXCAVATED INTERIOR OF MON. BOX TO DEPTH OF 30", FOUND NOTHING BUT HIT HARD SURFACE IN BOTTOM OF HOLE. TRAVERSED WEST TOWNSHIP LINE, TO DETERMINE POSITION ON STANDARD LINE AT DISTANCE 27.06' NORTH OF M-7 DELTA TWP. COULD NOT SET STANDARD BAR AT ACTUAL LOCATION DUE TO MON. BOX NOT BEING CENTERED. SET STANDARD INGHAM COUNTY REMON. BAR/CAP STAMPED 30090, 0.06' EAST OF TRUE CORNER POSITION. MEASURED NORTH 2633.15' TO A-6.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-7, T4N, R2W, LANSING TOWNSHIP, INGHAM COUNTY. SET STANDARD INGHAM COUNTY REMON. BAR/CAP STAMPED 30090 IN MON. BOX 0.06' EAST OF TRUE POSITION, ON C/L WAVERLY ROAD AND ST. JOSEPH HIGHWAY.

WITNESSED BY:

ED. N/T #12034, NW/S P. POLE, S 40° W, 74.60'

SET N/T #30090, NE/S P. POLE, N 60° W, 35.82'

SET N/T #30090, SW/S 12" PINE, S 34° E, 106.45'

SET N/T #30090, E/S UTIL. POLE, S 27° W, 102.52'

M-7, T4N, R3W, STANDARD REMON. BAR/CAP IN MON. BOX), SOUTH, 27.06'

BEARINGS GIVEN ARE MAGNETIC.

Signed by David R. Lohr

Date JUNE 3, 2002

Surveyor's Michigan License No. 30090



P.A. 345 INGHAM COUNTY
PEER APPROVED 6/04/2002

A-7: LANSING TOWNSHIP, PART A CONTINUED:

4. CORNER REFERENCED IN ORIGINAL FIELD NOTES FROM MSHD DATED JULY, 1939, BY E.A. BELLENBAUM, SURVEY PARTY CHIEF. NOTES STATE: "SECTION CORNER COMMON TO SEC. 18-19, LANSING TWP., INGHAM CO. STA. 79 + 54.84 - THIS IS P.I. #2 - SEE WITNESSES IN ALIGNMENT NOTES. 1-1/2" IRON ALSO BOATSPIKE" (ALIGNMENT WITNESSES NOT FOUND)
NOTES ALSO SHOW NW COR. SEC. 24, DELTA TWP. STA. 79 + 27.78 ON C/L 24" - 3/4" GAS PIPE"
(THIS WOULD RESULT IN A CLOSING DISTANCE OF 27.06')
5. CORNER REFERENCED ON MDOT FORM 280 CARD, BY JON DAVIS, SURVEY CHIEF, DATED JULY, 1964.
"3/4 INCH SQUARE IRON IN MON BOX. IN INTERSECTION OF WAVERLY RD. & ST. JOE. HWY."
WITNESSED BY: N 60° W, 50.08' GUY POLE
S 35° E, 62.86' T.P.
S 30° W, 68.23' P.P.
6. CORNER REFERENCED ON MDOT FORM 280 CARD, BY DON FLUKE, SURVEY CHIEF, DATED FEB. 1965.
"NORTHWEST CORNER OF SECTION 19. 3/4" SQUARE IRON IN MONUMENT BOX, AT INTERSECTION OF WAVERLY RD. AND ST. JOSEPH (JOSEPH) HWY. WITNESSED BY: :
S 35° E, 62.86' T.P.
S 30° W, 68.23' P.P.
N 60° W, 32.08' GUY POLE
7. CORNER REFERENCED IN INGHAM COUNTY ROAD COMMISSION GRID MAP, DATED 1/1/72. "MON. BOX."
WITNESSED BY: SE COR. LAMP POST, NNW, 73.2'
SE COR. LAMP POST, NW, 40.45'
SE COR. LAMP POST, WNW, 78.1'
C/L FLAG POLE, ESE, 87.65
GRID MAP SHOWS A CLOSING DISTANCE OF 27.06'
8. CORNER REFERENCED IN WOLVERINE ENGINEERING COPY OF INGHAM COUNTY ROAD COMMISSION GRID MAP, NOT DATED "MON. BOX IN CONC. 1" IRON INSIDE."
WITNESSED BY: SE COR. CONC. LAMP POST, 73.2', NNW
SE COR. CONC. LAMP POST BASE, 40.45', NW
SE COR. CONC. LAMP POST BASE, 78.1', WNW
C/L FLAG POLE, 87.65, ESE
GRID MAP SHOWS A CLOSING DISTANCE OF 27.06'
9. CORNER REFERENCED IN LCRC DATED SEPT. 26, 1972, BY JAMES A. PORTER, RLS #19003, AND RECORDED IN LIBER 2, PAGE 127. PART B STATES: "MICHIGAN DEPT. STATE HIGHWAY WITNESSES.
S 35° E, 62.86' BRASS TAG AND NAIL IN TELEPHONE POLE (POLE HAS BEEN REPLACED)
S 30° W, 68.23' BRASS TAG AND NAIL IN POWER POLE
N 60° W, 32.08' GUY POLE (POLE REMOVED)
PART C STATES: "ADDED THE FOLLOWING WITNESSES:
N 48° W, 34.62' BRASS TAG AND NAIL IN NEW TELEPHONE POLE
S 32° E, 62.92' BRASS TAG AND NAIL IN NEW TELEPHONE POLE
10. NO OTHER REFERENCES FOUND.



2002-054415
Page: 2 of 2
09/04/2002 08:36A

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

INGHAM

(County)

Located In:

Corner Code #

LANSING TOWNSHIP.

1. Public Land Survey

T 4N R 2W

B-5

2. Property Controlling
in Section

S

T

R

T

R

T

R

T

R

3. Miscellaneous
Property in Sec.

S

T

R

T

R

T

R

4. Lot No.

Recorded Plat

5. Private Claims



2002-054416

Page: 1 of 2

09/04/2002 08:36A

Register of Deeds Stamp & File Number

I, DAVID R. LOHR, PS

in a field survey on JUNE 27, 2001,

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. CORNER SET BY MUSGROVE EVANS, U.S. DEPUTY SURVEYOR IN FEB., 1827.
"SET 1/4 SEC. POST fw AN" WITNESSED BY:

IRONWOOD 4", N 41° E, 4 LKS. (2.64')

BEECH 14", S 48° E, 26 LKS. (17.16')

NOTES SHOW DISTANCE EAST OF 40.00 CH. (2640') AND WEST OF 44.66 CH. (2947.56)

2. CORNER REFERENCED IN SURVEY BY W.A. ROWE, COUNTY SURVEYOR, DATED OCT. 31, 1899, AND RECORDED IN BOOK 1, PAGE 2, COUNTY SURVEYORS RECORDS. CORNER SHOWN AS "#5" - "STONE SET f.w.", WITNESSED BY: WHITE ASH, 10 IN., N 52-1/2° E, 70 LKS (46.2')
ELM, 8 IN., N 42-1/2° W, 67 LKS (44.22')
SURVEY SHOWS DISTANCE EAST OF 40.00 CH. (2640.0') AND WEST OF 45.00 CH. (2970.00')

3. CORNER REFERENCED IN RESURVEY OF LANSING TOWNSHIP, DATED 1909, AND RECORDED IN BOOK 5, PAGE 218, COUNTY SURVEYORS RECORDS, BY SURVEYOR R.J. ROBB, "ALL CORNERS ARE MARKED BY CEMENT POSTS 2.5' LONG - 3" SQUARE AT TOP - 4" SQUARE AT BOTTOM." WITNESSED BY:
"APPLE 6" N-E 44' AND W. ASH 12" N-E 51' "

CONTINUED ON BACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

SEARCHED AT APPARENT LOCATION OF CORNER AND FOUND RED PAINT MARK IN CIRCLE ON NEWER BIT SURFACE OF SAGINAW HIGHWAY. SAGINAW HIGHWAY WAS MILLED AND RESURFACED IN SUMMER OF 2000, REMOVING ANY PHYSICAL EVIDENCE OF CORNER. FOUND FOUR OF SURVEYOR AUTENRIETH WITNESSES FROM 1998 (IRON 50' NORTH IS GONE) RE-SET POSITION USING HIS FOUR REMAINING WITNESSES. CUT 12" X 4" CORE IN NEWER BIT. PAVEMENT AND FOUND REMAINS OF MDOT ACKERMAN PLUG ON C/L CRACK WITHIN 0.08' OF RE-ESTABLISHED POSITION. COULD NOT DETERMINE EXACTLY WHERE ACKERMAN PLUG WAS LOCATED DUE TO PLUG REMOVAL. CORED THRU AN ADDITIONAL 9" OF CONCRETE, WHICH WAS PROBABLY THE BASE OF THE OLD MEDIAN ISLAND. TO GRAVEL. SET STANDARD INGHAM COUNTY REMON. BAR/CAP STAMPED 30090 AT LOCATION OF RE-SET PK NAIL. ACCEPTED LOCATION OF NAIL AS PER LIBER 1, PAGE 367, AND SET STANDARD INGHAM COUNTY REMON. BAR WITH ALUMINUM CAP STAMPED 30090 IN MONUMENT BOX. MEASURED NORTH 2652.74' TO B-4; EAST 2732.13 TO C-5, SOUTH 2627.63' TO B-6 AND WEST 2967.70' TO A-5.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-5, T4N, R2W, LANSING TOWNSHIP, INGHAM COUNTY. SET STANDARD INGHAM COUNTY REMON. BAR WITH 2 1/2" ALUMINUM REMON. CAP IN MON. BOX FROM RECORDED WITNESSES. WITNESSED BY:
FD. N&T #25832 (L. BRYAN), SE/S POWER POLE, S69° W, 116.91'
FD. N&T #25832 (L. BRYAN), NE/S POWER POLE, S34° E, 61.40'
NE CORNER PORCH #3115 SAGINAW HWY., S20° E, 77.94'
NE CORNER OF BRICK BUILDING, S20° W, 95.56'
BEARINGS GIVEN ARE MAGNETIC.


Signed by

David R. Lohr

Date

JUNE 3, 2002

Surveyor's Michigan License No. 30090



P.A. 345 INGHAM COUNTY

PEER APPROVED 6/04/2002 M

B-5: LANSING TOWNSHIP, PART A CONTINUED:

4. CORNER REFERENCED IN THE PLAT OF "DRYER FARM" DATED APRIL 23, 1925, BY J.A. DINSMORE, REG. CIVIL ENGINEER, AND RECORDED IN LIBER 8 OF PLATS, PAGE 35. NO MENTION OF MONUMENT OR WITNESSES GIVEN. PLAT DRAWING DESCRIBES CORNER AS THE P.O.B AND ALSO THE SOUTHEAST CORNER OF THE PLAT. PLAT SHOWS A DISTANCE WEST TO THE N-S 1/8 LINE OF 1032.7'
5. CORNER REFERENCED IN THE PLATS OF "EDGEMONT PARK AND EDGEMONT PARK NO. 3", DATED APRIL 12, 1948 AND APRIL 3, 1953, BY CLYDE K. STEPHENS, RLS #3829, AND RECORDED IN LIBER 14 OF PLATS, PAGE 42, AND LIBER 16 OF PLATS, PAGE 47. NO MENTION OF MONUMENT OR WITNESSES GIVEN. PLAT DRAWINGS SHOW A TOTAL DISTANCE WEST TO A-5 OF 2968.59.
6. CORNER REFERENCED ON MDOT FORM 280 CARD, BY F.K. HOLMES, SURVEY CHIEF, DATED JULY 1964. "S 1/4 COR. SECTION 7, 3/4" ACKERMAN PLUG." WITNESSED BY:
TWIN 10" MAPLE, S 10° W, 55.58'
8" MAPLE, S 09° E, 58.75'
P.P., S 45° E, 59.15'
REAR OF CARD SHOWS A DISTANCE EAST TO C-5 OF 2637.76' (MEASURED 2732.13')
7. CORNER REFERENCED ON MDOT FORM 280 CARD, BY MYRON L. PETRIE, SURVEY CHIEF, DATED DEC. 1971. "SOUTH 1/4 CORNER, SECTION 7. FOUND 3/4" ACKERMAN PLUG." WITNESSED BY:
S.20° E. - 77.94' - N.E. COR. PORCH FOND. HOUSE #3115
S.20° W. - 95.56' - N.E. COR. BRICK BLDG. MICH. TWP. ASSC.
NORTH - 50.00' - 1/2" PIPE, PROP. COR.
S.45° E - 59.15' - POWER POLE,
8. CORNER REFERENCED IN LCRC DATED NOV. 17, 1971, BY NELSON E. JONES, LAND SURVEYOR #02934, AND RECORDED IN LIBER 1, PAGE 367. PART B STATES: "FOUND ACKERMAN PLUG IN HIGHWAY FROM WITNESSES ON RECORD BY THE MICHIGAN DEPARTMENT OF STATE HIGHWAYS. NOV. 3, 1965." PART C STATES: "ACKERMAN PLUG IN HIGHWAY, RE-WITNESSED BY MYRON L. PERTIE, SURVEY CHIEF AND PARTY. DEC. 1971." WITNESSED BY: SAME WITNESSES AS ITEM #A-7.
9. CORNER REFERENCED IN LCRC DATED MARCH 5, 1998, BY JEFFREY K. AUTENRIETH, P.S.#31588, AND RECORDED IN LIBER 9, PAGE 319. PART A STATES: "THIS DOCUMENT BEING RECORDED TO PERPETUATE THE EXISTING MONUMENT AND UPDATE WITNESSES FOR THIS CORNER, PREVIOUSLY RECORDED IN LIBER 1 OF CORNERS, PAGE 367, INGHAM COUNTY RECORDS." PART B STATES: B-5, NO EVIDENCE OF MONUMENT FOUND AT THIS LOCATION. RESET P.K. NAIL AND TAG #25832 (L. BRYAN) FROM REMAINING WITNESSES IN LIBER 1 OF CORNERS, PAGE 367. FOUND NORTHEAST CORNER CONCRETE PORCH FOUNDATION HOUSE #3115, S.20° E, 77.94' AND NORTHEAST CORNER BRICK BUILDING, S.20° W, 95.56' PART C STATES: "B-5, T4N, R2W - RESET P.K. NAIL AND TAG #25832 IN CENTERLINE SAGINAW HIGHWAY (M-43)." WITNESSED BY:
SET NAIL AND TAG #25832 (L. BRYAN) IN SOUTHEAST SIDE UTILITY POLE, S69° W, 116.91'
SET NAIL AND TAG #25832 (L. BRYAN) IN NORTHEAST SIDE UTILITY POLE, S34° E, 61.40'
NORTHEAST CORNER CONCRETE PORCH FOUNDATION TO HOUSE #3115, S20° E, 77.94'
NORTHEAST CORNER BRICK BUILDING, S20° W, 95.56'
FOUND 1/2" BAR, S 18° W, 39.92'
10. NO OTHER REFERENCES FOUND.



2002-054416

Page: 2 of 2

09/04/2002 08:36A

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

INGHAM

(County)

Located In:

Corner Code #

LANSING TOWNSHIP.

1. Public Land Survey

T 4N R 2W

B-6

2. Property Controlling
in Section

S

T R

T R

T R

T R

T R

3. Miscellaneous
Property in Sec.

S

T R

T R

4. Lot No.

Recorded Plat

5. Private Claims



2002-054417

Page: 1 of 2

09/04/2002 08:36A

Register of Deeds Stamp & File Number

I, DAVID R. LOHR, P.S.

, in a field survey on MAY 22, 2002,

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. CORNER NOT SET IN ORIGINAL GLO SURVEY OF 1827.

2. CORNER REFERENCED IN SURVEY, BY W.A ROWE, COUNTY SURVEYOR, DATED NOV. 3, 1899, AND RECORDED IN BOOK 1, PAGE 2, COUNTY SURVEYOR RECORDS. "STONE SET" NO WITNESSES GIVEN. SURVEY SHOWS A DISTANCE WEST TO A-6 OF 44.97 CH. (2968.02'), EAST TO C-6 OF 40.00 CH. (2640') AND SOUTH TO B-7 OF 39.88 CH. (2632.08')

3. CORNER REFERENCED ON INGHAM COUNTY ROAD COMMISSION GRID MAP, NOT DATED, AS "MON. BOX" NO WITNESSES GIVEN.

4. CORNER REFERENCED IN SURVEYS, DATED 2/05/73 AND 9/06/73, BY RONNIE M. LESTER, RLS #18998, AND RECORDED IN LIBER 1, PAGE 669 & 1002. "CENTER OF SECTION 18, T4N, R2W, FOUND MON. BOX WITH 3/4" BAR." WITNESSED BY:

SET NAIL & TAG NE SIDE POWER POLE, NW, 93.34'

SET NAIL & TAG SE SIDE 10" SPRUCE, NE, 42.32'

SET NAIL & TAG @ SW CORNER RAILROAD TIE USED AS A MAILBOX, SE, 63.26'

CONTINUED ON BACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
SEARCHED AT APPARENT LOCATION OF CORNER AND FOUND 1" X 30" STEEL BAR IN BROKEN MONUMENT BOX ON C/L CRACK OF MICHIGAN AVENUE AS PER LCRC OF LIBER 6, PAGE 215. SAWCUT THRU 10" OF CONCRETE PAVEMENT TO REPLACE MONUMENT BOX. EXCAVATED INTERIOR OF MON. BOX TO 36" DEPTH TO FIND NO OTHER EVIDENCE. ACCEPTED LOCATION OF FOUND 1" STEEL BAR AS CORNER. MEASURED WEST TO A-6 OF 2967.70', EAST TO C-6 OF 2636.72' AND NORTH TO B-5 OF 2627.63'. SET STANDARD INGHAM COUNTY REMON. BAR AND PA 345 CAP STAMPED 30090 IN POSITION OF FOUND 1" STEEL BAR.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
B-6, T4N, R2W, LANSING TOWNSHIP, INGHAM COUNTY. FOUND 1" X 30" STEEL BAR. SET STANDARD INGHAM COUNTY REMON. BAR/PA 345 CAP STAMPED 30090. WITNESSED BY:

ED. N&T #16053, SE/S P. POLE, N 58° E, 40.95'

SET N&T #30090, SE/S P. POLE, N 86° E, 159.35'

SET N&T #30090, SW/S 18" ASH, S 32° E, 101.90'

ED. N&T #16053, S/S P. POLE, N 70° W, 93.66'

BEARINGS GIVEN ARE MAGNETIC.



Signed by David R. Lohr

Date JUNE 3, 2002

Surveyor's Michigan License No. 30090

B-6 T4N, R2W, LANSING TOWNSHIP, PART A CONTINUED:

5. CORNER REFERENCED IN LCRC, DATED 2/05/78, BY RONNIE M. LESTER, RLS #18998, AND RECORDED IN LIBER 4, PAGE 228. PART B STATES: "B-6 FOUND MONUMENT BOX CONTAINING 3/4" BAR IN ACCORDANCE WITH ADJACENT PLATS AND SURVEYS." SAME WITNESSES AS ITEM A-3 ABOVE.
6. CORNER REFERENCED IN LCRC, DATED 2/09/82, BY JAMES E. STEPHENS, LLS #16053, AND RECORDED IN LIBER 6, PAGE 215. PART B STATES: "FOUND MONUMENT BOX CONTAINING 3/4 INCH BAR AS RECORDED IN LIBER 4 OF CORNERS, PAGE 228.
PART C STATES: "3/4" BAR IN MONUMENT BOX IN CENTERLINE OF MICHIGAN AVENUE."
WITNESSED BY: NAIL & TAG IN SE SIDE UTILITY POLE N.W. 93.34'
NAIL & TAG IN SE SIDE UTILITY POLE N.E. 41.05'
BACK OF CURB NORTH 24.50'
BACK OF CURB SOUTH 24.52'
7. NO OTHER REFERENCES FOUND.



2002-054417
Page: 2 of 2
09/04/2002 08:36A

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

INGHAM

(County)

Located In:

Corner Code #

LANSING TOWNSHIP.

1. Public Land Survey

T 4N R 2W

B-7

2. Property Controlling
in Section

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

4. Lot No.

Recorded Plat

5. Private Claims



2002-054418

Page: 1 of 2

09/04/2002 08:36A

Register of Deeds Stamp & File Number

I, DAVID R. LOHR, P.S.

, in a field survey on MAY 22, 2002,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. CORNER SET BY MUSGROVE EVANS, U.S. DEPUTY SURVEYOR IN MARCH
OF 1827. "SET A 1/4 SEC. POST, fw a" WITNESSED BY:

BEECH 18", S 54° E, 15 LKS. (9.90')

BEECH 11", N 74° W, 12 LKS. (7.92')

GLO NOTES SHOW DISTANCES EAST OF 40 CH. (2640') AND WEST OF 44.51 CH. (2937.66')

2. CORNER REFERENCED IN SURVEY, BY W.A ROWE, COUNTY SURVEYOR, DATED NOV. 3, 1899, AND RECORDED
IN BOOK 1, PAGE 2, COUNTY SURVEYOR RECORDS. "STONE & SMALL STONE IN CENTER OF HIGHWAY."
NO WITNESSES GIVEN. SURVEY SHOWS A DISTANCE WEST TO A-7 OF 44.69 CH. (2949.54'), EAST TO
C-7 OF 40.16 CH. (2650.56') AND NORTH TO B-6 OF 39.88 CH. (2632.08')

3. CORNER REFERENCED IN SURVEY OF LANSING TOWNSHIP IN 1909 BY R.J.ROBB, IN BOOK 5, PAGE 218,
AS "CEMENT POST", 2.5 FT. LONG, 3" SQUARE AT TOP AND 4" SQUARE AT BOTTOM, WITNESSED BY:
EIM, 3", S 3° E, , 16' - GUAGE OF S. RAIL OF M. U. R. , NORTH. 20.8',
NO DISTANCES SHOWN ON SURVEY.

CONTINUED ON BACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
SEARCHED AT APPARENT LOCATION OF CORNER BUT COULD FIND NO EVIDENCE OF CORNER AS RECORDED.
FOUND THREE OF SURVEYOR BRYAN'S WITNESSES AS PER ITEM A-13, BUT THEY DID NOT CROSS
SATISFACTORILY. SINCE 1997, AREA HAS BEEN EXCAVATED FOR SEWER IMPROVEMENTS, WHICH REMOVED THE
NORTH HALF OF THE CONCRETE STREET AND REPLACED IT WITH BIT. PAVEMENT. I BELIEVE THAT THE
CORNER WAS REMOVED DURING THESE SEWER IMPROVEMENTS. RE-ESTABLISHED POSITION OF CORNER USING
DATA FROM SURVEYOR BEAVERS SURVEY OF ITEM A-11. EXCAVATED THRU 8" OF BIT. AND CONCRETE TO
FIND NO OTHER EVIDENCE. SET STANDARD INGHAM COUNTY REMON. BAR AND PA 345 CAP STAMPED 30090 IN
NEW MONUMENT BOX, 0.10 FT. NORTH OF C/L JOINT OF MICHIGAN AVENUE AND ON C/L OF LENTZ COURT.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
B-7, T4N, R2W, LANSING TOWNSHIP, INGHAM COUNTY. SET STANDARD INGHAM COUNTY REMON. BAR AND PA
345 CAP STAMPED 30090 IN NEW MONUMENT BOX. WITNESSED BY:

FD. N&T #25832, NE/S UTILITY POLE, N 40° W, 41.80'

FD. N&T #25832, NE/S UTILITY POLE, N 80° W, 159.10'

FD. N&T #25832, E/S 20" APPLE, N 24° E, 86.00'

FD. N&T #25832, E/S UTILITY POLE, S 08° E, 37.25'

BEARINGS GIVEN ARE MAGNETIC.

Signed by

David R. Lohr

Date JUNE 3, 2002

Surveyor's Michigan License No. 30090



B-7: T4N, R2W, LANSING TOWNSHIP, PART A CONTINUED:

4. CORNER REFERENCED IN "HORN NOTES" AS THE FOLLOWING: "RECOVERED THE CEMENT POST (SET BY ROY ROBB IN 1909) LEANING TO THE SOUTH EVIDENTLY TO PLACE THE TOP OVER THE TOP OF A LARGE FIELD STONE WHICH MAY HAVE BEEN THE ORIGINAL CORNER. SET A 1921 STANDARD MONUMENT WITH FLUSH TOP HOLE. REFERENCES" - GAUGE WEST RAIL MANUFACTURER'S RAILROAD, EAST, 22.8'
GAUGE SOUTH RAIL MANUFACTURER'S RAILROAD, NORTH, 20.8'
SOUTH WEST CORNER CROSSING DIAMOND, N. E., 30.5'
5. CORNER REFERENCED IN PLAT OF "SUPERVISOR'S PLAT OF BAILEY ACRES", DATED 6/12/34, BY FRANCIS N. BATEMAN, REGISTERED SURVEYOR # 1479, AND RECORDED IN LIBER 11 OF PLATS, PAGE 25. NO MENTION OF MONUMENT OR WITNESSES GIVEN. PLAT SHOWS A CONCRETE MONUMENT SET ON THE NORTH RIGHT-OF-WAY OF ST. JOSEPH STREET, 25.00 EAST AND WEST OF THE NORTH-SOUTH 1/4 LINE.
6. CORNER REFERENCED ON WOLVERINE ENGINEERING COPY OF INGHAM COUNTY ROAD COMMISSION GRID MAP, NOT DATED, AS "3/4 IRON" WITNESSED BY: SP. 20", 51.25, NE
SP 10" ELM, 57.05, ENE
(+) IN CURB, 37.0, SSW
7. CORNER REFERENCED ON MDOT FORM 280 CARD, BY JON DAVIS, SURVEY CREW CHIEF, DATED JULY 1964, AS "1" STEEL PIN" WITNESSED BY: N 50° W, 39.44', P. P.
N 55° E, 60.36', 16" ELM
SOUTH, 38.97', METAL SIGN POST
8. CORNER REFERENCED IN LCRC, DATED 9/26/72, BY JAMES A. PORTER, RLS #19003, AND RECORDED IN LIBER 2, PAGE 125. PART B STATES: "FROM MICHIGAN DEPT. STATE HIGHWAY WITNESSES: FOUND 1" STEEL PIN IN C.L. ST. JOSEPH STREET." SAME WITNESSES AS ITEM A-7 ABOVE.
PART C STATES: "VERIFIED ABOVE WITNESSES: EXCEPT 16" ELM NOW A 16" STUMP.
ADDED WITNESS: N 25° E, 68.41', BRASS TAG & NAIL IN 10" APPLE TREE
9. CORNER REFERENCED IN SURVEY, DATED 10/31/72, BY JAMES A. PORTER, RLS #19003, AND RECORDED IN LIBER 1, PAGE 477. SAME WITNESSES AS ITEM A-8 ABOVE.
10. CORNER REFERENCED IN SURVEY, DATED 12/01/75, BY LAVERNE J. HENDRYX, RLS #3276, AND RECORDED IN LIBER 2, PAGE 1280. NO MENTION OF MONUMENT OR WITNESSES GIVEN, NO DISTANCES GIVEN.
11. CORNER REFERENCED IN SURVEYS, DATED 4/21/88 AND 11/04/92, BY PETER D. BEAVER, RLS #25828, AND RECORDED IN LIBER 6, PAGE 1073 & 1074. "N 1/4 COR. SEC. 19, 1" ST. PIN IN C/L ST. JOE."
WITNESSED BY: N 50° W, 39.44', N/T IN POWER POLE
N 50° E, 60.36', 16" ELM STUMP
SOUTH, 38.97', METAL SIGN POST
N 25° E, 68.41', N/T IN 10" APPLE TR.
12. CORNER REFERENCED IN UNRECORDED SURVEY, DATED 4/28/88, BY DAVID R. LOHR, LLS #30090. NO MENTION OF MONUMENT OR WITNESSES GIVEN. SURVEY SHOWS A DISTANCE WEST TO A-7 OF 2955.66'.
13. CORNER REFERENCED IN ALTA TITLE SURVEY, #96-B-51004, DATED 1/10/97, BY LARRY A. BRYAN, LLS #25832. "FOUND 1" STEEL BAR IN CENTERLINE OF ST. JOSEPH STREET. WITNESSED BY:
FOUND NAIL & TAG #25832 IN NORTHWEST SIDE OF UTILITY POLE, N 75° E, 96.56'
FOUND NAIL & TAG #25832 IN NORTHEAST SIDE OF UTILITY POLE, N 45° W, 41.75'
FOUND NAIL & TAG #25832 IN NORTHEAST SIDE OF LIGHT POLE, S 15° E, 37.03'
SET NAIL & TAG #25832 IN NORTHEAST SIDE OF UTILITY POLE, N 75° W, 158.03'
14. NO OTHER REFERENCES FOUND.



2002-054418

Page: 2 of 2

09/04/2002 08:36A

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

INGHAM

(County)

Located In:

Corner Code #

LANSING TOWNSHIP.

1. Public Land Survey

T 4N R 2W

C-5

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No.

5. Private Claims

S T R

Paula Johnson

INGHAM COUNTY
REGISTER OF DEEDS

RECORDED

L-10 P-158

CRNR 11.00

2001-060847

Register of Deeds Stamp & File Number

2001-060847

Page: 1 of 2

11/14/2001 08:20A

I, DAVID R. LOHR, P.S., in a field survey on JUNE 12, 2001, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. CORNER SET BY MUSGROVE EVANS, U.S. DEPUTY SURVEYOR IN MARCH OF 1827. "SET POST COR. TO SEC. 7, 8, 17 & 18, fw a" WITNESSED BY: W. O. 24", N 45 W, 16 LKS. (10.56')

MAPLE 4", S 31° E, 15 LKS. (9.90')

GLO NOTES SHOW DISTANCES NORTH AND SOUTH OF 40 CH. (2640')

2. CORNER REFERENCED IN SURVEY, BY W.A ROWE, COUNTY SURVEYOR, DATED NOV. 3, 1899, AND RECORDED IN BOOK 1, PAGE 2, COUNTY SURVEYOR RECORDS. "WHITE STONE & BRICK SET IN PLACE OF OLD POST FOUND IN CENTER OF HIGHWAY, fw

APPLE 8", N 35-1/2° W, 69 LKS. (45.54')

SUGAR 6", N 21° E, 45 LKS (29.70')

OAK 3", S 70-1/2° W, 109 LKS (71.94')

SURVEY SHOWS A DISTANCE WEST TO C-4 OF 40 CH. (2640')

3. CORNER REFERENCED IN SURVEY OF LANSING TOWNSHIP IN 1909 BY R.J.ROBB, IN BOOK 5, PAGE 218, AS "CEMENT POST", 2.5 FT. LONG, 3" SQUARE AT TOP AND 4" SQUARE AT BOTTOM, WITNESSED BY: APPLE 8" N-W, 45.5', SUGAR 6", N-E, 29.7' OAK 3", S-W, 72'. NO DISTANCES SHOWN ON SURVEY.

CONTINUED ON BACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

SEARCHED AT APPARENT LOCATION OF CORNER AND FOUND 1" STEEL PIN IN MONUMENT BOX AS PER LCRC OF LIBER 1, PAGE 363. CORNER FALLS DIRECTLY UNDER 2" BOTTOM RAIL OF PERIMETER FENCE AROUND GENERAL MOTORS ASSEMBLY PLANT. COULD NOT GAIN ACCESS TO EXCAVATE INTERIOR OF MON. BOX OR EVEN REMOVE EXISTING STEEL PIN. ACCEPTED LOCATION OF FOUND 1" IRON AS CORNER AS DESCRIBED BY MDOT. MEASURED WEST TO B-5 OF 2638.94' AND NORTH TO C-4 OF 2652.10'. THIS CORNER LOCATION FALLS ON THE EXTENSION OF THE CENTERLINE OF SAGINAW STREET BOTH EAST AND WEST AND ABOUT 98 FT. NORTH OF THE RAILROAD BRIDGE OVER SAGINAW STREET RELOCATED.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-5, T4N, R2W, LANSING TOWNSHIP, INGHAM COUNTY. FOUND 1" IRON IN MONUMENT BOX. WITNESSED BY:

SET N&T #30090, S/S UTILITY POLE, N 60° E, 117.97'

FD. PK & MDOT TAG, S/S ELEC. POLE, S 73° E, 88.35'

C/L 3" GALV. FENCE POST, NORTH, 23.18'

C/L 3" ANCHOR POST BASE, N 42° E, 93.10'

TRAV. PT. LA3-48-428, (#4 BAR/CAP) S 87° E, 93.20'

BEARINGS GIVEN ARE MAGNETIC.

Signed by

David R. Lohr

Date SEPT. 10, 2001

Surveyor's Michigan License No. 30090



FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT, 1995

ADAPTED FOR WORD PROCESSING JAN, 1999

P.A. 345 INGHAM COUNTY

PEER APPROVED 9/11/2001

C-5: T4N, R2W, LANSING TOWNSHIP, PART A CONTINUED:

4. CORNER REFERENCED IN "HORN NOTES" AS THE FOLLOWING: "IN 1919, THE MARK WAS RECOVERED BY C. M. CADE WHO USED SAME IN CONNECTION WITH TOPOGRAPHIC SURVEYS. THE FOLLOWING REFERENCES WERE MADE AT THAT TIME. APPLE N. W., 45.1'
SUGAR N. E., 79.7' (29.7'??)
OAK 3", S.W., 71.0'
"+" ON W RAIL E 22.56 FEET.
THE LAST REFERENCE IS STATION ZERO OF THE CONTROL TRAVERSE FOR TOPOGRAPHY IN THIS SECTION. THE STATE HIGHWAY DEPARTMENT PLACED AROUND THIS MONUMENT A SPECIAL CASTING IN THE ASPHALT PAVEMENT. ALSO SET IRON PIPE OVER CENTER OF POST AND SURROUNDED SAME WITH CONCRETE."
5. CORNER REFERENCED IN LCRC, DATED 04/28/71, BY CLYDE K. STEPHENS, RLS#3829, AND RECORDED IN LIBER 1, PAGE 25. PART B STATES: "5/8" ROD IN MONUMENT BOX FOUND IN PROJECTION OF EXISTING SECTION LINE ROAD AND ON A PROJECTION OF CHAIN LINK FENCE TO THE SOUTH. (SAGINAW STREET) PART C STATES: THE ROD IN THE MONUMENT BOX WAS LEFT IN POSITION WITH THE FOLLOWING WITNESSES: STEPHENS ENGINEERING TAG IN POWER POLE N 48° 11'W, 83.85', STEPHENS TAG IN POWER POLE S 76° 14'E, 106.45', STEPHENS TAG IN POWER POLE, SOUTH, 46.33 FEET."
6. CORNER REFERENCED ON MDOT FORM 280 CARD, DATED DECEMBER 1971, BY MYRON L. PIETRIE, SURVEY CHIEF. "S.E. CORNER, SECTION 7, FOUND MON. BOX WITH 1" PIN." WITNESSED BY:
N. 60° W, - 83.95' - P.P. & T.P.
N. 20° E, - 93.45' - END FE. POST - 4' CHAIN LINK.
EAST, - 87.77' - POWER POLE.
EAST, - 23.12' - GAUGE EDGE W. RAIL - 2 ND. TRACK
7. CORNER REFERENCED IN LCRC, DATED 11/15/71, BY N.C. JONES, RLS#2934, AND RECORDED IN LIBER 1, PAGE 363. PART B STATES: "FOUND MONUMENT BOX WITH 1" PIN, FROM WITNESSES ON RECORD BY THE MICHIGAN DEPARTMENT OF STATE HIGHWAYS, JULY 1964. PART C STATES: "MONUMENT BOX WITH 1" PIN, RE-WITNESSED BY MYRON L. PETRIE, SURVEY CHIEF AND PARTY, DEC. 1971." WITNESSED BY:
N. 60° W, - 83.95' - POWER POLE & TELEPHONE POLE. (GONE)
N. 20° E, - 93.45' - END FENCE POST - 4' CHAIN LINK. (GONE)
EAST, - 87.77' - POWER POLE. (GONE)
EAST, - 23.12' - GAUGE EDGE W. RAIL - 2 ND. TRACK EAST (MOVED)
8. CORNER REFERENCED IN LCRC, DATED 03/11/91, BY THOMAS G. MORAN, RLS#25860, AND RECORDED IN LIBER 7, PAGE 226. PART B STATES: "C-5: SEC COR COM TO SECS. 7, 8, 17 & 18, FOUND 1" IRON PIN IN MON. BOX FROM MDOT WITNESSES." PART C STATES: "C-5: IRON PIN IN MON. BOX." WITNESSED BY:
SOUTH, 99.69' N. END OF RR BRIDGE NE COR W'LY BEAM
S 25° E, 97.86', N. END OF RR BRIDGE NW COR E'LY BEAM
N 05° W, 23.08', FENCE CORNER S'LY & W'LY FENCES
S 60° E, 87.52', NAIL & TAG IN POWER POLE.
9. NO OTHER REFERENCES FOUND.



2001-060847

Page: 2 of 2

11/14/2001 08:20A

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
INGHAM

(County)

Located In:

Corner Code #

LANSING TOWNSHIP.

1. Public Land Survey

T 4N R 2W

C-6

2. Property Controlling
in Section

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

4. Lot No.

Recorded Plat

5. Private Claims



2002-054419

Page: 1 of 2

09/04/2002 08:36A

Register of Deeds Stamp & File Number

I, DAVID R. LOHR, P.S.

in a field survey on APRIL 29, 2002,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. CORNER SET BY MUSGROVE EVANS, U.S. DEPUTY SURVEYOR IN MARCH
OF 1827. "SET 1/4 SEC. POST fw a" WITNESSED BY:

MAPLE 12", S 41° E, 8 LKS. (5.28')

MAPLE 9", S 88° W, 7 LKS. (4.62')

GLO NOTES SHOW DISTANCES NORTH AND SOUTH OF 40 CH. (2640')

2. CORNER REFERENCED IN SURVEY, BY W.A ROWE, COUNTY SURVEYOR, DATED NOV. 3, 1899, AND RECORDED
IN BOOK 1, PAGE 2, COUNTY SURVEYOR RECORDS. "STONE & GAS PIPE SET", fw

MAPLE 8", N 51° E, 67-1/2 LKS. (45.55')
SURVEY SHOWS A DISTANCE WEST TO B-6 OF 40 CH. (2640')

3. CORNER REFERENCED IN SURVEY OF LANSING TOWNSHIP IN 1909 BY R.J.ROBB, IN BOOK 5, PAGE 218,
AS "CEMENT POST", 2.5 FT. LONG, 3" SQUARE AT TOP AND 4" SQUARE AT BOTTOM, WITNESSED BY:
MAPLE 15" N-E, 59-1/2', GAUGE OF W. RAIL OF MANY. R.R. EAST, 20.8'. NO DISTANCES SHOWN ON
SURVEY.

CONTINUED ON BACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

SEARCHED AT APPARENT LOCATION OF CORNER AND FOUND 1" x 15" PIPE IN MONUMENT BOX AS PER LCRC
OF LIBER 1, PAGE 131, (ITEM A-5). CORNER FALLS ON CENTERLINE OF MICHIGAN AVENUE ON WEST ROW
OF RAILROAD TRACK INTO GENERAL MOTORS ASSEMBLY PLANT. EXCAVATED INTERIOR OF MON. BOX TO FIND
BRICK PAVERS AT DEPTH OF 18", COULD NOT EXCAVATE FURTHER. MEASURED EAST 22.64' TO THE WEST
GAUGE LINE OF THE RAILROAD (THE EAST EDGE OF THE WEST RAIL), THIS COMPARES WITH THE RECORDED
DISTANCE OF 22.8' AS PER HORN'S WITNESS (ITEM A-4) AND STEPHENS WITNESS OF 22.40' (ITEM A-6).
ACCEPTED LOCATION OF FOUND 1" PIPE AS CORNER AND RESET FOUND PIPE ABOVE PAVERS, SETTING PA 345
CAP STAMPED #30090 ON IT. MEASURED WEST TO C-5 OF 2636.72' AND NORTH TO C-5 OF 2631.42'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-6, T4N, R2W, LANSING TOWNSHIP, INGHAM COUNTY. FOUND 1" PIPE IN MONUMENT BOX. WITNESSED BY:

FD. N&T #30897, W/S P. POLE, N 08° E, 26.20'

FD. N&T #30897, SW/S P. POLE, S 60° E, 59.15'

SET N & KEBS TAG, W/S P. POLE, S 02° W, 64.30'

NE CORNER BLDG. #2301-2303, S 65° W, 73.90'

SET N & KEBS TAG, SW/S P. POLE, N 75° W, 92.80'

BEARINGS GIVEN ARE MAGNETIC.

Signed by David R. Lohr

Date MAY 7, 2002

Surveyor's Michigan License No. 30090



C-6: T4N, R2W, LANSING TOWNSHIP, PART A CONTINUED:

4. CORNER REFERENCED ON PAGE 26 OF "HORN'S NOTES" AS THE FOLLOWING: "RECOVERED CEMENT POST (SET BY ROY ROBB IN 1909) IN CENTER OF FILL 22.8 FEET WEST OF GAUGE LINE OF RAILROAD AND 59.5 FEET FROM THE MAPLE. ON REMOVING THE CEMENT POST AN IRON PIPE OF CONSIDERABLE AGE WAS FOUND ABOUT .15 FOOT NORTH OF SAME. THIS WAS TAKEN AS THE CORNER AND REPLACED WITH A 1921 STANDARD MONUMENT#. REFERENCES"
GAUGE OF WEST RAIL MANUFACTURER'S RAILROAD, EAST 22.8 FEET.
MAPLE N 62° 45' E, 59.60'
OAK N 76° 40' W, 75.80'
#1921 STANDARD MONUMENT WAS A ROUND CONCRETE POST 48" IN LENGTH, 12" AT THE BOTTOM AND 9" AT THE TOP, WITH A 1/2" GAS PIPE AND A BRASS PLUG.
5. CORNER REFERENCED IN LCRC, DATED 07/15/71, BY CLYDE K. STEPHENS, RLS#3829, AND RECORDED IN LIBER 1, PAGE 131. PART B STATES: "A 3/4 INCH IRON PIPE IN A MONUMENT BOX WAS FOUND IN THE CENTERLINE OF THE 1/4 LINE ROAD (MICHIGAN AVENUE)
PART C STATES: THE IRON IN THE MONUMENT BOX AT THE E 1/4 CORNER OF SECTION 18 WAS WITNESSED WITH THE FOLLOWING: SURVEY TAG IN THREE UTILITY POLES, N 02° 20' E, 25.75 FT.
N 66° 58' E, 53.65 FT.
S 62° 37' E, 59.0 FT.
6. CORNER REFERENCED IN LCRC, DATED 02/09/82, BY JAMES E. STEPHENS, RLS#16053, AND RECORDED IN LIBER 6, PAGE 216. PART B STATES: "A 3/4 INCH IRON PIPE IN A MONUMENT BOX WAS FOUND IN THE CENTERLINE OF MICHIGAN AVENUE, AS RECORDED IN LIBER 1 OF LAND CORNERS, PAGE 131."
PART C STATES: "3/4 INCH IRON PIPE WITNESSED BY:
NAIL AND TAG IN UTILITY POLE, N 02° 20' E, 25.75 FT.
NAIL AND TAG IN UTILITY POLE, S 62° 37' E, 59.0 FT.
NAIL AND TAG IN UTILITY POLE, NW, 73.74 FT.
WEST EDGE OF MOST WESTERLY RAILROAD EAST 22.40'
7. NO OTHER REFERENCES FOUND.



2002-054419
Page: 2 of 2
09/04/2002 08:36A

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

INGHAM

(County)

Located In:

Corner Code #

LANSING TOWNSHIP.

1. Public Land Survey

T 4N R 2W

C-7

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No.

Recorded Plat

5. Private Claims



2002-054420

Page: 1 of 2

09/04/2002 08:36A

Register of Deeds Stamp & File Number

I, DAVID R. LOHR, P.S., in a field survey on APRIL 29, 2002, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
1. CORNER SET BY MUSGROVE EVANS, U.S. DEPUTY SURVEYOR IN MARCH OF 1827. "SET POST COR. TO SECS. 17, 18, 19 & 20, fw a"

WITNESSED BY: BEECH 12", S 80° E, 4 LKS. (2.64')

ELM 13", S 55° W, 35 LKS. (23.10')

GLO NOTES SHOW DISTANCES NORTH AND SOUTH OF 40 CH. (2640')

2. CORNER REFERENCED IN SURVEY, BY W.A ROWE, COUNTY SURVEYOR, DATED NOV. 3, 1899, AND RECORDED IN BOOK 1, PAGE 2, COUNTY SURVEYOR RECORDS. "STONE SET BY PRESTON IN CENTER OF E. & W. ROAD 6 FT. WEST FROM LINE OF FENCE RUNNING NORTH AND 2 FT. EAST OF FENCE RUNNING SOUTH." NO WITNESSES GIVEN. SURVEY SHOWS A DISTANCE WEST TO B-7 OF 40.16 CH. (2650.66')

3. CORNER REFERENCED IN SURVEY OF LANSING TOWNSHIP IN 1909 BY R.J.ROBB, IN BOOK 5, PAGE 218, AS "CEMENT POST", 2.5 FT. LONG, 3" SQUARE AT TOP AND 4" SQUARE AT BOTTOM, WITNESSED BY: GUAGE OF W. RAIL OF MANY. R.R. EAST, 20.8', GUAGE OF S. RAIL OF M. U., NORTH. 208', S.W. COR. CROSSING SQUARE N-E, 30.5'. NO DISTANCES SHOWN ON SURVEY.

CONTINUED ON BACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
SEARCHED AT APPARENT LOCATION OF CORNER AND FOUND BOATSPIKE IN MONUMENT BOX AS PER LCRC OF LIBER 3, PAGE 27, (ITEM A-9). CORNER FALLS ON CENTERLINE OF ST. JOSEPH HIGHWAY ON WEST ROW OF RAILROAD TRACK, 22.5' EAST OF THE C/L OF CLARE STREET. EXCAVATED INTERIOR OF MON. BOX TO FIND BRICK PAVERS AT DEPTH OF 20" WITH SMALL HOLE UNDER BOATSPIKE. COULD NOT REMOVE BRICK PAVERS BUT HIT CONCRETE AT DEPTH OF 24". ACCEPTED LOCATION OF FOUND BOATSPIKE AS CORNER AND SET STANDARD REMON. BAR & PA 345 CAP #30090 IN POSITION OF FOUND BOATSPIKE. NO TRAVERSING PERFORMED.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
C-7, T4N, R2W, LANSING TOWNSHIP, INGHAM COUNTY. FOUND BOATSPIKE IN MONUMENT BOX. SET STANDARD REMON. BAR & PA 345 CAP #30090. WITNESSED BY:
FD. N&T #16053, N/S P. POLE, S 03° E, 26.90'
SET N & KEBS TAG, N/S P. POLE, S 70° E, 84.78'
SET N & KEBS TAG, S/S P. POLE, N 69° E, 76.60'
SET N & KEBS TAG, W/S P. POLE, N 12° E, 73.63'
FD N&T #30897, S/S P. POLE, N 70° E, 66.78'
C/L RAILROAD GUAGE, (C/L TRACKS) EAST, 24.68'

BEARINGS GIVEN ARE MAGNETIC.

Signed by David R. Lohr

Date MAY 7, 2002

Surveyor's Michigan License No. 30090



C-7: T4N, R2W, LANSING TOWNSHIP, PART A CONTINUED:

4. CORNER REFERENCED ON PAGE 45 OF "HORN'S NOTES" AS THE FOLLOWING: "RECOVERED THE CEMENT POST (SET BY ROY ROBB IN 1909) LEANING TO THE SOUTH EVIDENTLY TO PLACE THE TOP OVER THE TOP OF A LARGE FIELD STONE WHICH MAY HAVE BEEN THE ORIGINAL CORNER. SET A 1921 STANDARD MONUMENT# WITH FLUSH TOP HOLE. REFERENCES"
GAUGE WEST RAIL MANUFACTURER'S RAILROAD, EAST, 22.8'
GAUGE SOUTH RAIL MANUFACTURER'S RAILROAD, NORTH, 20.8'
SOUTH WEST CORNER CROSSING DIAMOND, N. E., 30.5'
#STANDARD 1921 MONUMENT CONSISTED OF A ROUND CONCRETE MONUMENT 48" IN LENGTH, 12" AT THE BOTTOM AND 9" AT THE TOP, WITH A 1/2" GAS PIPE AND A BRASS PLUG.
5. CORNER REFERENCED IN UNRECORDED SURVEY NUMBER L-812-A BY CLYDE W. STEPHENS, CIVIL ENGINEER #3025, DATED 12/18/46, AS THE "WEST 1/4 POST OF SEC. 17, T4N, R2W, LANSING TWP." NO MENTION OF MONUMENT OR WITNESSES GIVEN.
6. CORNER REFERENCED ON WOLVERINE ENGINEERING COPY OF INGHAM COUNTY ROAD COMMISSION GRID MAP, NOT DATED, AS "MON. BOX" WITNESSED BY: TOP SWITCH FOR R.R., 32.5', SSE
STEEL COR. POST, 53.0, SE
COR. CONC. LAMP POST BASE, 59.0, ESE
SW COR. CATCH BASIN, 51.2, ENE
7. CORNER REFERENCED ON PAGE 83 OF MDOT PLAN BOOK FOR INGHAM COUNTY. NO MENTION OF MONUMENT OR WITNESSES GIVEN. PLAN SHOWS A DISTANCE WEST TO B-7 OF 2645.86' "COR. TO COR."
8. CORNER REFERENCED IN LCRC, DATED 12/17/73, BY JAMES E. STEPHENS, RLS#16053, AND RECORDED IN LIBER 3, PAGE 27. PART B STATES: "A BOAT SPIKE IN A MONUMENT BOX WAS FOUND IN THE CENTERLINE OF THE SECTION LINE ROAD (ST. JOE)
PART C STATES: THE BOAT SPIKE FOUND AT THE NE CORNER WAS LEFT IN POSITION WITH THE FOLLOWING WITNESSES:
SURVEY TAG IN THE NORTH SIDE OF A UTILITY POLE, S 07° 10' E, 26.84 FEET
SURVEY TAG IN THE WEST SIDE OF A UTILITY POLE, S 04° 30' E, 36.17 FEET
SURVEY TAG IN THE EAST SIDE OF A UTILITY POLE, N 68° 43' W, 65.96 FEET
9. CORNER REFERENCED IN SURVEYS, DATED 12/18/73, BY JAMES E. STEPHENS, RLS#16053, AND RECORDED IN LIBER 1, PAGES 1123 & 1124. SAME WITNESSES AS ITEM A-6 ABOVE.
10. CORNER REFERENCED IN SURVEY, DATED 5/07/87, BY MARK W. WITALEC, LLS #30897, AND RECORDED IN LIBER 5, PAGE 186. "FOUND BOAT SPIKE IN S.W. SIDE OF MONUMENT BOX." WITNESSED BY"
S.S.E., 26.80', SUR. TAG #16053, N. SIDE UTIL. POLE
N.N.E., 36.17', SUR. TAG #16053, W. SIDE UTIL. POLE
N.W., 66.68', PK & CAP #30897, S.W. SIDE UTIL. POLE
EAST, 24.73' TO C/L R.R. GUAGE
11. CORNER REFERENCED IN LCRC, DATED 4/17/87, BY MARK W. WITALEC, LLS #30897, AND RECORDED IN LIBER 6, PAGE 332. SAME WITNESSES AS ITEM A-11 ABOVE.
12. CORNER REFERENCED IN SURVEY, DATED 11/04/92, BY PETER D. BEAVER, RLS #25828, AND RECORDED IN LIBER 6, PAGE 1074. "NE COR. SEC. 19, BOAT SPIKE IN MON. BOX."
WITNESSED BY: SSE, 26.80', N/T IN N. SIDE UTIL. POLE
NNE, 36.17', N/T IN W. SIDE UTIL. POLE
NW, 66.68', PK/CAP S.W. SIDE UTIL. POLE
EAST, 24.73', C/L OF R.R. GUAGE
13. NO OTHER REFERENCES FOUND.



2002-054420

Page: 2 of 2

09/04/2002 08:36A