



T. 4 N R. 1 W Meridian Twp. 33151A SEC. NO. 36

DESCRIPTION Found 6" pointed rock
6 inches above ground. W $\frac{1}{4}$ corner Sec.
36, T4N, R1W, Meridian Twp., Ingham Co.



WITNESSES
N 15 E 30.22' 30" Twin Poplar
S 28 E 29.07' 24" Triple Oak
S 32 W 32.14' 22" Poplar



Philip Wetoskey RLS 1-12 April, 1967

MICHIGAN STATE HIGHWAY DEPARTMENT

SURVEY CHIEF

DATE


CO. INGHAM

TWP. LOCKE

RECORDED

T. 4 N R. 2 E SEC. NO. 33

RECORDED: 3-76 (Date) 3 (Libre) 548 (Page)



S $\frac{1}{4}$ Corner Section 33, common to 4
2" Pipe over Stone

WITNESSES

18" Maple S 30° E 4.08'
10" Maple S 40° W 50.68'
40" Maple North 2.80'
28" Maple N 65° W 31.46'
Boatspike in $\frac{1}{4}$ M-52 (Sta 141+39.56)
West 110.86'





Harold J. Schumaker
SURVEY CHIEF

12-12-75
DATE

GOV'T. MONUMENT WITNESSES RECORD

280 (10/74)

Previous editions may be used until 12/72.



CO. INGHAM TWP. LOCKE
T. 4 N R. 2 E SEC. NO. 33

RECORDED: 3-10-76 (Date) 3 (Libre) 543 (Page)

DESCRIPTION

SW Corner Section 33
T-Iron in $\frac{1}{4}$ Dietz Rd.

WITNESSES

40" Maple (PK S side) S 20° W 56.21'
38" Maple (PK N side) S 85° W 27.14'
23" Maple (PK S side) N 45° E 46.69'
Fe. Line West



Harold J. Schumaker
SURVEY CHIEF

REG. NO.

12-12-75
DATE E-13




1318.47



N

K-12

T4N, R2E
Locke Twp.
Ingham Co.




2556.63

95°32'23"

2.54.2

110.83

POT 141+39.23




T3N, R2E
Leroy Twp.

T3N, R2E
Leroy Twp.

T4N, R2E
Locke Twp.
Ingham Co.

95°32'23"

POT 141+39.23




110.83

2.54.2

2556.63

X

SOURCE: Form 280 Gov. Mon. Witness Record
TRANSCRIBED from ~~ORIGINAL~~ DUPLICATE on file at Remon. Office

280 (10/74) GOV'T. MONUMENT WITNESSES REC'D Previous editions may be used until 12/72.	T. <u>4 N</u> R. <u>2 E</u> SEC. NO. <u>33</u>	RECORDED: <u>3-10-76</u> <u>3</u> <u>543</u> (Date) (Libre) (Page)
		DESCRIPTION SW Corner Section 33 T-Iron in $\angle$ Dietz Rd.
WITNESSES 40" Maple (PK S side) S 20° W 56.21' 38" Maple (PK N side) S 85° W 27.14' 23" Maple (PK S side) N 45° E 46.69' Fe. Line West		
	<u>Harold J. Schumaker</u> SURVEY CHIEF	<u>12-12-75</u> DATE

LOCKE E-13
LEROY E-1
" F-1

L.P. NW 35.42
NE cor lot SW 176.2'

sign post SW 30.21
sign post

19

20

21

22

23

Stone
20" Elm N. 29.7'
18" Elm S.E. 54.3'
20" Apple SW 51.7'

Mon. Box
16" Elm NE. 45.3'
26" Maple SW 99.0'
26" Maple N. 82.5'

1" Pipe
T.P. NW. 46.4'
P.P. WNW. 66.82'
12" Oak S.S.E. 53.27'

Stone brick pile, poor shaft
(19.72)(11C-10)
28" Oak N57°00'E 48.33'
30" Oak S23°35'E 72.69'
8" Oak S62°20'W 53.45'
20" Hickory N59°15'W 68.65'
22" Hickory N28°30'W 72.57'

30

29

28

27

26

Stone
6" Elm NE. 76.5'
Anch. post S. 28.3'
tri. Elm N. 55.5'

Stone, brick
Anch. post SW 36.0'
Road sign NE 39.8'
8" Oak NW 80.0'
8" Elm S.S.E. 123.2'
Anch. post S.E. 45.5'
14" Maple NE. 157.2'

1-1/2" hon. brick
5" Elm S. 21'-2"
5" Pigout E.S.E. 88'-10"
15" Elm W.S.W. 79'-9"
16" Elm WNW. 96'-1"

Stone
P.P. E. 43.5'
Anch. post W. 30.83'
T.P. S.S.E. 45.53'

Stone
6" Hickory N. 28.0'
12" Maple S.E. 44.5'

Stone
10" Maple S.E. 30.6'
10" Oak S. 31.8'

31

32

33

34

35