

Red Mon. Box 1/2" X 7/8" Hdwl cor. S. 24 5' E 32.15' 1/2" X 7/8" E. Abut. Bridge 1' E 12.45' 5450 W 66.77'	20	21 R.R. Spike 20" Elm N.N.E. 114.42' 19" Cherry E.S.E. 47.3' 22" Cherry E.N.E. 58.98' N.E. cor. hdwl. SW. 91.1'	
1" Iron 26" Maple E. 18.57' 8" Elm S.W. 33.9' 21" Maple N.N.W. 65.73'	D-9 14" fence post in conc.	E-9 1-1/4" Iron, brick 12" Elm S.S.W. 77.35' 16" Elm N.W. 53.61' 33'± from transmission line	
29	D-10 Stone, boat spike 28" Elm S.W. 54.82' 7" Elm S.E. 69.9' 26" Cherry N.E. 35.48' 5" Elm N. 27.98'	E-10 Boat spike 38" Maple W.N.W. 66.8' 11" Cherry S.W. 43.06' P.P. W.N.W. 42.94' P.P. N.N.E. 44.8'	28
32	D-11 3/4" Iron (1969) Guy Pole E.S.E. 37.43' 22" Walnut S.S.W. 81.00' P.P. W.N.W. 75.50'	E-11 Mon. Box (1969) SW. bridge cor. W.S.W. 41.18' End bridge W. 38.80' NW. bridge cor. W.N.W. 41.19'	33 3/4" Iron, brick (MSHD. 855) 29" Elm N.W. 98.02' 27" Oak S.S.E. 41.72' 26" Ash E.S.E. 87.30' Stone, brick 12" Maple S.E. 12" Apple S.W. 6" Elm N.W.
32	D-12	E-12	33
Boat spike 19" Elm S.S.W. 42.83' P.P. N.N.E. 75.87'	D-13 2" Iron 42" Maple S.W. 35.59' 44" Maple S.E. 41.4' P.P. N.W. 46.92' NW. cor. house fond. SW. 76.7'	E-13 1" Pipe 14" Elm N.N.W. 95.27' 13" Elm S. 101.96' End post SW. 42.98'	R.R. Iron

(T.I.N. R.I.W. Leslie Twp., Ingham)

Rd Comm. - Vevay

REVISED - JANUARY
 1972

TRANSCRIBED from ORIGINAL on file at REMONUMENTATION OFFICE
DUPLICATEtownship survey
Section 29

- 1 - See Sec. 20 E-9 UNRECORDED
4 - See Sec. 33 E-11 RECORDED
- D-11 [C - MSHD tag - 38" maple N46°W45.45' D-11 UNRECORDED
" " - 20" elm N19°E52.06'
" " - 9" Walnut S57°E48.25'
- (New) 1/4 x 3/4 x 10" iron pin E-11 RECORDED
MSHD tag - 18" box elder S65°E98.74'
" " - 26" Oak N40°E104.70'
" " - 20" Locust S20°E52.41'
" " - 18" maple S46°W44.55'
- U - Stone & boat Spike
MSHD tag - 20" elm S39°W54.82' D-10 RECORDED
" " - 7" elm S55°E69.96'
" " - 26" W. Cherry N41°E25.48
" " - 5" elm N00°E27.98'
- D - boat Spike E-10 RECORDED
MSHD tag - 11" W. Cherry S41°W82.06'
" " - 30" maple N79°W66.80'
" " - power pole N60°W42.74'
" " - power pole N92°E44.80'
- (New) 1/4" iron bar & boat Spike E-9 UNRECORDED
MSHD tag - 12" elm S20°W77.36'
" " - 16" elm N38°W53.61'
33' ± from transmission prop line
- 2 - 1" iron rod
MSHD tag - 26" maple N88°E18.57' C-9 UNRECORDED
" " - 8" elm S44°W88.70'
" " - 21" maple N31°W45.78'

TRANSCRIBED from ORIGINAL on file at REMONUMENTATION OFFICE
DUPLICATETownship Vevay
Section 33

1 - See Sec. 27 G-11 RECORDED

A - See Sec. 28 F-11 RECORDED

D - R.R. iron G-12 RECORDED

2 - 0 3/4 x 1/4 x 10" iron in pin

6" Box Elder N67W 97.74 E-11 RECORDED

5" box elder N 62° E 79.14

18" Locust S 28° E 52.60

3 - Boat spike E-13 UNRECORDED

Apple 16" S66E 53.27

Apple 14" N30E 48.80

Apple 12" N17W 45.74

2 - 1/4 x 5/8 x 10" iron pin E-11 RECORDED

MSHO tag-18" box elder S62°E 78.94

" " -26" Oak N40°E 41.70'

" " -20" Locust S20°E 52.61'

" " -18" Maple S40°W 44.55'

A - Boat spike

MSHO tag-27" elm N57°W 70.02' F-11 RECORDED

" " -27" Oak S81°E 41.72'

" " -26" Ash S75°E 47.90'

E-13


FORM 280

TRANSCRIBED from ORIGINAL on file at REMONUMENTATION OFFICE
DUPLICATE

GOV'T. MONUMENT WITNESSES RECORD

Form 280
(Rev. 3/60)

T. 2 N. R. 1 W. VEVAY TWP. N. 1/4 COR. SEC. NO. 32



Ingham Co.
DESCRIPTION
BOAT SPIKE (Found)
4 Barnes Rd.

D-11


WITNESSES

31' M. N. 50' M. - 45.42'

22" WAL. S. 45 W. - 50.95'

13" WAL. S. 55 E. - 48.18'

65



MICHIGAN STATE HIGHWAY DEPARTMENT

Frank Holmes
SURVEY CHIEF

Feb. 63


DATE D-11

SE 1/4 21

REMONUMENTATION OFFICE

32 & 29 1/4 COR.
S. 50 W. 45.42'-31" Maple
S. 65 E. 48.18'-13" Walnut
S. 45 W. 50.96'-22" Walnut

D-11



NW-SW
Sec. 33

SW-NW
Sec. 33

NW-NW
Sec. 33

FILE
33-R-3


P. 14

ROUTE	COUNTY	PROJECT	SHEET NO.
US127	Ingham	SE-SW Sec 28	64-33
		SE-SW Sec 28	64-33

Proj. 33-79
C.S. 33031


Proj. 33-79

Amel	Grantor	Inst	Date Recorded	Libr-Page
23	John M. Mitchell	D	5-15-56	720-249 LR
23	"	"	"	"
24	Albert R. Humphrey	"	9-27-56	720-269 "
24	Charles R. Smalley	"	2-8-57	720-101 "
25	Leonard H. Fellows	"	9-27-56	720-105 "
26	Lester L. Johnson	GC	"	720-30 "
26	Leonard H. Fellows	D	"	720-101 "
26	Lester L. Johnson	GC	"	720-34 "



BEVAY TWP.
T.2N.-R.1W.

DATE	BY	REVISED	REVISION
22	Charles R. Landon	11-28-56	250 - 350 - 4-2



Curve Data
 A = 3° 45' R
 D = 0° 15'
 R = 22918.33'
 T = 750.27'
 L = 1500.00'
 P.I. = Sta. 880 + 84.42

NW-NW
 Sec. 4

SW-SW
 Sec. 33

33-R-3

P. 13