

11-09-04

D. Lohr - R. Kelsel

L-2: 1/2 bar cap (smashed)

1m circle of stones. Ed witness trees (3) but no tags. No evidence of anchor post remains. Ed small wedged shaped stone along SW/S of rebar. Accepted rebar & set standard Remon B&C 30090

Witnesses to L-2:

1 Ed Scan, set NAT 30090 E/S 20" oak

N 08 E 10.00'

2 set NAT 30090 NW/S 24" oak

N 27 E 13.11'

3 set NAT 30090 S/S 9" Hick


S 80 E 3.15'

4 set NAT 30090 SW/S 12" Elm

N 40 W 17.60'

5 set NAT 30090 S/S 6" Elm

S 65 W 6.98'



AV-2-26

11-09-04 O. Lohr - R. Helse

L-5: F&Y^{1/2} rebar in Mon. Box
2' Ab. of d. Columbia & on
Tree & Brush now to South.

1	F&Y	N&T	30090	SE/S	Guy Pole
			AD 26		24.08
2	F&Y	N&T	16053	NE/S	AD Hick,
			S 55		70.60
			E		
3	F&Y	N&T	30090	NE/S	UH Pole
			S 44		46.70
			E		
4	F&Y	N&T	30090	N/S	UH Pole
			S 82		129.45'
			W		

L-3

CND

d Columbia


⑤ ⑤ ⑤

AD-2-a7

11-09-04 D. Lohr-R. H. H. H.

M-2: FD 1" x 3/8" Solid Steel
 Frost Pn in Mon. Box and
 College Rd & excavation like West
 Remnant 1" Pn & excavated to
 48" - Found nothing. Accepted
 1" Pn & set standard Remnant
 Box & Cap # 30090

1	FD NE Corner	Hsc #261	91.20
2	FD SE Corner	Hsc #261	74.60
3	Set NGT 30090	S/S TW. 12" E/M	51.45
4	FD Box Cap in Mon. Box R-2	S 05 W	52.42
5	Set NGT 30090	W/S P Pole	197.80



A0-2-28

Nov. 15, 2004

D. Lohr-K. Nelsel

M-3: FD 1/2" B&C in Mon Box
to College Rd & Columbia Rd West

- 1 Set NAT 30090 S/S Guy Pole
N 85 E 193.10
- 2 FD 1/2" B&C in Mon Box A-3
S 03 W 66.00
- 3 FD NAT 16053 w/15 Util. Pole
S 30 W 100.36
- 4 Set B&C 30090 at B/Curb
N 65 W 26.54
- 5 FD K&S E/S F. Pole
N 03 W 225.79'

