






LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in

Eaton

Located In

Corner Code 11

89 MAY 12 AM 11:28

- | | | | | | | |
|-----------------------------------|---|---|----|---|----|-----|
| 1 Public Land Survey | | T | 2N | R | 3W | M-2 |
| | | T | | R | | |
| | | T | | R | | |
| | | T | | R | | |
| 2 Property Controlling in Section | S | T | | R | | |
| | S | T | | R | | |
| 3 Miscellaneous Property in Sec. | S | T | | R | | |
| | S | T | | R | | |

Register of Deeds Stamp & File Number

- 4 Lot No
 5 Private Claims

Recorded Plat

Larry A. Bryan as a field surveyor, **February 2**, 1989

as a field surveyor, I have surveyed the above described land in accordance with the requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules, therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management, or by a decree of a Court of Law, and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors, or by a decree of a Court of Law, established, re-established, monumented, re-monumented, re-surveyed, found, or corrected below.


NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A Description of original monument and accessories and/or subsequent restoration

M-2 Original monument and accessories destroyed.

B Description of corner evidence found and/or method applied in restoring or re-establishing corner

M-2 Found 3/4" bar in monument box 3' East of centerline of Waverly Road on fence line West. As called for on Liber 2 of surveys Page 242.



C Description of monument for corner and accessories established to perpetuate locating the position of the corner

**M-2 East 1/4 corner Section 1, T2N, R3W
 Found 3/4" bar in monument box
 Set nail & tag Northeast side 12" cherry, N75°W, 30.25'
 Set nail & tag North side 12" Walnut, S75°E, 99.13'
 Set nail & tag West side 46" Sycamore, S10°E, 198.60'**

Signed by

Surveyor's Michigan License No.

Larry A. Bryan
 25832

Date

2-21-89

Eaton Rapids

Corr. Aurelius

1/2" Iron
28" Elm SSE. 44.2'
22" Cherry S.E. 31.4'
30" Oak NNW. 87.3'
32" W. Elm NW. 30.9'

Stone & Brick
30" Elm SW. 79.0'
24" Elm S.W. 34.5'
6" Maple NE. 34.0'

Stone & Tile
18" Maple N.W. 44.6'
15" Maple S.W. 39.4'
18" Elm NE. 50.0'

Stone & Brick
15" Elm NW. 41.8'
Anch. post SW. 40.5'
Anch. post NE. 57.4'

Flow post
Anch. post E. 27.5'
12" Walnut NW. 42.3'
12" Maple S.W. 51.2'

Wood Stake
14" Apple S.E. 53.3'
12" Maple S.W. 58.2'
Anch. post N. 34.6'

Stone
10" Maple N.W. 95.5'
10" Cherry N. 33.3'

Stone
30" Elm NE. 46.7'
16" Maple N.W. 45.3'
14" Maple S.W. 66.2'

Stone & Brick
14" Oak NNW. 58.2'
Anch. post S. 25.5'
Anch. post N. 28.2'

Stone & Brick
8" Maple WNW. 76.0'
14" Maple E.N.E. 99.7'
Anch. post NE. 37.0'

16" Tree S.E. 31.7'

3/4" Iron (ICRC 1965)
18" Elm NE. 48.37'

AURELIUS
ROAD COMMISSION WITNESS MAP

16" Tree SE 31.7'
3/4" Iron (I.C.R.C. 1965)

AURELIUS
ROAD COMMISSION LITTLE 5

9	8	7	
Stone & Brick 30" Elm SW 79.0 24" Elm SW 34.5 6" Maple NE 34.0	Stone & Tile 18" Maple NW 44.6 15" Maple SW 39.4 18" Elm NE 50.0	Wood Stake 14" Apple SE 53.3 12" Maple SW 58.2 Anch post N. 34.6	
4	5	6	
Stone & Brick 30" Elm SW 79.0 24" Elm SW 34.5 6" Maple NE 34.0	Stone & Tile 18" Maple NW 44.6 15" Maple SW 39.4 18" Elm NE 50.0	Wood Stake 14" Apple SE 53.3 12" Maple SW 58.2 Anch post N. 34.6	1/2" Iron 28" Elm SSE 44.2 22" Cherry SE 31.4 30" Oak NW 87.3 32" Elm NW 30.9