

INGHAM COUNTY-BUNKERHILL TWP.
LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIEBER 5 PC 316

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. <u>1</u> N. <u>1</u> E. <u>1</u> S. R. <u>1</u> W.	G-11
2. PROPERTY CONTROLL- ING IN SECTION	T. <u> </u> N. <u> </u> E. <u> </u> S. R. <u> </u> W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. <u> </u> N. <u> </u> E. <u> </u> S. R. <u> </u> W.	
4. LOT NO. <u> </u> , RECORDED PLAT <u> </u>		
5. PRIVATE CLAIMS <u> </u>		

FILED

SEP 19 2 52 PM '79

REGISTER OF DEEDS

Paula Johnson

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 9, 19 79, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on , 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

G-11

Post set in original government survey by J. Wampler, between Jan. 30 and Feb. 8, 1826. Corner referred to in a survey by A. Jackson, Co. Surveyor, May 10, 1854 (v.2,p.201). Corner referred to in a survey by T.J. Brown, Co. Surveyor, Jan. 20, 1860 (v.2,p.363). Corner re-established as a stone, brick and crockery in a survey by E.A. Calkins, Co. Surveyor, April 28, 29 & 30, 1902 (v.5, p.26).
Corner identified as stone, brick and crockery by Wm. Berryman, Co. Surveyor, date unknown and in the records of the Ingham Co. Road Comm. revised grid map, 1972.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-11

Excavated a hole 10' x 10' to an average depth of 2.0' centered on west edge of Williamston Road and on tree line to the west. Found 3/4" iron bar at ground surface + 15.95' west of the centerline of Williamston Road and on tree line to the west. Found pointed stone surrounded by red brick and pottery, 1.8' below road surface + 14.67' west of the centerline of Williamston Road and on tree line to the west. Accepted pointed stone with brick and pottery for corner as called for by E.A. Calkins, County Surveyor. Measured south + 2638' to G-12 in close accord with G.L.O. distance. Excavation conducted by Ingham County Survey and Remonumentation Project crew.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-11

NW Corner, Section 34, T1N-R1E
Set 4" x 36" concrete monument with 1/2" x 38" rerod and cap #18998 with concrete collar and cover in location of pointed stone described above:
Nail & tag, #18998, east side 30" Beech, NW, 38.33'
Nail & tag, #18998, east side 15" Twin Beech, North, 92.34'
Nail & tag, #18998, east side 15" Walnut, North, 162.68'
Nail & tag, #18998, southeast side 36" Oak, NE, 117.84'

SIGNED BY Ronnie M. Lester

DATE Sept 17, 1979


SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

~~XX~~



CHIEF OF SURVEY PARTY
APPROVED AND SIGNED BY *Sam D. Smith*
MICHIGAN REGISTERED LAND SURVEYOR
Director, Ingham County Survey and
Remonumentation Project

DATE 9.17.79



SURVEYOR'S MICHIGAN REGISTRATION NO. 17624

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

INGHAM COUNTY-BUNKERHILL TWP.
LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LSEB 5 PG 327

FOR CORNERS OF --:	LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>1</u> N. <u>1</u> E. <u>1</u> S. R. W.	<u>G-12</u>
2. PROPERTY CONTROLL- ING IN SECTION _____	T. _____ N. _____ E. _____ S. R. W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ E. _____ S. R. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

FILED

OCT 9 1 09 PM '79

REGISTER OF DEEDS

Paula Johnson
 INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
 FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 10, 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

G-12

Post set in original government survey by J. Wampler between Jan. 30 and Feb. 8, 1826. Corner referred to in a survey by T.J. Brown, Co. Surveyor, Jan. 20, 1860 (v.2, p.363). Corner re-established as a 1" gas pipe surrounded by stones in a survey by R.J. Robb, County Surveyor, April 5, 1910 (v.5, p.59). Corner identified as a pipe in the records of Wm. Berryman, County Surveyor, date unknown and in the Ingham County Road Commission revised grid map, 1972.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-12

Excavated a hole 6' x 8' to an average depth of 3.0' mostly east of the centerline of Williamston Road and + 7.5' south of fence line to the west. Found 1" x 2.5' gas pipe surrounded by stones 2.3' below road surface + 2.5' east of the centerline of Williamston Road and + 7.5' south of fence line to the west. Accepted gas pipe for corner as called for by R.J. Robb, County Surveyor. Measured north + 2639' to G-11, measurement in close accord to G.L.O. distance. Excavation conducted by Ingham County Survey and Remonumentation Project crew.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-12

W $\frac{1}{2}$ Corner, Section 34, T1N-R1E

Set 4" x 36" concrete monument with $\frac{3}{8}$ " x 38" rerod and cap #18998 with concrete collar and cover in location of gas pipe described above:

Nail & tag, #18998, northwest side 36" Oak, SW, 48.77'

Nail & tag, #18998, south side power pole, WNW, 53.49'

Nail & tag, #18998, south side 24" Oak, NW, 36.52'

Nail & tag, #18998, east side 20" Maple, NW, 79.22'

SIGNED BY Ronnie M. Lester DATE Oct 3, 1979

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998


XX

SIGNED BY GARY D. LESTER
 APPROVED AND SIGNED BY _____
 SURVEYOR
 No. 17624

CHIEF OF SURVEY PARTY
Gary D. Lester
 MICHIGAN REGISTERED LAND SURVEYOR
 Director, Ingham County Survey and
 Remonumentation Project

DATE 10-3-79

SURVEYOR'S MICHIGAN REGISTRATION NO. 17624



1708

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
 REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

INGHAM COUNTY-BUNKERHILL TWP.
LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. <u>1</u> N. <u>X</u> R. <u>1</u> E. <u>X</u>	<u>G-12</u>
2. PROPERTY CONTROLLING IN SECTION	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	
3. MISCELLANEOUS PROPERTY IN SECTION	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

L.5 p.327

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 10, 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

G-12

Post set in original government survey by J. Wampler between Jan. 30 and Feb. 8, 1826. Corner referred to in a survey by T.J. Brown, Co. Surveyor, Jan. 20, 1860 (v.2, p.363). Corner re-established as a 1" gas pipe surrounded by stones in a survey by R.J. Robb, County Surveyor, April 5, 1910 (v.5, p.59). Corner identified as a pipe in the records of Wm. Berryman, County Surveyor, date unknown and in the Ingham County Road Commission revised grid map, 1972.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-12

Excavated a hole 6' x 8' to an average depth of 3.0' mostly east of the centerline of Williamston Road and + 7.5' south of fence line to the west. Found 1" x 2.5' gas pipe surrounded by stones 2.3' below road surface + 2.5' east of the centerline of Williamston Road and + 7.5' south of fence line to the west. Accepted gas pipe for corner as called for by R.J. Robb, County Surveyor. Measured north + 2639' to G-11, measurement in close accord to G.L.O. distance. Excavation conducted by Ingham County Survey and Remonumentation Project crew.


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-12

W $\frac{1}{2}$ Corner, Section 34, T1N-R1E
Set 4" x 36" concrete monument with $\frac{1}{2}$ " x 38" rerod and cap #18998 with concrete collar and cover in location of gas pipe described above:
Nail & tag, #18998, northwest side 36" Oak, SW, 48.77'
Nail & tag, #18998, south side power pole, WNW, 53.49'
Nail & tag, #18998, south side 24" Oak, NW, 36.52'
Nail & tag, #18998, east side 20" Maple, NW, 79.22'


SIGNED BY Ronnie M. Lester DATE Oct 3, 1979

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998



CHIEF OF SURVEY PART
DATE _____
MICHIGAN REGISTERED LAND SURVEYOR
Director, Ingham County Survey and
Remonumentation Project

DATE 10-3-79



SURVEYOR'S MICHIGAN REGISTRATION NO. 17624

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED, MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

INGHAM COUNTY-BUNKERHILL TWP.

LIBER 5 PG 294

FILED

REGISTER OF DEEDS

REGISTER OF DEEDS STAMP AND
FILING NUMBER

A. Description of original monument and accessories and/or subsequent restoration:

Corner referred to in a survey by T.J. Brown, County Surveyor, Jan. 20, 1860 (v.2,p.363)

Corner identified as iron shaft, brick and stone by Wm. Berryman, County Surveyor, date unknown and in the records of the Ingham Co. Road Comm., revised grid map, 1972.

G-13

Excavation conducted by Ingham County Survey and Remonumentation Project crew.

G-13

Nail & tag, #18998, south side Ash clump, NW, 33.92'

SECRET

STATE OF MICHIGAN
JERRY D. LESVER
SUPERVISOR
No. 17624
REGISTERED LAND SURVEYOR
SURVEYORS MICHIGAN

CHIEF OF SURVEY PARTY

DATE _____

DATE 9.6.79

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 26, 1971
REVISED MAY 14, 1975

1675

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

LAND CORNER RECORDATION CERTIFICATE

LIBER 8 PAGE 118 FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY 34 T. 1 N. R. 1 E.	XX	H-11 I-11 H-12
2. PROPERTY CONTROLLING IN SECTION T. N. S. R. E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION T. N. S. R. E. W.		
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

RECORDED

APR 8 10 01 AM '94

REGISTERED
TOWNSHIP, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, RON HELSEI do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram-over) were, in a field survey on APRIL 1993, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey or 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

H-11 G.L.O. BEARING TREES & MONUMENT LOST
I-11 LOST
H-12 NOT SET IN G.L.O. SURVEYS

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

H-11 CO. SURVEYOR SET PIPE & STONE IN 1902 VOL. 5, PG. 26
FD 3" DIA. STEEL POST IN THE EAST SIDE OF A 60" OAK ON FENCE LINE TO THE SOUTH,
POST WAS IN CLOSE ACCORD WITH G.L.O. MEAS EAST & CO. SURVEYOR MEAS., WEST, VOL. 2,
PG. 201
4" MAPLE, N34½W, 1½LKS
8" MAPLE, N43W, 24½LKS
I-11 RECORDED AS A PK BY BOSS, LIBER 1, PG. 403
FD ½" PIPE IN MON BOX & WITNESSED
H-12 NO EVIDENCE OR COUNTY SURVEYS; SET BY INTERSECTION ½ LINES
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

<p>H-11 3" STEEL POST N & T 10" OAK, N60°E, 25.51' N & T 26" ASH, SOUTH, 25.19' N & T 16" WALNUT, S45°E, 33.65' N & T 12" MAPLE, S80°E, 24.23'</p> <p>H-12 SET ½" B & C N & T 6" ELM, S45°W, 4.50' N & T 12" CHERRY, NORTH, 10.00' N & T 16" HICKORY, N45°E, 21.93' N & T 14" HICKORY STUMP, N30°W, 11.77'</p>	<p>I-11 ½" PIPE & MON BOX N & T 20" CEDAR, SSE, 57.18' N & T 30" WALNUT, SSW, 59.58' N & T 30" CHERRY, WNW, 91.58' N & T UTILITY POLE, NNE, 92.75'</p>
--	--

SIGNED BY Ron Helsei DATE 6-3-93

SURVEYOR'S MICHIGAN REGISTRATION NO. 18994


FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR


2604

SURVEYOR'S MICHIGAN REGISTRATION NO. _____




CORNER NUMBERING CODE DIAGRAMS FOR IDENTIFYING LAND CORNER RECORDATIONS AND INDEXING

FOR PROPERTY CORNERS WITHIN THE SECTION.
(MENTIONED OVER AND EXCLUDE LOT CORNER)




1. Above coded numbers are positioned on 1/16 fractional lines of the section.
2. Township corner code numbers shall be applied to corners of above typical section not numbered.
3. Miscellaneous property corners within a section, located at points other than numbered above, shall be referenced to at least two of above corner code numbers.
4. Private claim corners to be tied to rectangular land corners if possible - sketch required below.

T. —, R. — (MENTIONED OVER)
FOR PUBLIC LAND SURVEY CORNERS IN THE



Apply letter prefix for corner points encircled above for identifying corner recordation numbers over.

EXPLANATORY SKETCH IF NECESSARY -- BELOW



H-12

LAND CORNER RECORDATION CERTIFICATE

LIBER 8 PAGE 118 FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY—34— T. 1— N. XX R. 1— E. XX		H-11 I-11 H-12
2. PROPERTY CONTROLL- ING IN SECTION—, T. — N. — R. — E. —		
3. MISCELLANEOUS PROPERTY IN SECTION—, T. — N. — R. — E. —		
4. LOT NO. —, RECORDED PLAT —		
5. PRIVATE CLAIMS —		

RECORDED

APR 8 10 01 AM '94

REGISTERED DEEDS

TACAMAC COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, RON HELSEL do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on APRIL 1993, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

H-11 G.L.O. BEARING TREES & MONUMENT LOST
I-11 LOST
H-12 NOT SET IN G.L.O. SURVEYS

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

H-11 CO. SURVEYOR SET PIPE & STONE IN 1902 VOL. 5, PG. 26
FD 3" DIA. STEEL POST IN THE EAST SIDE OF A 60" OAK ON FENCE LINE TO THE SOUTH,
POST WAS IN CLOSE ACCORD WITH G.L.O. MEAS EAST & CO. SURVEYOR MEAS., WEST, VOL. 2,
PG. 201
4" MAPLE, N34½W, 1½LKS
8" MAPLE, N43W, 24½LKS
I-11 RECORDED AS A PK BY BOSS, LIBER 1, PG. 403
FD ½" PIPE IN MON BOX & WITNESSED
H-12 NO EVIDENCE OR COUNTY SURVEYS; SET BY INTERSECTION ¼ LINES
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-11 3" STEEL POST	I-11 ½" PIPE & MON BOX
N & T 10" OAK, N60°E, 25.51'	N & T 20" CEDAR, SSE, 57.18'
N & T 26" ASH, SOUTH, 25.19'	N & T 30" WALNUT, SSW, 59.58'
N & T 16" WALNUT, S45°E, 33.65'	N & T 30" CHERRY, WNW, 91.58'
N & T 12" MAPLE, S80°E, 24.23'	N & T UTILITY POLE, NNE, 92.75'
H-12 SET ½" B & C	
N & T 6" ELM, S45°W, 4.50'	
N & T 12" CHERRY, NORTH, 10.00'	
N & T 16" HICKORY, N45°E, 21.93'	
N & T 14" HICKORY STUMP, N30°W, 11.77'	


SIGNED BY Ron Helsel DATE 6-3-93SURVEYOR'S MICHIGAN REGISTRATION NO. 18994

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTYAPPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR


2604

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Form No. MLM735
COMPILED, BROS. & CO., KALAMAZOO, MICH.FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 197
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS


CORNER NUMBERING CODE DIAGRAMS FOR IDENTIFYING LAND CORNER RECORDATIONS AND INDEXING

FOR PROPERTY CONTROLLING AND MISC.
 PROPERTY CORNERS WITHIN THE SECTION
 (MENTIONED OVER AND EXCLUDE LOT CORNER)




1. Above coded numbers are positioned on 1/16 fractional lines of the section.
2. Township corner code numbers shall be applied to corners of above typical section not numbered.
3. Miscellaneous property corners within a section, located at points other than numbered above, shall be referenced to at least two of above corner code numbers.
4. Private claim corners to be tied to rectangular land corners if possible - sketch required below.

FOR PUBLIC LAND SURVEY CORNERS IN THE
 T. _____, R. _____ (MENTIONED OVER)



Apply letter prefix for corner points enclosed above
 for identifying corner recordation numbers over.

EXPLANATORY SKETCH IF NECESSARY -- BELOW



LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

H-13

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. <u>1</u> N. <u>1</u> R. <u>1</u> E. <u>1</u>	H-13
2. PROPERTY CONTROLLING IN SECTION	T. <u> </u> N. <u> </u> R. <u> </u> E. <u> </u>	
3. MISCELLANEOUS PROPERTY IN SECTION	T. <u> </u> N. <u> </u> R. <u> </u> E. <u> </u>	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Maynard R. Dyer, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on September 16, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on , 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Post set in original government survey by J. Wampler, January 31, 1826.
Corner referred to in a survey of Hoyt Road (now Baseline Road) by A. Jackson, County Surveyor, June 28, 1839 in Miscellaneous County Surveyor's records.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Excavated a 10' x 10' hole to an average depth of 1.5' on the centerline of Baseline Road on a tree-fence line to the north. No evidence of monumentation found. Excavated a 7.5' x 10' hole to an average depth of 2', north of initial excavation. No evidence of monumentation found, corner considered lost. Corner set midway and on standard township line between G-13 and I-13, \pm 9.5' north of the centerline of Baseline Road on tree-fence line north.
Excavation conducted by Ingham County Survey and Remonumentation Project crew.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

S $\frac{1}{2}$ Corner, Section 34, T1N-R1E
Set 4" x 36" concrete monument with $\frac{1}{2}$ " x 38" rerod and cap with concrete collar and cover in location described above:
Nail & tag, west side 30" Walnut, North, 64.62'
Nail & tag, south side 8" Oak, NE, 47.20'
Nail & tag, north side 34" Oak, ESE, 169.20'
Nail & tag, south side 32" Walnut, NW, 68.44'



SIGNED BY Maynard R. Dyer

DATE 1-21-81

SURVEYOR'S MICHIGAN REGISTRATION NO. 21565

(SEAL)

SIGNED BY

CHIEF OF SURVEY PARTY

DATE


APPROVED AND SIGNED BY

Gary D. Lester
MICHIGAN REGISTERED LAND SURVEYOR

DATE

Director, Ingham County Survey and Remonumentation Project

SURVEYOR'S MICHIGAN REGISTRATION NO. 17624



FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION AND SURVEYING

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LICEN

6 PG 141

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 1 N. R. 1 E.	H-13
2. PROPERTY CONTROLLING IN SECTION	T. N. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

FILED

JAN 29 9 35 AM '81

REGISTER OF DEEDS

Paula Johnson
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Maynard R. Dyer, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on September 16, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on , 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

H-13

Post set in original government survey by J. Wampler, January 31, 1826.
Corner referred to in a survey of Hoyt Road (now Baseline Road) by A. Jackson, County Surveyor, June 28, 1839 in Miscellaneous County Surveyor's records.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

H-13


Excavated a 10' x 10' hole to an average depth of 1.5' on the centerline of Baseline Road on a tree-fence line to the north. No evidence of monumentation found. Excavated a 7.5' x 10' hole to an average depth of 2'; north of initial excavation. No evidence of monumentation found, corner considered lost. Corner set midway and on standard township line between G-13 and I-13, + 9.5' north of the centerline of Baseline Road on tree-fence line north.
Excavation conducted by Ingham County Survey and Remonumentation Project crew.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:


H-13

S $\frac{1}{2}$ Corner, Section 34, T1N-R1E
Set 4" x 36" concrete monument with $\frac{1}{2}$ " x 38" rerod and cap with concrete collar and cover in location described above:
Nail & tag, west side 30" Walnut, North, 64.62'
Nail & tag, south side 8" Oak, NE, 47.20'
Nail & tag, north side 34" Oak, ESE, 169.20'
Nail & tag, south side 32" Walnut, NW, 68.44'

SIGNED BY Maynard R. Dyer DATE 1-21-81
SURVEYOR'S MICHIGAN REGISTRATION NO. 21565 (SEAL)



SIGNED BY DATE
APPROVED AND SIGNED BY Gary D. Lester DATE 1-22-81
DIRECTOR, Ingham County Survey and Remonumentation Project
SURVEYOR'S MICHIGAN REGISTRATION NO. 17624



LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 1 PG 403

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>24</u> T. <u>1</u> N. R. <u>1</u> E.		<u>1-11</u>
2. PROPERTY CONTROLLING IN SECTION T. <u>1</u> N. R. <u>1</u> E.		
3. MISCELLANEOUS PROPERTY IN SECTION T. <u>1</u> N. R. <u>1</u> E.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

FILED

MAR 27 1 57 PM '72

REGISTER OF DEEDS
Mia Bell Humphrey
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, OSCAR BOSS, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on DEC 27, 1971, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:
UNKNOWN

B. Description of corner evidence found and or method applied in restoring or re-establishing corner:

SET: P.K. NAIL
EXISTING OCCUPATION SERVED
AS EVIDENCE IN RE-ESTABLISHING
CORNER

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

P.K. NAIL
N 45° W - 80.5 - S.E. CORNER OF PORCH
N 45° E - 146.12 - S.W. CORNER OF HOUSE
S 20° W - 59.33 - NAIL E. SIDE 20' ELM



SIGNED BY Oscar Boss

DATE March 27, 1972

SURVEYOR'S MICHIGAN REGISTRATION NO. 13574

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE

(SEAL)

202 SURVEYOR'S MICHIGAN REGISTRATION NO.

Form No. MLM735
Copyright © 1969, S. L. O. Association, Mich.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

CORNER NUMBERING CODE DIAGRAMS FOR IDENTIFYING LAND CORNER RECORDATIONS AND INDEXING

FOR PUBLIC LAND SURVEY CORNERS IN THE
T. 1N R. 1E (MENTIONED OVER)

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													


Apply letter prefix for corner points encircled above for identifying corner recordation numbers over.

FOR PROPERTY CONTROLLING AND MISC.
PROPERTY CORNERS WITHIN THE SECTION
(MENTIONED OVER AND EXCLUDE LOT CORNER)

				2	
3		4		5	
		8		9	
10		11		12	
		15		16	

1. Above coded numbers are positioned on 1/16 fractional lines of the section.
2. Township corner code numbers shall be applied to corners of above typical section not numbered.
3. Miscellaneous property corners within a section, located at points other than numbered above, shall be referenced to at least two of above corner code numbers.
4. Private claim corners to be tied to rectangular land corners if possible - sketch required below.

EXPLANATORY SKETCH IF NECESSARY -- BELOW



INGHAM COUNTY-BUNKERHILL TWP.
LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 5 PG 291

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. <u>1</u> N. <u>X</u> R. <u>1</u> E. <u>X</u>		<u>I-12</u>
2. PROPERTY CONTROLLING IN SECTION _____ .T. _____ N. _____ S. _____ R. _____ E. _____ W. _____		
3. MISCELLANEOUS PROPERTY IN SECTION _____ .T. _____ N. _____ S. _____ R. _____ E. _____ W. _____		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

FILED

SEP 11 4 39 PM '79

REGISTER OF DEEDS

Paula Johnson
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 31, 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

I-12

Post set in original government survey by Joseph Wampler dated between Jan. 30 and Feb. 8, 1826.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I-12

Excavated a hole 10' x 10' to an average depth of 1.5' on the centerline of Haynes Road and on fence line to the east and west. Found china and pottery fragments 0.7' below road surface + 2.8' west of the centerline of Haynes Road and + 1.8' north of fence line to the east and west. Accepted china and pottery as accessories to corner as it has been perpetuated. Stone probably occupied corner but can be assumed to have been removed. Measured north + 2635' to I-11 and south + 2647' to I-13. Excavation conducted by Ingham County Survey and Remonumentation Project crew.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-12

E $\frac{1}{2}$ Corner, Section 34, T1N-R1E

Set 4" x 36" concrete monument with $\frac{1}{2}$ " x 38" rerod and cap #18998 with concrete collar and cover in location of china and pottery described above:

Nail & tag, #18998, east side 36" Oak, NNW, 503.80'

Nail & tag, #18998, northwest side 8" Elm, NNE, 41.43'

Nail & tag, #18998, south side 24" Hickory, East, 18.83'


Nail & tag, #18998, east side 24" Walnut, WSW, 28.68'

SIGNED BY Ronnie M. Lester

DATE Sept 6, 1979

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

(SEA)



CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY [Signature]
Director, Ingham County Survey and
Remonumentation Project

DATE 9-6-79

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 17624

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

1673

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--

LOCATED IN--

CORNER CODE-NUMBER

LIBER

4 PG 94

1. PUBLIC LAND SURVEY 35&36. 1 N. R. 1 E.

I-13, M-13

FILED

2. PROPERTY CONTROLLING IN SECTION. T 1 N. R. 1 E. W.

#16 See other Sheet

SEP 23 11 25 AM '77

3. MISCELLANEOUS PROPERTY IN SECTION. T. S. R. W.

REGISTER OF DEEDS

Paul Johnson

INGHAM COUNTY, MICH.

4. LOT NO. RECORDED PLAT

REGISTER OF DEEDS STAMP AND FILING NUMBER

5. PRIVATE CLAIMS

I, George M. Young do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 8/9, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 8/9, 1977, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:


I-13 original monuments & accessories obliterated
M-13
15" Walnut N.W. 60.9'
12" Pine S. SW. 57.6'
2" Elm S.E. 78.8'
Pinch Post N.E. 40.4
Iron & Title
Ingham County Road Comm.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner.

I-13
Found 1" Rod 0.5' Below Asphalt
M-13
Found 1"x1" Rod 0.6' under Road Surface

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-13
#16 nail & Cap in 12" Apple N 45° W 96.40'
#16 nail & Cap in 24" Willow N 10° E 207.12'
#PK nail in 24" Walnut N 30° E. 47.10'
M-13
#16 nail & cap in 8" Hickory N 60° W 47.55'
#16 nail & cap in 30" Hickory S 30° E 43.49
#16 nail & cap in Power Pole S 50° W 83.72
1"x1" Rod.



SIGNED BY George M. Young DATE September 20, 1977

SURVEYOR'S MICHIGAN REGISTRATION NO. 17640

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION JAN 28, 1971
REVISED MAY 14, 1973

1096

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET