


INDEX TO PUBLIC LAND SURVEY CORNER RECORDATIONS FILED IN

TOWN 3 NORTH SOUTH, RANGE 2 EAST WEST

TOWNSHIP CORNER NUMBERING CODE DIAGRAM



CORNER INDEX

CODE NO.	FILING NUMBER	CODE NO.	FILING NUMBER
A-1	Liber 1 pg 375	D-1	Liber 4 pg 315
← A-2	Liber 1 pg 373	D-2	Liber 4 pg 8
← A-3	Liber 4 pg 308	D-3	Liber 2 pg 597
← A-4	Liber 2 pg 443	D-4	Liber 6 pg 171
A-5	Liber 2 pg 443	D-5	Liber 2 pg 335
A-6	Liber 5 pg 296	D-6	Liber 2 pg 583
A-7	Liber 3 pg 241	D-7	Liber 2 pg 333
A-8	Liber 6 pg 5	D-8	Liber 3 pg 539
← A-9	Liber 3 pg 269	D-9	Liber 5 pg 347
← A-10	Liber 3 pg 269	D-10	Liber 5 pg 383
← A-11	Liber 2 pg 215	D-11	Liber 3 pg 93
A-12	Liber 2 pg 213	D-12	Liber 4 pg 77
A-13		D-13	Liber 3 pg 93
← B-1	Liber 4 pg 216	E-1	Liber 2 pg 533
← B-2	Liber 4 pg 216	E-2	Liber 3 pg 549
← B-3	Liber 3 pg 620	E-3	Liber 1 pg 119
← B-4	Liber 4 pg 308	E-4	Liber 1 pg 121
← B-5	Liber 4 pg 111	E-5	Liber 2 pg 337
B-6	Liber 4 pg 111	E-6	Liber 2 pg 579
← B-7	Liber 3 pg 243	E-7	Liber 3 pg 239
B-8	Liber 10 pg 412	E-8	Liber 4 pg 103
← B-9	Liber 4 pg 352	← E-9	Liber 4 pg 103
B-10		← E-10	Liber 4 pg 196
B-11	Liber 6 pg 321	← E-11	Liber 1 pg 135
B-12	Liber 4 pg 102	E-12	Liber 1 pg 133
← B-13	Liber 4 pg 102	E-13	Liber 3 pg 93
← C-1	Liber 4 pg 217	F-1	Liber 1 pg 357
← C-2	Liber 4 pg 217	F-2	Liber 3 pg 549
← C-3	Liber 3 pg 620	F-3	Liber 1 pg 357
C-4	Liber 5 pg 219	F-4	Liber 1 pg 549
← C-5	Liber 2 pg 523	F-5	Liber 1 pg 565
← C-6	Liber 2 pg 513	F-6	Liber 2 pg 381
C-7	Liber 2 pg 567	F-7	Liber 2 pg 353
C-8	Liber 6 pg 132	F-8	Liber 4 pg 110
C-9	Liber 4 pg 351	F-9	Liber 3 pg 245
← C-10	Liber 4 pg 5	F-10	Liber 4 pg 196
← C-11	Liber 3 pg 93	F-11	Liber 4 pg 318
← C-12	Liber 2 pg 69	F-12	Liber 7 pg 241
C-13	Liber 1 pg 591	F-13	Liber 5 pg 312
← C-3	Liber 4 pg 81	← D-7	Liber 3 pg 569
			Liber 3 pg 628

CORNER INDEX

CODE NO.	FILING NUMBER	CODE NO.	FILING NUMBER
G-1	Liber 1 pg 355	K-1	Liber 5 pg 298
G-2	Liber 1 pg 365	K-2	Liber 4 pg 149
G-3	Liber 1 pg 361	K-3	Liber 2 pg 131
G-4	Liber 1 pg 251	K-4	Liber 1 pg 33
G-5	Liber 1 pg 579	K-5	Liber 1 pg 277
G-6	Liber 1 pg 487	K-6	Liber 1 pg 275
G-7	Liber 1 pg 561	K-7	Liber 1 pg 447
G-8	Liber 1 pg 101	K-8	Liber 2 pg 617
G-9	Liber 2 pg 297	K-9	Liber 4 pg 197
G-10	Liber 2 pg 297	K-10	Liber 5 pg 330
G-11	Liber 4 pg 135	K-11	Liber 1 pg 449
G-12	Liber 2 pg 411	K-12	Liber 2 pg 67
G-13	Liber 2 pg 413	K-13	Liber 2 pg 161
H-1	Liber 6 pg 182	L-1	Liber 6 pg 251
H-2		L-2	
H-3	Liber 2 pg 599	L-3	Liber 3 pg 621
H-4	Liber 4 pg 306	L-4	Liber 3 pg 621
H-5	Liber 1 pg 17	L-5	Liber 1 pg 279
H-6	Liber 1 pg 489	L-6	Liber 7 pg 172
H-7	Liber 1 pg 559	L-7	Liber 1 pg 427
H-8	Liber 1 pg 97	L-8	Liber 7 pg 435
H-9	Liber 3 pg 199	L-9	Liber 4 pg 114
H-10	Liber 2 pg 297	L-10	Liber 4 pg 61
H-11	Liber 5 pg 319	L-11	Liber 1 pg 349
H-12	Liber 2 pg 411	L-12	Liber 6 pg 9
H-13	Liber 2 pg 413	L-13	Liber 2 pg 163
I-1	Liber 3 pg 460	M-1	
I-2	Liber 1 pg 41	M-2	Liber 5 pg 168
I-3	Liber 2 pg 139	M-3	Liber 5 pg 353
I-4	Liber 1 pg 35	M-4	Liber 5 pg 324
I-5	Liber 1 pg 31	M-5	Liber 5 pg 348
I-6	Liber 1 pg 571	M-6	Liber 3 pg 379
I-7	Liber 1 pg 569	M-7	Liber 3 pg 379
I-8	Liber 1 pg 99	M-8	Liber 5 pg 77
I-9	Liber 4 pg 251	M-9	Liber 4 pg 114
I-10	Liber 3 pg 199	M-10	Liber 4 pg 61
I-11	Liber 4 pg 133	M-11	Liber 1 pg 287
I-12	Liber 2 pg 551	M-12	Liber 3 pg 438
I-13	Liber 2 pg 413	M-13	Liber 2 pg 165
J-1	Liber 6 pg 361	K-5	Liber 1 pg 283
J-2	Liber 6 pg 361	C-13	Liber 2 pg 69
J-3	Liber 2 pg 141	J-5	Liber 2 pg 129
J-4	Liber 1 pg 43	K-4	Liber 2 pg 133
J-5	Liber 1 pg 281	J-4	Liber 2 pg 143
J-6	Liber 1 pg 285	K-12	Liber 2 pg 159
J-7	Liber 1 pg 573	G-5	Liber 2 pg 339
J-8	Liber 2 pg 617	D-5	Liber 2 pg 387
J-9	Liber 6 pg 315	D-7	Liber 2 pg 389
J-10	Liber 7 pg 297	G-2	Liber 2 pg 479
J-11	Liber 1 pg 451	D-7	Liber 2 pg 573
J-12	Liber 1 pg 445	D-5	Liber 2 pg 577
J-13	Liber 8 pg 298	J-11	Liber 3 pg 43
G-6	Liber 3 pg 201	J-12	Liber 3 pg 43
G-7	Liber 3 pg 201	K-11	Liber 3 pg 45
G-8	Liber 3 pg 201	F-5	Liber 3 pg 121
F-1	Liber 3 pg 117		

INGHAM COUNTY
NE Corner, Section 36, T3N, R2W

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 1 PC 287

FOR CORNERS OF--	Sec.	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	36	T. 3 N. R. 2 W.	M-11
2. PROPERTY CONTROLLING IN SECTION		T. N. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION		T. N. S. R. E. W.	
4. LOT NO. _____, RECORDED PLAT _____			
5. PRIVATE CLAIMS _____			

FILED.

Dec 3 3 15 PM '71

REGISTER OF DEEDS
Mrs. Bill Humphrey
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Ronnie M. Lester do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on November 1 1971, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on November 1 1971, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Original monument and accessories obliterated.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 1/2" bar at intersection of College and Harper Roads.
Field measurement South in close accord with original government measurement.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1/2" bar at intersection of College and Harper Roads
Nail & Tag SW side power pole SE, 39.88'
Nail & Tag NE side power pole NW, 37.78'
MDSH Nail & Tag NW side power pole NE, 33.60'

SIGNED BY

Ronnie M. Lester

DATE

Nov 30, 1971

SURVEYOR'S MICHIGAN REGISTRATION NO.

18998

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY


MICHIGAN REGISTERED LAND SURVEYOR

DATE

SURVEYOR'S MICHIGAN REGISTRATION NO.

Form No. ML M730
HOBLEDAY BROS. & CO., KALAMAZOO, MICH.


FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS



INDEX TO PUBLIC LAND SURVEY CORNER RECORDATIONS FILED IN

TOWN 3 NORTH SOUTH, RANGE 2 EAST WEST

TOWNSHIP CORNER NUMBERING CODE DIAGRAM



CORNER INDEX

CODE NO.	FILING NUMBER	CODE NO.	FILING NUMBER
----------	---------------	----------	---------------

A-1		D-1	
A-2	Li. 7 pg. 128	D-2	
A-3	Li. 10 pg. 118	D-3	Li. 7 pg. 138 →
A-4	Li. 10 pg. 119	D-4	
A-5		D-5	
A-6		D-6	Li. 7 pg. 295
A-7		D-7	Li. 7 pg. 296
A-8		D-8	Li. 7 pg. 54
A-9	Li. 4 pg. 353	D-9	
A-10	Li. 4 pg. 353	D-10	
A-11	Li. 4 pg. 352	D-11	L 6 P 6 7
A-12		D-12	
A-13		D-13	Li. 6 pg. 89
B-1	Li. 7 pg. 129	E-1	
B-2	Li. 7 pg. 130	E-2	Li. 8 pg. 424
B-3	Li. 7 pg. 131	E-3	Li. 9 pg. 567
B-4	Li. 4 pg. 319	E-4	
B-5	Li. 4 pg. 307	E-5	Li. 9 pg. 568
B-6		E-6	Li. 6 pg. 334 →
B-7	Li. 10 pg. 411	E-7	Li. 6 pg. 335 →
B-8		E-8	
B-9	Li. 5 pg. 116	E-9	Li. 4 pg. 196 →
B-10		E-10	Li. 5 pg. 112 →
B-11		E-11	Li. 5 pg. 110 →
B-12		E-12	Li. 6 pg. 360
B-13	Li. 9 pg. 316	E-13	Li. 6 pg. 360
C-1	Li. 7 pg. 132	F-1	Li. 6 pg. 137
C-2	Li. 7 pg. 133	F-2	
C-3	Li. 7 pg. 134	F-3	Li. 6 pg. 375
C-4	Li. 8 pg. 446	F-4	Li. 6 pg. 220 →
C-5	Li. 6 pg. 214	F-5	
C-6	Li. 10 pg. 380	F-6	
C-7		F-7	Li. 7 pg. 230
C-8		F-8	Li. 5 pg. 192 →
C-9	Li. 6 pg. 365	F-9	Li. 8 pg. 632
C-10	Li. 4 pg. 351	F-10	Li. 5 pg. 114 →
C-11	Li. 4 pg. 351	F-11	Li. 5 pg. 115 →
C-12	Li. 9 pg. 317	F-12	
C-13	Li. 6 pg. 359	F-13	

CORNER INDEX

CODE NO.	FILING NUMBER	CODE NO.	FILING NUMBER
G-1	Li. 6 pg. 137 →	K-1	
G-2	Li. 7 pg. 174	K-2	Li. 6 pg. 250 →
G-3	Li. 7 pg. 175	K-3	Li. 6 pg. 261
G-4	Li. 6 pg. 296 →	K-4	
G-5	Li. 8 pg. 605	K-5	Li. 6 pg. 316
G-6	Li. 8 pg. 611	K-6	Li. 6 pg. 256
G-7		K-7	Li. 8 pg. 89
G-8		K-8	Li. 7 pg. 168 →
G-9	Li. 6 pg. 223 →	K-9	Li. 8 pg. 85
G-10	Li. 5 pg. 111 →	K-10	
G-11	Li. 5 pg. 113 →	K-11	
G-12	Li. 5 pg. 129 →	K-12	
G-13	Li. 9 pg. 65	K-13	

H-1	Li. 7 pg. 176	L-1	Li. 6 pg. 262
H-2		L-2	
H-3	Li. 7 pg. 137	L-3	Li. 6 pg. 263
H-4		L-4	
H-5	Li. 6 pg. 77 →	L-5	
H-6	Li. 8 pg. 603	L-6	
H-7	Li. 8 pg. 606	L-7	Li. 7 pg. 185 →
H-8	Li. 9 pg. 161	L-8	
H-9	Li. 8 pg. 514	L-9	Li. 8 pg. 81
H-10	Li. 9 pg. 39 6-225	L-10	
H-11	Li. 8 pg. 512	L-11	
H-12	Li. 9 pg. 67	L-12	
H-13	Li. 9 pg. 308	L-13	

I-1	Li. 7 pg. 161	M-1	
I-2	Li. 7 pg. 178	M-2	
I-3		M-3	
I-4	Li. 6 pg. 290 →	M-4	
I-5	Li. 8 pg. 304 →	M-5	
I-6	Li. 8 pg. 613	M-6	
I-7	Li. 5 pg. 30 →	M-7	Li. 8 pg. 79
I-8	Li. 6 pg. 346 →	M-8	Li. 8 pg. 93
I-9	Li. 6 pg. 348 →	M-9	Li. 8 pg. 95
I-10	Li. 9 pg. 41	M-10	Li. 6 pg. 225
I-11	Li. 9 pg. 43	M-11	
I-12	Li. 9 pg. 113	M-12	
I-13	Li. 9 pg. 310	M-13	

THIS IS
H 10

B-5	Li. 4 pg. 317 →
E-10	Li. 6 pg. 67 →
E-11	Li. 6 pg. 67 →
G-10	Li. 6 pg. 224 →
J-7	Li. 6 pg. 243
K-2	Li. 6 pg. 260
G-4	Li. 6 pg. 303 →
J-4	Li. 6 pg. 314
G-1	Li. 6 pg. 347
F-4	Li. 6 pg. 354 →
I-4	Li. 7 pg. 146 →
Li. 17	Memorandum Li. 7 pg. 282
G-4	Li. 7 pg. 310
B-9	Li. 7 pg. 389
C-9	Li. 7 pg. 390
C-10	Li. 7 pg. 391

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Delhi Township, Ingham County

LEED

4 16 197

FOR CORNERS OF--

LOCATED IN--

CORNER CODE NUMBER

1. PUBLIC LAND SURVEY ... 23 T. 3. N. 2. R. 2. W. K-9

FILED

2. PROPERTY CONTROLLING IN SECTION ... T. N. R. W.

3. MISCELLANEOUS PROPERTY IN SECTION ... T. N. R. W.

4. LOT NO. ... RECORDED PLAT

5. PRIVATE CLAIMS

MAY 4 2 47 PM '78

REGISTER OF DEEDS

Paul Johnson

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Ron Helsel, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on January 20, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on January 20, 1978, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

K-9, I.C.R.C. Witness: NW corner tile filling station NE, 71.7'
Spike 16" maple 230' WNW
Spike 16" maple 30.7' SW

B. Description of corner evidence found and or method applied in restoring or re-establishing corner:

K-9, Fd. railroad spike and original witnesses & rewitnessed

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-9, SE Corner: N85°W, 23.12' Nail & tag 30" maple
S45°W, 31.55' Nail & tag 28" maple
N80°E, 39.22' Corner block bldg.
S85°E, 46.64' Corner block bldg.

SIGNED BY

Ron Helsel

DATE January 24, 1978

SURVEYOR'S MICHIGAN REGISTRATION NO. 18994

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE

SURVEYOR'S MICHIGAN REGISTRATION NO. 1195

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 25, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER

1 PG 349

FOR CORNERS OF--	Sec.	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	36	T. 3 N. R. 2	L-11
2. PROPERTY CONTROLLING IN SECTION		T. N. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION		T. N. S. R. E. W.	
4. LOT NO. _____		RECORDED PLAT _____	
5. PRIVATE CLAIMS _____			

FILED

FEB 16 4 06 PM '72

REGISTER OF DEEDS
Mrs. Bill Humphrey
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Ronnie M. Lester do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram-over) were, in a field survey on December 16 1971, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on December 16 1971, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Original monument and accessories obliterated.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 1" bar 2.7' South of centerline of Harper Road
on old tree line North.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1" bar 2.7' South centerline Harper Road

Nail & Tag East side of power pole NNE, 31.04'
Nail & Tag North side of 10" boxelder SE, 38.15'
Nail & Tag East side of 8" boxelder North, 43.03'

SIGNED BY Ronnie M. Lester DATE Feb 16 1972
SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY
APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.

Form No. MLM736
DOUGLASS, BROS. & CO., ANN ARBOR, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 20, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

NE Cor. Sec. 35, T3N, R2W
LAND CORNER RECORDATION CERTIFICATE
 FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 1 PG 449

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>35</u> T. <u>3</u> N. R. <u>2</u> W.		<u>K-11</u>
2. PROPERTY CONTROLLING IN SECTION _____ T. _____ N. S. R. E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ N. S. R. E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

FILED

APR 12 1 15 PM '72
 REGISTER OF DEEDS
Mia Bell Humphrey
 INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
 FILING NUMBER

I, Fred N. White do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on Nov. 27 1971, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Original Corner & Witnesses obliterated

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

*Found "T" iron from MSHD & Ingham County Road
 Commission records.*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

"T" iron in E. Harper & Edger Roads

*48" Maple S80°E 95.70'
 12" Ash S10°W 90.72'
 Twin Maple N25°W 127.57'
 9" Elm stump WNW 100.5'
 16" Elm stump NNW 68.3'*

SIGNED BY Fred N. White

DATE 12-17-71

SURVEYOR'S MICHIGAN REGISTRATION NO. 12034

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____

CHIEF OF SURVEY PARTY

DATE _____

APPROVED AND SIGNED BY _____

MICHIGAN REGISTERED LAND SURVEYOR

DATE _____

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

NE corner of Section 35, T3N, R2W, Delhi Township, Ingham County, Michigan

LIBER

316 45
FILED

FOR CORNERS OF: LOCATED IN: CORNER CODE NUMBER

1. PUBLIC LAND SURVEY 35 T. 3 N. R. 2 W. K-11

2. PROPERTY CONTROLLING IN SECTION T. N. R. E.

3. MISCELLANEOUS PROPERTY IN SECTION T. N. R. E.

4. LAST NO. RECORDED PLAT

5. PRIVATE CLAIMS

MAR 27 10 39 AM '74

REGISTER OF DEEDS

Emil M. Lewis
INGHAM COUNTY, MICH

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Fred N. White do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on February 25, 1974 established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1974, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

Original Corner & Witnesses Lost.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found "T" iron in centerline Harper Road and Edgar Road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

"T" iron

48" Maple	S80°E	95.70'
12" Ash	S10°W	90.72'
Twin Maple	N25°W	127.57'
9" Elm Stump	NNW	100.5'
16" Elm Stump	NNW	68.3'

SIGNED BY Fred N. White DATE 2-27-74


SURVEYOR'S MICHIGAN REGISTRATION NO. 12034

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____



666

Form No. MLM735
DOUGLASS BROS. & CO., Kalamazoo, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF: LOCATED IN: CORNER CODE NUMBER

1. PUBLIC LAND SURVEY Sec 25, 3, N. R. 2, W. L-10 M-10

2. PROPERTY CONTROLLING IN SECTION T. N. S. R. E. W.

3. MISCELLANEOUS PROPERTY IN SECTION T. N. S. R. E. W.

4. LOT NO. RECORDED PLAT

5. PRIVATE CLAIMS

LIBER 4 PG 61

FILED

MAY 24 10 58 AM '77

REGISTER OF DEEDS

Paul Johnson
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on May 13, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

L-10 Center of Section 25. No record of corner being set in original government survey.

M-10 E 1/4 Corner Section 25. Original monument and accessories obliterated.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

L-10 Found concrete corner post that has been used by three area surveyors in previous surveys. Set 1/2" bar & cap at base of post.

M-10 Found 3/8" iron rod 10" below surface of College Road from information provided by Stephen's Engineering. Raised to surface with 1/2" bar & cap.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-10 1/2" bar & cap at base of concrete post. Fences South, East, & West.

Nail & tag in East side 5" elm, North, 48.25'

Nail & tag in North side fence post, East, 6.89'

Nail & tag in power pole, W.S.W., 141.80'

M-10 1/2" bar & cap as described above

1/2" pinch pipe, West, 31.30'

Nail & tag in South side 48" maple, E.S.E., 50.01'

S.W. corner frame house #1252, (5' high), E.N.E., 74.00'

Nail & tag in N.W. side 36" maple, N.E., 48.65'

SIGNED BY Ronnie M. Lester

DATE 5/23/77

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE



SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

1063

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971

REVISED MAY 12, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF— LOCATED IN— CORNER CODE NUMBER

1. PUBLIC LAND SURVEY—Sec 25, T. 3 N., R. 2 W. L-10 M-10

2. PROPERTY CONTROLLING IN SECTION— T. N. S. R. E. W.

3. MISCELLANEOUS PROPERTY IN SECTION— T. N. S. R. E. W.

4. LOT NO. —, RECORDED PLAT —

5. PRIVATE CLAIMS —

LIBER. 4 PG 61

FILED

MAY 24 10 58 AM '77

REGISTER OF DEEDS

Paul Johnson
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on May 13, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

L-10 Center of Section 25. No record of corner being set in original government survey.

M-10 E 1/4 Corner Section 25. Original monument and accessories obliterated.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

L-10 Found concrete corner post that has been used by three area surveyors in previous surveys. Set 1/2" bar & cap at base of post.

M-10 Found 3/8" iron rod 10" below surface of College Road from information provided by Stephen's Engineering. Raised to surface with 1/2" bar & cap.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-10 1/2" bar & cap at base of concrete post. Fences South, East, & West.

Nail & tag in East side 5" elm, North, 48.25'

Nail & tag in North side fence post, East, 6.89'

Nail & tag in power pole, W.S.W., 141.80'

M-10 1/2" bar & cap as described above

1/2" pinch pipe, West, 31.30'

Nail & tag in South side 48" maple, E.S.E., 50.01'

S.W. corner frame house #1252, (5' high), E.N.E., 74.00'

Nail & tag in N.W. side 36" maple, N.E., 43.65'

SIGNED BY Ronnie M. Lester

DATE 5/23/77

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____

CHIEF OF SURVEY PARTY


DATE _____

APPROVED AND SIGNED BY _____

MICHIGAN REGISTERED LAND SURVEYOR

DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____



1063

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

REVISED MAY 14, 1975

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 4 K 114

FOR CORNERS OF -- LOCATED IN -- CORNER CODE NUMBER

1. PUBLIC LAND SURVEY 1 3 N. R. 2 W. M-9, L-9

FILED

2. PROPERTY CONTROL L-9
ING IN SECTION 1 N. R. 1 W.3. MISCELLANEOUS
PROPERTY IN SECTION 1 N. R. 1 W.

4. LOT NO. RECORDED PLAT

5. PRIVATE CLAIMS

NOV 28 8 40 AM '77

REGISTER OF DEEDS

Doris Johnson

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER1. Ronnie M. Lester

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 2, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 11/11/77, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of Law:

A. Description of original monument and accessories and/or subsequent restoration:

M-9 Original monument and accessories obliterated.

L-9 Original monument and accessories obliterated.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

M-9 MDSH calls for 1" iron pipe in centerline of College Road, 19.80' South of Alaiedon Corner, C.E. Smith 1963 witnessed.
Found railroad spike at this location and one MDSH witness tag that matched 1963 call.
Measured South 2635.78'. Measured West 2624.62'.
L-9 Set 1/2" bar & cap at base of remains of old fence corner post, with fences South and East. Measured East 2624.62'. Measured South 2645.08'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-9 Railroad spike
1/2" bar (Alaiedon corner) North, 20.29'
MDSH tag in West side power pole, S.S.E., 149.22'
Nail & tag in West side 30" cottonwood, E.S.E., 62.53'
Nail & tag in North side 6" elm, East, 64.80'.
L-9 1/2" bar & cap
Nail & tag in East side 36" maple, N.N.W., 14.15'.
Nail & tag in East side 6" oak, S.S.E., 94.09'.
Nail & tag in East side 24" maple, South, 109.30'.

SIGNED BY Ronnie M. Lester DATE 11/11/77SURVEYOR'S MICHIGAN REGISTRATION NO. 18998


(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR



SURVEYOR'S MICHIGAN REGISTRATION NO. _____

1116

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 4 Pg 114

FOR CORNERS OF -- LOCATED IN -- CORNER CODE NUMBER

1. PUBLIC LAND SURVEY 1 3 N. R. 2 W. M-9, L-9

FILED

2. PROPERTY CONTROL L-9
ING IN SECTION 1 N. R. 1 W.3. MISCELLANEOUS
PROPERTY IN SECTION 1 N. R. 1 W.

4. LOT NO. RECORDED PLAT

5. PRIVATE CLAIMS

Nov 28 8 40 AM '77

REGISTER OF DEEDS

C. Johnson

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 2, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of Law:

A. Description of original monument and accessories and on subsequent restoration:

M-9 Original monument and accessories obliterated.

L-9 Original monument and accessories obliterated.

B. Description of corner evidence found and on method applied in restoring or re-establishing corner:

M-9 MDSH calls for 1" iron pipe in centerline of College Road, 19.80' South of Alaiedon Corner, C.E. Smith 1963 witnessed.
Found railroad spike at this location and one MDSH witness tag that matched 1963 call.
Measured South 2635.78'. Measured West 2624.62'.
L-9 Set 1/2" bar & cap at base of remains of old fence corner post, with fences South and East. Measured East 2624.62'. Measured South 2645.08'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-9 Railroad spike
1/2" bar (Alaiedon corner) North, 20.29'
MDSH tag in West side power pole, S.S.E., 149.22'
Nail & tag in West side 30" cottonwood, E.S.E., 62.53'
Nail & tag in North side 6" elm, East, 64.80'.
L-9 1/2" bar & cap
Nail & tag in East side 36" maple, N.N.W., 14.15'.
Nail & tag in East side 6" oak, S.S.E., 94.09'.
Nail & tag in East side 24" maple, South, 109.30'.

SIGNED BY Ronnie M. Lester DATE 11/11/77SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

(SEAL)


FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR



SURVEYOR'S MICHIGAN REGISTRATION NO. _____

1116

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in

<u>INGHAM</u> (County)	Located in:	Corner Code ##
1. <u>DELHI TOWNSHIP</u> Public Land Survey	T <u>3N</u> R <u>2W</u>	<u>L-9</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

DEC 2 12 18 PM '93

REGISTER OF DEEDS

Paula Johnson
 INGHAM COUNTY, MICH.

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

I, R.W. Steadman, in a field survey on September 25, 1993 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. Original corner set by Musgrove Evans D.S. in Jan 1827
 Elm 18 S7W 16
 Beech 10 N57E 8

(OVER)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Searched apparent area of corner and found $\frac{1}{2}$ " Bar and cap #18998 at N.E. Corner fence post hole with all of R. Lesters witness trees still standing. Excavated all around post and found a few pieces of broken tile among the general run of the mill fence post stones. Accepted bar and cap as corner and replaced with standard Bar and cap.

Field work conducted by Dave Clifford PS#25837

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Standard Ingham County 3/4"x24" Steel Remonumentation Bar and PA 345 Cap #11370 in N.E. Side Old Anchor Post Hole.

Set Nail & Tag #25837 in E. Side 30" Basswood (Not Maple)
 Az 326° 14.15'
 Set Nail & Tag #25837 in E. Side 6" Basswood Az 96° 19.00'
 Set Nail & Tag #25837 in S. Side 6" Basswood Az 102° 23.65'
 Set Nail & Tag #25837 in S.E. Side 6" Elm Az 316° 2.20'
 Set Nail & Tag #25837 in W. Side 25" Maple Az 181° 109.31'

Signed by Richard W. Steadman Date November 23, 1993Surveyor's Michigan License No. 11370

2581

P.A. 345 INGHAM COUNTY
 PEER APPROVED 11/23/1993 PC

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEY, JAN. 28, 1971
 REVISED MAY 14, 1978
 REVISED JAN., 1982

2. T.J. Brown Deputy Co. Surveyor used corner in a survey dated April 1851 recorded in Vol. C page 20 with no mention of monument or witnesses.
3. Ronnie Lester LS#18998 recorded corner in Nov. 1977 in Liber 4 of corners page 114 as a $\frac{1}{2}$ " Bar and cap set at the base of remains of old fence corner post, with fences South and East.

Nail & Tag in East side 36" Maple NNW 14.15'

Nail & Tag in East side 6" Oak SSE 94.09'

Nail & Tag in East side 24" Maple South 109.30'

2581

001E#6251	0008	HSSR	\$2.00
001E#6251	0008	CORNER	\$9.00

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in

_____**INGHAM**_____
 _____**DELHI TOWNSHIP**_____
 1. Public Land Survey T 3N R 2W K-9
 T _____ R _____
 T _____ R _____
 T _____ R _____
 2. Property Controlling S _____ T _____ R _____
 in Section S _____ T _____ R _____
 3. Miscellaneous S _____ T _____ R _____
 Property in Sec. S _____ T _____ R _____

DEC 2 12 19 PM '93

REGISTER OF DEEDS
Paula Johnson
 INGHAM COUNTY, MICH.

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

I, R.W. Steadman, in a field survey on SEPTEMBER 10 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. Original Post set by Musgrove Evans D. S. 1st Jan 1827
Aspen 14" N85½°E 55.0 lks
DO 10" N5E 95.0 lks
2. T. J. Brown Dep. Co. Surveyor used corner in a Survey in Oct. 1851 recorded in Vol. C Page 7 with no mention of monument of witnesses.

(OVER)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Searched apparent area of corner and found the railroad spike was destroyed by recent sewer and street construction. Dug large hole (4' x 3') at intersection of Witnesses of A-6. Failed to find any evidence of historical monument. Reestablished corner by intersection of witnesses of A-3, A-4, A-5, A-6, A-8. Witnesses A-8 a & c are the same as A-6 c & d. Witness A-8 e is plat monument called for in A-5. Witnesses A-6 a & b are the same as Witnesses A-4 A& b and A-3 a & b which are the historical witnesses of E. A. Calkins, Co. Surveyor. All witnesses of items A-3 to A-8 are still in existence except for A-4c. Witnesses all match within a 0.2 diameter circle. Set Standard Bar & Cap in Mon. Box at center of circle.

Field work conducted by Dave Clifford PS#25837

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Standard Ingham County Remonumentation 3/4" x 24" stel Bar & PA345
 Cap #11370 in Monument Box 1100' West of centerline Edgar Road.

Found Nail & Tag #17640 (George Young) in S.E. Side 36" Maple Az 229° 31.22'
 Found Nail & Tag #17640 in S. Side 34" Maple Az 295° 22.28'
 Found Nail & Tag #17640 in S.W. Side 50" Maple Az 347° 69.36
 Corner Block Bldg Az 66° 39.25'
 Corner Block Bldg. Az 100° 46.58'
 2" pipe in Conc. Monument Az 90° 33.00'

Signed by Richard W. Steadman Date November 23 1993Surveyor's Michigan License No. 11370

P.A. 345 INGHAM COUNTY
 PEER APPROVED 11/23/93

2583

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 29, 1971
 REVISED MAY 14, 1975
 REVISED JAN., 1983

3. E. A. Calkins, Co. Surveyor used corner in a survey in Dec. 1900 and Oct. 1901 recorded in Vol. 5 page 22 as O.P.F. set marble monument marked "C. P." F. W.
 - a. Maple 4 N 70½ W 35 lks (23.1)
 - b. DO 3 S46W 46½ lks (30.7')
4. Ingham County Road Commission (ICRC) Grid Map 1" Pipe, marble mon., brick.
 - a. 16" Maple WNW 23.0
 - b. 16" Maple S.W. 30.7
 - c. N.W. Cor. gas station 71.7'
5. Supervisors's Plat of Rose Mill Farm as recorded in Liber 15, page 8 by Rosewell Wolcott RLS in 1949 calls for corner and shows a plat monument 33.00' East.
6. Ron Helsel LS#18994 recorded corner in Jan. 1978 in Liber 4 of Corners page 197 as found railroad spike from I.C.R.C. Witnesses.
 - a. S85°W 21.12' Nail & Tag 30" Maple
 - b. S45°W 32.55' Nail & Tag 28" Maple
 - c. N80°E 39.22 Corner Block Bldg.
 - d. S85°E. 46.64' Corner Block Bldg.
7. R. Helsel used corner in a survey dated Jan. 1978 recorded in Liber 3 page 319 with the same monument and witnesses as in item #6.
8. Ronnie Lester LS#18998 used corner in a survey in Oct. 1992 recorded in Liber 6 page 1054 as a found railroad spike.
 - a. S. W. Corner Block Bldg. 67° Az 46.6'
 - b. S. W. Corner Block Bldg. 42° Az 76.0
 - c. N. W. Corner Block Bldg. 105° Az 39.2
 - d. N. W. Corner Block Bldg 30° Az 90.6
 - e. 2" pipe in concrete monument Az. 94° 33.00'

2583

001E#6251	0008	MSSR	\$2.00
001E#6251	0008	CORNER	\$9.00

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ingham County
 (County)

Located in:

Corner Code ##**FILED****DEC 2 12 20 PM '93**

REGISTER OF DEEDS.

INGHAM COUNTY, MICH.

Register of Deeds Stamp & File Number

Delhi Township
 1. Public Land Survey

T 3N R 2W

M-9

2. Property Controlling
 in Section

S T R

3. Miscellaneous
 Property in Sec.

S T R 4. Lot No. , Recorded Plat 5. Private Claims

I, Richard W. Steadman, in a field survey on September 10, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. Original Corner set by Lucious Lyon D.S. in January 1826
 Ash 7" S17°W 15 LKS
 Maple 5" N28°W 27 LKS
2. Corner Recorded by T.J. Brown, County Surveyor in April 1851 in Volume C, page 20, Ingham County Surveyors Records with no mention of monument or witnesses.

(continued on back)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Searched at apparent location of Corner and got strong magnetic reading 20' ± South of A-9 Alaledon Township. Excavated surface and found Railroad Spike. Removed Railroad Spike and got strong magnetic reading directly beneath it. Excavated and found 1" Pinchpipe 24" long. Removed 1" pipe and got strong magnetic reading directly beneath it. Excavated to a depth of 3.5 feet and hit another bituminous surface with a hole in it and a 1 1/4" pipe in hole. Excepted Railroad Spike, 1" pipe and 1 1/4" pipe as Corner markers and left 1 1/4" pipe in place and set Standard Bar & Cap above it. Corners lies on centerline of College Road with no occupation line to the West. R. Lester's 30" Poplar Witness to East is still standing and closely matches location of Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Standard 3/4" x 24" Iron Bar with P.A.345 cap#11370 in monument box. Set Nail & Tag #25837 (PS David L. Clifford) in South side 30" Poplar, Az., 113°, 62.86'
 CL Road Sign Post, Az., 32°, 69.25'
 Set Nail & Tag #25837 in east side Multiple Maple, Az., 348°, 102.81'
 CL Railroad Crossing Signal Post, Az., 189°, 235.10'
 Boot Spike @ SW Corner Section 18, Alaledon Township, Az., 0°, 20.32'

Signed by Richard W. Steadman Date October 11, 1993Surveyor's Michigan License No. 11370

2588

P.A.345 INGHAM COUNTY
 PEER APPROVED 10/20/93

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1979
 REVISED MAY 14, 1978
 REVISED JAN., 1983

3. MDSH Surveyor C.E. Smith Witnessed Corner in 1963 as a
 1" Pipe in Center of College Road.
 P. Pole S15°E 149.56'
 15" Poplar S60°E 64.40'
4. Ronnie M. Lester LS#18998 Recorded Corner in November 1977 in Liber 4 of
 Corners, page 115, Ingham County Records as a Found Railroad Spike matching
 MDSH witnesses of 1963
 MDSH tag in west Side power pole SSE, 149.22'
 Nail & Tag in west side 30" Cottonwood, ESE 62.53'
 Nail & Tag in north side 6" Elm, East 64.80'

001E6251	0008	MSSR	\$2.00
001E6251	0009	CORNER	\$9.00

2588

Section 25, Dalhi Township
Ingham County

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF	LOCATED IN	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	3 S. R. 2. E.	M-9, L-9
2. PROPERTY CONTROL AND IN SITUATION		
3. MISCELLANEOUS PROPERTY IN SITUATION		
4. LOCATED	RECORDED PLAT	
5. PRIVATE CLAIMS		

Lib. 4 10 114

FILED

Nov 28 8 40 AM '77

REGISTER OF DEEDS
Ingham County, Mich.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

Ronnie M. Lester do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 2, 1977, established, re-established, monumented, monumented, recovered, or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were in a field survey on November 2, 1977, found, recovered, tested, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of Law.

A. Description of original monument and accessories and/or subsequent restoration.

M-9 Original monument and accessories obliterated.

L-9 Original monument and accessories obliterated.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner.

M-9 MDSH calls for 1" iron pipe in centerline of College Road, 19.80" South of Alaledon Corner, C.E. Smith 1963 witnessed.
Found railroad spike at this location and one MDSH witness tag that matched 1963 call.
Measured South 2635.78'. Measured West 2624.62'.
L-9 Set 1/2" bar & cap at base of remains of old fence corner post, with fences South and East. Measured East 2624.62'. Measured South 2645.08'.

C. Description of monument for corner and accessories established to perpetuate location, the position of the corner.

M-9 Railroad spike
1/2" bar (Alaledon corner) North, 20.29'.
MDSH tag in West side power pole, S.S.E., 149.22'.
Nail & tag in West side 30" cottonwood, E.S.E., 62.53'.
Nail & tag in North side 6" elm, East, 64.80'.
L-9 1/2" bar & cap
Nail & tag in East side 36" maple, N.N.W., 14.15'.
Nail & tag in East side 6" oak, S.S.E., 94.09'.
Nail & tag in East side 24" maple, South, 109.30'.

SIGNED BY Ronnie M. Lester

DATE 11/27/77

SURVEYOR'S MICHIGAN REGISTRATION NO. 18978

FOR STATE AND UNITED STATES AGENCIES

SIGNED BY

CHIEF OF SURVEY PARTY


DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE

SURVEYOR'S MICHIGAN REGISTRATION NO.



1116

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

ORIGINAL on file at Ing. Co. Reg. of Deeds
 DUPLICATE

Northwest Corner Section 30, T3N, R1W
 Ingham County

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF - LOCATED IN - CORNER CODE NUMBER
 1. EASEMENT AND SEPARATE 3 3 1 2 A-9
 2. PROPERTY CORNER IN SECTION 1 N E 1
 3. MISCELLANEOUS PROPERTY IN SECTION 1 N E 1
 4. EASEMENT AND SEPARATE 3 3 1 2
 5. PROPERTY CORNER IN SECTION 1 N E 1
 6. MISCELLANEOUS PROPERTY IN SECTION 1 N E 1
 7. EASEMENT AND SEPARATE 3 3 1 2
 8. PROPERTY CORNER IN SECTION 1 N E 1
 9. MISCELLANEOUS PROPERTY IN SECTION 1 N E 1

FILED 4 16 115

FILED

Nov 20 8 40 AM '77

REGISTER OF DEEDS

Paul Johnson

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
 FILING NUMBER

I, Donnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in the above survey were in a field survey on Nov 12 1977, established, recovered, restored, or re-established, as expressed below and in accordance with regulations and rules of the Michigan State Board of Registration for Land Surveyors, and in accordance with the instructions of the United States Department of the Interior, Bureau of Land Management, and the Federal Board of Survey and Mapping, that the corner points mentioned in lines 3, 4 and 5 above were in a field survey on Nov 12 1977, found, recovered, restored, established or re-established as expressed below and in accordance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Federal Board of Survey and Mapping.

A. Description of original monument and accessories and of subsequent restoration:

A-9 Original monument and accessories obliterated.

B. Description of corner evidence found and of method applied in restoring or re-establishing corner:

A-9 HDSH call for corner in 1963 - no witness or description except for call to be 19.80' North of Delhi corner which they describe and witness 19.80' matches GLO call of 30 links. Found 1/2" bar 20.29' North of Delhi corner. Accepted as corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-9 1/2" bar 11.5' South of centerline of dirt Road to East.
 Railroad spike South, 20.29' (NE corner Section 25)
 Nail & tag in North side 6" elm, East, 68.20'
 Nail & tag in West side 30" cottonwood, E.S.E., 71.41'
 HDSH tag in West side power pole, S.S.E., 169.15'

SIGNED BY Donnie M. Lester

DATE 11/11/77

SURVEYOR'S MICHIGAN REGISTRATION NO. 16948

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____


DATE _____

APPROVED AND SIGNED BY _____

MICHIGAN REG. OF LAND SURVEYORS

DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____



1117

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
 REVISED MAY 14, 1974

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

CORN

RECORDATION CERTIFICATE

L4 p

14

IBED from

ORIGINAL
DUPLICATE

on file at

Ing. Co. Reg. OF Deeds

Section 25, Delhi Township
Ingham County

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

USER 46 114

FILED

Nov 29 9 40 AM '77

REGISTER OF DEEDS

Ingham County, Mich.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

FOR CORNERS OF: LOCATED IN: CORNER CODE NUMBER

1. PUBLIC LAND SURVEY 3 6 2 9 M-9, L-9

2. PROPERTY CONTROL-
ING IN SECTION3. MISCELLANEOUS
PROPERTY IN SECTION

4. FOUND RECORD IN PLACE

5. PRIVATE CLAIMS

1. Ronnie M. Lester do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 2, 1977, established, re-established, monumented, re-monumented, recovered or restored as specified below and in conformance with regulations and rules therefor as applied to the current record of survey notation of the United States Department of the Interior, Bureau of Land Management and in accordance with a court of law. Furthermore that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on November 2, 1977, found, recovered, restored, established or re-established as specified below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decision of a Court of Law.

2. Description of original monument and accessories and/or subsequent restoration:

M-9 Original monument and accessories obliterated.

L-9 Original monument and accessories obliterated.

3. Description of corner evidence found and method applied in restoring or re-establishing corner:

M-9 MDSH calls for 1" iron pipe in centerline of College Road; 19.80' South of Alaiadon Corner, C.E. Smith 1963 witnessed.
Found railroad spike at this location and one MDSH witness tag that matched 1963 call.
Measured South 2635.78'. Measured West 2624.62'.
L-9 Set 1/2" bar & cap at base of remains of old fence corner post, with fences South and East. Measured East 2624.62'. Measured South 2645.08'.

4. Description of monument for corner and accessories established to perpetuate location the position of the corner:

M-9 Railroad spike
1/2" bar (Alaiadon corner) North, 20.29'
MDSH tag in West side power pole, S.S.E., 149.22'
Nail & tag in West side 30" cottonwood, E.S.E., 62.53'
Nail & tag in North side 6" elm, East, 64.80'.
L-9 1/2" bar & cap
Nail & tag in East side 36" maple, N.N.W., 14.15'.
Nail & tag in East side 6" oak, S.S.E., 94.09'.
Nail & tag in East side 24" maple, South, 109.39'.

SIGNED BY: Ronnie M. Lester

DATE: 11/14/77

SURVEYOR'S MICHIGAN REGISTRATION NO. 13278

(SEAL)

FOR STATE AND UNITED STATES AGENCIES

SIGNED BY:

CHIEF OF SURVEY PARTY

DATE:

APPROVED AND SIGNED BY:

MICHIGAN REGISTRATION LAND SURVEYOR

DATE:

SURVEYOR'S MICHIGAN REGISTRATION NO.



1116

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1976

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

FILING REQUIREMENT OF ACT 74, HIGH PRIORITY

Noted for study, Eugene C. Hunt

1967 4 16 197

FUN CORNERS OF -

LOCATED IN -

CORREN CODE NUMBER

1. INTRODUCTION AND SUMMARY

231 2 0 0 20 8

K-9

FILED

2. FROM KEY CONCEPTS
TO NEW SOLUTIONS

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104. 105. 106. 107. 108. 109. 110. 111. 112. 113. 114. 115. 116. 117. 118. 119. 120. 121. 122. 123. 124. 125. 126. 127. 128. 129. 130. 131. 132. 133. 134. 135. 136. 137. 138. 139. 140. 141. 142. 143. 144. 145. 146. 147. 148. 149. 150. 151. 152. 153. 154. 155. 156. 157. 158. 159. 160. 161. 162. 163. 164. 165. 166. 167. 168. 169. 170. 171. 172. 173. 174. 175. 176. 177. 178. 179. 180. 181. 182. 183. 184. 185. 186. 187. 188. 189. 190. 191. 192. 193. 194. 195. 196. 197. 198. 199. 200. 201. 202. 203. 204. 205. 206. 207. 208. 209. 210. 211. 212. 213. 214. 215. 216. 217. 218. 219. 220. 221. 222. 223. 224. 225. 226. 227. 228. 229. 230. 231. 232. 233. 234. 235. 236. 237. 238. 239. 240. 241. 242. 243. 244. 245. 246. 247. 248. 249. 250. 251. 252. 253. 254. 255. 256. 257. 258. 259. 260. 261. 262. 263. 264. 265. 266. 267. 268. 269. 270. 271. 272. 273. 274. 275. 276. 277. 278. 279. 280. 281. 282. 283. 284. 285. 286. 287. 288. 289. 290. 291. 292. 293. 294. 295. 296. 297. 298. 299. 300. 301. 302. 303. 304. 305. 306. 307. 308. 309. 310. 311. 312. 313. 314. 315. 316. 317. 318. 319. 320. 321. 322. 323. 324. 325. 326. 327. 328. 329. 330. 331. 332. 333. 334. 335. 336. 337. 338. 339. 340. 341. 342. 343. 344. 345. 346. 347. 348. 349. 350. 351. 352. 353. 354. 355. 356. 357. 358. 359. 360. 361. 362. 363. 364. 365. 366. 367. 368. 369. 370. 371. 372. 373. 374. 375. 376. 377. 378. 379. 380. 381. 382. 383. 384. 385. 386. 387. 388. 389. 390. 391. 392. 393. 394. 395. 396. 397. 398. 399. 400. 401. 402. 403. 404. 405. 406. 407. 408. 409. 410. 411. 412. 413. 414. 415. 416. 417. 418. 419. 420. 421. 422. 423. 424. 425. 426. 427. 428. 429. 430. 431. 432. 433. 434. 435. 436. 437. 438. 439. 440. 441. 442. 443. 444. 445. 446. 447. 448. 449. 450. 451. 452. 453. 454. 455. 456. 457. 458. 459. 460. 461. 462. 463. 464. 465. 466. 467. 468. 469. 470. 471. 472. 473. 474. 475. 476. 477. 478. 479. 480. 481. 482. 483. 484. 485. 486. 487. 488. 489. 490. 491. 492. 493. 494. 495. 496. 497. 498. 499. 500. 501. 502. 503. 504. 505. 506. 507. 508. 509. 510. 511. 512. 513. 514. 515. 516. 517. 518. 519. 520. 521. 522. 523. 524. 525. 526. 527. 528. 529. 530. 531. 532. 533. 534. 535. 536. 537. 538. 539. 540. 541. 542. 543. 544. 545. 546. 547. 548. 549. 550. 551. 552. 553. 554. 555. 556. 557. 558. 559. 560. 561. 562. 563. 564. 565. 566. 567. 568. 569. 570. 571. 572. 573. 574. 575. 576. 577. 578. 579. 580. 581. 582. 583. 584. 585. 586. 587. 588. 589. 590. 591. 592. 593. 594. 595. 596. 597. 598. 599. 600. 601. 602. 603. 604. 605. 606. 607. 608. 609. 610. 611. 612. 613. 614. 615. 616. 617. 618. 619. 620. 621. 622. 623. 624. 625. 626. 627. 628. 629. 630. 631. 632. 633. 634. 635. 636. 637. 638. 639. 640. 641. 642. 643. 644. 645. 646. 647. 648. 649. 650. 651. 652. 653. 654. 655. 656. 657. 658. 659. 660. 661. 662. 663. 664. 665. 666. 667. 668. 669. 670. 671. 672. 673. 674. 675. 676. 677. 678. 679. 680. 681. 682. 683. 684. 685. 686. 687. 688. 689. 690. 691. 692. 693. 694. 695. 696. 697. 698. 699. 700. 701. 702. 703. 704. 705. 706. 707. 708. 709. 710. 711. 712. 713. 714. 715. 716. 717. 718. 719. 720. 721. 722. 723. 724. 725. 726. 727. 728. 729. 730. 731. 732. 733. 734. 735. 736. 737. 738. 739. 740. 741. 742. 743. 744. 745. 746. 747. 748. 749. 750. 751. 752. 753. 754. 755. 756. 757. 758. 759. 760. 761. 762. 763. 764. 765. 766. 767. 768. 769. 770. 771. 772. 773. 774. 775. 776. 777. 778. 779. 780. 781. 782. 783. 784. 785. 786. 787. 788. 789. 790. 791. 792. 793. 794. 795. 796. 797. 798. 799. 800. 801. 802. 803. 804. 805. 806. 807. 808. 809. 810. 811. 812. 813. 814. 815. 816. 817. 818. 819. 820. 821. 822. 823. 824. 825. 826. 827. 828. 829. 830. 831. 832. 833. 834. 835. 836. 837. 838. 839. 840. 84

4. MISCILLANEOUS PROPERTIES IN SOLUTION

A

A 101 No.

RECEIVED BY THE FBI

5. PRIVATE PLACEMENTS

I, Ron Helmer, do hereby certify that the requirements of P.L. 94-407, Chapter 1 of 1976, the corner points mentioned in items 1 and 2 above were, in a field survey on January 29, 1976, established, reestablished, monumented, re-monumented, recovered or restored as expressed below and in conformity with regulations and rules, therefore, as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in items 1, 4 and 5 above were, in a field survey on _____, _____, 19____ found, re-found, re-established or re-established as expressed below and in conformity with the rules of the Michigan State Board of Registration for Land Surveyors or by a Decree of a Court of Law.

A. Description of original nonnatural and accessories and of subsequent restoration

F-9, I.C.R.C. Witness: SW corner tile filling station NE, 71.7'
Spike 16" maple 230' NW
Spike 16" maple 30.7' NE

B. Description of other evidence found and of method applied in restoring or re-establishing correct

K-9, Rd. railroad spike and original witnesses & rewrite. (redacted)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

K-9, SE Corner: 385°W, 71.12' Rail & tag 30" maple
545°W, 71.55' Rail & tag 20" maple
180°E, 39.22' Corner black bldg.
505°E, 66.64' Corner black bldg.

SIGNED BY

DATE January 24, 1978

SURVIVORS MEET-PLAN REGISTRATION NO.

18994

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____

DATE:

APPROVED AND SIGNED BY

WAT

SURVEYOR'S MICHIGAN REGISTRATION NO.

1195

FORM APPROVED BY MICHIGAN STATE BOARD OF REFORMATION, JAN. 28, 1957
REVISED MAY 14, 1971

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET