

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

E 1/4 corner of Section 6, T4N, R2W,

City of Lansing

FILED 116 575

FOR CORNERS OF--

LOCATED IN--

CORNER CODE NUMBER

FILED

1. PUBLIC LAND SURVEY 1 4N 2 R2W C-2

2. PROPERTY CONTROLLING IN SECTION 1 S. R. 1

3. MISCELLANEOUS PROPERTY IN SECTION 1 S. R. 1

4. LOT NO. RECORDED PLAT

5. PRIVATE CLAIMS

JUN 26 10 34 AM '72

REGISTER OF DEEDS

P. M. Lewis
REGISTER OF DEEDS, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Clyde K. Stephens do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram--over) were, in a field survey on November 19, 1971, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

The original monument was not found.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A 3/4 inch iron pipe was set from old ties from 1946 and from Delta Grande Sub. #1.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

The 3/4 inch iron pipe set at the E 1/4 corner was witnessed with the following:

NO°50'W 85.50 feet to a concrete monument at the SE. corner of Delta Grande Sub. #1.
NW. corner of a 1- story frame house N85°33'E 78.0 feet.
NW. corner of a 1- story frame house #2211 S4°40'E 30.35 feet.
NO°50'W 25.20 feet to the face of the curb on Delta River Drive.

SIGNED BY

Clyde K. Stephens

DATE November 19, 1971

SURVEYOR'S MICHIGAN REGISTRATION NO. 3829

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY


CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE



SURVEYOR'S MICHIGAN REGISTRATION NO.

288

Form No. 68, 6/73
COPYRIGHT 1968, S. CO., ANN ARBOR, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

1-575

12

Case no. for De lto Grande Sub. #1

DELTA RIVER DRIVE

~~N 0° 50' W~~ 85.50

~~NO 50 W~~

N 05° 33' E 78.0'

did not, ~~the~~

55.890E 30.35
54.000E

1100 Cor. 1-Story frame
house #12211

ANY. Con 1-5 story
1-2 story house

25

CLYDE STEPHENS 11-19-71

4N 2W SECT 6

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER

3 PG 79

FOR CORNERS OF--	Sec.	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	4	T 4 N R 2 W	E-3
2. PROPERTY CONTROLLING IN SECTION		N. R. E.	
3. MISCELLANEOUS PROPERTY IN SECTION		N. R. E.	
4. LOT NO.		RECORDED PLAT	
5. PRIVATE CLAIMS			

FILED

Apr 22 10 13 AM '74

REGISTER OF DEEDS

Carol M. Lewis
 INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Marvin E. Fouty do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 11-12 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and, or subsequent restoration:
 Original monument and accessories obliterated.

B. Description of corner evidence found and, or method applied in restoring or re-establishing corner:
 A cement post 2.5' long, 3" square at the top and 4" square at the bottom was set in 1909 by County Surveyor Robb, from Ingham County records. The corner was called for on Culvers Subdivision of lot 16 and part of lot 17, Townsends Subdivision on Sections 4, 5, 8 and 9, 14N, R2W, City of Lansing and Lansing Township, Ingham County, Michigan as recorded in Liber 7 of Plats Page 7. The corner was witnessed by dimensions to the corners of lot 18 of said plat. The corner position is now occupied by a garage constructed in 1969. A Reference monument was set and witnessed as noted below and in sketch (over).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 SW corner Section 4, 14N, R2W,
 4" bar with ident. cap set as Reference Monument.
 Witnesses to Reference Monument which is S01°25'26"W 79.43' from inaccessible Section corner. (Bearing relative and referenced to Highway BL-96 which is recorded to bear N50°15'00"W).
 Nail and Tag South side 8" pine, W 15.20'
 Nail and Tag West side 8" pine, NE 19.97'
 NW Corner House #723 South 79.50'

SIGNED BY Marvin E. Fouty

DATE 3/21/74

SURVEYOR'S MICHIGAN REGISTRATION NO. 18989

FOR STATE AND UNITED STATES AGENCIES:


SIGNED BY Chief of Survey Party

DATE

APPROVED AND SIGNED BY Michigan Registered Land Surveyor


DATE

SURVEYOR'S MICHIGAN REGISTRATION NO.




CORNER NUMBERING CODE DIAGRAMS FOR IDENTIFYING LAND CORNER RECORDATIONS AND INDEXING

FOR PUBLIC LAND SURVEY CORNERS IN THE
T. 4N , R. 2W (MENTIONED OVER)




Apply letter prefix for corner points encircled above
for identifying corner recordation numbers over.

FOR PROPERTY CONTROLLING AND MISC.
PROPERTY CORNERS WITHIN THE SECTION
(MENTIONED OVER AND EXCLUDE LOT CORNER)



1. Above coded numbers are positioned on 1/16 fractional lines of the section.
2. Township corner code numbers shall be applied to corners of above typical section not numbered.
3. Miscellaneous property corners within a section, located at points other than numbered above, shall be referenced to at least two of above corner code numbers.
4. Private claim corners to be tied to rectangular land corners if possible - sketch required below.

EXPLANATORY SKETCH IF NECESSARY -- BELOW



LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 6 PG 14

FILED

FEB 19 10 55 AM '80

REGISTER OF DEEDS
Paula Johnson
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. <u>4</u> N. <u>2</u> R. <u>3</u> W.	<u>E 2</u>
2. PROPERTY CONTROLLING IN SECTION	T. _____ N. _____ R. _____ E. _____ S. _____ W. _____	
3. MISCELLANEOUS PROPERTY IN SECTION	T. _____ N. _____ R. _____ E. _____ S. _____ W. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		


I, DOUGLAS W. HOOTH, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on January 22, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
Found 1" Square Iron 10" Deep under Fence post. From distances given us by Steadman & Pierson Inc.
1" Square Iron 325' North SW Corner of lot #25. 1966 Survey.
House #720 Willey St.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1" Square Iron. (10" Deep)
N-05-W 10.47' 5" Poplar -
S-65-E 23.90' 17" Maple -
S-45-W 21.48' 7" Poplar -
N-55-W 10.96' 5" Poplar -
N-35-W 129.23' SE Cor. Conc. -
Elk. Bldg.



SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY May St. Halter Survey Chief DATE Jan. 24, 1980

APPROVED AND SIGNED BY Douglas W. Hooth DATE FEBRUARY 5, 1980

(SEAL)

MICHIGAN DEPARTMENT OF TRANSPORTATION
SURVEYOR'S MICHIGAN REGISTRATION NO. 7966

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 20, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

INGHAM COUNTY - LANSING TWP.
LAND CORNER RECORDATION CERTIFICATE
 FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 6 PG 17

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. <u>4</u> N. <u>X</u> , R. <u>2</u> E. <u>W</u>		<u>E-1</u>
2. PROPERTY CONTROLLING IN SECTION _____, T. _____ N. _____ S., R. _____ E. _____ W. _____		
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____ N. _____ S., R. _____ E. _____ W. _____		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

FILED

MAR 5 11 31 AM '80
 REGISTER OF DEEDS
Paula Johnson
 INGHAM COUNTY, MICH.
 REGISTER OF DEEDS STAMP AND
 FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 5, 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

E-1 A. Description of original monument and accessories and/or subsequent restoration:

Post set in original government survey by Musgrove Evans Feb. 10-27, 1827.
 Corner recorded to fall 12 links (7.92') west of Clinton County corner.
 Corner referred to in Recorded Subdivision Plat of Hylewood Subdivision, 1929 (L.11, p.25).

E-1 B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

During investigation found a 1/2" bar inside a 3/4" octagonal pipe .60' below road surface, + 7.5' south of the centerline of Sheridan Road and + 667.5' west of the centerline of Northdale Road south. Accepted 1/2" bar for corner. Bar in accord with monumentation found in plat of Hylewood subdivision.
 Research conducted by Ingham County Survey and Remonumentation Project staff.

E-1 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

NE Corner, Section 5, T4N-R2W
 Found 1/2" bar in location described above:
 Southeast corner of foundation, house #642, NW, 126.30'
 Nail & tag, #18998, west side 7" triple Maple, NNE, 41.52'
 Nail & tag, #18998, west side 14" power pole, SE, 27.55'
 Nail & tag, #18998, west side 20" cotton wood, SSW, 40.20'
 1/2" pipe, E-13, DeWitt Twp., East, 7.47'

SIGNED BY Ronnie M. Lester


SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

SIGNED BY _____

APPROVED AND SIGNED BY Gary D. Lester
 CHIEF OF SURVEY PARTY
 MICHIGAN REGISTERED LAND SURVEYOR
 Director, Ingham County Survey
 and Remonumentation Project

SURVEYOR'S MICHIGAN REGISTRATION NO. 17624



1773

INGHAM COUNTY - LANSING TWP.
LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 6 PG 34

FOR CORNERS OF --:	LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. 4 N. 3, R. 2 E. W.		C-1
2. PROPERTY CONTROLLING IN SECTION _____, T. _____ N. S., R. _____ E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____ N. S., R. _____ E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

FILED

MAR 13 11 20 AM '80

REGISTER OF DEEDS

Paula Johnson
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on January 25, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

1 A. Description of original monument and accessories and/or subsequent restoration:

Post set in original government survey by Musgrove Evans, February 10-27, 1827.

1 B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

During investigation, found a very old 3" square concrete surrounded by old railroad spikes, + 21.50' east from C-13 Dewitt, T5N-R2W, + 13.0' east from a 5' high woven wire fence and + 103.5' north from the railroad track. Distances in close accord with C&O Railroad R.O.W. Map. Accepted 3" square concrete with railroad spikes as perpetuation of corner.

Research conducted by Ingham County Survey and Remonumentation Project staff.

1 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

NW Corner, Section 5, T4N-R2W

Found 3" concrete surrounded by old railroad spikes in location described above:

Nail & tag, #18998, south side twin 5" Ash, WNW, 38.60'

Nail & tag, #18998, south side multi 4" Ash, NE, 6.88'

Nail & tag, #18998, west side twin 8" Ash, SE, 10.65'

Nail & tag, #18998, east side 8" Ash, West, 22.05'

C-13 Dewitt Twp., Clinton Co., 3" brass cap on 3" iron pipe, West, 21.50'



SIGNED BY Ronnie M. Lester

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

SIGNED BY _____

APPROVED AND SIGNED BY _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 17624



FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 20, 1971
REVISED MAY 14, 1973

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 6 PG 35

FILED

MAR 13 11 20 AM '80

REGISTER OF DEEDS

Paula Johnson
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. <u>4</u> N. <u>X</u> S. R. <u>2</u> E. <u>X</u> W.		C-3
2. PROPERTY CONTROLL- ING IN SECTION_____, T. _____ N. _____ S. R. _____ E. _____ W.		
3. MISCELLANEOUS PROPERTY IN SECTION_____, T. _____ N. _____ S. R. _____ E. _____ W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on January 28, 19 80, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C-3 A. Description of original monument and accessories and/or subsequent restoration:

Post set in original government survey by Musgrove Evans, February 10-27, 1827.
Corner referred to in a survey by T.J. Brown, Dep. County Surveyor, August 29, 1864.
Corner identified as a cement post in Cade's 1921 survey. No new mark set because Bateman disagrees with location as placed by Robb. (Cement post apparently set by Robb.)
Corner referred to in Recorded Subdivision Plats: Shirley Park, 1955 (L.19, p.19), and Stockman's Subdivision, date unknown (L.14, p.11).



C-3 B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

During investigation, found 1/2" pipe in square concrete monument + 20' east of east bank of the Grand River. Accepted 1/2" pipe in square concrete monument as that identified in Cade's survey as corner as there has been no evidence found to dispute location. Research conducted by Ingham County Survey and Remonumentation Project.

C-3 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SE Corner, Section 6, T4N-R2W
Found 1/2" pipe in square concrete monument in location described above:
Nail & tag, #18998, south side 20" Oak, WNW, 7.87'
Nail & tag, #18998, west side 8" Oak, North, 13.97'
Nail & tag, #18998, north side 4" Maple, East, 41.13'
Nail & tag, #18998, east side 24" Oak, South, 22.16'

SIGNED BY Ronnie M. Lester
SURVEYOR'S MICHIGAN REGISTRATION NO. 18998



SIGNED BY _____
APPROVED AND SIGNED BY Sam H. [Signature]
CHIEF OF SURVEY PARTY
REGISTERED LAND SURVEYOR
Ingham County Survey
and Remonumentation Project

SURVEYOR'S MICHIGAN REGISTRATION NO. 17624

1786

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 26, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

INGHAM COUNTY - LANSING TWP.

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER

6 16 43

FOR CORNERS OF --	LOCATED IN --	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. <u>4</u> N. <u>8</u> , R. <u>2</u> E. <u>W.</u>		<u>D-3</u>
2. PROPERTY CONTROLLING IN SECTION _____, T. _____ N. _____ S., R. _____ E. _____ W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____ N. _____ S., R. _____ E. _____ W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

FILED

MAR 21 8 32 AM '80

REGISTER OF DEEDS

Dana Johnson

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on January 22, 19 80, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- D-3 A. Description of original monument and accessories and/or subsequent restoration:
Post set in original government survey by Musgrove Evans, February 10-27, 1827.
Corner referred to in a survey by T.J. Brown, County Surveyor, August 29, 1864 (v.3, p.14).
Corner identified in Robb's notes as a "cement post 3" x 3" x 30 replacing a stone set by Bartholomew. This post was recovered by C.M. Cade in 1919... It was evidently at the intersection of fences running east and west and south and has been used by Bateman in surveys in this vicinity, being accepted by him as the true corner... Set a standard 1921 Mark." according to Cade's 1921 survey, p.6.
Corner referred to in Recorded Subdivision Plats: Beechenbrook, 1892 (v.2, p.13); Bassett's Subd., 1917 (v.6, p.21); Susan Park; 1956 (v.19, p.42); Jenison Park, 1957 (v.21, p.1).
- D-3 B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
During investigation, found 9" diameter concrete monument with 5/8" bar (Cade's Standard 1921 City Lansing monument) at south side of Muskegon Avenue + 658' east of centerline of Comfort Street. Accepted concrete monument with 5/8" bar as perpetuation of corner as called for by C.M. Cade.
Research conducted by Ingham County Survey and Remonumentation Project staff.

- D-3 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

S $\frac{1}{4}$ Corner, Section 5, T4N-R2W
Found 9" diameter concrete monument with 5/8" bar in location described above:
SE Corner of brick Board of Water and Light pump house, NW, 104.24' fd. only
Nail & tag, #18998, east side 18" Ash, North, 49.16' Gmc.
Nail & tag, #18998, southwest side 18" Maple, East, 18.18'
NE Corner of house #1425, SSW, 49.68'

SIGNED BY Ronnie M. Lester

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

SIGNED BY _____

APPROVED AND SIGNED BY _____

CHIEF OF SURVEY PARTY

Dana Johnson
DIRECTOR, Ingham County Survey
and Remonumentation Project

SURVEYOR'S MICHIGAN REGISTRATION NO. 17624

1791

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

6-43

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 6 PAGE 266

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. 4 N. 8, R. 2 18 W.	D-1
2. PROPERTY CONTROLLING IN SECTION_____	T. _____ N. S., R. _____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. S., R. _____ E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

FILED

FEB 13 '0 32 AM '85

REGISTER OF DEEDS

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Larry A. Bryan, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on September 27, 1984, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

D-1 Original monument and accessories obliterated.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-1 Found old triangular iron plate

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-1 North 1/4 Section 5
Set nail & tag East side 22" Hickory, S45°W, 9.57'
Set nail & tag North side 20" Hickory, S45°E, 10.40'
Northwest corner concrete headwall, N15°E, 36.50'
Centerline corner post foundation South 1/4 corner Section 32, T5N, R2W, West, 6.45'

SIGNED BY Larry A. Bryan DATE 2-12-85


SURVEYOR'S MICHIGAN REGISTRATION NO. 25832

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____



2014

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 20, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

6-266

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 6 289

FILED

For corners in

INGHAM
(County)

Located In:

Corner Code ##

1. Public Land Survey

T 4N. R 2W.

D-3

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

AUG 1 1 19 PM '86

REGISTER OF DEEDS

INDIAN COUNTY, MICH.

Register of Deeds Stamp & File Number

I, MARK W. WITALEC, in a field survey on JULY 3, 19 86,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:


FOUND 9" DIA. CONC. MON. WITH IRON
(PREVIOUSLY REC. IN L.6, P.43 OF CORNER RECORDS)
BELOW WITNESSES ARE PER L.6, P.43

✓ S.E. COR. BRICK B.W.L. PUMP HOUSE, N.W., 104.24' (GONE 7-3-86)
NAIL & TAG #18998 E. SIDE 18" ASH, NORTH 49.16' (GONE 7-3-86)
NAIL & TAG #18998 S.W. SIDE 18" MAPLE, EAST 18.18'
N.E. COR. HOUSE #1425, S.S.W. 49.68'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

9" DIA. CONC. MON. WITH IRON

EAST 18.18' NAIL & TAG S.W. SIDE 18" MAPLE ✓
S.S.W. 49.68' N.E. COR. HOUSE #1425 FOUNDATION ✓
N.E. 43.36' P.K. (SET) S.E. SIDE U.P. ✓
S.E. 7.3' CENTERLINE "CITY SURVEY MONUMENT" BOX ✓
S. 24.57' TO FOUND "T" IRON



Signed by

Mark W. Witalec

Date

8-1-86

Surveyor's Michigan License No.

30897

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, 2000, 2001, 2002
REVISED MAY 14, 1975
REVISED JAN. 1983

2036

6-289

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

INGHAM

(County)

Located In: CITY
OF LANSING

Corner Code #

FILED

JUL 28 10 30 AM '93

REGISTER OF DEEDS

Paula Johnson

INGHAM COUNTY, MICH.

Register of Deeds Stamp & File Number

1. Public Land Survey

T 4N. R 2W.

C-3

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, MARK W. WITALEC, in a field survey on JULY 1, 1993

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L.6, P. 35, INGHAM COUNTY LAND CORNER RECORDATION CERTIFICATE

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 4" SQUARE CONC. MONUMENT WITH 3/4" IRON PIPE CAST IN CENTER (MON. LEANS TO N.W. - USED CENTERLINE AT GROUND LEVEL)


THIS LOCATION VERIFIED BY A.P. NO. 11 MONUMENTATION:

1. S. 2638.98' TO COR. C-4 (2640' PER PLAT)
2. E. 694.27' TO CONC. MON. (695' PER PLAT)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

4" SQUARE CONC. MON.

- W.N.W. 8.0' TO N. & T. #18998 S. SIDE 22" OAK
N. 14.34' TO N. & T. #18998 W. SIDE 7" TREE
E. 41.1'± TO MAPLE STUMP
S. 21.70' TO N. & T. #18998 E. SIDE 34" OAK
E. 37.85' TO SPIKE IN N. SIDE VERT. TIMBER POST



Signed by

Mark W. Witalec

Surveyor's Michigan License No. 30897

7-22-1993

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS

REVISED MAY 14, 1975
REVISED JAN., 1983

2477

7-331

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in

Ingham Located In: City of Lansing Corner Code ##
 (County)

1. Public Land Survey T 4 N R 2 W D-1
 T _____ R _____
 T _____ R _____
 T _____ R _____

2. Property Controlling S _____ T _____ R _____
 in Section S _____ T _____ R _____

3. Miscellaneous S _____ T _____ R _____
 Property in Sec. S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

DEC 2 9 23 AM '94

REGISTER OF DEEDS

Paula Johnson
 INGHAM COUNTY, MICH.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Mark W. Witalec Oct. 27, 1994

I, _____, in a field survey on _____, 19____,
 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
 current manual of survey instructions of the United States Department of the Interior, Bureau of Land
 Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
 Court of Law; established, re-established, monumented, re-monumented recovered, found as
 expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
 on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

Triangular iron plate (Per L. 6, P. 266, Ingham County Land Corner Recordation Certificates)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" iron pipe with surveyor's identification cap #25828

*Remaining witnesses from the corner certificate noted above (L. 6, P. 266) check well with this location.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 3/4" iron pipe with surveyor's identification cap #25828

S 45° W 9.67' to nail and brass tag #25832 in E. side of 18" hickory tree
 S 45° E 10.40' to nail and brass tag #25832 in N. side of hickory tree
 N 15° E 36.44' to 1.1' wide concrete headwall (W'ly corner of SW'ly. end of headwall)
 W 3.87' to form nail & tag in S. side of 5'± high, 12"± dia. wood fence post
 S 1.4' to 5' high chain link fence
 W 8.4' to 5' high chain link fence
 W 6.48' to found iron with identification cap #25828 in 18"± dia. concrete
 E.ly 2625.62' to Cor. E-1 (NE cor., Section 5)



Signed by

Mark W. Witalec
 30897

Date

11-23-1994

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
 REVISED MAY 14, 1975
 REVISED JAN. 1983

2763

8-419

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ingham
 (County)

Located In:
 City of Lansing
 4 N 2 W

Corner Code ≠#

E-1

FILED

DEC 29 23 AM '94

REGISTER OF DEEDS

Paula Johnson
 INGHAM COUNTY, MICH.

Register of Deeds Stamp & File Number

1. Public Land Survey

T _____ R _____

T _____ R _____

T _____ R _____

T _____ R _____

2. Property Controlling
in Section

S _____ T _____ R _____

S _____ T _____ R _____

3. Miscellaneous
Property in Sec.

S _____ T _____ R _____

S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Mark W. Witalec, in a field survey on November 22, 1994, 19_____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1/2" bar in 3/4" octagon pipe

(Per L. 6, P. 17, Ingham County Land Corner Recordation Certificates)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" smooth rod with surveyor's identification cap #28409 in Sheridan Road pavement
 *Witnesses remaining from L. 6, P. 17, Ingham County L.C.R.C.'s check well with this location.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set a monument box over the found rod with identification cap #28409

South 33.00' to found iron #25828

NW 126.22' to SE corner of house foundation (House #642)

NE 33.62' to form nail and tag in west side of utility pole

SE 27.52' to nail and tag #18998 in west side of utility pole

SSW 40.15' to nail and tag #18998 in west side of 28" cottonwood tree

South 2.5'± to the south edge of 24'± wide asphalt pavement (Sheridan Road)

Signed by

M. W. Witalec

Date

11-23-1994

Surveyor's Michigan License No.

30897



FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
 REVISED MAY 14, 1975
 REVISED JAN., 1983

2764

8-420