## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

			Libei	8 7 PAGE 217
FOR CORNERS OF -: LOCA	ATED IN-:	CORNER CODE	NUMBER	FILED
I. PUBLIC LAND SURVEY 4 T.	1 \$. R. 1 W.	F-2, G-2		•
2. PROPERTY CONTROLL- ING IN SECTION, T	N. E.		Hov	28 12 44 PM 'SD
3. MISCELL AMERICA				- or needs
PROPERTY IN SECTION,T	S., R W.			
4. LOT NO, RECORDED I	PLAT		'`	ម្រឹក
5. PRIVATE CLAIMS.			REGISTER	OF DEEDS STAMP AND
the corner points mentioned in lines 1 am re-established, monumented, re-monuner and rules therefore as required in the cut Bureau of Land Management or by a dec and 5 above were, in a field survey on as expressed below and in conformance we Decree of a Court of law:  1. Description of original monument and F-2 CORNER NOT SET IN OF G-2 UNKNOWN	nted, recovered or re- rrent manual of surve- cree of a court of law.  with the rules of the Manual of surve-	ter's survey on	dl below and in conform he United States Depart to the corner points m covered, restored, estab and of Registration for I	mauce with regulations artment of the Interior. mentioned in lines 3, 4
B. Description of corner evidence found F-2 CORNER SET BY BOSS REC FOUND ORIGINAL BAR & CA G-2 CORNER SET & RECORDED B FOUND BOSS BAR & CAP 28 CORNER WAS IN CLOSE ACC	L. 3, PAGE 533 AP & WITNESSES 1 BY BOSS, L. 3, 1 B' WEST OF ! BAG	TAGS PAGE 533		
* Ducamental and a				
C. Description of monument for corner in F-2 BOSS BAR & CAR 0.3 PROPERTY.	ud accessories establis	shed to perpetuate	locating the position of	the corner:
F-2 BOSS BAR & CAP 0.3 FEE NO5°W 9.94', NAIL WEST WEST 35.10', NAIL SOUT S75°W 31.6', NAIL SOUT	H/SIDE TRIPLE 6	HICKORY	4-WAY FENCE INT	ERSECTION
G-2 4" BAR IN INTERSECTION	OF DRAIN			
N10°E 28.35' N & T, WE N85°W 17.92' LESTER BA	ጽ ዴ <i>ር</i> ልው			
WEST 27.77' BOSS BAR & WEST 20.8' CEDAR FENCE	CAP POST			
SIGNED BY Son / Lelso	()	<b>.</b>	TEAUG. 22.1	90 h.
			reaug221	OF MICH
SURVEYOR'S MECHICAN REGISTRATI FOR STATE AND UNITED STATES AC				RON
			A A	ELSEL LAND
GIGNED BYCHIEF OF	SURVEY PARTY	DA"	re su su	RVEYOR AS
ALLOOLED WAD SIGNED BA	MICHIGAN REGISTERED LAN	D SURVEYOR		18994
			Think the	LAND STATE
URVEYOR'S MICHICAN REGISTRATI	ON NO			sittle
65			STATE BOARD OF REGIS	TRATION, JAN, 28, 1971


### LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. PA 1970 19 500

FOR CORNERS OF -:	LOCATED IN~:	CORNER CODE NUMBER	FILED
1. PUBLIC LAND SURVEY	4 T. 1 8 R. 1 W	F-2, G-2, G-3	
2. PROPERTY CONTROLL- ING IN SECTION-		,	Feb 3 8 39 8H 7
3. MISCELLANEOUS PROPERTY IN SECTION			REGISTER OF DEEDS
4. LOT NO, RE		P To the state of	INGHAM COUNTY MICH
	CORDED PLAT	de de la company	TRUTAN COUNTY PROTE
5. PRIVATE CLASS			REGISTER OF DEEDS STAMP AND FILING NUMBER
restored as expressed below of survey instructions of the court of faw. Furthermon  19 formance with the rules of t w:	and in conformance with re United States Department to, that the corner points , found, recovered, restored the Michigan State Board of	gulations and rules therefore of the Interior, Bureau of Land mentioned in lines 3, 4 and 1 , established or re-established	ted, re-monumented, recovered or as required in the current manual d Management or by a decree of a 5 above were, in a field survey on d as expressed below and in contors or by a Decree of a Court of
F-2 1/2" iron set (fen G-2 1/2" iron set (iro	ce intersection) n 3"West of east ban	applied in restoring or re-esta c of stream)	nb. shing corner:
F-2 1/2" iron set (fen	ce intersection) n 3"West of east ban		ub. shing corner:
F-2 1/2" iron set (fen G-2 1/2" iron set (iron G-3 1/2" iron set (fen G-3 1/2" iron set (fen C. Description of monumententer Section, Sec. 4 W. 31.60 Nail S/S 12" treest 35.10 Nail S/S 10" tw. 9.93 Nail W/S 4" tree 1/4 corner, Sec. 4 est 28.00 iron set 17.95 Nail S/S 4" treest 17.95 Nail S/S 4" treest 17.95 Nail S/S 4" treest 28.00 iron set	ce intersection) n 3'West of east ban ce intersection)  for corner and accessorie:	c of stream}	cating the position of the comer:
F-2 1/2" iron set (fen G-2 1/2" iron set (iron G-3 1/2" iron set (fen G-3 1/2" iron set (fen C. Description of monument enter Section, Sec. 4 W. 31.60 Nail S/S 12" trest 35.10 Nail S/S 10" trest 35.10 Nail S/S 4" tree 1/4 corner, Sec. 4 est 28.00 iron set	ce intersection) n 3'West of east ban ce intersection)  for corner and accessorie:	c of stream) s established to perpetuate lo , Sec. 4 Nail S/S 6" Thorn tre O Nail N/S 4:" Thorn t	cating the position of the comer:
F-2 1/2" iron set (fen G-2 1/2" iron set (iron G-3 1/2" iron set (fen G-3 1/2" iron set (fen C. Description of monumententer Section, Sec. 4 W. 31.60 Nail S/S 12" treest 35.10 Nail S/S 10" tw. 9.93 Nail W/S 4" tree 1/4 corner, Sec. 4 est 28.00 iron set 17.95 Nail S/S 4" treest 17.95 Nail S/S 4" treest 17.95 Nail S/S 4" treest 28.00 iron set	ce intersection) n 3"West of east ban ce intersection)  for corner and accessorie:	c of stream) s established to perpetuate lo , Sec. 4 Nail S/S 6" Thorn tre O Nail N/S 4:" Thorn t	cating the position of the comer:
F-2 1/2" iron set (fen G-2 1/2" iron set (iro G-3 1/2" iron set (fen G-3 1/2" iron set 4 W. 31.60 Nail S/S 12" treest 35.10 Nail S/S 10" tree 1/4 corner, Sec. 4 est 28.00 iron set 17.95 Nail S/S 4" tree W. 24.79 Nail N/S 4" tree W. 24.79 Nail N/S 4" tree	ce intersection) n 3"West of east ban ce intersection)  for corner and accessories G-3 SE corner ee Due East 2.43 ree Due North 3.1 Due West 85.4	c of stream)  s established to perpetuate lo , Sec. 4 Nail S/S 6" Thorn tre D Nail N/S 4:" Thorn t 2 Nail S/S 18" tree  DATE	cating the position of the comer:
F-2 1/2" iron set (fen G-2 1/2" iron set (iro G-3 1/2" iron set (iron G-3 1/2" iron set (fen C. Description of monument senter Section, Sec. 4 W. 31.60 Nail s/S 12" trest 35.10 Nail s/S 10" tw. 9.93 Nail W/S 4" treet 1/4 corner, Sec. 4 est 28.00 iron set 17.95 Nail s/S 4" tree W. 24.79 Nail N/S 4" tree SIGNED BY	ce intersection) n 3"West of east ban ce intersection)  for corner and accessorie: G-3 SE corner ee Due East 2.43 ree Due North 3.1 Due West 85.4	c of stream)  s established to perpetuate lo , Sec. 4 Nail S/S 6" Thorn tre D Nail N/S 4:" Thorn t 2 Nail S/S 18" tree  DATE	cating the position of the comer: se tree
F-2 1/2" iron set (fen G-2 1/2" iron set (iro G-3 1/2" iron set (iron G-3 1/2" iron set (fen G-3 1/2" iron set 35.10 Nail s/s 12" trest 35.10 Nail s/s 10" two 9.93 Nail W/S 4" treet 1/4 corner, Sec. 4 set 28.00 iron set 17.95 Nail s/s 4" treet 1/2 1/2 Nail s/s 4" treet 1/2 Nail s/s	ce intersection) n 3"West of east ban ce intersection)  for corner and accessorie: G-3 SE corner ee Due East 2.43 ree Due North 3.1 Due West 85.4  ree Colstration No: 1357	c of stream)  s established to perpetuate lo , Sec. 4 Nail S/S 6" Thorn tre 0 Nail W/S 4;" Thorn t 2 Nail S/S 18" tree  DATE 4	cating the position of the comer:
F-2 1/2" iron set (fen G-2 1/2" iron set (iro G-3 1/2" iron set (iron G-3 1/2" iron set (fen G-3 1/2" iron set 35.10 Nail S/S 12" treet 35.10 Nail S/S 12" treet 35.10 Nail S/S 4" treet 28.00 iron set 17.95 Nail S/S 4" tree M. 24.79 Nail N/S 4" tree M. 24.79 Nai	ce intersection) n 3"West of east ban ce intersection)  for corner and accessories G-3 SE corner ee Due East 2.43 Tree Due North 3.1 Due West 85.4  EGISTRATION NO: 1357  STATES AGENCIES:	c of stream)  s established to perpetuate lo , Sec. 4 Nail S/S 6" Thorn tre 0 Nail W/S 4;" Thorn t 2 Nail S/S 18" tree  DATE	cating the position of the comer: se tree
F-2 1/2" iron set (fen G-2 1/2" iron set (iro G-3 1/2" iron set (iron G-3 1/2" iron set (fen G-3 1/2" iron set 35.10 Nail s/5 12" trest 35.10 Nail s/5 10" trest 35.10 Nail s/5 4" treet 1/4 corner, Sec. 4 est 28.00 iron set 17.95 Nail s/5 4" treet 17.95 Nail s/5 Nail s/5 Nail s/5 Nail s/5 Nail s/5	ce intersection) n 3"West of east ban ce intersection)  for corner and accessories G-3 SE corner ee Due East 2.43 ree Due North 3.1 Due West 85.4  EGISTRATION NO. 1357 STATES AGENCIES:	c of stream)  s established to perpetuate lo , Sec. 4 Nail S/S 6" Thorn tre D Nail N/S 4t" Thorn t 2 Nail S/S 18" tree  DATE  DATE  LAND BURNESON DATE:	cating the position of the comer:
F-2 1/2" iron set (fen G-2 1/2" iron set (iro G-2 1/2" iron set (iron G-3 1/2" iron set (fen G-3 1/2") set	for corner and accessories G-3 SE corner ee Due East 2.43 ree Due North 3.1 Due West 85.4  FORTATION NO: 1357  STATES AGENCIES: CHIEF OF SURVEY FASTY MICRORAR MINIMAGEN	c of stream)  s established to perpetuate lo , Sec. 4 Nail S/S 6" Thorn tre 0 Nail W/S 4;" Thorn t 2 Nail S/S 18" tree  DATE	cating the position of the comer: se tree
F-2 1/2" iron set (fen G-2 1/2" iron set (iro G-3 1/2" iron set (iron G-3 1/2" iron set (fen G-3 1/2" iron set 35.10 Nail s/5 12" trest 35.10 Nail s/5 10" trest 35.10 Nail s/5 4" treet 1/4 corner, Sec. 4 est 28.00 iron set 17.95 Nail s/5 4" treet 17.95 Nail s/5 Nail s/5 Nail s/5 Nail s/5 Nail s/5	ce intersection) n 3"West of east ban ce intersection)  for corner and accessorie: G-3 SE corner ee Due East 2.43 ree Due North 3.1 Due West 85.4  EGISTRATION NO: 1357 STATES AGENCIES: CHIEF OF SUMMER PLANTY Y. MICHIGAN MICHIGAN GGISTRATION NO.	c of stream)  s established to perpetuate lo , Sec. 4 Nail S/S 6" Thorn tre Dail W/S 4;" Thorn t  Nail S/S 18" tree  DATE  LAND SURVEYOR  DATE	cating the position of the comer:  BE  THE STATE OF THE S


## CORNER NUMBERING CODE DIAGRAMS FOR IDENTIFYING LAND CORNER RECORDATIONS AND INDEXING

FOR PUBLIC LAND SURVEY CORNERS IN THE T. J.M., R. A.M. (MENTIONED OVER)



Apply letter prefix for corner points encircled above for identifying corner recordation numbers over.

FOR PROPERTY CONTROLLING AND MISC. PROPERTY CORNERS WITHIN THE SECTION (MENTIONED OVER AND EXCLUDE LOT CORNER)




- 1. Above coded numbers are positioned on 1/16 fractional lines of the section.
- 2. Township corner code numbers shall be applied to corners of above typical section not numbered.
- Miscellaneous property corners within a section, located at points other than numbered above, shall be referenced to at least two of above corner code numbers.
- d. Private claim corners to be tied to rectangular land corners if possible sketch required below.

EXPLANATORY SKETCH IF NECESSARY --- BELOW

S逆窓でゆう。\*\*のひろのひ 冷水

### TOWNSHIP CORNER NUMBERING CODE DIAGRAM



### TOWNSHIP CORNER NUMBERING CODE DIAGRAM

1 A	В	C D	E F	<b>G</b> H	1 J	K L
2	- 6	5	<b></b>	3	J	T O
з 📙					↓ ↓	
4	 7	<b>-</b>	9 -	<b>-</b> 60-	<del> </del> <del> </del> <del> </del> <del> </del>	12 —
5		<b>-</b>	<b> </b>	<b>-</b>	ļ .	
6	- 18 —		16	15 —	14-	13
7	<b>.</b>	ļ <b>.</b>			<b> </b>	┥—↓
8	- 19 <u>—</u>	20 -	21 _	22 —	23_	24
9 📥	┿	<b>-</b>	- <b>-</b>			
10	-30 <u>—</u>	   29 -	28	27	26	25
11 -	+-	<del> </del>			-	<del> </del>
12	 -31	  32-	33 —	34-	35	 36
13	Щ.	<u> </u>				

### CORNER INDEX

6 18 17 16 7 8 19 20 21 9 10 30 29 28 11 12 31 32 33 13	22 23 24	G-9 Liber 7 pg. 268 G-10 G-11	K-2 Siber 4 pg. 347 -> K-3 Siber 9 pg. 302 K-4 Liber 9 pg. 167 K-5 K-6 K-7 Si-8 pg. 75 K-8 K-9 K-10 K-11 Siber 6 pg. 13
	CODE NO. FILING NUMBER	G-12 G-13	K-12 Lider 5 fg-15
A-1  A-2  A-3  A-4  A-5  A-6  A-6  A-7  A-8  A-9  A-10  A-11  A-12	D-1 D-2 D-3 D-4 Like 6 pg. 167 D-6 D-7 Like 6 pg. 167 D-8 D-9 Like 9 pg. 328 D-10 D-11	H-1 Liber 8 pg. 148 H-2 Liber 8 pg. 144 H-3 Liber 5 pg. 380 -> 2H-4 Liber 8 pg. 191 H-5 Liber 8 pg. 146 H-6 H-7 H-8 H-9 H-10	L-1 Lible. 9 pg. 275 L-2 Lible. 9 pg. 277 L-3 L-4 L-5 L-6 L-7 Lible Pg. 77 L-8 L-9 L-10 L-11
B-1 B-2 B-3 B-4 I/-//3 B-5 B-6 I/-//7 B-7 B-8 B-9 B-10 B-11 L-//, P. 238 B-12 B-13 L-//, P 240	E-1 E-2 E-3 E-4 Liber 6 pg. 73 E-5 Siber 6 pg. 73 E-6 Ciber 6 pg. 167 E-7 Liber 5 pg. 178 -7 E-8 E-9 Liber 9 pg. 328 E-10 E-11 E-12 E-13	1-1 Li. 8 pg. 122 1-2 Li 7 pg. 403 1-3 Li 8 pg. 195 1-4 Li 8 pg. 193 1-5 Li 8 pg. 189 1-6 1-7 1-8 1-9 1-10 1-11	M-1 M-2 Like 9 pg 151 M-3 Like 9 pg 284 M-4 M-5 M-6 M-7 M-8
C-4 24 10 29. 310 C-5 11 10 29. 308 C-6 11-107 C-7 Liker 5 pg. 57/1-109 C-8 C-9 5 P 36 41-7742 C-10 41- P244 C-11 Liber 5 pg. 21 C-12 4-11 P246	F-6 F-7 Liter 5 pg. 180 F-8 Li.7pg. 267	1-12 ———	E-7 Li. 6 pg. 167  G-2 Li 8 pg. 197  H-3 Li 8 pg. 248  M-2 Li 9 pg. 282  J-2 Li 9 pg. 296  K-2 Li 9 pg. 300  F-9 Li 9 pg. 319  A-7 Li 10 Lg. 314

# LAND CORNER RECORDATION CERTIFICATE LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -: Sec.	LOCATED IN -:	CORNER CODE NUMBER	FILED
1. PUBLIC LAND SURVEY 5	T. 1 N. R. 1	<u>C-2</u>	
2 1010/2017/10/2017	N. E. V. S., R. W.		FEB 16 4 06 PH '72
3. MISCELLANEOUS PROPERTY IN SECTION			Mia Bull Humphry
4. LOT NO, RECO			менам солиту, <b>місн</b> .
5. PRIVATE CLAIMS			
I. Ronnie M. Lester			REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentioned in field survey on December restored as expressed below an of survey instructions of the Uncourt of law Furthermore, December 23 1971. f	23 1971, established, d in conformance with regul ited States Department of that the corner points me ound, recovered, restored established.	re-established, monument ations and rules therefore a he luterior, Bureau of Land ntioned in lines 3,4 and 5 trablished or recognitional	P.A. 74, Michigan P.A. of 1970, code diagram—over) were, in a ed, re-monumented, recovered or s required in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in construction, by a Decree of a Court of
A. Description of original monu	ment and accessories and/	or subsequent restoration.	
	nument and accessori		
_		es oblitterated.	
		•	
	:		
B. Description of corner evidence	e found and/or method app	lied in restoring or re-estab	lishing corner:
Set 1/2" ba Section on	r on line between NW fence line to West. n acceptable accord	corner and SW corner Measured distances of with original government	of
C. Description of monument for	corner and accessories es	tablished to pornature to a	ala al estado
1/2" bar 2.0	West centerline of	F Thirthin Dead	ting the position of the corner:
Nail & Tag S Nail & Tag S	South side 20" boxeld North side 20" walnut West side 12" twin me	der, West 37.50'	
	i.		
SIGNED BY The Property	m. Esta	DATE 2	an 11. 1972
SURVEYOR'S MICHIGAN REGIS			(SEAL)
FOR STATE AND UNITED STA	TES AGENCIES:	the second constraint of the second second	T SEAL )
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED BY.	30 CHIGÁN RÉGISTERED LANÓ	SURVEYOR DATE	(SEAL)
The second second	!		
SURVEYOR'S MICHIGAN REGIST FORM No. MLM735 SOUNCEDAY BROWN & CO., RALAMAZOO, MICH.	FORM A	PPROVED BY MICHIGAN STATE BOA	HD OF REGISTRATION, JAN. 28, 1971
BRI BROW & COLUNAL AMAZON, MICH.	OISTRIB	UTED BY MICHIGAN SOCIETY OF	REGISTERED LAND ELLOUPSON

# Ingham County NE Corner, Section 5, TIN, RIW LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

				=
FOR CORNERS O	Sec.		CORNER CODE NUMBER	FILED.
1. PUBLIC LAN	D SURVEY 5	$T_{-}$ $=$ $\frac{1}{\Phi}$ , $R_{-}$ $=$ $\frac{1}{W}$	E-1	P 10 4
2. PROPERTY C	CONTROLL.	.т S., R W.		FEB 16 4 06 PH 172
3 MISCRITANE	ALIS		THE STATE OF	REGISTER OF DEEDS
PROPERTY	N SECTION	St	and the second second second second second	Mia Bill Humphray INGHAM COUNTY, MICH.
4. LOT NO	, RECO	RDED PLAT	The state of the s	
5. PRIVATE CL.	AIMS	ili. Mirani wa kata masa masa kata ka ka		95010760 00 0000
				REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner point field survey of restored as export survey instruction of law. December 23 formance with law:	n December  n Dece	23 19 71. established in conformance with regulated States Department of that the corner points mound, recovered, restored, e Michigan State Board of R	tiffied with circles on index I, re-established, monument lations and rules therefore a the Interior, Bureau of Land entioned in lines 3, 4 and 5 stablished or re-established egistration for Land Surveyo	P.A. 74, Michigan P.A. of 1970, code diagram – over) were, in a rd, re-monumented, recovered of a required in the current manual Management or by a decree of a above were, in a field survey of as expressed below and in control or, by a Decree of a Court of
A. Description	of original monu	ment and accessories and	or subsequent restoration;	
	Original m	onument and accessor	ies obliterated.	
B. Description	of corner eviden	ce found and/or method ap	plied in restoring or re-estab	lishing corner:
	10" maple, NW Corner 1	ds 1" pipe 7°E, 28.22' N27°E, 78.46' leadwall S69°E, 36.0 leadwall N72°E, 35.9	5' 6'	
C. Description	of monument for	corner and accessories e	stablished to perpetuate loca	ating the position of the corner:
			ast edge of Northboun	
	W Corner I	SE side 18" ash NNE neadwall S69°E, 36.0 neadwall N72°E, 35.9	51	
	$\mathcal{L}$			
SIGNED BY	Marine	711 Copes		in 11,1972
SURVEYOR'S	HCHIGAN REGI	STRATION NO. 1899	98	(SEAL)
FOR STATE AN	AD UNIȚED STA	TES AGENCIES:	er een 'n Merkeling in 'n 1942 in 1942	er sente e menument e sellake a medid ambilishings.
SIGNED BY L		CHIEF OF SURVEY PARTY	DATE	
APPROVED AN	OSIGNED BY		ts 4 mms	
		MICHIGAN PEGISTERED LAN	DATE DATE	( SEAL )
1	01125			
Form No. ML 9735		TRATION NO.	APPROVED BY 11 GAMES	
DOUBLEDAY BROS, & CO.	. FALAM 4 200, MICH	DISTRI	BUTED BY MICHIGAN STATE 80; BUTED BY MICHIGAN SOCIETY OF	RD OF REGISTRATION, JAN. 28, 1971 REGISTERED LAND SURVEYORS

### INGHAM COUNTY

## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 1 P. 34

FOR CORNERS OF~:	Sec.	LOCA	TED	ŧN−;			CORNER CODE NUMBER	FILED
1. POBLIC LAND SURVEY		т.	1_	N. <b>\$</b> . R.	l	3	E-2	
2. PROPERTY CONTROLL- ING IN SECTION		: T		N. S., R.		E.		FEB 16 4 06 PM *72
3. MISCELLANEOUS PROPERTY IN SECTION								Mia Bell Humphry
4, LOT NO,	RECORI	око р	i.at				<del>-</del> .	іменам социту, місн.
5. PRIVATE CLAIMS							· - ····	REGISTER OF DEEDS STAMP AND
Ronnie M. Leste			. (	lo he	eby c	ertif	y that under requirements of	P.A. 74, Michigan P.A. of 1970

1. Ronnte M. Lester do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on December 23 19.71, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3.4 and 5 above were, in a field survey on December 23 19.71, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monoment and accessories and or subsequent testoration:

Original monument and accessories obliterated.

B. Description of corner evidence found and or method applied in restoring or re-establishing corner:

Found 3/4" iron rod on line between NE & SE Corners of Section on line with fence to East.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" iron centerline road on fence line to East

Wail & Tag SW side 10" crabapple NW, 49.50' Wail & Tag NW side 24" stump SW, 56.60' SW Corner of iron fence post, East, 34.25'

SIGNED BY

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

FOR STATE AND UNITED STATES AGENCIES:

DATE

SPACE OF SCHOOL PART SURVEY PART.

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

1 SEAL 1

SURVEYOR'S MICHGAN REGISTRATION NO.

Form No. MLM735
HOME COAY BROS. & CO., SALAMAZOO, MICH.

## FILING REQUIREMENT OF ACT 74. MICH.

do horeby certify that under requirements of P.A.  corner points mentioned in lines 1 and 2 above were, an a field survey on November 19 established, manumented, re-monumented, recovered or restared as expressed below and in certification as required in the current manual of survey instructions of the United States ream of Land Management or by a decree of a court of law. Furthermore, that the corner pair 15 above were, in a field survey on November 19 1975, Jound, recovered, restored, restored, expressed below and in conformance with the rules of the Michigan State Board of Registration cree of a Court of law.  Description of original monument and accessories and or subsequent restoration:  E-3 Original monument and accessories obliterated.  Description of corner evidence found and or method applied in restoring or re-establishing corner. Found 3/4" from rod .1" under asphalt.  Description of monument for corner and accessories astablished to perpetuate locating the position of the first of	FILED
INGLES SECTION 1 S. R. & W.  INCLUDED THE COURT OF THE C	
PROPERTY IN SECTION 1  RECORDED PLAT  DESCRIPTION RECORDED PLAT  And hereby certify that under requirements of P.A.  Course points mentioned in lines I and 2 above were, in a field survey on November 15 in the stabilished, monumented, re-monumented, recovered or restored as expressed below and in control rules therefore as required in the current information of law. Furthermore, that the corner points were, in a field survey in Movember 19 1975, hound, recovered, restored, expressed below and in conformance with the rules of the Michigan State Board of Registration cree of a Court of law.  Description of original monument and accessories and or subsequent restoration:  E-3 Original monument and accessories obliterated.  Description of corner evidence found and/or method applied in restoring or re-establishing corner and accessories obliterated.  Description of monument for corner and accessories astablished to perpetuate locating the position of monument for corner and accessories astablished to perpetuate locating the position of monument for corner and accessories astablished to perpetuate locating the position of monument for corner and accessories astablished to perpetuate locating the position of monument for corner and accessories astablished to perpetuate locating the position of monument for corner and accessories astablished to perpetuate locating the position of matrix and the first property of th	
Course M. Young do hereby certify that under requirements of P.A. corner points mentioned in lines I and 2 above were, in a field survey on November 14 established, manumented, re-monumented, recovered or restored as expressed below and in clouds therefore as required in the current manual of survey instructions of the United States ream of Land Management of by a decree of a court of law. Furthermore, that the corner point is above were, in a field survey on November 19 19.75 hound, recovered, restored, expressed below and in conformance with the rules of the Michigan State Board of Registration cree of a Court of law.  Description of original monument and accessories and or subsequent restoration:  E-3 Original monument and accessories obliterated.  Description of corner evidence found and or method applied in restoring or re-establishing corner. The properties of the properties	APR 13 9 31 AH T
Ceouge M. Young do hereby certify that under requirements of P.A. corner points mentioned in lines 1 and 2 abine were, in a field survey on November 15 stablished, manumented, re-monumented, recovered or restored as expressed below and in claudes therefore as required in the current manual of survey instructions of the United States reau of Land Management or by a decree of a court of law. Furthermore, that the corner point is above were, in a field survey on Movember 19 19.75, found, recovered, restored, expressed below and in conformance with the rides of the Michigan State Board of Registration cross of a Court of law.  Description of original monument and accessories and or subsequent restoration:  E-3 Original monument and accessories obliterated.  Description of corner evidence found and or method applied in restoring or re-establishing corner. Pound 3/4" from rod .1' under asphalt.  Description of monument for corner and accessories established to perpetuate locating the position of the line of line of the line of the line of line of the line of line	Paula Johnson
Corner points mentioned in lines I and 2 above were, in a field survey on November 15 stabilished, manimented, re-monumented, recovered or restared as expressed below and in a rules therefore as required in the current manual of survey instructions of the United States reau of Land Management or by a decree of a court of law. Furthermore, that the corner point is above were, in a field survey on November 19 1975, bound, recovered, restored, expressed below and in corner points and in control law. Furthermore, that the corner points are not a field survey on November 19 1975, bound, recovered, restored, expressed below and in conformance with the rules of the Michigan State Board of Registration cross of a Court of law.  Description of original monument and accessories and or subsequent restoration:  E-3 Original monument and accessories obliterated.  Description of corner evidence found and or method applied in restoring or re-establishing corner.  E-3 Found 3/4" from rod .1' under asphalt.  Description of incomment for corner and accessories astablished to perpetuate locating the position of the first of	INCHAS COUNTY, MICH
Description of corner evidence found and or method applied in restoring or re-establishing corner.  E-3 Found 3/4" iron rod .1' under asphalt.  Description of monument for corner and accessories established to perpetuate locating the position of the properties of	1975, establish onformance with regulation Department of the Interiors are the interiors and the interiors are the interiors.
Description of corner evidence found and or method applied in restoring or re-establishing corner.  E-3 Found 3/4" iron rod .1' under asphalt.  Description of monument for corner and accessories established to perpetuate locating the position of mail in 18" Maple N 45° E 60.55'  Nail in 18" Maple N 45° E 60.55'  Nail in 4" Elm S 89° E 37.11'  Nail in 18" Walnut S 25° E 99.50'  NA 10 1.880  DATE APRIL 11,  RECISTRATION NO. 17640	
Description of monument for corner and accessories established to perpetuate locating the positive of Mail in 18" Maple N 45° E 60.55'  Nail in 4" Elm S 89° E 37.11'  Nail in 18" Walnut S 25° E 99.50'  NED BY  DATE APRIL 11,  RIVEYOR'S MICHIGAN RECISTRATION NO. 17640	
Description of monument for corner and accessories established to perpetuate locating the positive of Mail in 18" Maple N 45° E 60.55'  Nail in 4" Elm S 89° E 37.11'  Nail in 18" Walnut S 25° E 99.50'  NED BY  DATE APRIL 11,  RIVEYOR'S MICHIGAN RECISTRATION NO. 17640	
Description of monument for corner and accessories established to perpetuate locating the positive of Mail in 18" Maple N 45° E 60.55'  Nail in 4" Elm S 89° E 37.11'  Nail in 18" Walnut S 25° E 99.50'  NED BY  DATE APRIL 11,  RIVEYOR'S MICHIGAN RECISTRATION NO. 17640	
Description of monument for corner and accessories established to perpetuate locating the positive of Mail in 18" Maple N 45° E 60.55'  Nail in 4" Elm S 89° E 37.11'  Nail in 18" Walnut S 25° E 99.50'  NED BY  DATE APRIL 11,  RIVEYOR'S MICHIGAN RECISTRATION NO. 17640	
E-3 Nail in 18" Maple N 45° E 60.55' Nail in 4" Elm S 89° E 37.11' Nail in 18" Walnut S 25° E 99.50'  NED BY  DATE APRIL 11, RVEYOR'S MICHIGAN RECISTRATION NO. 17640	
E-3 Nail in 18" Maple N 45° E 60.55' Nail in 4" Elm S 89° E 37.11' Nail in 18" Walnut S 25° E 99.50'  NED BY  DATE APRIL 11, RVEYOR'S MICHIGAN RECISTRATION NO. 17640	ion of the name.
RVEYOR'S MICHIGAN RECISTRATION NO. 17640	
RVEYOR'S MICHIGAN RECISTRATION NO. 17640	1978
) One was	(SEAL)
R STATE AND UNITED STATES AGENCIES:	er europ een
NED BYDATEDATE	
PROVED AND SIGNED BYDATE	
MICHIGAN REGISTERED LAND BURYEYOR	(SEAL)
EVEYOR'S MICHICAN REGISTRATION NO	
FORM APPROVED BY MICHIGAN STATE BOARD OF	

# FILING REQUIREMENT OF ACT 74. MICH. PA.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	, LER 4 To 343
1. PUBLIC LAND SURVEY	T. 1 8, R. 1	ж.	FILED
		W	,,,,
2. PROPERTY CONTROLL. ING IN SECTION——— 3. MISCELLANEOUS		w	SEP 13 10 33 AH "?
PROPERTY IN SECTION	,T S., R (	E.	REGISTER OF DEEDS
4. LOT NO, REC	ORDED PLAT		There Johnson
5. PRIVATE CLAIMS			INGHAM COUNTY, MICH
			REGISTER OF DEEDS STAMP AND FILING NUMBER
re-established, monumented, re- and rules therefore as required i Bureau of Land Management or and 5 above were, in a field surve as expressed below and in confor Decree of a Court of law:	monumented, recovered or in the current manual of su by a decree of a court of la ey on	restored as expressed below an rvey instructions of the United w. Furthermore, that the corn, 19found, recovered, ree Michigan State Board of Regis	of P.A. 74, Michigan P.A. of 1970, 16
<ul> <li>A. Description of original monu</li> <li>C-3</li> </ul>	ment and accessories and/o	r subsequent restoration:	
May 1, 1854 (v.2, p 25, 1873 (v.3, p.72 date unknown. Corner identified as and as a stone in ti dated Jan, 1, 1969	1983, by T.J. Brow 2), and in Miscellan a pointed stone by the Ingham County Ro	aa commission lecolus,	y Surveyor, dated a survey dated April ecords, surveyor and Surveyor, date unknown, revised grid map,
east of centerline or Found 1.3' x 1.0' lan numerous pieces of contents and and + 1.0' are in accord with the Road Commission Record Barryman in survey not content and the second second and the second and cover in 1 Nail & tag, #18998 w	f Tuttle Road and + rge, pointed, blue rockery, 2.0' benea rockery by Jacks of the center hose given by Jacks rds. Accepted pointed above. Excavare echacitist accessories estated in TIN-RIW a monument with ½"; location of large by the rest side (8" which is the second of the second	2.5 north of the centrock surrounded and surth the surface, located fine of Tuttle Road. on, Calkins, Barryman, ted blue rock as corner tion conducted by Inghablished to perpetuate locating the x 38" rerod, cap #18998 Lue stone described about 15 cm.	ported by 12 stones and 1 on the centerline of Witness trees found and Ingham County described by Wm. am County Survey and a position of the comer:
Nail & tag, #18998, n Nail & tag, #18998, n Nail & tag, #18998, n	TOTTHESET BITTO TOUT I	AND ONE OF LAND	
Nail & tag, #18998, w	est side 18" Butter	nsn., SW, 61.17'	
SIGNED BY Roune	m Rett	DATE	9.lu/98
SURVEYOR'S MICHICAN REG	ISTRATION NO18	1998	BELLEY WAY
KONKONAK KANAKA KANAK KANAK	XXXXXXXXXXXX	The second section of the sect	Barra A
SENED BY		DATE	* RONNIE M. LESTER
APPROVED AND SIGNED BY	I Jan W. da	A 01170 1	SURVEYOR
LESTER D LAND D SUIVE UIT R SURVE VIR'S MICHEGAN REGI	constrainment across LLO1	and Survey and ect	269908 24170
(な) (すっつつ)	of expert	Property of the second	A Address of Lines.
MARCH LAND	AY PLACE SKETCH ON	BACK OR ATTACHED SHEE	RD OF REGISTRATION, JAN. 26, 1971 REVISED MAY 14, 1975.

## LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT OF ACT 74, MICH. PA1970

			use of of
FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	eu eo
1. PUBLIC LAND SURVEY	""	C-1	FILED
2. PROPERTY CONTROLL- ING IN SECTION-	,T N. E. W.		Oct 25   31 PH 278
3. MISCELLANEOUS PROPERTY IN SECTION	,T N. R E. W.		REGISTER OF DEEDS
4, LOT NO, RECO	RDED PLAT		INGHAM COUNTY, MICH.
5. PRIVATE CLAIMS	-		REGISTER OF DEEDS STAMP AND
the corner points mentioned in line re-established, monumented, re-mand rules therefore as required in Bureau of Land Management or b and 5 above were, in a field survey as expressed below and in conform Decree of a Court of law:	es I and 2 above were, in a fit on the current manual of survey y a decree of a court of law, I on the current manual of the Minance with the rules of the M	old survey on Septembored as expressed below and instructions of the United Si Furthermore, that the corner 9 , found, recovered, restichigan State Board of Registr	in conformance with regulations ates Department of the Interior, points mentioned in lines 3, 4
Corner identified by Corner identified by map dated Jan. 1, 19	rke in original gover a survey by A. Jacks stone in Miscellaneo ed April 25, 1873. While Barryman, County Ingham County Road Co 69.	nment survey dated F con, County Surveyor, is County Surveyors R Surveyor, as a cedar mulsion as iron and	dated May 1, 1854  ecords by T.J. Brown,  post, stone and iron rod.  stone in revised grid
how woonwood on C 12	ment box at road surf e Road south. Measur Vevay Twp., T2N-RLW tte L.3, P.185 (PA 74) Illing distance. Four Wm. Barryman in surve	Tace, at the intersected east + 150' to 5/ by George Young, R.L. dated July 16, 1974	tion of the centerline of 8" iron in monument S:#11370, in Corner . Measurement in close
C. Description of monument for C-1 No Corner, Section 5, Left 1, pipe in monum Nail 6 tag, #18998, w Nail 6 tag, #18998, s Nail 6 tag, #18998, s 1 iron in monument b 149,28	TIN-RIW ent box as described est side of Power Pol with side 18" Wild Che	aboye: Le, SW, 31.75' Erry, East, 296,30'	position of the corner:
SIGNED BY Conne	m lesta	DATE 10	ιο/10
SURVEYOR'S MICHICAN REGI	STRATION NO. 1899	<u>Kananana</u> ,	ogi.
FOR STATE AND UNITED STA	NTES: AGENCIES:		BONNE M. LESTER
SPATISTICS	CHIEFOF SHOWN DAVID	DATE	3 SURVEYOR
SUMMERUM 1	Mirector, Ingham Count enonumentation Project STRATION NO.	<b>:t</b>	23 / 1999 (PAC) (111)
White interest 142	PORMAPPI AY PEACE SKETCH ON B	COVED BY MICHIGAN STATE BOAI ACK 'OR' ATTACHED SHEE	PEVICED MAY 16 1075

INGHAM COUNTY - LESLIE TWP.

## LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

	*			1552	6 M	84
	FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER		<b>G</b> 10	O <sub>Z</sub>
	1. PUBLIC LAND SURVEY	T. 1 %, R. 1 %.	D-1	I	FILED	
	2. PROPERTY CONTROLL- ING IN SECTION-	,r N. E. W.		. :-		
	3. MISCELLANEOUS PROPERTY IN SECTION	N. R. E. W.		Aug 27	4 04 PM	
	4. LOT NO , RECO	ORDED PLAT		REGIS	ea Johnson	m.
	5. PRIVATE CLAIMS	! 			4 COUNTY, M	
				REGISTER OF DE	EDS STAMP A	WD.
	I, Ronnie M. Lester the corner points mentioned in li re-established, monumented, re- and rules therefore as required i Bureau of Land Management or and 5 above were, in a field surve as expressed below and in confor Decree of a Court of law:	nes 1 and 2 above were, in a fi monumented, recovered or res in the current manual of survey by a decree of a court of law, ey on	tored as expressed below and y instructions of the United St Furthermore, that the corner found recovered resty	in conformance ates Department points mention	with regulated in lines	shed, ations erior, 3, 4 ished
D-1	A. Description of original monu	ment and accessories and/or st	absequent restoration:			
D-1	No post set in orig Corner referred to	ginal government surve in a survey of the Ba	ey. arber Drain.			
D-1	B. Description of corner evidence	e found and/or method applie	ed in restoring or re-establishing	g corner:		
	excavation revealed way and on the town of Plains Road and to E-1 and east + 1	o' x 10' to an average in physical evidence iship line between C-1 tree line to the sout 136.38' to D-13, Veva) and by Ingham County St	e of monumentation. Of and E-1 Leslie. Corth. Measured west ± 27. T2N-RIW	orner re-es ner falls o 652.8' to C	tablished n the cent -1, east	d mid-
D-1	C. Description of monument for	corner and accessories establis	shed to perpetuate locating the	position of the c	orner:	
	and cover in locat; Nail & tag, #18998, Nail & tag, #18998, Nail & tag, #18998, Nail & tag, #18998,	5, TIN-RIW  the monument with '2" y  ton described above:    east side 8" Elm, SS    northwest side power    west side 28" Maple    north side 26" Maple    T2N-RIW, East, 136.38	SW, 4' above ground, 3 r pole, ENE, 115.32' , SE, 35.98' e, SE, 87.43'		oncrete (	collar
	SIGNED BY (Louise)	m. Lesta	DATE AU	19.1980		20
	SURVEYOR'S MICHIGAN REC	istration no. 18998		(SEAS)		
	NORATIO SEMENTALIONE DASS	OTERAGENCIES:		2	RONA M. LES LAME SURVEY	
	PEROVEDESSIERSIGNED BY LAND SURVEYOR No.	ULTRACTOR INCOME AND A CONTROL OF STREET		19-80 (SEAL)	18898	
18	SUMPRIS MICHIGAN REC	1	ROVED BY MICHIGAN STATE BOAR	REVI	ON, JAN, 28, SED NAY 14.	
10000	De la contrata del contrata del contrata de la contrata del la contrata de la contrata del la contrata de la contrata de la contrata de la contrata de la contrata del la contrata	AAY PLACE SKETCH ON B	ACA UR ALIACHED SHEE	1		