

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICHIGAN

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>27</u> T. <u>1</u> N. <u>2</u> E. <u>W.</u>		(I-9)
2. PROPERTY CONTROLLING IN SECTION _____ T. _____ S. R. _____ E. _____ W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ S. R. _____ E. _____ W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

1527 4 16 126

FILED

FEB 1 3 57 PM '78

REGISTER OF DEEDS
J. J. Johnson
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Kay Don Fluke do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on October 16, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

G L O

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:


Found $\frac{1}{2}$ inch rod approximately $\frac{1}{4}$ mile east of property controlling corner 27-2, measured distance of 1316.13 feet between points. Used corner as found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Witnessed $\frac{1}{2}$ inch rod. (South-80.07-Telephone pole) (North-35.97-Telephone pole) (N50E-84.94-Elm 17")

SIGNED BY Kay D. Fluke DATE January 27, 1978
SURVEYOR'S MICHIGAN REGISTRATION NO. 18988

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY
APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR



SURVEYOR'S MICHIGAN REGISTRATION NO. _____

1126

Form No. ML 1578
DOUGLASS BROS. & CO., KALAMAZOO, MICH.

FORM 4. ISSUED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

INGHAM COUNTY - OGDENAGA TWP.

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

BOOK 4 P. 328

FILED

SEP 5 9 54 AM '70

REGISTER OF DEEDS

R. A. Johnson
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 1 N. R. 2 E. W.	I-11
2. PROPERTY CONTROLLING IN SECTION	T. N. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on June 6, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
I-11

Post set by Harvey Parke in original survey dated Oct., 1825 to Jan., 1826. Corner referred to in a subsequent survey by A. Jackson, County Surveyor, dated April, 1853 (v.2, p.146). Corner identified as stone and crockery by the following surveyors in subsequent surveys: by A.P. Drake in March, 1880 (v.3, p.167) and in Nov., 1881 (v.3, p.183); by Wm. Barryman in Jan., 1932; and by the Ingham County Road Commission records on the revised grid map dated Jan., 1969.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
I-11

Excavated hole 5' x 5' to an average depth of 2' on the centerline of Olds Road and on extended fence line to the south. Found railroad spike, at the surface, on the centerline of Olds Road and on extended fence line south. Found large flat rock 1' beneath railroad spike. Found large pointed rock and crockery 1.8' below surface, beneath railroad spike and flat rock. Measured west to H-11 + 2640' in close accord with Drake's measurement in a survey dated March, 1880 and with the G.L.O. measurement. Accepted pointed rock and crockery as corner described by A. P. Drake and Wm. Barryman above.

C. Description of monument for corner and accessories established to perpetuate location of corner:
I-11

NE Corner, Section 34, T1N-R2W
Set 4" x 36" concrete monument with 1/2" x 38" rerod with cap #18998, with concrete collar and cover, in place of large pointed rock described above:
Nail & tag, #18998, east side 16" Hickory, NNE, 21.31'
Nail & tag, #18998, east side 10" Twin Walnut, South, 30.73'
Nail & tag, #18998, east side 8" Wild Cherry, SSE, 40.09'
Nail & tag, #18998, north side Triple Hickory, WSW, 79.46'

SIGNED BY Ronnie M. Lester DATE 8/31/70

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998


XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

SIGNED BY _____ DATE _____

APPROVED AND ISSUED BY *[Signature]* DATE 8/31/70

Director, Ingham County Survey and Monumentation Project

REGISTRATION NO. 17625



LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970
 NW COR. SEC 34, T14N R2W ON MDQA
 N 1/2 P1st S4, T14N R2W ON MDQA

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	G-11, H-11
2. PROPERTY CONTROLLING IN SECTION	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	
3. MISCELLANEOUS PROPERTY IN SECTION	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	
4. LOT NO. _____	RECORDED PLAT _____	
5. PRIVATE CLAIMS _____		

FILED

APR 26 12 17 PM '78

REGISTER OF DEEDS

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Laverne J. Hendryx, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on April 14, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-11, 1" gas pipe
 H-11, Set driven from line
 extended from the east
 from survey

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-11 1" gas pipe
 Ingham County tag in 6" Ash NW 41.45
 PK nail E. Side 14" Cherry NNW 128.75
 PK nail E. Side PP NE 56.47
 H-11 Set driven
 PK nail E. Side 8" Elm S 24'-1 1/2"
 PK nail E. Side 8" Ash SW 174 2 1/4
 PK nail E. Side 12" Elm NE 77.5"

SIGNED BY Laverne J. Hendryx DATE April 21, 78


SURVEYOR'S MICHIGAN REGISTRATION NO. 3276

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____



INGHAM COUNTY - ONONDAGA TWP.

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBR 4 13 371

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. <u>1</u> N. <u>2</u> E. <u>W.</u>		<u>H-9</u> ✓
2. PROPERTY CONTROLLING IN SECTION_____ T. _____ N. _____ S. _____ R. _____ E. _____ W. _____		
3. MISCELLANEOUS PROPERTY IN SECTION_____ T. _____ N. _____ S. _____ R. _____ E. _____ W. _____		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

FILED

SEP 19 8 54 AM '78

REGISTER OF DEEDS
Russ Johnson
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on June 13, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
H-9

Post set by Harvey Parke in original government survey, dated Oct. 1825 to Jan. 1826. Corner mentioned in a survey by A. Jackson, County Surveyor, survey dated Oct. 1854 (v.2, p.218).

Corner identified as pointed stone (crockery 2" down) by Wm Barryman, County Surveyor. Corner identified as stone and crockery by Ingham County Road Commission records, revised grid map, 1972.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
H-9 Excavated hole 5' x 5' at average depth of 2.5' in centerline Bellevue Road on fence line to the north and south. Found boat spike in centerline, on fence line, 0.40' below surface. Found second boat spike lying horizontally to centerline, 1.20' below surface, 2' west of first boat spike. Found 0.30' long wooden stake surrounded by three large rocks 2.70' below surface, over a pointed rock (24" x 11" x 4") surrounded by clay tile and crockery, 3.0' below surface, located + 1.0' south of centerline of Bellevue Road and + 1.0' west of extended fence line to the north and south. Accepted long pointed rock with tile and crockery as corner described by Wm. Barryman in survey noted above. Excavation conducted by Ingham Co. Survey & Remonumentation Project crew.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
H-9

St. Corner, Section 22, T1N-R2W

Set 4" x 36" concrete monument with 1/2" x 38" rerod, cap #18998, with concrete collar and lid, at location of pointed rock described above:

Nail & tag, #18998, west side 24" Hickory, South, 35.03'

Nail & tag, #18998, southwest side 12" Hickory, SE, 46.97'

Nail & tag, #18998, northeast side 30" White Oak, SE, 80.97'

Nail & tag, #18998, south side 10" Poplar, NE, 69.12'

SIGNED BY Ronnie M. Lester

DATE 9/14/78

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

XXXXXXXXXXXXXXXXXXXXXXXXXXXX

SIGN

CHIEF SURVEYOR

DATE

Doug R. Smith
Director, Ingham County Survey and Remonumentation Project


DATE

SURVEYOR'S MICHIGAN REGISTRATION NO. 17624

1365

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 22, 1977
REVISOR MAY 14, 1978

MAY PLACE NOTICE ON BACK OR ATTACHED SHEET



168

INGHAM COUNTY - ONONDAGA TWP.
LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 1 N. R. 2 E.	G-10
2. PROPERTY CONTROLLING IN SECTION	T. N. S. R. E.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

FILED

JUN 1 12 45 PM '81

REGISTER OF DEEDS

Paula Johnson

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on March 27, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

G-10 A. Description of original monument and accessories and/or subsequent restoration:
Original government survey by Harvey Parks, March 20, 1825,
Corner referred to in a survey by A. Jackson, County Surveyor, May 9, 1839 (v.1, p.16).

G-10 B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
Investigation revealed location of corner is in ditch line of old abandoned North-South road way. Fences East and West not opposite each other. Set corner midway and on line between G-9 and G-11. Measured North and South 2640.05'. Corner falls 22' North of fence East and 6' North of fence West at East edge of bank on old roadway.
Investigation conducted by Ingham County Survey and Remonumentation Project crew.

G-10 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
East 1/4 Corner, Section 28, T1N, R2W
Set 1/2" bar and cap #18998 at location described above:
Nail & tag, #18998, Southeast side 30" Oak, N10°E, 18.45'
Nail & tag, #18998, North side 8" Wild Cherry, East, 10.34'
Nail & tag, #18998, East side 30" Oak, S30°E, 26.07'
Nail & tag, #18998, North side 24" Maple, S60°W, 50.78'


SIGNED BY Ronnie M. Lester DATE 5/20/81

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

FOR STATE AND COUNTY RECORDS

SIGNED GARY D. LESTER CHIEF OF SURVEY PARTY DATE _____
APPROVED AND SIGNED BY GARY D. LESTER MICHIGAN REGISTERED LAND SURVEYOR
Director, Ingham County Survey and Remonumentation Project

SURVEYOR'S MICHIGAN REGISTRATION NO. 17624



LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

East 1/4 corner Section 27, Onondaga Twp.

LIBER 6 PAGE 230
FILED

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 1 N. R. 2 E.	I-10
2. PROPERTY CONTROLLING IN SECTION	T. N. S. R. E.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

FEB 1 1 16 PM '83
REGISTER OF DEEDS
Frank Johnson
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, LARRY A. BRYAN, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on August 10, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law.

A. Description of original monument and accessories and/or subsequent restoration:

I-10 Original monument and accessories obliterated

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I-10 Found anchor post on East-West fence line, excavated around post and found no evidence of corner. Long time residence of property to North has always accepted post as being property line with adjoining land owners. Accepted post as corner set 1/2" bar w/cap.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-10 East 1/4 corner Section 27, T1N, R2W
Set 1/2" bar w/cap at anchor post
Set nail & tag North side 12" Elm, East, 29.90'
Set nail & tag East side 36" Elm, North, 25.12'
Southwest corner of house, N30°W, 85.00'

SIGNED BY Larry A. Bryan DATE 10-8-81

SURVEYOR'S MICHIGAN REGISTRATION NO. 25832

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____



LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 7 PAGE 319

FILED

For corners in
INGHAM

(County)

Located In: ONONDAGA Corner Code ##
TWP.

1. Public Land Survey	T 1N R 2W	H-10
	T 1N R 2W	I-10
	T R	
	T R	
2. Property Controlling in Section	S 27 T 1N R 2W	16
	S 27 T 1N R 2W	9
3. Miscellaneous Property in Sec.	S T R	
	S T R	

APR 12 8 22 AM '93

REGISTER OF DEEDS

Paul Johnson
INGHAM COUNTY, MICH.

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, RON HELSEL, in a field survey on MAY, 19 92,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law, established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

16-NOT SET IN ORIGINAL GOVERNMENT SURVEY
9-NOT SET IN ORIGINAL GOVERNMENT SURVEY
H-10 NOT SET IN ORIGINAL GOVERNMENT SURVEY
I-10 ORIGINAL CORNER LOST

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

16-CORNER SET BY COUNTY SURVEYOR & REESTABLISHED BY SURVEYOR FLUKE & RECORDED IN LIBER 4,
PAGE 129, FOUND $\frac{1}{2}$ " REBAR
9-SET $\frac{1}{2}$ " BAR & CAP AT MID POINT BETWEEN CENTER OF SECTION 27 & WEST $\frac{1}{4}$ CORNER
H-10 BAR & CAP AT BASE OF ANCHOR POST ESTABLISHED BY BRYAN LAND SURVEYS BUT UNRECORDED
I-10 RECORDED IN LIBER 6, PAGE 168, INGHAM COUNTY DEEDS, FOUND $\frac{1}{2}$ " IRON BAR & CAP


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

16-REWITNESSED

$\frac{1}{2}$ " REBAR
BAR & CAP S45°E, 46.4'
N & T E/SIDE WOOD POST, N40°E, 55.54'
REMON C & CAP, S48°E, 10.47'
N & T E/SIDE 4" WOOD POST, S45°W, 45.25'
9-N & T S/SIDE 12" WALNUT, S85°W, 35.73'
N & T S/SIDE 20" MAPLE, N40°W, 55.73'
N & T S/SIDE WOOD ANCHOR POST, EAST, 17.8'
N & T W/SIDE 18" MAPLE, S45°W, 60.35'

H-10 N & T S/SIDE 16" CHERRY, EAST, 2.17'
N & T E/SIDE 8" WALNUT, S45°W, 4.73'
N & T E/SIDE 26" OAK, S30°W, 12.35'
N & T E/SIDE 12" OAK, S15°E, 21.07'

I-10 N & T 12" ELM, EAST, 29.90'
N & T E/SIDE 36" ELM, NORTH, 25.12'
SW COR. HSE FDN., N30°W, 85.00'
N & T P. POLE, N50°E, 0.47'



Signed by Ron Helsel
Surveyor's Michigan License No. 18994

Date MAY 18, 1992