

Cor 18-17

19-20  
Wheatfield

LAND CORNER RECORDATION CERTIFICATE  
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF-- LOCATED IN-- CORNER CODE NUMBER

1. PUBLIC LAND SURVEY 20 T. 3 N. R. 1 E. C-7

2. PROPERTY CONTROLLING IN SECTION T. N. R. E.

3. MISCELLANEOUS PROPERTY IN SECTION T. N. R. E.

4. LOT NO. RECORDED PLAT

5. PRIVATE CLAIMS

FILED  
2 PG 183

Nov 29 10 50 AM '72  
REGISTER OF DEEDS  
Paul M. Lewis  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Fred N. White do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on July 28, 1972 established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1972, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

Original Corner & Witnesses Obliterated.

B. Description of corner evidence found and or method applied in restoring or re-establishing corner:

Found 1/4" Reinforcement Bar; 1" below blacktop surface on fence lines to North & South.  
Verified by adjoining corners and lines.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1/4" Reinforcement Bar

Set Nail in North Side 18" Walnut	S40°E	37.85'
1/2" Iron in Fence to South	South	33.08'
Set Nail in East Side 20" Walnut	N45°W	43.65'



SIGNED BY Fred N. White

DATE 10-27-72

SURVEYOR'S MICHIGAN REGISTRATION NO. 12034

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ CHIEF OF SURVEY PARTY

DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ MICHIGAN REGISTERED LAND SURVEYOR

DATE \_\_\_\_\_

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

SOURCE: CORNER RECORDATION CERTIFICATE

TRANSCRIBED from ORIGINAL on file at REGISTER OF DEEDS  
~~DUPLICATE~~

LAND CORNER RECORDATION CERTIFICATE  
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF: LOCATED IN: CORNER CODE NUMBER  
1. PUBLIC LAND SURVEY 18 T. 3N S. R. 1E A-5, A-6, A-7  
2. PROPERTY CONTROLLING IN SECTION T. S. R. E.  
3. MISCELLANEOUS PROPERTY IN SECTION T. S. R. E.  
4. LOT NO. RECORDED PLAT  
5. PRIVATE CLAIMS

LIBER 4 PG 99

FILED

SEP 23 11 26 AM '77

REGISTER OF DEEDS  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, George M. Young, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on June 9, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on June 9, 1977, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- A-5 Original monument & accessories obliterated  
A-6 Original monument & accessories obliterated  
A-7 Original monument & accessories obliterated

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- A-5 Set corner on section line 234 chains north of NE corner of Section 13, T3N, R1W  
A-6 Set corner on section line at a prorated distance measured between SW corner of Section 19 & NW corner of Section 18, T3N, R1E  
A-7 Set corner on section line at a prorated distance measured between SW corner Section 19 & NW corner Section 18, T3N, R1E

C. Description of monument for corner and accessories established by perpetuating the position of the corner:

- A-5 #16 Nail & Cap in 40" Maple N10°E 279.41'  
#16 Nail & Cap in Anchor Post S50°E 38.02'  
South edge of South direction sign post  
N80°W 26.08'  
A-6 Set 1/2" x 24" Re-rod with cap  
#16 Nail & Cap in 15" Oak N30°E 87.15' FD  
#16 Nail & Cap in P.P. S85°E 144.13' FD  
#16 Nail & Cap in 15" Oak S20°E 153.96' FD  
A-7 #16 Nail & Cap in 18" Ash N20°E 148.65'  
#16 Nail & Cap in 18" Ash N40°E 52.12'  
#16 Nail & Cap in 15" Ash N80°E 107.25'  
Set 1/2" x 24" Re-rod with Cap

FD 12

FD 24

FD 20

SIGNED BY George M. Young

SURVEYOR'S MICHIGAN REGISTRATION NO. 17540

FOR STATE AND UNITED STATES AGENCIES

SIGNED BY

APPROVED AND SIGNED BY

CHIEF OF SURVEY PARTY

MICHIGAN REGISTERED LAND SURVEYOR

DATE

August 10, 1977

(SEAL)

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.

1101

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
REVISED MAY 18, 1978

INGHAM COUNTY

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 3 N. R. 1 E.	C-5
2. PROPERTY CONTROLLING IN SECTION	T. N. R. E.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R. E.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

LIBER 4 PG 101

FILED

OCT 4 9 08 AM '77

REGISTER OF DEEDS  
Ingham County, Mich.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on September 28, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on September 28, 1977, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

C-5 Original monument and accessories obliterated  
I.C.R.C. records call for iron, stone and brick with following Witnesses:  
16" maple, S.E., 44.6'  
34" maple, S.W., 58.0'  
Anchor post, South, 25.61'  
1 1/4" South, 33.00'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C-5 Northwest corner Section 17, T3N, R1E  
Excavated and found plow point 1.0' below surface on centerline of Noble Road on old occupation line North and South. Several of above witnesses are in close accord.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-5 Left plow point and covered with monument box in Roadway.  
Nail & tag in North side 36" maple, S.W., 56.20'  
Nail & tag in N.E. side 20" maple, S.E., 44.50'  
M.D.S.H. Nail & tag in West side corner post, South, 25.95'

SIGNED BY Ronnie M. Lester


SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

DATE 9/29/77

(REAL)



LAND CO

FILING

FOR CORNERS OF:-

1. PUBLIC LAND SURVEY	T. N. R. E.
2. PROPERTY CONTROLLING IN SECTION	T. N. R. E.
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R. E.
4. LOT NO.	RECORDED PLAT
5. PRIVATE CLAIMS	

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on September 28, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on September 28, 1977, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

J-12 No record of monument

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

J-12 Found 1" pipe at NE Co MDSH records also call

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-12 1" pipe 1.0' South of E MDSH nail & tag in West Nail & tag in West side Nail & tag in East side

SIGNED BY Ronnie M. Lester

SURVEYOR'S MICHIGAN REGISTRATION NO.

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY