

SOURCE: CORNER RECORDATION CERTIFICATE

TRANSCRIBED from ORIGINAL on file at REGISTER OF DEEDS
~~DUPLICATE~~

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 3 PG 105

FOR CORNERS OF:	LOCATED IN:	CORNER CODE NUMBER	FILED
1. PUBLIC LAND SURVEY. 1, 3, 5 2 N R. 2 1	N R. 2 1	K-1 D-2, E-2, H-2	APR 16 AM 11 18
2. PROPERTY CONTROLLING IN SECTION T N S. R. E.	T N S. R. E.		
3. MISCELLANEOUS PROPERTY IN SECTION T N S. R. E.	T N S. R. E.		
4. LOT NO. RECORDED PLAT			
5. PRIVATE CLAIMS			

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Oscar Bann do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 6-8 19 73 established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey or 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

K - 1 Unknown
D-2 Unknown
E-2 Unknown
H-2 Unknown

FILED

APR 25 9 21 AM '74
REGISTER OF DEEDS
Paul M. Lewis
INGHAM COUNTY, MICH.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

K - 1 P.K. Nail fd.
D-2 1/2" reinforced iron fd.
E-2 3/4" solid iron fd.
H-2 Monument box fd.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K - 1 N. 80°W. 269.0 Spike N/A 30" Oak
South 62.76 Spike E/S 10" Choke Cherry
N. 40°W. 86.9 Spike E/S Edison Pole
South 24.62 centerline 4" pipe with cones

E-2 1/4 CORNER, Sec. 5
S. 9°E. 160.78 Sp. W/S 12" tree
S. 79°E. 27.91 P.K. NW/S 8" tree clump
West 68.69 Sp. S/S Edison pole

D-2 Center Section, Sec. 5
S. 45°E. 11.00 Sp. SW/S 10" tree
S. 30°W. 8.95 Sp. NW/S 12" tree
S. 60°W. 18.74 Sp. S/S 14" tree

H-2 CENTER SECTION, Sec. 3
S. 75°W. 127.0 fence post
N. 70°W. 130.9 fence post
N. 10°W. 189.6 fence post

SIGNED BY Oscar Bann DATE 4-10-74

SURVEYOR'S MICHIGAN REGISTRATION NO. 13574

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY DATE

APPROVED AND SIGNED BY DATE

SURVEYOR'S MICHIGAN REGISTRATION NO.

Form No. 10, 1970
Replaces Form 5-60, Lansing, Mich.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

686

WHITE OAK
township

T 2 N, R 2 EW

K-1
corner code attachment no.

p. 1 of 1

SOURCE: CORNER RECORDATION CERTIFICATE

TRANSCRIBED from ORIGINAL on file at REGISTER OF DEEDS
~~DUPLICATE~~

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBR 10 397

FOR CORNERS OF:	LOCATED IN:	CORNER CODE NUMBER	FILED
1. PUBLIC LAND SURVEY	1. T. 2. N. 2. E.	K-3 L-1	MAR 27 1 56 PM '72 REGISTER OF DEEDS MacCallum MICHIGAN COUNTY, MICH.
2. PROPERTY CONTROLLING IN SECTION	3. N. 4. E.		
3. MISCELLANEOUS PROPERTY IN SECTION	5. N. 6. E.		
4. LOT NO.	RECORDED PLAT		REGISTER OF DEEDS STAMP AND FILING NUMBER
5. PRIVATE CLAIMS			

I, Oscar Barr do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on SEPTEMBER 17, 1971, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1971, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
UNKNOWN

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
K-3 FOUND 1/2" IRON
L-1 SET PK NAIL

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
K-3 1/2" IRON
N45°E - 157.20 - H.W. CORNER OF W. WING OF HOUSE
S66°E - 53.67 - SPIKE IN 20' OAK
S50°W - 32.47 - SPIKE IN 19' OAK
L-1 PK NAIL
N45°E - 120.13 - SPIKE IN POWER POLE
S32°E - 110.49 - SPIKE IN 15' POPLAR
N30°W - 46.10 - SPIKE IN CORNER FENCE POST

SIGNED BY Oscar Barr DATE March 19, 1972

SURVEYOR'S MICHIGAN REGISTRATION NO. 13574 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____ (SEAL)

199 SURVEYOR'S MICHIGAN REGISTRATION NO.

Form No. 28, 07/70
Revised 1970 by G. C. HARRIS, JR.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 20, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

WHITE OAK
township

T 2 N, R 2 EW

K-3
corner code attachment no.

p. 1 of 1

INGHAM COUNTY-WHITE OAK TWP.
LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. <u>2</u> N. <u>X</u> , R. <u>2</u> E. <u>X</u>		<u>M-3</u>
2. PROPERTY CONTROLLING IN SECTION_____, T. _____ N. _____ S., R. _____ E. _____ W. _____		
3. MISCELLANEOUS PROPERTY IN SECTION_____, T. _____ N. _____ S., R. _____ E. _____ W. _____		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 19, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

M-3

Post set in original government survey by J. Wampler dated between November 22 and 30, 1825.

Corner referred to in a survey by A. Jackson, County Surveyor, dated November, 1838 (v.1, p.149).

Corner referred to in a survey by T.J. Brown, County Surveyor, dated January, 1860 (v.2, p.367).

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

M-3

Excavated a hole 9' x 5' to an average depth of 3' on the centerlines of Columbia and Kane Roads. Found a pointed rock (9" x 6" x 3") on the centerline of Columbia Road and 1.5' west of centerline of Kane Road and a ½" iron bar on the centerline of Columbia Road and 1.5' east of centerline of Kane Road. Set ½" bar with cap in location of found rock on November 18, 1977 and set ½" bar with cap in location of iron bar described above on December 2, 1977 until distance measurements could be made. Measured west + 2670' to L-3 from location of rock described above, in close accord with survey by A. Jackson noted above. Accepted rock for corner. Excavation conducted by Ingham County Survey and Remonumentation Project crew.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-3

SE Corner, Section 1, T2N-R2E

Set 4" x 36" concrete monument with ½" x 38" rerod and cap #18998, in location of rock described above:

Nail & tag, #18998, southwest side 40" Maple, SE, 30.10'

Nail & tag, #18998, southeast side 12" Hickory, SW, 43.48'


Nail & tag, #18998, south side 18" Oak, ENE, 26.37'

Nail & tag, #18998, south side 12" Walnut, WSW, 73.21'


3/4" iron, in centerline of Kane Road and on fence line east, South, 96.24'

SIGNED BY Ronnie M. Lester DATE April 4, 1979

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998



SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY
MICHIGAN REGISTERED LAND SURVEYOR
Director, Ingham County Survey and
Remonumentation Project
SIGNED BY GARY D. LESTER DATE 4-20-79
MICHIGAN REGISTERED LAND SURVEYOR
No. 17624



SOURCE: CORNER RECORDATION CERTIFICATE L.5, P.1

TRANSCRIBED from ~~ORIGINAL~~ DUPLICATE on file at Remonumentation Office

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

50 1

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER	FILED
1. PUBLIC LAND SURVEY—	T. N. R. P.		
2. PROPERTY CONTROL— E.G. IN SECTION—	1. T. 2. N. R. 2. P.	L-2: 1-3	
3. SCIENTIFIC PROPERTY IN SECTION—	T. N. R. P.		
4. LOT NO.—	RECORDED PLAT—		
5. PRIVATE CLAIMS—			

Oct 11 8 25 AM '78

REGISTER OF DEEDS
Benjamin
EMMA COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Gary R. Ross, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 12-12-77, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 12-12-77, established, re-established, recovered or restored as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

L-2: Unknown

L-3: Unknown

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

L-2: 1/2" Iron set @ fence intersection North-West

L-3: 1/2" Iron Rd. at intersection of road & ditch (4) to North

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-2: Center Sec. 1 White Oak-Ingham 1/2" Iron West N. N/S 6" Elm 33.18' N30°W E. S/S tree clump 32.58' S80°W N. N/S tree clump 29.78'	L-3: S 1/4 Cor. Sec. 1 White Oak-Ingham 1/2" Red South N. N/S P.P. 153.53' N70°W N. N/S cable post 56.91' N80°W N. N/S 16" Elm 124.31' N80°E N. S/S 6" Poplar 106.18'
---	--

SIGNED BY Gary R. Ross
SURVEYOR'S MICHIGAN REGISTRATION NO. 17022
FOR STATE AND UNITED STATES AGENCIES:

DATE 7-18-78

SIGNED BY _____
CHIEF OF SURVEY PARTY

DATE _____

APPROVED AND SIGNED BY _____
MICHIGAN REGISTERED LAND SURVEYOR


DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, 1973 P.A. 1973
REVISED MAY 1977

1389

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET



TE OAK
ship

T 2 N, R 2 EW

L-2

corner code attachment no.

0

p. 1 of 1

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF--

LOCATED IN--

CORNER CODE NUMBER

LIBER

5 PG 176

FILED

JAN 31 10 36 AM '79

REGISTER OF DEEDS

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

1. PUBLIC LAND SURVEY

T. N. S. R. E. W.

2. PROPERTY CONTROLLING IN SECTION

1 T. 2 N. R. 2 E. W. K-2

3. MISCELLANEOUS PROPERTY IN SECTION

T. N. S. R. E. W.

4. LOT NO. RECORDED PLAT

5. PRIVATE CLAIMS

1. Gary R. Boss

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 11-28-1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1977, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

K-2: Nail in cor. fence post at fence intersection (N-S-E) Boss
Engr. survey #1876 (dated 11-2-71)

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

K-2: Set 1/2" Iron from previous survey

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-2: W 1/4 Cor. Sec. 1 T2N-R2E

East 17.30' N. S/S fence post
North 97.79' N. E/S 14" Hickory
West 7.42' N. S/S 14" Hickory
South 12.40' N. E/S 12" Hickory

SIGNED BY

Gary R. Boss

DATE

1-22-79

SURVEYOR'S MICHIGAN REGISTRATION NO. 17022

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE

SURVEYOR'S MICHIGAN REGISTRATION NO.

1563

T2N-R2E

K-2 ATT 40

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

SOURCE: CORNER RECORDATION CERTIFICATE
TRANSCRIBED from ORIGINAL on file at REGISTER OF DEEDS
~~PUBLICATION~~

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF: LOCATED IN: CORNER CODE NUMBER
1. PUBLIC LAND SURVEY T. 2 N. R. 2 E. K-3 L-1
2. PROPERTY CONTROLLING IN SECTION T. S. R. L-1
3. MISCELLANEOUS PROPERTY IN SECTION T. S. R. L-1
4. LOT NO. RECORDED PLAT
5. PRIVATE CLAIMS

FILED 1 PC 397

Mar 27 1 56 PM '72
REGISTER OF DEEDS
Mac Gill Thompson
MICHIGAN COUNTY, MICH

REGISTER OF DEEDS STAMP AND
FILED NUMBER

I, Orson Ross do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on February 12, 1971, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
UNKNOWN

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
K-3 Found 1/2" iron
L-1 SET PK NAIL

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
K-3 1/2" iron

N45°E - 157.30 - N.W. CORNER OF N. WING OF HOUSE
S65°E - 53.67 - SPIKE IN 2" OAK
S50°W - 32.49 - SPIKE IN 1" OAK

L-1 PK NAIL
N57°E - 120.13 - SPIKE IN PINE POLE
S32°E - 110.49 - SPIKE IN 1" POPLAR
N30°W - 45.10 - SPIKE IN CORNER FENCE POST

SIGNED BY Orson Ross DATE March 10, 1972

SURVEYOR'S MICHIGAN REGISTRATION NO. 13574
FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY Chief of Survey Party DATE
APPROVED AND SIGNED BY Michigan Registered Land Surveyor DATE

189 SURVEYOR'S MICHIGAN REGISTRATION NO.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 22, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS