

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT. 74, MICH. P.A. 1970

LIBER **2 PG 43**  
FILED

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>7</u> T. <u>2</u> N. S. R. <u>2</u> E. W.		<u>B-3, B-4, C-3</u>
2. PROPERTY CONTROLLING IN SECTION _____, T. _____, S. _____, R. _____, E. _____, W. _____		
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____, S. _____, R. _____, E. _____, W. _____		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

AUG 28 12 29 PM '72  
REGISTER OF DEEDS  
*Carroll M. Lewis*  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, OSCAR BOSS do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on JUNE 20 1912, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

**A. Description of original monument and accessories and/or subsequent restoration:**

B-3: UNKNOWN  
B-4: UNKNOWN  
C-3: UNKNOWN

**B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:**

B-3: SET P.K. NAIL  
SECTION DIVISION  
B-4: SET 1/2" IRON  
SECTION DIVISION  
C-3: SET P.K. NAIL  
OCCUPATION FENCE LINE



**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

<p>B-3: P.K. NAIL S 35° 38' E - 38.64 - NAIL N. SIDE 12" TREE S 40° E - 27.63 - NAIL N.W. SIDE 24" TREE S 35° 48' W - 31.32 - NAIL N. SIDE 12" TREE</p>	<p>C-3: P.K. NAIL N 13° 40' E - 28.12 - NAIL N. SIDE 14" HICKORY S 83° 45' E - 119.71 - NAIL N. SIDE 20" MAPLE S 71° 57' W - 129.10 - NAIL N. SIDE 18" OAK</p>
<p>B-4: 1/2" IRON NORTH - 19.74 - NAIL S. SIDE 12" TREE S 70° E - 28.43 - NAIL S. SIDE 20" TREE S 5° E - 46.15 - NAIL W. SIDE 14" TREE</p>	

SIGNED BY Oscar Boss DATE 8-23-72

SURVEYOR'S MICHIGAN REGISTRATION NO. 1357A (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ CHIEF OF SURVEY PARTY DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ MICHIGAN REGISTERED LAND SURVEYOR DATE \_\_\_\_\_ (SEAL)

343

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

Form No. M.L.M.735  
DUBLIN, OHIO, S. CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>2N</u> N. S., R. <u>2E</u> E. W.	A-3
2. PROPERTY CONTROLLING IN SECTION _____	.T. _____ N. S., R. _____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION _____	.T. _____ N. S., R. _____ E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

LIBER **5 16 96**

FILED

**Jan 3 8 29 AM '79**

REGISTER OF DEEDS

*Paul Johnson*  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Richard W. Steadman, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on April 10, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:  
**Original Monument:** wood post set by Joseph Wampler, U.S. Deputy Surveyor in 1825; bearing trees: 12" Ash S42-1/2°E 13 lks. and 24" Lynn N23°E 37 lks. After determining it to be lost, Deputy County Surveyor T. J. Brown re-established this corner in a survey dated January 15, 1869 and recorded in Volume 3, Page 44, County Surveyor's Records. "A post from which a 2" Apple bears N71-3/4°E 191 lks. and 8" Sugar S40-3/4°W 67-1/2 lks.  
 In a survey dated April 14, 1911 and recorded in Surveyors Record Volume 3 of County Surveyor's Records, R. J. Robb, County Surveyor, found a stone marking this corner witnessed by a Maple N.E. 49-1/2 lks. (39.27 ft.).

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  
 At measurement from Robb's bearing tree, dug hole in intersection of Columbia and Meech Roads. About 4 ft. below the surface, found stone with broken crockery around it.


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
 Raised location of stone to surface with 3/4" iron pipe and monument box.  
 Witnesses: 36" Maple (Robb B.T.) N.E. 39.89 ft.  
 10" Maple E.N.E. 74.11 ft.  
 14" Ash W.N.W. 50.88 ft.  
 Corner for T2N, R1E (set 3/4" pipe and monument box) South 104 lks. = 68.64 ft.

SIGNED BY Richard W. Steadman DATE December 22, 1978  
 SURVEYOR'S MICHIGAN REGISTRATION NO. 11370

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY  
 APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_



INGHAM COUNTY - WHITE OAK TWP.  
**LAND CORNER RECORDATION CERTIFICATE**  
 FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>2</u> N. S. R. <u>2</u> E. W.	A-4
2. PROPERTY CONTROLLING IN SECTION _____	T. _____ N. S. R. _____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. S. R. _____ E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

LIBER **6 PG 103**

FILED

Nov 13 1 06 PM '80

REGISTER OF DEEDS  
*Paula Johnson*  
 INGHAM COUNTY, MICH.  
 REGISTER OF DEEDS STAMP AND  
 FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 8, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A-4 A. Description of original monument and accessories and/or subsequent restoration:

No post set in original government survey.  
 Corner identified as "a post set by A. Jackson, June 18, 1857" in a survey by T.J. Brown, Deputy County Surveyor, January 15, 1869 (v.3, p.44).

A-4 B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Excavated a hole 10' x 10' to an average depth of 3.5' on the centerline of Meech Road and on a fence line to the east. Found large stones throughout excavation probably used for fill. Corner considered lost. Set corner on standard township line midway between A-5 and A-3 White Oak. Location of corner falls on centerline of Meech Road and fence line east. Measured north + 2620.0' to A-3 and south + 2620.0' to A-5. Measured north + 2551.4' to M-3 Ingham and south 84.54' to M-4 Ingham.  
 Excavation conducted by Ingham County Survey and Remonumentation Project crew.

A-4 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

$\frac{1}{4}$  Corner, Section 7, T2N-R2E  
 Set 4" x 36" concrete monument with  $\frac{1}{2}$ " x 38" rerod and cap #18998 with concrete collar and cover in location described above:  
 Nail & tag, #18998, east side 14" Cherry, NNW, 188.02'  
 Nail & tag, #18998, east side 40" Maple, SW, 85.00'  
 Nail & tag, #18998, west side 12" Ash, NE, 118.00'  
 $\frac{1}{2}$ " iron, M-4 Ingham Twp., South, 84.54'


SIGNED BY Ronnie M. Lester DATE 10/8/80

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

APPROVED AND SIGNED BY Gary D. Lester DATE 11.3.80



MICHIGAN REGISTERED LAND SURVEYOR  
 Director, Ingham County Survey  
 and Remonumentation Project



**1852**

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
 REVISED MAY 14, 1978

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

INGHAM COUNTY - WHITE OAK  
**LAND CORNER RECORDATION CERTIFICATE**  
 FILING REQUIREMENT OF ACT 74, MICH. P.A.1970



FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>2</u> N. <u>2</u> E. <u>W.</u>	<u>C-4</u>
2. PROPERTY CONTROLL- ING IN SECTION _____	T. _____ N. _____ E. _____ S. _____ R. _____ W. _____	_____
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ E. _____ S. _____ R. _____ W. _____	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

LIBER **6 PG 191**  
 FILED  
**JUN 4 1 55 PM '81**  
 REGISTER OF DEEDS  
*Paula Johnson*  
 INGHAM COUNTY, MICH.  
 REGISTER OF DEEDS STAMP AND  
 FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on March 2, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior Bureau of Land Management or by a Decree of a Court of law. ~~See the corner points mentioned in lines 1 and 2 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:~~

- A. Description of original monument and accessories and/or subsequent restoration:  
 C-4 Original government survey by J. Wampler, November 30, 1825.  
 No subsequent record of monumentation available in public records.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  
 C-4 Investigation at corner location revealed old fence post at intersection of fences North, West and East and on field separation South. Measured South 2643.24', measured North 2665.82'. Accepted fence corner post as best evidence of perpetuated corner location. Set 1/2" bar and cap in remains of fence corner post.  
 Investigation conducted by Ingham County Survey and Remonumentation Project crew.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
 C-4 West 1/4 Corner, Section 8, T2N, R2E  
 Set 1/2" bar and cap #18998 at location described above:  
 Nail & tag, #18998, South side 4" Cherry, Northeast, 17.27'  
 Nail & tag, #18998, North side 16" Oak stump, East, 25.31'  
 Nail & tag, #18998, Northeast side 3" Oak, West, 6.53'  
 Nail & tag, #18998, Northeast side triple Ash stump, Northwest, 11.05'

SIGNED BY *Ronnie M. Lester* DATE 5/20/81  
 SURVEYOR'S MICHIGAN REGISTRATION NO. 18998



APPROVED AND SIGNED BY *Gary D. [Name]* DATE 5/20/81  
 CHIEF OF SURVEY PARTY  
 MICHIGAN REGISTERED LAND SURVEYOR  
 Director, Ingham County Survey  
 and Remonumentation Project  
 SURVEYOR'S MICHIGAN REGISTRATION NO. 17624

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

LIBER 8 PAGE 209

FILED

For corners in

INGHAM

Located in:

Corner Code #:

(County)  
White Oak Township

- |                                       |                         |            |
|---------------------------------------|-------------------------|------------|
| 1. Public Land Survey                 | T <u>2N</u> R <u>2E</u> | <u>A-5</u> |
|                                       | T _____ R _____         | _____      |
|                                       | T _____ R _____         | _____      |
|                                       | T _____ R _____         | _____      |
| 2. Property Controlling in Section    | S _____ T _____ R _____ | _____      |
|                                       | S _____ T _____ R _____ | _____      |
| 3. Miscellaneous Property in Sec.     | S _____ T _____ R _____ | _____      |
|                                       | S _____ T _____ R _____ | _____      |
| 4. Lot No. _____, Recorded Plat _____ |                         |            |
| 5. Private Claims _____               |                         |            |

SEP 14 8 43 AM '94

REGISTERED DEEDS  
 REGISTERED INSTRUMENTS  
 REGISTERED MICH.

Register of Deeds Stamp & File Number

I, R. W. Steadman, in a field survey on June 31, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
2	3	4	5	6	7	8	9	10	11	12	13	14
3	4	5	6	7	8	9	10	11	12	13	14	15
4	5	6	7	8	9	10	11	12	13	14	15	16
5	6	7	8	9	10	11	12	13	14	15	16	17
6	7	8	9	10	11	12	13	14	15	16	17	18
7	8	9	10	11	12	13	14	15	16	17	18	19
8	9	10	11	12	13	14	15	16	17	18	19	20
9	10	11	12	13	14	15	16	17	18	19	20	21
10	11	12	13	14	15	16	17	18	19	20	21	22
11	12	13	14	15	16	17	18	19	20	21	22	23
12	13	14	15	16	17	18	19	20	21	22	23	24
13	14	15	16	17	18	19	20	21	22	23	24	25

A. Description of original monument and accessories and/or subsequent restoration:

- 1825: Wood post set by Joseph Wampler, U. S. Deputy Surveyor, 150 links north of M-5, T2N, R1E; bearing trees: 15" Ash S14-1/2°E 50 links and 5" Tamarack N86-3/4°E 40-1/2 links.
- 12-28-1839: Volume 1, Page 152, County Surveyor Anson Jackson used this corner, noting the original bearing trees for witnesses, but does not describe the monument.

(Continued on back)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" iron pipe and cap 11370 in good condition in monument box in center of Meech Road and about 5 feet North of center of Iosco Road. 1976 witnesses gone, except for M-5, T2N, R1E.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Left 1/2" iron pipe and cap 11370 in place as found in monument box to mark t corner, and took the following witnesses (bearings are magnetic):

- Set nail and tag 11370 in W. side 20" Walnut S33°W 141.39 feet
- Set nail and tag 11370 in SW side 12" Elm S16°E 131.82 feet
- Set nail and tag 11370 in SW side 20" Walnut S61°E 149.74 feet

(Continued on back)

Signed by Richard W. Steadman Date July 12, 1994  
 Surveyor's Michigan License No. 11370

PEER APPROVED 7/13/94 [Signature]  
 F. A. 345 INGHAM COUNTY  
SEEN APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 11  
 REVISED MAY 14, 11  
 REVISED JAN. 11

5027

F. 2651

LIBER 8 PAGE 210

A-5, T2N, R2E

Part A - Continued

- 3). 4-26-1976: Land Corner Recordation Certificate (Rec. 1-16-79, L5-P143), R. W. Steadman L.P.S. 11370 "dug hole in the intersection of Meech and Iosco Roads, but found nothing. Re-established the corner on the township line as defined by the quarter corner next north for T2N, R1E and the corresponding section corner for T2N, R1E (see Items 4) and 5) below), and at the USPLS recorded jog distance south of it. Set 1/2" iron pipe and monument box to mark the corner. Witnesses: telephone pole S20°E 80.71 ft., wood anchor post S64°E 87.64 ft., 20" Maple N71°E 76.17 ft. Corner for T2N, R1E (set 3/4" iron pipe and monument box - 1973) South 99 ft." Note: A-5 is North of M-5, not South of it.
- 4). 6-22-1973: Land Corner Recordation Certificate for M-4, T2N, R1E (Rec. 1-16-79, L5-P147), R. W. Steadman "dug hole in Meech Road opposite fence West, and about 2 ft. below the surface, found a long pointed stone with a hub cap alongside, and broken crockery and small stones around. Raised location of stone to surface with 3/4" iron pipe and set monument box. Witnesses: 24" Maple WNW 23.08 ft., 22" Maple SSE 131.51 ft., wood culvert post NNE 83.03 ft."
- 5). 6-25-1973: Land Corner Recordation Certificate for M-5, T2N, R1E (Rec. 1-16-79, L5-P146), R. W. Steadman "dug hole in the intersection of Meech and Iosco Roads but found nothing. Re-established corner by proportional measurements from possession evidence North, South, and West. Set 3/4" iron pipe in monument box to mark the corner. Witnesses: 30" Maple NNW 66.94 ft., 14" Walnut SSW 74.63 ft., Telephone pole SW 59.72 ft., Telephone pole NE 39.15 ft."

Part C - Continued

Set nail and tag 11370 in S. side 12" Elm N72°E 70.80 feet  
Set nail and tag 11370 in S. side 15" Elm N68°W 66.66 feet  
Found 1/2" iron rod and cap marked "Ingham Temp. Pt." S07°E 3.94 feet  
Found 1/2" iron pipe and cap 11370 in monument box (corner for T2N, R1E)  
S04°W 99.00 feet

OCT 3 1 16 PM '94

REGISTER OF DEEDS  
*Paul J. Johnson*  
INGHAM COUNTY, MICH.

SURVEY &  
REMONUMENTATION  
APR 10 1995  
COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in INGHAM located in: Corner Code ##

White Oak Township

1. Public Land Survey T 2N R 2E B-5  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	I
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

I, R. W. Steadman, in a field survey on June 14, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1). 1825: Wood post set by Joseph Wampler, U. S. Deputy Surveyor; bearing trees: 6" Sugar N21°W 19 links and 12" Sugar S72°W 8 links.
- 2). 12-28-1839: Volume 1, Page 152, County Surveyor Anson Jackson used this corner and notes the original bearing trees as witnesses, but does not describe the monument.

(Continued on back)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" iron pipe and cap in monument box in center of Iosco Road; pipe was in good condition but cap was unreadable. Replaced the pipe with standard Ingham County Remonumentation 3/4" iron rod and cap.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" smooth iron rod and cap stamped "P. A. 345, PS 11370" in monument box and took the following witnesses (bearings are magnetic):

- Found nail and tag 11370 in N. side 20" stump S61°E 61.92 feet
- Set nail and tag 11370 in W. side 22" Maple N04°W 27.37 feet
- Set nail and tag 11370 in N. side 12" Hickory S47°W 33.63 feet
- Set nail and tag 11370 in S. side triple 8" Elm N56°W 59.58 feet
- Set nail and tag 11370 in S. side twin 10" Elm N81°E 88.93 feet
- Set nail and tag 11370 in N. side 14" Hickory S64°E 75.60 feet

Signed by Richard W. Steadman Date September 9, 1994  
Surveyor's Michigan License No. 11370

P.A. 345 INGHAM COUNTY  
PEER APPROVED 9/14/94 *PC*

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 22, 71  
REVISED MAY 14, 81  
REVISED JAN., 87

2666

LIBER 8 PAGE 237

B-5, T2N, R2E

Part A - Continued

- 3). 4-26-76: Land Corner Recordation Certificate (Rec. 1-06-79, L5-P145), R. W. Steadman L.P.S. 11370 "dug hole in Iosco Road but found nothing; location falls in road cut area. Re-established corner in center of road opposite fence lines North and South. Set 1/2" iron pipe and monument box to mark the corner. Witnesses: 8" Hickory S47°W 34.09 feet, 20" Oak S62°W 61.90 feet, 18 Maple N08°W 27.55 feet\*.
- 4). 6-02-76: Certified Survey Map (Rec. 6-10-76, L2-P725), R. W. Steadman calls for the monument and witnesses given in 3). above.
- 5). 10-18-1988: Private Records of D. L. Clifford L.P.S. 25837 surveying for the subsequently cancelled Supercollider Project - surveyed Section 18, T2N, R2E, and established coordinates for the corners. Computation of distances from his coordinates indicates that it is 2668.61 feet East, 2671.00 feet South, and 2148.24 feet West to the adjacent corners.

LIBER 8 PAGE 240  
FILED

SURVEY &  
REMONUMENTATION  
APR 10 1995  
COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

OCT 3 1 17 PM '94

REGISTER OF DEEDS  
*Debra J. Johnson*  
INGHAM COUNTY, MICH.

For corners in INGHAM (County) Located in: \_\_\_\_\_ Corner Code # C-5

White Oak Township

1. Public Land Survey T 2N R 2E \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

Register of Deeds Stamp & File Number

R. W. Steadman, in a field survey on June 14, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L
2												
3												
4												
5												
6												
7												
8												
9												
10												
11												
12												
13												

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1). 1825: Wood post set by Joseph Wampler, U. S. Deputy Surveyor; bearing trees: 14" Sugar S19°W 18 links and 3" Ironwood N55°E 12 links.
- 2). I find no further mention of this corner in available records until the Land Corner Recordation Certificate listed in 3). below.

(Continued on back)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found concrete monument with cap 18998 in good condition in monument box in center of Iosco Road.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Left concrete monument with cap 18998 in monument box as found to mark the corner and took the following witnesses (bearings are magnetic):

- Found nail and tag 18998 in W. side Power Pole N10°E 25.42 feet
- Found nail and tag 18998 in E. side 15" Hickory S16°W 87.33 feet
- NW corner foundation House #3010 S19°E 189.71 feet
- Set nail and tag 11370 in SW side 22" Chinese Elm S33°E 41.15 feet
- Set nail and tag 11370 in S. side 28" Elm N76°E 83.54 feet

Signed by Richard W. Steadman Date September 9, 1994

Surveyor's Michigan License No. 11370

P.A. 345 INGHAM COUNTY  
PEER APPROVED 9/14/94 AC

2668

LIGER 8 PAGE 241

C-5, T2N, R2E

Part A - Continued

- 3). 4-03-81: Land Corner Recordation Certificate (Rec. 6-04-81, L6-P193), R. M. Lester L.P.S 18998 indicates excavation was made but nothing found. Corner was re-established on road centerline opposite fence North. "Measured South 2687.66 feet, North 2643.24 feet, West 2668.97 feet, and East 2625.19 feet. Excavation by Ingham County Survey and Remonumentatio Project Crew". A 4" by 36" concrete monument with collar and cap 18998 was set and witnessed by: nail and tag 18998 in W. side Power Pole N10°E 25.44 feet, nail and tag 18998 in S. side 10" Hawthorne N70°E 83.65 feet, nail and tag 18998 in SW side 12" Cottonwood S70°E 41.47 feet, nail and tag in E. side 12" Hickory S10°W 87.38 feet.
- 4). 10-18-94: Private records of D. L. Clifford L.P.S. 25837 surveying for the subsequently cancelled Supercollider Project - surveyed Section 18, T2N, R2E, and established coordinates for the corners. Computation of distances from his coordinates indicates that it is 2687.52 feet South and 2668.61 feet West to the adjacent corners.