LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 3 PG 562

FILED

APR 28 1 59 PM '76

REGISTER OF DEEDS

Carol M. Lewis

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	Sec. 31 T. 2N N. S. R. 2E E. W.	C11 A12
2. PROPERTY CONTROLLING IN SECTION—	T. N. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

I, Marvin F. Fouty, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 11-8, 19 75, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on , 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A Description of original monument and accessories and or subsequent restoration

C11 Original monument and accessories obliterated. No record of subsequent restoration by the County Surveyor.

A12 [illegible] position occupied by newer anchor post with [illegible]

B Description of corner evidence found and or method applied in restoring or reestablishing corner

C11 Set 1/2" bar and cap from adjacent occupation lines.

A12 Set 1/2" bar and cap at base of Anchor Post.

C Description of monument for corner and accessories established to perpetuate locating the position of the corner

C11 W 1/4 Corner Section 31, T2N, R2E 1/2" bar and cap
Nail and Tag East side 14" Maple North 21.30'
Nail and Tag West side 6" Beech NE 12.70'
Nail and Tag North side 6" cherry ENE 15.03'

A12 NE Cor. Section 31, T2N, R2E 1/2" bar and cap
Nail and Tag SE side 22" Maple West 25.32'
Nail and Tag North side 32" Oak East 20.38'
Nail and Tag W side 26" Maple NE 35.75'

LCRC L5 pg 204
Reverses Witnesses
Between C-11 & A-12

SIGNED BY Marvin Fouty DATE April 26, 1976

SURVEYOR'S MICHIGAN REGISTRATION NO. 18989

STATE OF MICHIGAN
MARVIN F. FOUTY
LAND SURVEYOR
No. 18989
REGISTERED LAND SURVEYOR
(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

951

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

SOURCE: CRC

TRANSCRIBED from ~~ORIGINAL~~ DUPLICATE on file at Lenon

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

This Recordation Certificate is to correct the original Recordation Certificate in Liber 3, Page 562. (Witnesses in C below errored in designation A-12 & C-11

LIBER 5 PG 204

FILED

MAR 13 11 11 AM '79

REGISTER OF DEEDS

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	Sec. 31 T. 2N S. R. 2E W.	C11 A12
2. PROPERTY CONTROLLING IN SECTION	T. S. R.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

I, Marvin F. Fouty, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 11-8, 19 12, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ____, 19 ____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law.

A. Description of original monument and accessories and/or subsequent restoration:

C11 Originalmonument and accessories obliterated. No. record of subsequent restoration by the County Surveyor.

A12 The South 1/2 of the Section was surveyed in June 1900 by County Surveyor E.A. Calkins who set an oak post with stone and accessories. Corner position occupied by newer anchor post with fences North, South and East.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C11 Set 1/2" bar and cap from adjacent occupation lines.

A12 Set 1/2" bar and cap at base of Anchor Post.

C. Description of monuments for corner and accessories established to perpetuate locating the position of the corner:

A12 W 1/4 corner Section 31, T2N, R2E, 1/2" bar and cap
Nail and Tag East side 14" Maple North 21.30'
Nail and Tag West side 6" Beech NE 12.70'
Nail and Tag North side 6" cherry ENE 15.03'

C11 NE Cor. Section 31, T2N, R2E 1/2" bar and cap
Nail and Tag SE side 22" Maple West 25.82'
Nail and Tag North side 32" Oak East 20.39'
Nail and Tag N side 26" Maple NE 35.75'

SIGNED BY William F. Fouty DATE 2-27-78

SURVEYOR'S MICHIGAN REGISTRATION NO. 18989

STATE OF MICHIGAN — MARVIN F. FOUTY — LAND SURVEYOR No. 18989 — REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES

SIGNED BY _____ (CHIEF OF SURVEY PARTY) DATE _____

APPROVED AND SIGNED BY _____ (AUTHORIZED REGISTERED LAND SURVEYOR) DATE _____ (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 20, 1971 REVISED MAY 14, 1975

1587 MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

A-4

T2NR2E

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

North 1/4 corner, Section 31, T2N, R2E, White Oak Township

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 2 N. ●, R. 2 E. ●	B-11
2. PROPERTY CONTROLLING IN SECTION	T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

LIBER 6 PAGE 37

FILED

Mar 17 1 00 PM '80

REGISTER OF DEEDS

Dana Johnson

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, James E. Stephens, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on February 21, 19 80, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

The original monument and accessories were not found

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

This recordation will suppliment the recordation in Liber 3, Page 357, Ingham County Records.
A 1/2" solid iron rod found at the location of an old fence post at the intersection of fences.
Rodd had been hit and was replaced with another 1/2" solid iron rod from previously recorded witnesses.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

The 1/2" solid iron rod at the N. 1/4 corner has the following witnesses.

Nail in N.W. side of 12" Oak tree NWLY 12.19 feet
Nail in East side of 12" Oak tree North 26.6 feet
Nail in West side of 20" Oak tree North 4.9 feet
Nail in East side of 12" Poplar tree S.W. 12.71 feet

SIGNED BY James E. Stephens DATE March 14, 1980

SURVEYOR'S MICHIGAN REGISTRATION NO. 16053 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

STATE OF MICHIGAN — JAMES E. STEPHENS — LAND SURVEYOR (SEAL) NO. 16053 — REGISTERED LAND SURVEYOR

1788

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

SOURCE: CORNER RECORDATION CERTIFICATE

TRANSCRIBED from ORIGINAL ~~DUPLICATE~~ on file at REGISTER OF DEEDS

[redacted]

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 3 PG 355

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T 2N S. R. 2E E. W.	A-11
2. PROPERTY CONTROLLING IN SECTION	T. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. E. W.	

4. LOT NO. ..... RECORDED PLAT .....

5. PRIVATE CLAIMS .....

FILED

MAR 17 11 23 AM '75

REGISTER OF DEEDS

Enid M. Louis

INGHAM COUNTY, MICH

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Richard W. Steadman, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on June 16, 19 73, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ..... 19 ..., found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Original monument: wood post set by Joseph Wampler, U.S. Deputy Surveyor in 1825. Bearing trees: 23" R. Oak S17E 116 lks., no other. I find no public record of a restoration of this corner.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Dug large, deep hole in Meech Road, but found nothing. Re-established corner opposite fence East and on Northerly extension of fence which begins at south edge of Swan Road intersection and runs South to West 1/4 corner of Section 31 (wood anchor post).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" iron pipe for corner at above described location.

Witnesses:	3/4" iron pipe	East	33.02 ft.
	14" Walnut	W.S.W.	24.74 ft.
	12" Oak	W.N.W.	35.21 ft.
	Largest trunk of triple W. Cherry	S.S.E.	77.69 ft.

SIGNED BY Richard W. Steadman DATE February 20, 1975

SURVEYOR'S MICHIGAN REGISTRATION NO. 11370

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY ..... (CHIEF OF SURVEY PARTY) ..... DATE .....

APPROVED AND SIGNED BY ..... (MICHIGAN REGISTERED LAND SURVEYOR) ..... DATE .....

..... REGISTRATION NO. .....

T2NR2E

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 3 PG 357

FOR CORNERS OF—:	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 2N S. R. 2E E. W.	B-11
2. PROPERTY CONTROLLING IN SECTION	T. N. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

FILED

MAR 17 11 21 AM '75

REGISTER OF DEEDS

Grant M. Lewis

INGHAM COUNTY, MICH

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Richard W. Steadman, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on June 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ..... 19 .., found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of Law:

A. Description of original monument and accessories and/or subsequent restoration:

Original monument: wood post set by Joseph Wampler U.S. Deputy Surveyor in 1825. Bearing trees: 20" W. Oak N84W 41 lks., and 26" Elm S42 1/2W 66 lks.

Restoration: From the Ingham County Surveyors Records, Vol. 5, Page 40, in a survey dated May 31, 1900, Deputy County Surveyor E. A. Calkins calls for this corner to be a "post of oak, iron to be set, from which bears a 10" Elm N3°E 46 lks. and a 15" W. Swp. Oak S46W 48 lks."

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found wood anchor post at four way fence intersection.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I assumed that the wood anchor post marks the corner.

Witnesses:	14" Oak	North	4.9 ft.
	8" Oak	N.N.W.	26.6 ft.
	Twin 4" Ironwood	W.N.W.	23.5 ft.

SIGNED BY Richard W. Steadman DATE February 20, 1975

SURVEYOR'S MICHIGAN REGISTRATION NO. 11370

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY ..... (CHIEF OF SURVEY PARTY) ..... DATE .....

APPROVED AND SIGNED BY ..... (MICHIGAN REGISTERED LAND SURVEYOR) ..... DATE .....

SURVEYOR'S MICHIGAN REGISTRATION NO. .....

822

Form No. ML M730
DOUBLEDAY - MOSS, S CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 3 PG 353

FILED

MAR 17 · 11 23 AM '75

REGISTER OF DEEDS

Ernie M. Lewis

INGHAM COUNTY, MICH

REGISTER OF DEEDS STAMP AND FILING NUMBER

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 2N S., R. 2E N., E., W.	B-13
2. PROPERTY CONTROLLING IN SECTION	T. ____ S., R. ____ N., E., W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. ____ S., R. ____ N., E., W.	
4. LOT NO. ____, RECORDED PLAT		
5. PRIVATE CLAIMS		

I, Richard W. Steadman do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on August 9, 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Original monument: wood post set by Joseph Wampler, U.S. Deputy Surveyor in 1825. Bearing trees: 11" B. Oak N68 W 112 lks., and 9" W. Oak N66 E 99 lks.

Restoration: From the Ingham County Surveyors Records, Vol. 5, on Page 40: in a survey dated May 31, 1900, Deputy County Surveyor E. A. Calkins set a 1 1/4" steel mower shaft from which bears a 7" W. Oak N54°W 228 1/2 lks., and a 12" R. Oak N89°W 150 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

In East-West fence, found mower shaft with stones around set by Calkins.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Left Calkins mower shaft in place for the corner.

Witnesses:			
	wood anchor post (fence north)	West	28.5 ft.
	36" Oak	W.N.W.	101.34 ft.
	20" Oak	East	69.67 ft.
	5" W. Cherry	N.W.	1.77 ft.

SIGNED BY Richard W. Steadman DATE February 20, 1975

SURVEYOR'S MICHIGAN REGISTRATION NO. 11370

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY ____ (CHIEF OF SURVEY PARTY) DATE ____

APPROVED AND SIGNED BY ____ (MICHIGAN REGISTERED LAND SURVEYOR) DATE ____

SURVEYOR'S MICHIGAN REGISTRATION NO. ____

820

Form No. MR 08735 (DOUBLEDAY PRESS, S.W., KALAMAZOO, MICH.)

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 20, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

DUPLICATE On File at REGISTER OF DEEDS

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 3 PG 325

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 2 ★★ S. R. 2 ★★★★ E.	C-12, C-13, D-12
2. PROPERTY CONTROLLING IN SECTION	T. ____ N. S. R. ____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. ____ N. S. R. ____ E. W.	
4. LOT NO. ____ RECORDED PLAT		
5. PRIVATE CLAIMS		

FILED

Jan 25 1 49 PM '75

REGISTER OF DEEDS

Grant M. Lewis

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, George M. Young do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on Dec. 31, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

C-12 Original monument and accessories not found
C-13 Original monument and accessories not found
D-12 Original monument and accessories not found

B. Description of corner evidence found and or method applied in restoring or re-establishing corner:

C-12 Found 3/4" iron rod
C-13 Found old anchor post
D-12 Found 1" iron pipe

C. Description of monument for corner and accessories established to perpetuate/locating the corner:

C-12 3/4" iron rod - Nail in 18" Oak N 50° W 80.35'
Nail in 18" Oak N 40° W 60.47'
Face of 2" iron post N 20° W 46.38'
C-13 Old Anchor Post-Nail in 24" Maple South 39.95'
and 1/2" iron -Nail in 12" Hickory S 40° W 49.57'
Nail in 18" Oak S 50° W 25.76'
D-12 1" Iron Pipe - Nail in 18" Maple N 10° E 94.57'
Nail in 36" Maple N 15° E 71.83'
SE cor. House No. 3255 N 30° E 116.40'

STATE OF MICHIGAN — George M. Young — LAND SURVEYOR — No. 17640 — REGISTERED LAND SURVEYOR

SIGNED BY George M. Young DATE January 20, 1975

SURVEYOR'S MICHIGAN REGISTRATION NO. 17640

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE

(CHIEF OF SURVEY PARTY)

APPROVED AND SIGNED BY _____ DATE

(MICHIGAN REGISTERED LAND SURVEYOR)

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.

806

Form No. MLM736
BOURNEDALE PRESS & COMMUNICATIONS, DETROIT

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS