



CODE NO.	FILING NUMBER	CODE NO.	FILING NUMBER
G-1	Li. 8 pg. 57	K-1	Liber 6 pg. 82
G-2	Liber 1 PG 147 →	K-2	Liber 1 PG 155
G-3	Liber 1 PG 137	K-3	Liber 1 PG 157
G-4	Liber 3 pg. 67	K-4	Liber 1 PG 91
G-5	Liber 5 pg. 286	K-5	Liber 1 pg. 553 →
G-6	Liber 3 pg. 13	K-6	Liber 1 pg. 555
G-7	Liber 3 pg. 15	K-7	Liber 1 PG 271
G-8	Liber 3 pg. 126	K-8	Liber 1 PG 269
G-9	Liber 1 PG. 423 →	K-9	Liber 2 pg. 227
G-10	Liber 6 pg. 202	K-10	Liber 2 pg. 225
G-11	Liber 5 pg. 14	K-11	Liber 3 pg. 498
G-12	Liber 1 PG 11	K-12	Liber 3 pg. 496
G-13	Liber 1 Pg. 429	K-13	Liber 6 pg. 351


[illegible]

Form MLM736A INDEX TO LAND RECORDATION
DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.

ADDITIONAL PAGE IS ONE ~~PAGE~~^{AFTER} THE

AFT50

TOWNSHIP CORNER NUMBERING CODE DIAGRAM



WILLIAMSTON

CORNER INDEX

CORNER INDEX

CODE NO. FILING NUMBER CODE NO. FILING NUMBER

A-1 _____ D-1 *Liber 6 pg. 328* ✓
A-2 _____ D-2 _____
A-3 _____ D-3 *Liber 7 pg. 139*
A-4 _____ D-4 _____
A-5 _____ D-5 _____
A-6 _____ D-6 _____
A-7 _____ D-7 _____
A-8 _____ D-8 _____
A-9 _____ D-9 _____
A-10 _____ D-10 _____
A-11 _____ D-11 _____
A-12 _____ D-12 _____
A-13 _____ D-13 _____

B-1 _____ E-1 *Li. 8 pg. 103* → ✓
B-2 _____ E-2 *Li. 8 pg. 63* ✓
B-3 _____ E-3 *Li. 8 pg. 105* →
B-4 _____ E-4 *Liber 7 pg. 139* →
B-5 _____ E-5 *Liber 7 pg. 139*
B-6 _____ E-6 _____
B-7 _____ E-7 _____
B-8 _____ E-8 _____
B-9 _____ E-9 _____
B-10 _____ E-10 _____
B-11 _____ E-11 *Liber 7 pg. 192*
B-12 _____ E-12 *Liber 5 pg. 281* →
B-13 _____ E-13 *Liber 7 pg. 194*

C-1 *Liber 6 pg. 328* ✓ F-1 *Liber 5 pg. 95* →
C-2 _____ F-2 *Li. 8 pg. 69*
C-3 _____ F-3 *L.B.P. 376 & 377*
C-4 _____ F-4 *Li. 8 pg. 67*
C-5 _____ F-5 *Li. 8 pg. 65*
C-6 _____ F-6 _____
C-7 _____ F-7 _____
C-8 _____ F-8 _____
C-9 _____ F-9 _____
C-10 _____ F-10 _____
C-11 _____ F-11 _____
C-12 _____ F-12 _____
C-13 _____ F-13 _____

CODE NO. FILING NUMBER CODE NO. FILING NUMBER

G-1 *B-57* K-1 _____
G-2 *Li. 8 pg. 61* K-2 _____
G-3 *Li. 8 pg. 71* K-3 _____
G-4 *Liber 6 pg. 207* → K-4 _____
G-5 *Liber 5 pg. 321* → K-5 *Liber 7 pg. 124*
G-6 _____ K-6 _____
G-7 _____ K-7 _____
G-8 _____ K-8 _____
G-9 _____ K-9 _____
G-10 _____ K-10 _____
G-11 _____ K-11 _____
G-12 _____ K-12 _____
G-13 _____ K-13 _____

H-1 _____ L-1 _____
H-2 _____ L-2 _____
H-3 _____ L-3 _____
H-4 _____ L-4 _____
H-5 *Liber 6 pg. 240* L-5 _____
H-6 *Liber 6 pg. 368* L-6 _____
H-7 _____ L-7 _____
H-8 _____ L-8 _____
H-9 _____ L-9 _____
H-10 _____ L-10 _____
H-11 _____ L-11 _____
H-12 _____ L-12 _____
H-13 *Liber 5 pg. 99* L-13 _____

I-1 _____ M-1 _____
I-2 _____ M-2 _____
I-3 _____ M-3 _____
I-4 _____ M-4 _____
I-5 _____ M-5 _____
I-6 _____ M-6 _____
I-7 _____ M-7 _____
I-8 _____ M-8 _____
I-9 _____ M-9 _____
I-10 _____ M-10 _____
I-11 _____ M-11 *Liber 5 pg. 275*
I-12 _____ M-12 *Liber 5 pg. 275*
I-13 *Liber 6 pg. 351* M-13 _____

J-1 _____ E-12 *Li. 7 pg. 193*
J-2 _____ F-1 *Li. 8 pg. 59*
J-3 _____ G-4 *Li. 8 pg. 73*
J-4 _____ E-4 *Li. 8 pg. 107, 8-107 & 8*
J-5 _____ E-1 *8-103 & 104* ✓
J-6 _____ E-3 *8-105 & 106* ✓
J-7 _____ E-5 *8-374 & 375* ✓
J-8 _____ G-5 *8-378 & 379*
J-9 _____
J-10 _____
J-11 _____
J-12 _____
J-13 _____

[illegible]

Williamstown Twp										PAGE 42
Section	Liber	Page		Section	Liber	Page		Section	Liber	Page
14	8	649		21	4	899-900		26	4	1159-1160
15	1	116-117		22	1	863-866		26	5	249
15	1	510-511		22	1	1171-1172		26	5	543-544
15	1	620-621		22	2	142		26	5	570
15	1	1106		22	2	936-938		26	5	573
15	1	1171-1172		22	2	1221		26	5	580-581
15	2	365		22	3	48-49		26	5	602-603
15	2	689		22	4	863		26	6	101-102
15	2	806-807		22	5	1184-1185		26	6	830-831
15	3	1039		22	6	26-27		26	7	677-678
15	4	736		22	6	192-193		26	7	821-826
15	5	1205-1206		22	8	360-363		26	7	868-869
15	6	167-169		22	8	719		26	7	1083-1084
15	6	253-255		23	1	140		27	1	133
15	6	427-430		23	1	576-577		27	1	904
15	8	360-363		23	1	55		27	1	1103
16	3	1094		23	3	309-310		27	4	71-72
17	4	1228		23	6	107-109		27	6	830-831
17	5	25-26		24	2	7,8		27	8	128-133
17	5	65-68		25	1	1026-1027		27	8	138-149
17	5	604-607		25	1	1105		27	8	153-161
17	5	531-532		25	2	768-769		28	1	617-619
17	5	465-468		25	2	965-966		28	2	341-342
17	5	496-498		25	2	1214-1215		28	2	571
17	6	904-905		25	3	698-699		28	2	1035-1036
17	8	453-454		25	3	700-701		28	4	1087-1088
19	6	231-232		25	3	888-889		28	4	1221
20	2	413-414		25	3	901-904		28	5	1198
20	2	539-544		25	3	1219-1220		28	5	1213-1214
20	2	860		25	4	369		28	6	296-298
20	2	1100-1101		25	5	359-360		28	6	644
20	2	1277-1279		25	5	364		28	8	128-137
20	3	672		25	5	376-377		28	8	147-148
20	3	1197		25	7	195-197		28	8	152
20	3	755		25	7	375-376		28	8	591-592
20	4	881		26	1	121		29	1	137
20	5	1269-1271		26	1	226-227		29	4	1155-1156
20	6	64-65		26	1	233-234		29	5	579
20	6	68-69		26	1	301-302		29	5	596
20	6	99-100		26	1	401		29	6	12,13
20	6	128-129		26	1	507		31	2	848-849
20	6	229-230		26	2	362		31	6	456-457
20	6	290-291		26	2	591-592		32	2	848-849
20	6	418-419		26	2	960		32	4	215-216
20	7	476-477		26	4	872		32	4	666-667

C-S
 D-5 → NW
 NW
 NW
 SE
 SW
 NW
 SE
 NW
 SW

Williamston

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. REG. 1970
1/4 corner, Section 5, T4N, R1E, Williams Town Township
Ingham County

LIBR 3 PM 564

FILED

FOR CORNERS OF: LOCATED IN: CORNER CODE NUMBER
1. PUBLIC LAND SURVEY T. 4N. S. 1E. E. C-2
2. PROPERTY CONTROL: T. N. R. E.
3. MISCELLANEOUS: T. N. R. E.
4. LOT NO. RECORDED PLAT
5. PRIVATE CLAIMS

REGISTER OF DEEDS
MAY 14 3 43 PM '76
INGHAM COUNTY, MICH.
JAMES E. STEPHENS
FILING NUMBER

1. James E. Stephens do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above identified with circles on index code diagram (over) were, in a field survey on March 31, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1976, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of Law:

A. Description of original monument and accessories and or subsequent restoration:
The original monument and accessories were not found.

Checked records of 9 area Registered Land Surveyors.

B. Description of corner evidence found and or method applied in restoring or re-establishing corner:

A 3/4 inch iron pipe was set on a projection of a line between the NE corner of Section 1, T4N, R1E and the West line of GRAND BEND Subdivision at its intersection with a projection of an old fence line East of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
The 3/4 inch iron pipe set at the W 1/4 corner was witnessed with the following:

Survey tag on the East side of a 5" Poplar tree, S84°08'W 71.97 feet.
Survey tag on the SE side of a 6" Wild Cherry tree, N49°38'W 73.56 feet.
N89°24'E 27.89 feet to a 1 inch solid iron rod found at fence intersection.

SIGNED BY James E. Stephens DATE April 5, 1976


SURVEYOR'S MICHIGAN REGISTRATION NO. 18053

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY DATE

APPROVED AND SIGNED BY DATE

SURVEYOR'S MICHIGAN REGISTRATION NO.



Center Sec 4 413 413 9110 Wheatfield

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. PA. 1970

LIBR 3 PM 563

FILED

FOR CORNERS OF: LOCATED IN: CORNER CODE NUMBER
1. PUBLIC LAND SURVEY Sec. 4, T3N, R1E E. F2 G2 G3
2. PROPERTY CONTROL: T. N. R. E.
3. MISCELLANEOUS: T. N. R. E.
4. LOT NO. RECORDED PLAT
5. PRIVATE CLAIMS

REGISTER OF DEEDS
MAY 20 1 59 PM '76
INGHAM COUNTY, MICH.
JAMES E. STEPHENS
FILING NUMBER

1. Marvin F. Fouty do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 12-1-1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1975, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of Law:

F2 Description of original monument and accessories and or subsequent restoration:
Center Corner not set in government survey. The center of Section was established by County Surveyor G. Edwin Stokes in April 1884.

G2 Original monument and accessories obliterated.

G3 Original monument and accessories obliterated.

F2 Description of corner evidence found and or method applied in restoring or re-establishing corner:
Center of Section occupied by anchor post at intersection of 1/4 line fences. Set 1/2" bar and cap at base of anchor post

G2 Found anchor post called for as E 1/4 corner by Surveyor F.N. White. Set 1/2" bar and cap at base of anchor post.

G3 Found 1/2" bar in line road from witnesses furnished by Surveyor White.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F2 Center Sec. 4, T3N, R1E 1/2" bar and cap. G3 SE Cor. Sec. 4, T3N, R1E Nail and Tag W. side 20" Oak N 5.48' 1/2" bar Tag in Util. Pole NNW 26.92' Nail and Tag E. side 12" Poplar SW 18.58' 4" steel Gate Post NE 28.5' Nail and Tag E. side 12" Poplar E 33.88' 1 1/8" Square Iron N 33.00' Nail and Tag E. side 18" 1w. Map. NW 43.05'

SIGNED BY Marvin F. Fouty DATE April 26, 1976


SURVEYOR'S MICHIGAN REGISTRATION NO. 18989

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY DATE

APPROVED AND SIGNED BY DATE

SURVEYOR'S MICHIGAN REGISTRATION NO.



Section 5, T4N, R1E
Ingham County

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 4 PG 108

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 4 N. R. 1 E.	C-3, C-2
2. PROPERTY CONTROLLING IN SECTION	T. S. R. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. W.	
4. LOT NO. _____	RECORDED PLAT _____	
5. PRIVATE CLAIMS _____		

FILED

Nov 7 1 03 PM '77

REGISTER OF DEEDS
Paula Johnson
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October 27, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

- C-3 Original monument and accessories obliterated
Found old 1" bar at fence intersection North & East
- C-2 Original monument and accessories lost.
No record of corner being set in original survey.

B. Description of corner evidence found and or method applied in restoring or re-establishing corner:

- C-3 Set 1/2" bar & cap in Townline as established by N.E. & S.E. corners of Section 1, T4N, R1W, on line between South 1/4 of Section 5 as recorded and old 1" bar as mentioned above. Measured East 1384.59' to South 1/4 corner. Measured South to S.E. corner Section 1, 1193.82'
- C-2 Set 4" concrete monument on Townline as established above, Tape indexed distance (2621.26') north of S.W. corner of Section 5. Measured North to NE corner Section 1, T4N, R1W, 1472.54'. Measured North 152.50' to erroneously recorded corner shown in L 3, P 564.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- C-2 4" Concrete monument as described above
Nail & tag in North side 6" poplar, West, 75.25'
Nail & tag in S.W. side 6" poplar, N.W., 60.42'
3/4" pipe as recorded in L 3, P 564, North, 152.50'
- C-3 1/2" bar & cap as described above
1" bar, West in fence corner, 17.69'
Nail & tag in North side 22" oak, East, 16.32'
Nail & tag in N.W. side 4" poplar, N.N.E., 24.82'
Nail & tag in East side 4" oak, N.W., 20.98'

SIGNED BY Ronnie M. Lester DATE Nov 4, 1977


SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____



LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF-- LOCATED IN-- CORNER CODE NUMBER
1. PUBLIC LAND SURVEY 25 T. 2N S. 2W E. L-10, M-10
2. PROPERTY CONTROLLING IN SECTION T. N. S. R. E. W.
3. MISCELLANEOUS PROPERTY IN SECTION T. N. S. R. E. W.
4. LOT NO. RECORDED PLAT
5. PRIVATE CLAIMS

USE: 5 P 70
FILED
Nov 29 9 50 AM '78
REGISTER OF DEEDS
Ingham County, Mich.
FILING NUMBER


I, George M. Young, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 6/28, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 6/28, 1977, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- A. Description of original monument and accessories and/or subsequent restoration:
L-10 B. Ash 14" East 2 links
Surveyed & Recorded by A. Jackson September 4, 1845
M-10 D.O. 8" N 23 W 11 links
B. Ash 13" S 56 1/2 W 26 links
Surveyed & Recorded by A. Jackson September 4, 1845

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
L-10 Accessories obliterated. Found Anchor Post Accepted as perpetuation of Center.
M-10 Set 1/2" x 24" Re-rod with cap. @ proportion to distance between NE & SE corners of Section & 160 ch & 22 links E & W according to Survey by A. Jackson, September 4, 1845.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
L-10 #16 Nail & Cap in 6" Elm N 60° E 39.1'
#16 Nail & Cap in 8" Elm S 39.0'
#16 Nail & Cap in 15" Ash S 02° E 19.6'
Found Anchor Post Set 1/2" x 24" Re-rod with cap beside
M-10 #16 Nail & Cap in 12" Ash N 15° E 70.48'
#15 Nail & Cap in 20" Maple S 50° E 51.05'
#16 Nail in 18" Walnut S 30° W 36.10'
Set 1/2" re-rod with cap 0.1' under Asphalt

SIGNED BY George M. Young DATE October 11, 1978
SURVEYOR'S MICHIGAN REGISTRATION NO. 17640 (REAL)
FOR STATE AND UNITED STATES AGENCIES:
SIGNED BY DATE
APPROVED AND SIGNED BY DATE
SURVEYOR'S MICHIGAN REGISTRATION NO. (REAL)



INGHAM COUNTY - WILLIAMSTON TOWNSHIP
LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF-- LOCATED IN-- CORNER CODE NUMBER
1. PUBLIC LAND SURVEY T. 4 N. 1 E. C-1, D-1
2. PROPERTY CONTROLLING IN SECTION T. N. S. R. E. W.
3. MISCELLANEOUS PROPERTY IN SECTION T. N. S. R. E. W.
4. LOT NO. RECORDED PLAT
5. PRIVATE CLAIMS

USE: 5 P 69
FILED
Nov 27 3 54 PM '78
REGISTER OF DEEDS
Ingham County, Mich.
FILING NUMBER


I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on JUNE 27, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- A. Description of original monument and accessories and/or subsequent restoration:
C-1 Original monument and accessories obliterated.
Corner referred to by A. Jackson in survey dated June, 1843.
D-1 Original monument and accessories obliterated.
Corner referred to by A. Jackson in survey dated June, 1843.

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
C-1 Set 1/2" bar and cap at the base of an old broken corner post, fences south and east, from post.
Measured East 3468.84 to NE Corner Section 5, GLO Recorded 3472.92.
D-1 Set 1/2" bar and cap on line between NW Corner Section 5, and NE Corner Section 5, at proportional measurement from the NE Corner.
Measured East 2636.90, Measured West, 831.94.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
C-1 Set 1/2" Bar and cap
Nail & tag in East side 8" Ash, NE, 20.93'
Nail & tag in South side 18" Oak, ESE, 18.64'
Nail & tag in North side 24" Oak, WNW, 7.74'
D-1 Set 1/2" bar and cap 38 feet south of fence East & West and 26 feet West of fence North and South.
Nail & tag West side 12 poplar, NE, 25.30'
Nail & tag South side 18" Oak, West, 21.35'
Nail & tag West side 10" poplar, SW, 1.98'

SIGNED BY Ronnie M. Lester DATE 11/27/78
SURVEYOR'S MICHIGAN REGISTRATION NO. 18998
FOR STATE AND UNITED STATES AGENCIES:
SIGNED BY DATE
APPROVED AND SIGNED BY DATE
SURVEYOR'S MICHIGAN REGISTRATION NO. (REAL)



LIBER 6 PAGE 328

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in

Ingham

(County)

Located In:

Corner Code =#

1. Public Land Survey

T 4 N R 1 E

C-1, D-1

2. Property Controlling
In Section

S T R

3. Miscellaneous
Property In Sec.

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

APR 28 10 36 AM '87

REGISTER OF DEEDS

INGHAM COUNTY, MICH.

Register of Deeds Stamp & File Number

Larry A. Bryan, in a field survey on June 26, 1985, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-1 Original monument and accessories obliterated. Corner referred to by V.W. Royce in Survey dated February, 1911.

D-1 Corner not set in original Government Survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-1 Found pinch pipe at base of old corner post, fence lines North-South and East, 1/2" bar & cap #18998 as recorded in Liber 5, Page 69, Northeast 6.40 feet.

D-1 Set 1/2" bar & cap at base of old corner post, fence lines South, East-West, 1/2" bar & cap #18998 as recorded in Liber 5, Page 69, South 38 feet and West 20 feet.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-1 Northwest corner Sec. 5, T4N, R1E
Set nail & tag East side 36" Oak,
North, 10.00'
Set nail & tag South side 12" Ash,
N45°E, 26.93'
Set nail & tag North side 22"
Walnut, S50°E, 26.49'

D-1 North 1/4 corner Sec. 5, T4N, R1E
Set nail & tag East side 14" Oak, N10°E,
16.87'
Set nail & tag West side 6" Oak, West,
11.41'
Set nail & tag West side 10" Apple,
S45°E, 11.93'

Signed by

Surveyor's Michigan License No.

25832

Date

4-10-87

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 20, 1971
REVISED MAY 14, 1976
REVISED JAN., 1983

2075

328

13

SW CORNER, SECTION 4

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Section 9, T4N, R1E, Williamston Township, Ingham County, Michigan

LIBER 216 539

FILED

Nov 9 10 10 AM '73

REGISTER OF DEEDS

Paul M. Lewis
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

FOR CORNERS OF: LOCATED IN: CORNER CODE NUMBER
1. PUBLIC LAND SURVEY 2. T. 4 N. R. 1 E. 3 & F-4
PROPERTY CONTROLLING IN SECTION 3. S. R. E.
MISCELLANEOUS PROPERTY IN SECTION 4. T. S. R. E.
4. LOT NO. RECORDED PLAT
5. PRIVATE CLAIMS

I, Ron Helsel do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on August 24 1973 established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:
E-3 - Original Corner & Witnesses Lost.

F-4 - Original Corner Never Set.

MON BOX

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
E-3 Found 3/4" reinforcement bar, 1.5' East of physical centerline of Shoeman Road, and on physical centerline of Gulick Road to the East.

F-4 - Found rotted and leaning wood anchor post, with fence lines leading E, N, & S. Set 3/4" reinforcement bar at base of anchor post. Set corner from previous surveys.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-3 - 3/4" Reinforcement Bar	F-4 - 3/4" Reinforcement Bar
N & T - W. side 27" Elm	N & T - S. side 24" Maple
N & T - S. side Wood	N & T - S. side 30" Maple
Anchor Post	N & T - W. side 22" Maple
Centerline 3" iron	
Anchor post	
S35°E 53.72'	East 24.85'
N50°E 40.18'	West 27.55'
West 32.87'	S03°E 9.05'

SIGNED BY Ron Helsel DATE August 28, 1973

SURVEYOR'S MICHIGAN REGISTRATION NO. 18224

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Form No. 68-2000
Revised 1968, 68-2000, 68-2000, 68-2000

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 20, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

SW Cor. Sec. 4, T4N. R1E
LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 1 PG 223

FOR CORNERS OF: LOCATED IN: CORNER CODE NUMBER

1. PUBLIC LAND SURVEY 4 T. 4 N. R. 1 E. E-3
2. PROPERTY CONTROLLING IN SECTION T N E
3. MISCELLANEOUS PROPERTY IN SECTION T N E
4. LOT NO. RECORDED PLAT
5. PRIVATE CLAIMS

FILED

Nov 12 8 50 AM '71
REGISTER OF DEEDS
Mia Bell Humphrey
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

1. Fred N. White do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on Sept. 7, 1971, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1971, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

Original Corner & Witnesses Obliterated

B. Description of corner evidence found and or method applied in restoring or re-establishing corner:

Found 1/2" bar. 1" below point in E Shoeman & Gulick Rd
Verified from previous surveys and occupation lines

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1/2" iron bar. SE. MADE? SEE VIST PAGE (L-2, P. 539)
24" Hickory S 35° W 53.78'
4" Cor Post West 32.92'
Street sign N 45° E 36.98'

SIGNED BY Fred N. White
SURVEYOR'S MICHIGAN REGISTRATION NO. 12034

DATE Nov. 11, 1971

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ CHIEF OF SURVEY PARTY
APPROVED AND SIGNED BY _____ MICHIGAN REGISTERED LAND SURVEYOR

DATE _____
DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO.

Form No. 68, 8/72
PUBLISHED BY: S. C. P. PUBLISHING CO., FARMINGTON, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

Center Sec 24 Wheatfield

Wheatfield Twp., Ingham Co.

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. PA 1870 3 16 335

FOR CORNERS OF: Sec. LOCATED IN: CORNER CODE NUMBER
1. PUBLIC LAND SURVEY 24 T. 3 N. R. 1 E. L-8
2. PROPERTY CONTROL-
ING IN SECTION T. N. R. E.
3. MISCELLANEOUS
PROPERTY IN SECTION T. N. R. E.
4. LOT NO. RECORDED PLAT
5. PRIVATE CLAIMS

REGISTER OF DEEDS STAMP AND
FILING NUMBER

Feb 18 1 26 PM '75
REGISTER OF DEEDS
Paul M. Quinn
INGHAM COUNTY, MICH.

I, Ronnie H. Lester do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on December 10, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

L-8, Corner not set in original Government Survey. Survey in Vol. 2, Page 289 of Ingham County Surveyor's Notes, shows this corner to have been established by J.H. Mullett on May 23, 1856.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

L-8, Center of Section 24, T3N, R1E
Found large anchor post on East-West fence line, old fence to North. Lane fence 25' North for lane to East. No trace of witness trees of monument as called for. Set 1/2" bar on North side of post.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-8, 1/2" bar on North side 15" anchor post, old fences East and West
Nail & tag in SW side 32" oak, NW, 30.68'
Nail & tag North side 6" ash, SE, 1.20'
Nail & tag West side 48" elm, NNW, 25.35'

SIGNED BY Ronnie H. Lester DATE 12/12/74
SURVEYOR'S MICHIGAN REGISTRATION NO. 18998
FOR STATE AND UNITED STATES AGENCIES:
SIGNED BY DATE
APPROVED AND SIGNED BY DATE

REGISTERED LAND SURVEYOR

North Sec 8 Williamston

Williamston Twp., Ingham Co.

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. PA 1970 3 16 333

FOR CORNERS OF: Sec. LOCATED IN: CORNER CODE NUMBER
1. PUBLIC LAND SURVEY 8 T. 4 N. R. 1 E. D-3
2. PROPERTY CONTROL-
ING IN SECTION T. N. R. E.
3. MISCELLANEOUS
PROPERTY IN SECTION T. N. R. E.
4. LOT NO. RECORDED PLAT
5. PRIVATE CLAIMS

REGISTER OF DEEDS STAMP AND
FILING NUMBER

Feb 18 1 26 PM '75
REGISTER OF DEEDS
Paul M. Quinn
INGHAM COUNTY, MICH.

I, Ronnie M. Lester do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on JULY 8, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

D-3, Original monuments and accessories obliterated.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-3, Set 1/2" bar at intersection of fences North, South, East and West, Measurement to the East in close accord with original Government notes. Records of seven area surveyors revealed no additional or conflicting evidence.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-3, N 1/4 Corner of Section 8, T4N, R1E - Set 1/2" bar at intersection of fences North, South, East and West.
Nail & tag NE side 7" cherry, SE, 9.72'
Nail & tag East side twin 10" apple, SSE, 23.10'
Nail & tag South side 10" cherry, NNW, 12.48'

31101

SIGNED BY Ronnie M. Lester DATE July 10, 1974
SURVEYOR'S MICHIGAN REGISTRATION NO. 18998
FOR STATE AND UNITED STATES AGENCIES:
SIGNED BY DATE
APPROVED AND SIGNED BY DATE

REGISTERED LAND SURVEYOR

Section 5, T4N, R1E
Ingham County

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

1067 4 N 103

FOR CORNERS OF:-
1. PUBLIC LAND SURVEY...
2. PROPERTY CONTROL...
3. MISCELLANEOUS...
4. LOT NO...
5. PRIVATE CLAIMS...
LOCATED IN:-
E. 4. S. R. 1. S. R. 1. S. R. 1.
CORNER CODE NUMBER
C-3, C-2
FILED
NEW 7 1 03 PM '77
REGISTER OF DEEDS
GRACE G. JONES
MICHIGAN COUNTY, MICH.
REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in a field survey on October 27, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on October 27, 1977, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of Law:

A. Description of original monument and accessories and or subsequent restoration:

- C-3 Original monument and accessories obliterated
Found old 1" bar at fence intersection North & East
- C-2 Original monument and accessories lost.
No record of corner being set in original survey.

B. Description of corner evidence found and or method applied in restoring or re-establishing corner:

- C-3 Set 1/2" bar & cap in Townline as established by N.E. & S.E. corners of Section 1, T4N, R1W, on line between South 1/4 of Section 5 as recorded and old 1" bar as mentioned above. Measured East 1384.59' to South 1/4 corner. Measured South to S.E. corner Section 1, 1193.82'
- C-2 Set 4" concrete monument on Townline as established above, Tape indexed distance (2621.26') north of S.W. corner of Section 5. Measured North to NE corner Section 1, T4N, R1W, 1472.54'. Measured North 152.50' to erroneously recorded corner shown in L 3, P 564.

C. Description of monument for corner and accessories established to perpetuate location of the corner:

- C-2 4" Concrete monument as described above
Nail & tag in North side 6" poplar, West, 75.25'
- C-3 Nail & tag in S.W. side 6" poplar, N.W., 60.42'
- 3/4" pipe as recorded in L 3, P 564, North, 152.50'
- 1/2" bar & cap as described above
- 1" bar, West in fence corner, 17.69'
- Nail & tag in North side 22" oak, East, 16.32'
- Nail & tag in N.W. side 4" poplar, N.E., 24.82'
- Nail & tag in East side 4" oak, N.W., 20.98'


SIGNED BY: Ronnie M. Lester DATE: Nov 4, 1977

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY: _____ DATE: _____

APPROVED AND SIGNED BY: _____ DATE: _____



Ingham County

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

1068 4 N 107

FOR CORNERS OF:-
1. PUBLIC LAND SURVEY...
2. PROPERTY CONTROL...
3. MISCELLANEOUS...
4. LOT NO...
5. PRIVATE CLAIMS...
LOCATED IN:-
T. 4. S. R. 1. S. R. 1. S. R. 1.
CORNER CODE NUMBER
D-2
FILED
NEW 9 1 03 PM '77
REGISTER OF DEEDS
GRACE G. JONES
MICHIGAN COUNTY, MICH.
REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in a field survey on October 27, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on October 27, 1977, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of Law:

A. Description of original monument and accessories and or subsequent restoration:

- D-2 Corner not set in original government survey.
Corner established in 6/10/1845 by P. Jackson County Surveyor.

B. Description of corner evidence found and or method applied in restoring or re-establishing corner:

- D-2 Found old 1/2" pipe on occupation lines North and East. Used line between this pipe and South 1/4 corner of Section intersected with line between East 1/4 corner and West 1/4 corner to set center of section.
Measured East 2630.29 feet
West 1138.61 feet
South 2630.77 feet

C. Description of monument for corner and accessories established to perpetuate location of the corner:

- D-2 1/2" bar & cap as described above
Nail & tag in East side 5" maple, N.W., 17.66'
- Nail & tag in North side 8" maple, West, 7.00'
- Nail & tag in East side 5" maple, S.S.W. 5.16'
- Fence to East, South, 43.4'


SIGNED BY: Ronnie M. Lester DATE: 10/31/77

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY: _____ DATE: _____

APPROVED AND SIGNED BY: _____ DATE: _____



LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in

Ingham
(County)
William's town

Located In:

Corner Code #

1. Public Land Survey

T 4N R 1EE52. Property Controlling
in SectionS T R 3. Miscellaneous
Property in Sec.S T R

NOV 30 8 14 AM '94

REGISTER OF DEEDS

David Johnson
INGHAM COUNTY, MICH.

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat 5. Private Claims

I, Marvin Fouty, in a field survey on Sept. 4, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1. Post set in original Government Survey by Joseph Wampler D.S. in March 1826 with the following witnesses:
Ash 11" South 13 1/2
Lynn 36 N64W 19
2. A.P. Drake, County Surveyor reported using the corner in a survey dated March 1879 and recorded in Vol 3 Page 143 Ingham County Surveyors Records but did not mention monument or witnesses.
(Continued on Back)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Searched at probable location of the corner from witnesses above and found 3/4" rebar in monument box. Excavated around rebar and discovered it is imbedded in the top of a 6" wood post. The corner is 3.5' East of the centerline of Shoeman Road and 0.5' South of the centerline of Haslett Road on a fence line to the South. Survey dimensions from corner by various surveyors are Shellenbarger N2643.96'; Stephens N2643.68'; White N2643.91'; Bryan N2643.80'; R. Lester S2641.46'; R. Lester W2633.27'; Bryan E2633.79'; White E2633.83'; Stephens E 2634.50'. Accepted the 3/4" rebar in monument box as the perpetuated corner because of agreement with historical witnesses and measurements. Placed remonumentation cap #18989 on 3/4" pipe. Field work conducted by David Clifford, PS No. 25837

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- Standard 3/4" x 24" Ingham County Remonumentation Bar and PA345 Cap #18989 in monument box.
Found Stump AZ 18° 83.40'
Found Nail and Tag #18998 in 20" Hickory AZ 104° 103.73'
Found Nail and Tag #18998 in 38" Willow AZ 305° 103.95'
Southwest corner of Foundation House 519 Haslett Rd. AZ 40° 134.65'
Found Nail and Tag #25837 in 20" Cherry AZ 86° 207.25'
Found Maple Row Acres Sub.concrete monument AZ 176° 50.28'

Signed by Marvin FoutyDate Oct. 30, 1994Surveyor's Michigan License No. 18989FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

2739

P.A. 345 INGHAM COUNTY
PEER APPROVED 11/9/94 M

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF-- LOCATED IN-- CORNER CODE NUMBER
1. PUBLIC LAND SURVEY 25 T. 2N S. R. 2W E. L-10, M-10
2. PROPERTY CONTROLLING IN SECTION T. N. S. R. E. E.
3. MISCELLANEOUS PROPERTY IN SECTION T. N. S. R. E. E.
4. LOT NO. RECORDED PLAT
5. PRIVATE CLAIMS

Nov 29 9 50 AM '78
REGISTER OF DEEDS
INGHAM COUNTY, MICH.
FILING NUMBER

FILED

I, George M. Young, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 6/28 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 6/28 1977, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- L-10 B. Ash 14" East 2 links
Surveyed & Recorded by A. Jackson September 4, 1845
M-10 D.O. 8" N 23 W 11 links
B. Ash 13" S 56 1/2 W 26 links
Surveyed & Recorded by A. Jackson September 4, 1845

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- L-10 Accessories obliterated. Found Anchor Post Accepted as perpetuation of Center.
M-10 Set 1/2" x 24" Re-rod with cap. @ proportion to distance between NE & SE corners of Section & 160 ch & 22 links E & W according to Survey by A. Jackson, September 4, 1845.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- L-10 #16 Nail & Cap in 6" Elm N 60° E 39.1'
#16 Nail & Cap in 8" Elm E 39.0'
#16 Nail & Cap in 15" Ash S 02° E 19.6'
Found Anchor Post Set 1/2" x 24" Re-rod with cap beside
M-10 #16 Nail & Cap in 12" Ash N 15° E 70.48'
#16 Nail & Cap in 20" Maple S 50° E 51.05'
#16 Nail in 18" Walnut S 30° W 36.10'
Set 1/2" re-rod with cap 0.1' under Asphalt

SIGNED BY George M. Young DATE October 11, 1978

SURVEYOR'S MICHIGAN REGISTRATION NO. 17640

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

INGHAM COUNTY - WILLIAMSTON TOWNSHIP
LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF-- LOCATED IN-- CORNER CODE NUMBER
1. PUBLIC LAND SURVEY T. 4 N. R. 1 E. C-1, D-1
2. PROPERTY CONTROLLING IN SECTION T. N. S. R. E. E.
3. MISCELLANEOUS PROPERTY IN SECTION T. N. S. R. E. E.
4. LOT NO. RECORDED PLAT
5. PRIVATE CLAIMS

Nov 27 3 50 PM '78
REGISTER OF DEEDS
INGHAM COUNTY, MICH.
FILING NUMBER

FILED

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on June 27 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on June 27 1978, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- C-1 Original monument and accessories obliterated.
Corner referred to by A. Jackson in survey dated June, 1843.
D-1 Original monument and accessories obliterated.
Corner referred to by A. Jackson in survey dated June, 1843.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- C-1 Set 1/2" bar and cap at the base of an old broken corner post, fences south and east, from Measured East 3468.84 to NE Corner Section 5, GLO Recorded 3472.92.
D-1 Set 1/2" bar and cap on line between NW Corner Section 5, and NE Corner Section 5, at proportional measurement from the NE Corner. Measured East 2636.90, Measured West, 831.94.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- C-1 Set 1/2" Bar and cap
Nail & tag in East side 8" Ash, NE, 20.93'
Nail & tag in South side 18" Oak, ESE, 18.64'
Nail & tag in North side 24" Oak, MNW, 7.74'
D-1 Set 1/2" bar and cap 38 feet south of fence East & West and 26 feet West of fence North
Nail & tag West side 12 poplar, NE, 25.30'
Nail & tag South side 18" Oak, West, 21.35'
Nail & tag West side 10" poplar, SW, 1.98'

SIGNED BY Ronnie M. Lester DATE 11/23/78

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

LIBER 6 PAGE 328

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Ingham
(County)

Located in:

Corner Code: #

FILED

APR 20 10 36 AM '87

REGISTER OF DEEDS

Paul Johnson
INGHAM COUNTY, MICH.

Register of Deeds Stamp & File Number

1. Public Land Survey

T 4 N R 1 E

C-1, D-1

2. Property Controlling
In Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Larry A. Bryan, in a field survey on June 26, 19 85,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- C-1 Original monument and accessories obliterated. Corner referred to by
V.W. Royce in Survey dated February, 1911.
- D-1 Corner not set in original Government Survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- C-1 Found pinch pipe at base of old corner post, fence lines North-South
and East, 1/2" bar & cap #18998 as recorded in Liber 5, Page 69,
Northeast 6.40 feet.
- D-1 Set 1/2" bar & cap at base of old corner post, fence lines South, East-
West, 1/2" bar & cap #18998 as recorded in Liber 5, Page 69, South 38
feet and West 20 feet.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- C-1 Northwest corner Sec. 5, T4N, R1E
Set nail & tag East side 36" Oak,
North, 10.00'
Set nail & tag South side 12" Ash,
N45°E, 26.93'
Set nail & tag North side 22"
Walnut, S50°E, 25.49'
- D-1 North 1/4 corner Sec. 5, T4N, R1E
Set nail & tag East side 14" Oak, N10°E,
16.87'
Set nail & tag West side 6" Oak, West,
11.41'
Set nail & tag West side 10" Apple,
S45°E, 11.93'

Signed by

Surveyor's Michigan License No.

25832

Date

4-10-87

FOAM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

2075

328

138

NW CORNER, SECTION 4

Williamston Twp., Ingham Co.
LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER

3 M 161

FILED

FOR CORNERS OF:-	Sec.	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	5	T. 4 N. R. 1 E.	E-1
2. PROPERTY CONTROLLING IN SECTION		T. N. R. E.	
3. MISCELLANEOUS PROPERTY IN SECTION		T. N. R. E.	
4. LOT NO.		RECORDED PLAT	
5. PRIVATE CLAIMS			

JUL 12 2 06 PM '74

REGISTER OF DEEDS
Ingham County, Mich.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Ronnie M. Lester do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on May 15, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

E-1, Original monument and accessories obliterated.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-1, Re-set NE Corner of Section 5 from Dar-Lo Subdivision as recorded in Liber 25, Page 27, Ingham County records, Records of seven local surveyors failed to show any conflicting evidence.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-1, NE Corner of Section 5, T4N, R1E
Set 1/2" bar & cap, Corner falls 160.35' East of SE Corner Section 32, T5N, R1E
SE Corner Section 32, T5N, R1E, Found railroad spike, West, 160.35'
SE Corner Lot 53, Greenhills No. 1, 4" concrete monument, West, 193.94'
3/4" re-bar, East, 18.82'

SIGNED BY Ronnie M. Lester DATE May 18, 1974

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

724

Form No. 18, 1973
REVISED BY MICH. S. CO., ANN ARBOR, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

Will Set
Corner @
P.K.
All info
checks
DLK

W 1/4 CORNER, SECTION 4

W 1/4 Cor. Sec. 4, T4N, R1E
LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF: LOCATED IN: CORNER CODE NUMBER
1. PUBLIC LAND SURVEY 4 T. 4 N. R. 1 E. (E-2)
2. PROPERTY CONTROLLING IN SECTION T. N. R. 1.
3. MISCELLANEOUS PROPERTY IN SECTION T. N. R. 1.
4. LOT NO. RECORDED PLAT
5. PRIVATE CLAIMS

LIBER 1 1/2 221
FILED
Nov 12 8 50 AM '71
REGISTER OF DEEDS
Mia Bill Humphrey
INGHAM COUNTY, MICH.
REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Fred N. White do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on Sept 7 1971, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19. found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Original Corner & Witnesses obliterated

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 1/2" iron bar 1" below pav't in E Shoeman Rd.
Verified from previous surveys & occupation lines

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1/2" iron bar MON BOX
N.E. Corner of house foundation N 50° W 120.67'
NO NET 30" Oak N 45° E 64.23'
NO NET Corner Post East 34.17' LATH W/FLAGGING AND MON. TYPE PIECE OF
CONC. NEXT TO FAIRLY NEW FENCE POST

SIGNED BY Fred N. White
SURVEYOR'S MICHIGAN REGISTRATION NO. 12034
FOR STATE AND UNITED STATES AGENCIES:

DATE NOV. 11, 1971

SIGNED BY _____ DATE _____
APPROVED AND SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12034
Form No. 68, 6/72
PUBLISHED BY: S. CO., Kalamazoo, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Shiawassee
(County)

Located In:

Corner Code ##

RECORDED

94 SEP 22 PM 3:48

REGISTER OF DEEDS

Raye Hubbard
SHIAWASSEE COUNTY, MICH.

Register of Deeds Stamp & File Number

1. Public Land Survey T5N R 1E 12-13
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Terry L. Wiegman, in a field survey on August 24, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1) $\frac{1}{4}$ section post set in the original government survey by Joseph Wampler, Deputy Surveyor, in February, 1824 at 40.00 chains from the SE corner of Section 32. Intersected Meridian line at 30.26 chains from SE corner Section 32 at a point 31.75 chains North of the corner to Townships 4 & 5 North, Range 1 West.
- 2) County Surveyor V.W. Royce reported setting $\frac{1}{4}$ post on February 1, 1911 @ 40.14 $\frac{1}{2}$ chains from the SE corner of Section 32 with the following witness: B. Cherry 6" N45°W, 45" (Road Book 1A-Page 1).
- 3) County Surveyor O.M. Elliot reported using this corner in a survey dated 1958 with the same witness: B. Cherry 6" N45°W.
- 4) This corner is not referenced in the Plat of Green Hills No. 1 (L. 11, Pg. 188).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:


Search at probable location by extending South line of Green Hills No. 1 at prorated distance between the SE & SW corners of Section 32. No evidence of original or re-established corner was found and the witness was gone. The search area fell on a downed E-W fence line in the vicinity of an old occupation line to the North (cut-over area on West side-mature hardwoods on East side). Measurements to the North $\frac{1}{4}$ corner of Section 5, T4N, R1E (L. 8 of Corners, Pg. 103, Ingham County Records) showed it to fall 0.17' South of the extended South line of Green Hills No. 1 at a point 660.45' West of the SW corner of Green Hills No. 1. Measurements to the SW corner of Section 32 (same as NW corner Section 5, T4N, R1E-L. 6 of Corners, Pg. 328, Ingham County Records) showed it to fall 13.70' South of the extended South line of Green Hills No. 1. The location of this corner was questioned by Surveyor Royce in his February 1, 1911 survey recorded in Book F of Surveys and was advised by the Prosecuting Attorney to use the existing fence corner. The best evidence as to the location of the South $\frac{1}{4}$ corner of Section 32 points to re-establishing the corner on the extended South line of Green Hills No. 1 at a prorated distance between the SE and SW corners of Section 32.

40 chains (2640') x = 2643.10'
50.26 chains (3317.16') 3321.05'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set $\frac{1}{2}$ " bar & cap on old E-W fence line in vicinity of old occupation line to north with the following witnesses:

- SSE, 20.60' - Nail & tag in W. side 24" oak
W, 36.68' - Nail & tag in S. side 22" oak
NNE, 3.75' - Nail & tag in W. side 6" oak
NE, 19.60' - Nail & tag in SE side 12" poplar



Signed by Terry L. Wiegman

Date SEPTEMBER 20, 1994

Surveyor's Michigan License No. 39100

**REMONUMENTATION
SECTION 36, BATH TOWNSHIP
LAND CORNER RECORDATION CERTIFICATE**
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

Oct 11 8 49 AM '96

REGISTER OF DEEDS
CLINTON COUNTY, MICH.
Arden S. Pierson

LIBER 4, PAGE 156

Register of Deeds Stamp & File Number


For corners in

Clinton (County)	Located in:	Corner Code #
1. Public Land Survey	T 5N R 1W	M-13
Ingham County	T 4N R 1W	A-19
	T 5N R 1W	
	T 4N R 1W	
2. Property Controlling in Section	6 T 5N R 1W	
	9 T 4N R 1W	
3. Miscellaneous Property in Sec.	6 T 5N R 1W	
	9 T 4N R 1W	

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Arden S. Pierson P.S., in a field survey on July 16, 1996, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



N. 00° 43' 56\"/>

N. 89° 50' 12\"/>

A. Description of original monument and accessories and/or subsequent restoration:

- ◆ Original survey by Lucius Lyon, DS, 1826. From Post Corner of Townships 4 & 5 N, R1W, B. Oak 11\"/>

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/8\"/>

Set Standard Clinton County Monument and monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- Southeast Corner, Section 36
- *Set Standard Clinton County Monument and monument box.
- SE Corner Brick Fence at SE Corner Garage #9994 - N16°W - 124.87'
- Nail & tag #13039 in NW Side Power Pole - S75°W - 140.40'
- NW Corner Foundation of Garage - S15°E - 163.62'
- Nail & tag #13039 in SE Side 8\"/>

*Standard Clinton County Monument is a 2 1/4\"/>

Signed by Arden S. Pierson
Surveyor's Michigan License No. 13039

Date August 24, 1996

APPROVED BY
CLINTON COUNTY PEER GROUP
DATED 7/17/96
872

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JUL 26, 1991
REVISED MAY 14, 1995
REVISED JAN. 1993
REVISED OCT. 1988

2-2/13/96

REMONUMENTATION
SECTION 36, BATH TOWNSHIP
LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

LIBR

4 PAGE 254

 For corners in
Clinton
 (County)

Located in:

Corner Code #

1. Public Land Survey

T 58 R 1W

25-12

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lat No.

Recorded Plat

5. Private Claims

RECORDED

Dec 22 11 05 AM '97

 REGISTER OF DEEDS
 CLINTON COUNTY, MICH.
 Register of Deeds Stamp & File Number
 (Date) (Time)

1. Arden S. Pierson, PS

In a field survey on July 31, 1997

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- ◆ Original survey by Joseph Wampler, DS, 1924. Set 1/4 Mile East, witnessed by: W.O.3" - N34-1/2°W - 24 links; W.O.6" - S9-1/2°W - 58 links.
- ◆ Plat of Bonnie Meadows Estate No. 1, Liber 574, pages 272-274, dated May 1, 1979.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Located concrete monument at the Northeast corner of the Plat of Bonnie Meadows Estate No. 1, projected a line from the SE corner of section 36, through said NE corner the recorded distance of 2659.18 feet to the corner position. Accepted this point as a careful and faithful reestablishment of the position of the original corner - set standard Clinton County monument.

(SEE BACK OF SHEET FOR RELATIONSHIP OF LINE TO IRONS FOUND)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

East 4 Corner, Section 36

*Standard Clinton County Monument

Nail & tag #13039 in NW side 9" Elm - N41°E - 13.63'

Nail & tag #13039 in SW side 8" Oak - S41°E - 13.16'

Nail & tag #13039 in West side 12" Elm - S2°E - 32.52'

Nail & tag #13039 in South side 32" Maple - N85°W - 25.24'

4.6' East of fence line North & South

 APPROVED BY
 CLINTON COUNTY PEER GROUP
 DATED 7/22/97
 J. J. J.


*Standard Clinton County Monument is a 24" diameter Steel tube 30" long with a stamped brass cap and a breakaway magnetic base.

Signed by

Arden S. Pierson

Date

July 31, 1997

Surveyor's Michigan License No.

13039

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 1974

REVISED MAY 14, 1978

RECAPTURE FOR YOUR PROTECTION BY MICHIGAN, 1974

A 7/31/97

SOUTH 1/4 CORNER, SECTION 36, T5N, R1W, BATH TOWNSHIP, CLINTON COUNTY,
MICHIGAN (L-13)

CERTIFIED BOUNDARY SURVEY RECORDED IN LIBER 003, PAGE 623, DATED JULY 17, 1984
BY LARRY A. BRYAN P.S. #25832
(SHOWS POSITION OF CORNER)
FOUND 1/2" BAR AND CAP #19003, 5.0' SOUTH OF SOUTH EDGE OF ROAD.
FOUND NAIL AND TAG WEST SIDE 12" WALNUT - S45°E - 22.76'
FOUND NAIL AND TAG NORTH SIDE 18" OAK - WEST - 67.80'
FOUND NAIL AND TAG WEST SIDE 12" PINE - SOUTH - 41.65'

CERTIFIED BOUNDARY SURVEY RECORDED IN LIBER 004, PAGE 84, DATED JULY 17, 1984
BY LARRY A. BRYAN P.S. #25832
(SAME WITNESSES AS LIBER 003, PAGE 623.)

CERTIFIED BOUNDARY SURVEY RECORDED IN LIBER 004, PAGE 495, DATED MAY 31, 1990
BY LARRY A. BRYAN P.S. #25832
SOUTH 1/4 CORNER OF SECTION 36, T5N, R2W,
LIBER 002, PAGE 769
(SAME WITNESSES AS LIBER 003, PAGE 623.)

MORTGAGE REPORT RECORDED IN LIBER 582, PAGE 151 DATED NOVEMBER 25, 1992 BY
LARRY A. BRYAN P.S. #25832
(SHOWS POSITION OF CORNER)

LCRC LIBER 002, PAGE 769, DATED APRIL 6, 1990 BY LARRY A. BRYAN P.S. #25832
SOUTH 1/4 CORNER OF SECTION 36, T5N, R1W,
FOUND 1/2" IRON BAR AND CAP #19003 5.0' SOUTH OF SOUTH EDGE OF ROAD.
FOUND NAIL AND TAG WEST SIDE 12" WALNUT - S45°E - 22.76'
FOUND NAIL AND TAG NORTH SIDE 18" OAK - WEST - 67.80'
FOUND NAIL AND TAG WEST SIDE 12" PINE - SOUTH - 41.65'

PLAT OF BONNIE MEADOWS ESTATES NO. 3, RECORDED IN LIBER 007 OF PLATS, PAGES
56-58, DATED SEPTEMBER 14, 1993 BY LARRY A. BRYAN P.S. #25832
NOTES: SOUTH 1/4 CORNER OF SECTION 36, T5N, R1W, LIBER 002, PAGE 769

PLAT OF BONNIE MEADOWS LAKES ESTATES, RECORDED IN LIBER 8 OF PLATS, PAGES 52-
53, DATED 3/21/96 BY LARRY BRYAN PS#25832

CLINTON COUNTY REMONUMENTATION
SOUTH 1/4 CORNER OF SECTION 36, T5N, R1W, BATH TOWNSHIP, CLINTON COUNTY, MICHIGAN.
LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970 **LIBER 004 PAGE 339**

For corners in
CLINTON
 County

Located in:

Corner Code #

RECORDED

1. Public Land Survey

T 5N R 1W L-13

2. Property Controlling
in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No.

Recorded Plat

5. Private Claims

Dec 21 12 48 PM '99

REGISTER OF DEEDS
CLINTON COUNTY, MICH.County Recorder
Register of Deeds Stamp & File Number

I, Arden S. Pierson, PS, in a field survey on JULY 29, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
 TOWNSHIP BOUNDARY SURVEY BY LUCIUS LYON IN 1826.
 40.00 (CHAINS) SET H.M. POST

W.O. 5" - N51°E - .32 (21.12')
 B.O. 16" - N51 1/2°W - .27 (17.82')

-OVER-

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 FOUND 1/2" IRON AND CAP #19003 AS RECORDED IN LCRC LIBER 002, PAGE 789, DATED JULY, 1984 BY LARRY A. BRYAN P.S. #25832, AND ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE CORNER POSITION,

SET STANDARD CLINTON COUNTY MONUMENT WITH CARBONITE MARKER

* STANDARD CLINTON COUNTY MONUMENT IS A 2 1/2" DIAMETER STEEL TUBE, 30" LONG WITH A STAMPED BRASS CAP AND A BREAKAWAY MAGNETIC BASE.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.
SOUTH 1/4 CORNER OF SECTION 36, T5N, R1W, BATH TOWNSHIP, CLINTON COUNTY, MI (L-13)

STANDARD CLINTON COUNTY MONUMENT WITH CARBONITE MARKER.
 19.7' SOUTH OF PHYSICAL CENTERLINE COLEMAN ROAD.
 INGHAM COUNTY CORNER - EAST - DID NOT FIND.
 NAIL AND TAG #25832 IN SOUTHWEST SIDE 20" WALNUT - S20°E - 22.78'
 NAIL AND TAG #13039 IN NORTH SIDE 28" RED OAK - N70°W - 67.25'
 NAIL AND TAG #25832 IN NORTHEAST SIDE UTILITY POLE - N20°W - 92.75'
 NAIL AND TAG #13039 IN SOUTHWEST SIDE 24" OAK - S69°E - 84.83'

K-13 S89°15'24"W 2659.46'
 M-13 S89°50'12"E 2687.11'
 BEARINGS BASED ON SOLAR OBSERVATIONS TAKEN AT M-13

Signed by

Arden S. Pierson

Date JULY 29, 1999

Surveyor's Michigan License No.

13039



FORM APPROVED BY INGHAM STATE BOARD OF LAND SURVEYORS, JULY 22, 1991
 REVISED MAY 14, 1999
 REVISED JAN. 1988
 ADAPTED FOR WORD PROCESSING MARCH, 1999

11111

4 PAGE 255

